

**Environmental Monitoring Report
Phase-1,2 and 3 (Operation Phase)**



CONTENTS

1. Executive Summary
2. Summary of Monitoring Activities
3. Monitoring Results
4. Environmental Monitoring Form

Appendix

- A. Water and Waste Water Monitoring Report for August, 2023
- B. Water and Waste Water Monitoring Report for October, 2023
- C. Water and Waste Water Monitoring Report for December, 2023
- D. Air Monitoring Report for December, 2023
- E. Noise and Vibration Monitoring Report for December, 2023
- F. Traffic Volume Monitoring Report for December, 2023
- G. General Waste Disposal Record (September 2023 to February 2024)
- H. Sewage Treatment Monitoring Record (September 2023 to February 2024)
- I. Chemical consumption at Water Sending Station at TSEZ-B, Sludge Generated at Sewage Treatment Plant at TSEZ-A and Water Supply Volume to TSEZ-B (September 2023 to February 2024)



1. Executive Summary

The environmental inspection and compliance monitoring program will be implemented under the direction of Ministry of Natural Resources and Environmental Conservation (MONREC) with oversight by Thilawa SEZ Management Committee.

The monitoring record from August 2023 to Feb 2024 according to the Environment Monitoring Plan is submitted in conformity with the provision of Chapter 10, 10.1 Table 10.1/3 and 10.2, Table 10.2/3 Content of the ELA Report of Thilawa SEZ Development Project (Zone B).

2. Summary of Monitoring Activities

- a) Progress made to date on the implementation of the EMP against the submitted implementation schedule:

We submitted EMP for TSEZ Zone-B as following table.

Report No.	Description	Phase	Submission
1	Environmental Monitoring Report	Phase-1 Operation Phase	September, 2019
2	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	March, 2020
3	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	September, 2020
4	Environmental Monitoring Report	Phase-1 & 2 Operation Phase	March, 2021
5	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	September, 2021
6	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	March, 2022
7	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	September, 2022
8	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	March, 2023
9	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	September, 2023
10	Environmental Monitoring Report	Phase-1,2 & 3 Operation Phase	March, 2024

Report (No.10) is submitted this day attached with Operation Phase implementation schedule. Subsequent Operation Phase reports will be submitted on Bi-annually.

- b) Difficulties encountered in implementing of the EMP and recommendations for remedying those difficulties and steps proposed to prevent or avoid similar future difficulties:

None

- c) Number and type of non-compliance with the EMP and proposed remedial measures and timelines for completion of remediation:

- Depend on the exceeding parameters and situation

- d) Accidents or incidents relating to the occupational and community health and safety, and the environment:

Please refer to the attached Environmental Monitoring Form.



- e) Monitoring data on environmental parameters and conditions as committed in the EMP or otherwise required.

Please refer to the attached Environmental Monitoring Form.

3. Monitoring Result

Environmental Monitoring Plan report for operation phase implemented according to the following table, reference on Table 10.2-3, Chapter 10, EIA for Industrial Area of Zone-B.

Monitoring Plan (Operation Phase)

Category	Item	Location	Frequency	Remark
Air Quality	NO _x , SO ₂ , CO, PM ₁₀ , PM _{2.5}	Representative point inside the project area	1 week each in the dry and rainy seasons	December 2023, Air Quality Monitoring Report
Water Quality	Water temperature, pH, SS, DO, BOD ₅ , COD, color and odor, Total Nitrogen, Total Phosphorus, Sulphide, HCN, Oil, Grease, Formaldehyde, Phenols, Free chlorine, Zinc, Chromium, Arsenic, Copper, Mercury, Cadmium, Barium, Selenium, Lead, and Nickel	Outflow of retention pond to the creek (at least 3 sampling points/mixing point: discharge water, upstream water, and downstream water)	Every 3 month: Water temperature, pH, SS, DO, BOD ₅ , COD, color and odor. Every 6 month: all parameters	August 2023, October 2023 Water and Wastewater Quality Monitoring Report (Bi-monthly report) December 2023 Water and Wastewater Quality Monitoring Report (Bi-annually report)
Waste	-Amount of Non-hazardous waste management -Amount of hazardous waste management	Each Tenant	Twice/year (Submission of the environmental report by the tenants)	General waste disposal record
Soil Contamination	-Status of control of solid and liquid waste which causes soil contamination	Each Tenant	Twice/year (Submission of the environmental report by the tenants)	Monitoring will be started when the whole Zone-B is in Operation Stage
Noise and Vibration	- Noise and vibration level - Traffic Count	Tenants including Project Proponent	One time each in the dry and rainy seasons	Noise and Vibration Monitoring Report December 2023 Traffic Count Monitoring Report December 2023
Bottom Sediment	-Water quality monitoring (as indicator of the pollution of the bottom sediment)	Same as the water quality monitoring	-Additional analysis on the bottom sediment of creek, in case of finding continuous high concentration	Refer in Environmental Monitoring report
Hydrological Situation	-Checking the function of retention pond at heavy rain	Retention Pond	When the heavy rain	
Living and Livelihood/ Vulnerable Group/ Misdistribution of Benefit and Damage/ Children's Right	-The implementation status for CSR activities such as community support program	Around Project Site	Once/year	Refer in Environmental Monitoring report
Risks for Infectious Disease such as AIDS/HIV	-Status of measure against infectious diseases	Each tenant	Twice/year (Submission of the environmental report by the tenants)	
Occupational Health and Safety	-Record of accident and infectious diseases	Work site and office	Twice/year (Submission of the environmental report by the tenants)	



Category	Item	Location	Frequency	Remark
Community Health and Safety	Record of accidents and infectious diseases related to the community	Around the project site	Twice/year	Refer in Environmental Monitoring form
	The implementation status for CSR activities such as community support program	Around project site	Once/year	Refer in Environmental Monitoring form
Usage of Chemicals	Record of the type and quantity of chemicals and implementation status of control measures through self inspection	Each tenant (that uses chemicals)	Biannually	-

*Remark: Each locator will report their monitoring result directly to Environmental Section, One Stop Service Center, Thilawa SEZ Management Committee.

Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Environment Monitoring Form



Environment Monitoring Form

The latest results of the below monitoring items shall be submitted to Authorities on once at Pre -Construction Phase and on quarterly basis at Construction Phase, and on bi-annually base at Operation Phase. The items, standards to be applied, measurement points, and frequency for each monitoring parameter are established based on the EIA Report for Thilawa Special Economic Zone Development Project (Industrial Area of Zone B). Should there be any changes to the original plan, such change shall be reviewed and evaluated by environmental expert.

(1) General

1) Phase of the Project

- Please mark the current phase.

☐ Pre-Construction Phase ☐ Construction Phase ☒ Operation Phase

2) Obtainment of Environmental Permits

Name of permits	Expected issuance date	Actual issuance date	Concerned authority	Remarks (Conditions, etc.)
Approved letter for Environmental Impact Assessment (EIA) Report of Industrial Area, Thilawa Special Economic Zone (Zone-B)		29 th December 2016	Thilawa SEZ Management Committee	
Notification of the comments of Ministry of Natural Resources and Environmental Conservation regarding with the Standard Change of Wastewater Quality of Industrial Zone, Internal Regulations of Thilawa SEZ Zone-A and Zone-B	5 th January 2018	10 th January 2018	Thilawa SEZ Management Committee	

3) Response/Actions to Comments and Guidance from Government Authorities and the Public

Monitoring Item	Monitoring Results during Report Period	Duration of Report Period	Frequency
Number and contents of formal comments made by the public			Upon receipt of comments/ complaints
Number and contents of responses from Government agencies			

(2) Monitoring Results
1) Ambient Air Quality (December 2023)

NO₂, SO₂, CO, PM_{2.5}, PM₁₀

Location	Item	Unit	Measured Value (Mean)	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Referred International Standard	Frequency	Method	Note (Reason of excess of the standard)
AQ-1 (Monastery Compound of Phalan Village)	NO ₂	mg/m ³	0.078	0.596	0.2 mg/m ³ (1 Hour)	0.1 mg/m ³ (24 Hour)	-	One time / 6 months	Haz-Scanner EPA5	Refer to air quality report
	SO ₂	mg/m ³	0.020	0.082	0.02 mg/m ³ (24 Hours)	0.02 mg/m ³ (24 Hours)	-			
	CO	mg/m ³	0.200	2.297	-	10.26 mg/m ³ (24 Hours)	-			
	PM _{2.5}	mg/m ³	0.025	0.074	0.025 mg/m ³ (24 Hours)	0.025 mg/m ³ (24 Hours)	-			
	PM ₁₀	mg/m ³	0.044	0.124	0.05 mg/m ³ (24 Hours)	0.05 mg/m ³ (24 Hours)	-			

¹Remarks: Referred to the tentative target value of ambient air quality (Thilawa SEZ-B EIA Report for industrial area, Table 2.4-1). Reference to the air quality monitoring report (December 2023)

⁴²Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

Complaints from Residents

- Are there any complaints from residents regarding air quality in this monitoring period? ☐ Yes ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

2) (a) Water Quality - August 2023

Measurement Point: Effluent of Wastewater (SW-2 and SW-4 are attached as reference point only and they are natural creek water which are combine all the wastewater from the Local industrial water and domestic water from existing living environment. SW-7 is the main discharging point. GW-2 is also as reference point for monitoring of existing tube well located in the Monastery Compound near Zone-B area)

- Are there any effluents to water body in this monitoring period? ☐ Yes, ☒ No
If yes, please attach "Analysis Record" and fill in the items not to comply with Refereed International Standard

Location	Item	Unit	Measur ed Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequ- ency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Temperature	°C	29	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.7	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	24	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	3.37	-	-		Instrument Analysis Method	
	BOD ₅ ³	mg/L	63.82	50	Max 30		APHA 5210 B (5days BOD Test)	
	COD _C	mg/L	114	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Total Nitrogen (T-N)	mg/L	3.6	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	Refer to water quality report
	Total Phosphorous (T-P)	mg/L	<0.05	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	31.7	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 2150B (Threshold Odor Test)	
	Total Coliform ⁴	MPN/100ml	35000	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) ⁵	mg/L	80	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180.C)	
	Iron ^{6, 7}	mg/L	4.060	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
SW-4 (Reference point)	Mercury ⁸	mg/L	≤ 0.002	0.01	Max 0.005	Once per 2 months	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	Refer to water quality report
	Temperature	°C	28	< 3 (increase)	≤ 35		Instrument Analysis Method	
	pH	-	7.1	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS) ⁴	mg/L	206	50	Max 50		APHA 2540D (Dry at 105-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	4.96	-	-		Instrument Analysis Method	
	BOD5	mg/L	4.54	50	Max 30		APHA 5210 B (5days BOD Test)	
	CODCr	mg/L	14.7	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	0.6	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.31	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	14.46	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 2150B (Threshold Odor Test)	
	Total Coliform ⁴	MPN/100ml	35000	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) ⁵	mg/L	192	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180.C)	
	Iron ^{6, 7}	mg/L	14.860	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ⁸	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	

Location	Item	Unit	Measured Value (Max)	Country's Standard ¹²	Target value to be applied ¹¹	Frequency	Method	Note (Reason of excess of the standard)
SW-7 (Discharge Point)	Temperature	°C	28	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.7	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS) ⁷	mg/L	58	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	4.43	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	8.40	50	Max 30		APHA 5210 B (5days BOD Test)	
	CODCr	mg/L	21.7	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	11.4	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.20	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	26.25	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 21508 (Threshold Odor Test)	
	Total Coliform ⁸	MPN/100ml	93000	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	Max 10			
	Total Dissolved solids (TDS) ⁹	mg/L	126	-	Max 2000		APHA 5320 B (partition Gravimetric Method)	
	Iron ¹⁰	mg/L	3.270	3.5	Max 3.5		APHA 2540C (Total Dissolved Solids Dried at 380.C)	
GW-2 (Reference point)	Mercury ¹¹	mg/L	≤ 0.002	0.01	Max 0.005	Once per 2 months	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	Refer to water quality report
							APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Temperature	°C	29	< 3 (increase)	≤ 35		Instrument Analysis Method	
	pH	-	6.8	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	4	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	6.08	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	7.80	50	Max 30		APHA 5210 B (5days BOD Test)	
	CODCr	mg/L	12.2	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	< 0.5	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.65	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	29.66	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 21508 (Threshold Odor Test)	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
GW-2 (Reference point)	Total Coliform	MPN/100ml	23	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	Refer to water quality report
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) ⁴	mg/L	186	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ^{5, 7}	mg/L	7.350	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ⁸	mg/L	≤0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	

¹Remark: Reference to the Water and Wastewater Quality Monitoring Report (August 2023)

²Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

³Remark: SS results exceeded in the monitoring point of SW-4 than the target value be due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

⁴Remark: For the monitoring point of SW2 and SW-4 the result of total coliform exceeded than the target value ue due to three expected reasons: i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

⁵Remark: For the monitoring points of SW-2 the result of BOD exceeded might be due to two expected reasons i) high levels of organic pollution in the water, and ii) high nitrate levels which causes high plant growth and lower DO in the water body.

⁶ Remark: Recommendation from JICA Environmental expert (TSMC), to be more emphasized on Environmental and analyzing only.

⁷ Remark: For the monitoring point of SW-7, the results of SS exceeded due to expected reason the surface water run-off from bare land in Zone B

⁸ Remark: For the monitoring point of SW-7, the results of T-Coli exceeded due to expected reason i) natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the heavy rainfall and stormwater runoff can wash contaminants from surroundings into the retention pond, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels. Total coliforms do not affect

human health directly, self-monitoring was carried out to identify health impact by coliform bacteria. As for the result of E-Coli SW-7 was 24. It is considered that there is no significant impact to human health.

* Remark: For the monitoring point of GW-2, SW-2 and SW-4 the results of Iron exceeded due to the influence of natural origin (iron can reach out from the soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.

2) (a) Water Quality - October 2023

Measurement Point: Effluent of Wastewater (SW-2 and SW-4 are attached as reference point only and they are natural creek water which are combine all the wastewater from the Local industrial water and domestic water from existing living environment. SW-7 is the main discharging point. GW-2 is also as reference point for monitoring of existing tube well located in the Monastery Compound near Zone-B area)

- Are there any effluents to water body in this monitoring period?

☐ Yes, ☒ No

If yes, please attach "Analysis Record" and fill in the items not to comply with Refereed International Standard

Location	Item	Unit	Measure d Value (Max)	Country's Standard ²⁾	Target value to be applied ¹⁾	Frequ- ency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Temperature	°C	30	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.6	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	30	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	3.39	-	-		Instrument Analysis Method	
	BOD5	mg/L	5.06	50	Max 30		APHA 5210-B (5days BOD Test)	
	CODCr	mg/L	13.3	250	Max 125		APHA 5220-D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	1.8	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.25	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	14.13	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 2130B (Threshold Odor Test)	
	Total Coliform ³⁾	MPN/100 ml	35000	400	Max 400		APHA 9221-B (Standard Total Coliform Fermentation Technique)	
		mg/L	<3.1	10	Max 10		APHA 5520-B (partition Gravimetric Method)	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
	Oil and Grease	mg/L	96	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Total Dissolved solids (TDS) %	mg/L	2,060	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Iron ³	mg/l	≤ 0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ³							
SW-4 (Reference point)	Temperature	°C	30	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.9	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS) ¹	mg/L	102	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	4.33	-	-		Instrument Analysis Method	
	BOD5	mg/L	4.11	50	Max 30		APHA 5210 B (5days BOD Test)	
	CODCr	mg/L	9.6	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	< 0.5	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.16	2	Max. 2		APHA 4500-TP (Ascorbic Acid Method)	
	Color	TCU	13.94	-	150 Co.Pl ⁴		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 2150B (Threshold Odor Test)	
	Total Coliform ⁴	MPN/100 ml	1400	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) %	mg/L	112	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ³	mg/L	12,860	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ³	mg/l	≤ 0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
SW-7 (Discharge Point)	Temperature	°C	29	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to
	pH	-	7.2	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	38	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	6.01	-	-		Instrument Analysis Method	
	BOD5	mg/L	5.44	50	Max 30		APHA 5210 B (5days BOD Test)	
	CODCr	mg/L	4.4	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	< 0.5				HACH Method 10072 (TNT Persulfate Digestion Method)	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-7 (Discharge Point)	Total Phosphorous (T-P)	mg/L	0.05	-	Max. 80		APHA 4500-PE (Ascorbic Acid Method)	water quality report
	Color	TCU	3.75	2	Max. 2		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	150 Co.Pl *		APHA 2150B (Threshold Odor Test)	
	Total Coliform ²	MPN/100 ml	28000	-	-		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	400	Max 400		APHA 5520 B (partition Gravimetric Method)	Refer to water quality report
	Total Dissolved solids (TDS) *	mg/L	80	10	Max 10		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ²	mg/L	2.270	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ²	mg/	≤ 0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
GW-2 (reference point)	Temperature	°C	28	< 3 (increase)	≤ 35	Once per 2 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.8	6-9	6.0 - 9.0		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	2	50	Max 50		APHA 2540D (Dry at 103-105°C Method)	
	Dissolved Oxygen (DO)	mg/L	6.75	-	-		Instrument Analysis Method	
	BOD ₅	mg/L	3.76	50	Max 30		APHA 5210 B (5days BOD Test)	
	COD _{Cr}	mg/L	<0.7	250	Max 125		APHA 5220 D (Close Reflux Colorimetric Method)	
	Total Nitrogen (T-N)	mg/L	<0.5	-	Max. 80		HACH Method 10072 (TNT Persulfate Digestion Method)	
	Total Phosphorous (T-P)	mg/L	0.62	2	Max. 2		APHA 4500-PE (Ascorbic Acid Method)	
	Color	TCU	39.69	-	150 Co.Pl *		APHA 2120C (Spectrophotometric Method)	
	Odor	TON	1	-	-		APHA 2150B (Threshold Odor Test)	
	Total Coliform	MPN/100 ml	6.1	400	Max 400		APHA 9221 B (Standard Total Coliform Fermentation Technique)	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B (partition Gravimetric Method)	
	Total Dissolved solids (TDS) *	mg/L	200	-	Max 2000		APHA 2540C (Total Dissolved Solids Dried at 180°C)	
	Iron ²	mg/L	7.350	3.5	Max 3.5		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	
	Mercury ²	mg/	≤ 0.002	0.01	Max 0.005		APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	

*Remark: Reference to the Water and Wastewater Quality Monitoring Report (October 2023)

*2Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

*3Remark: SS exceeded in the monitoring point of SW-4 than the target value due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

*4Remark: For the monitoring point of SW-2 and SW4 the result of total coliform exceeded than the target value due to three expected reasons; i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

*5 Remark: For the monitoring point of SW-7, the results of T-Coli exceeded due to expected reason i) natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the heavy rainfall and stormwater runoff can wash contaminants from the surroundings into the retention pond, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels. Total coliforms do not affect human health directly, self-monitoring was carried out to identify health impact by coliform bacteria. As for the result of E-Coli SW-7 was 8.3. It is considered that there is no significant impact to human health.

*6 Remark: Recommendation from JICA Environmental expert (TSMC), to be more emphasized on Environmental and analyzing only.

*7 Remark: For the monitoring point of GW-2 and SW-4 the results of Iron exceeded due to the influence of natural origin (iron can reach out from the soil by run-off).

Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.

2) (b) Water Quality – December 2023

Measurement Point: Effluent of Wastewater (SW-2 and SW-4 are attached as reference point only and they are natural creek water which are combine all the wastewater from the Local industrial water and domestic water from existing living environment. SW-7 is the main discharging point. GW-2 is also as reference point for monitoring of existing tube well located in the Monastery Compound near Zone-B area)

- Are there any effluents to water body in this monitoring period?

☐ Yes, ☒ No

If yes, please attach "Analysis Record" and fill in the items not to comply with Refereed International Standard

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Temperature	°C	29	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to water quality report
	pH	-	7.5	6-9	6-9		Instrument Analysis Method	
	Suspended Solids (SS) ³	mg/L	70	50	Max 50		APHA 2540 D Method	
	Dissolved Oxygen (DO)	mg/L	3.57	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	17.67	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	50	250	Max 125		APHA 5220 D Method	
	Total Coliform ⁴	MPN/100 ml	160000	400	Max 400		APHA 9221 B Method	
	Total Nitrogen (T-N)	mg/L	2.3	-	Max 80		HACH Method 10072 Method	
	Total Phosphorous (T-P)	mg/L	0.31	2	Max 2		APHA 4500-P E Method	
	Color	TCU	36.03	-	Max 150		APHA 2120 C Method	
	Odor	TON	1	-	-		APHA 2150 B Method	
	Oil and Grease	mg/L	<3.1	10	Max 10		APHA 5520 B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	≤ 0.002	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.03		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.186	-	Max 1		APHA 3120 B Method	
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		HACH 8027 Method	Refer to water quality report
	Total Cyanide	mg/L	0.003	1	Max 1		APHA 4500-CN-C Method	
	Free Chlorine	mg/L	<0.1	-	Max 1		APHA 4500-CL G Method	
	Sulphide (S ₂ -)	mg/L	0.124	1	Max 1		HACH 8131 Method	
	Formaldehyde	mg/L	< 0.003	-	Max 1		HACH 8110 Method	
	Phenols	mg/L	< 0.002	0.5	Max 0.5		USEPA Method 420.1	
	Iron ⁵	mg/L	5.580	3.5	Max 3.5		APHA 3120 B Method	
	Total Dissolved Solids	mg/L	366	-	Max 2000		APHA 2540 C Method	
	Total Residual Chlorine	mg/L	< 0.1	0.2	Max 0.2		APHA 4500-CL G Method	
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1		ISO 11063:1994 Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-2 (Reference point)	Ammonia	mg/L	1.05	10	Max 10		HACH Method 10205 Method	
	Fluoride	mg/L	0.185	20	Max 20		APHA 4110 B Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
SW-4 (Reference point)	Temperature	°C	31	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to water quality report
	pH ³	-	10	6-9	6-9		Instrument Analysis Method	
	Suspended Solids (SS) ³	mg/L	114	50	Max 50		APHA 2540 D Method	
	Dissolved Oxygen (DO)	mg/L	8.85	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	11.69	30	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	30	250	Max 125		APHA 5220D Method	
	Total Coliform ⁴	MPN/100 ml	28000	400	Max 400		APHA 9221B Method	
	Total Nitrogen (T-N)	mg/L	3.8	-	Max 80		HACH Method 10072 Method	
	Total Phosphorous (T-P)	mg/L	0.38	2	Max 2		APHA 4500-P-E Method	
	Color	TCU	10.80	-	Max 150		APHA 2120C Method	
	Odor	TON	3	-	-		APHA 2150 B Method	
	Oil and Grease	mg/L	< 3.1	10	Max 10		APHA 5520B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	≤ 0.002	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.03		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.280	-	Max 1		APHA 3120 B Method	
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		HACH 8027 Method	Refer to water quality report
	Total Cyanide	mg/L	0.004	1	Max 1		APHA 4500-CN-C Method	
	Free Chlorine	mg/L	1.395	-	Max 1		APHA 4500-CL-G Method	
	Sulphide (S ₂ -)	mg/L	0.126	1	Max 1		HACH 8131 Method	
	Formaldehyde	mg/L	0.094	-	Max 1		HACH 8110 Method	
	Phenols	mg/L	0.010	0.5	Max 0.5		USEPA Method 420.1	



Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
SW-4 (Reference point)	Iron ³	mg/L	6.88	3.5	Max 3.5		APHA 3120 B Method	
	Total Dissolved Solids	mg/L	302	-	Max 2000		APHA 2540 C Method	
	Total Residual Chlorine	mg/L	< 0.1	0.2	Max 0.2		APHA 4500-CL G Method	
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1		ISO 11083:1994 Method	
	Ammonia	mg/L	0.11	10	Max 10		HACH Method 10305 Method	
	Fluoride	mg/L	1.395	20	Max 20		APHA 4110 B Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
SW-7 (Discharge point)	Temperature	°C	28	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to water quality report
	pH	-	7.9	6-9	6-9		Instrument Analysis Method	
	Suspended Solids (SS) ⁷	mg/L	366	50	Max 50		APHA 2540 D Method	
	Dissolved Oxygen (DO)	mg/L	4.68	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	8.47	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	19.4	250	Max 125		APHA 5220D Method	
	Total Coliform ⁸	MPN/100 ml	> 160000	400	Max 400		APHA 9221B Method	
	Total Nitrogen (T-N)	mg/L	3.5	-	Max 80		HACH Method 10072 Method	
	Total Phosphorous (T-P)	mg/L	0.78	2	Max 2		APHA 4500-P-E Method	
	Color	TCU	10.04	-	Max 150		APHA 2120C Method	Refer to water quality report
	Odor	TON	1.4	-	-		APHA 2150 B Method	
	Oil and Grease	mg/L	< 3.1	10	Max 10		APHA 5520B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	≤ 0.002	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.03		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.168	-	Max 1		APHA 3120 B Method	
	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		HACH 8027 Method	
	Total Cyanide	mg/L	< 0.002	1	Max 1		APHA 4500-CN-C Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²⁾	Target value to be applied ³⁾	Frequency	Method	Note (Reason of excess of the standard)
SW-7 (Discharge point)	Free Chlorine	mg/L	< 0.1	-	Max 1		APHA 4500-CL G Method	
	Sulphide (S ₂ -)	mg/L	0.515	1	Max 1		HACH 8131 Method	
	Formaldehyde	mg/L	0.396	-	Max 1		HACH 8110 Method	
	Phenols	mg/L	0.015	0.5	Max 0.5		USEPA Method 420.1	
	Iron ²⁺	mg/L	31.680	3.5	Max 3.5		APHA 3120 B Method	
	Total Dissolved Solids	mg/L	344	-	Max 2000		APHA 2540 C Method	
	Total Residual Chlorine	mg/L	< 0.1	0.2	Max 0.2		APHA 4500-CL G Method	
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1		ISO 11063:1994 Method	
	Ammonia	mg/L	0.74	10	Max 10		HACH Method 10205 Method	
	Fluoride	mg/L	1	20	Max 20		APHA 4110 B Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
GW-2 (Reference point)	Temperature	°C	29	< 3 (increase)	≤ 35	Once per 6 months	Instrument Analysis Method	Refer to water quality report
	pH	-	6.4	6-9	6-9		Instrument Analysis Method	
	Suspended Solids (SS)	mg/L	2	30	Max 50		APHA 2540 D Method	
	Dissolved Oxygen (DO)	mg/L	6.08	-	-		Instrument Analysis Method	
	BOD (5)	mg/L	7.68	50	Max 30		APHA 5210 B Method	
	COD (Cr)	mg/L	< 0.7	250	Max 125		APHA 5220D Method	
	Total Coliform	MPN/100 ml	140	400	Max 400		APHA 9221B Method	
	Total Nitrogen (T-N)	mg/L	< 0.5	-	Max 80		HACH Method 10072 Method	Refer to water quality report
	Total Phosphorous (T-P)	mg/L	0.65	2	Max 2		APHA 4500-P E Method	
	Color	TCU	74.55	-	Max 150		APHA 2120C Method	
	Odor	TON	1	-	-		APHA 2150 B Method	
	Oil and Grease	mg/L	< 3.1	10	Max 10		APHA 5520B Method	
	Mercury	mg/L	≤ 0.002	0.01	Max 0.005		APHA 3120 B Method	
	Zinc	mg/L	≤ 0.002	2	Max 2		APHA 3120 B Method	
	Arsenic	mg/L	≤ 0.010	0.1	Max 0.1		APHA 3120 B Method	
	Chromium	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Cadmium	mg/L	≤ 0.002	0.1	Max 0.03		APHA 3120 B Method	
	Selenium	mg/L	≤ 0.010	0.1	Max 0.02		APHA 3120 B Method	
	Lead	mg/L	≤ 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Copper	mg/L	≤ 0.002	0.5	Max 0.5		APHA 3120 B Method	
	Barium	mg/L	0.100	-	Max 1		APHA 3120 B Method	

Location	Item	Unit	Measured Value (Max)	Country's Standard ²	Target value to be applied ¹	Frequency	Method	Note (Reason of excess of the standard)
GW-2 (Reference point)	Nickel	mg/L	≤ 0.002	0.5	Max 0.2		APHA 3120 B Method	
	Cyanide	mg/L	< 0.002	0.1	Max 0.1		APHA 3120 B Method	
	Total Cyanide	mg/L	< 0.002	1	Max 1		HACH 8027 Method	
	Free Chlorine	mg/L	< 0.1	-	Max 1		APHA 4500-CN-C Method	
	Sulphide (S ₂ -)	mg/L	< 0.005	1	Max 1		APHA 4500-CL G Method	
	Formaldehyde	mg/L	< 0.005	-	Max 1		HACH 8131 Method	
	Phenols	mg/L	< 0.002	0.5	Max 0.5		HACH 8110 Method	
	Iron ¹⁰	mg/L	14.1	3.5	Max 3.5		USEPA Method 420.1	
	Total Dissolved Solids	mg/L	200	-	Max 2000		APHA 3120 B Method	
	Total Residual Chlorine	mg/L	< 0.1	0.2	Max 0.2		APHA 2540 C Method	
	Chromium (Hexavalent)	mg/L	< 0.05	0.1	Max 0.1		APHA 4500-CL G Method	
	Ammonia	mg/L	0.21	10	Max 10		ISO 11085:1994 Method	
	Fluoride	mg/L	0.227	20	Max 20		HACH Method 10205 Method	
	Silver	mg/L	≤ 0.002	0.5	Max 0.5		APHA 4110 B Method APHA 3120 B Method	

¹Remark: Reference to the Water and Wastewater Quality Monitoring Report (December 2023)

²Remark: Referred to the National Emission Quality Guideline (NEQG) 29th December 2015

³Remark: SS result exceeded in the monitoring point of SW-2, SW-4 than the target value due to expected i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

⁴Remark: For the monitoring point of SW2, SW4 the result of total coliform exceeded than the target value due to expected reasons i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) contaminants from the surroundings into the Shwe Pyauk creek may contain fecal matter and other pollutants, leading to increase coliform levels and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

⁵Remark: For the monitoring point of SW-2 and SW-4, the result of iron exceeded due to expected reason i) due to the influence of natural origin (iron can reach out from the soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low area by run-off or strong wind.

* Remark: The results of pH at the monitoring point of SW-4 exceeded the target value due to expected reason i) wastewater discharged that may contains detergents and soap-based products from the local industrial zone outside of Thilawa SEZ.

* Remark: For the monitoring point of SW-7, the results of SS exceeded due to the expected reason i) the surface water run-off from bare land in Zone B.

* Remark: For the monitoring point of SW-7, the results of Total Coliform exceeded due to the expected reason i) natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and animals, especially the excrement of the creature and death of freshwater fishes in and along the retention pond. Total coliforms do not affect human health directly, self-monitoring was carried out to identify health impact by coliform bacteria. As for the result of E-Coli SW-7 was 6.8. It is considered that there is no significant impact to human health.

* Remark: For the monitoring point of SW-7, Iron exceeded due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron and iron remains in the natural environment for a long time, additional water quality monitoring was carried out at the same location on (January 9, 2024) by MJTD for more identification of iron. The Result of additional monitoring is compared with that of December 5, 2023, the additional monitoring result is lower to 1204mg/L.

* Remark: For the monitoring point of reference tube well (GW-2), iron result exceeded than the target value due to expected reason i) the influence of natural origin (iron can reach out from soil by run-off). Moreover, Thilawa SEZ area is mainly composed of iron rich soil (lateritic soil), and it can be saturated in the underlying confined aquifer.

3) Soil Contamination (only operation phase)

Situations environmental report from tenants

- Are there any serious issues regarding soil contamination in this monitoring period? ☐ Yes, ☒ No

If yes please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Issues on Soil Contamination	Countermeasures

Remark: Soil contamination survey will be done after the whole Zone-B is operation stage.



4) Noise Level (December 2023)

Location	Item	Unit	Measured Value (Mean)	Measured Value (Max)	Country's Standard	Target value to be applied*	Referred International Standard	Frequency	Method	Note (Reason of excess of the standard)
Residential Area NV-2 (11 December 2023)	Leq (day)	dB(A)	50	55	Refer to NEQC Article 1.3	60	Refer the section 2.4 in EIA main report	One time / 3 months		
	Leq (evening)	dB(A)	-	-		55				
	Leq(night)	dB(A)	-	-		50				
Along the road (NV-1) (12 December 2023)	Leq (day)	dB(A)	60	62		75				
	Leq(night)	dB(A)	-	-		70				

*Remarks: Referred to the tentative target value of ambient air quality (EIA Report for industrial area, Table 2.4-8). Reference to the noise and vibration monitoring report (December 2023)

Remark: Due to has Curfew and we could monitor day time only.

Complaints from Residents

- Are there any complaints from residents regarding noise in this monitoring period? ☐ Yes, ☒ No

If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

5) Solid Waste

Measurement Point: Storage for Sludge* (Operation Phase)

Are there any wastes if sludge in this monitoring period?

☒ Yes, ☐ No

If yes, please report the amount of sludge and fill in the results of solid waste management activities.



Item	Date	Generated from	Unit	Value	Disposed to
General Waste with Green Waste	28 September 2023	Landscaping and Plantation	Kg	1850	Waste disposing to Than Lynn Development Committee, Yangon Division
General Waste with Green Waste	1 November 2023	Landscaping and Plantation	Kg	1900	Waste disposing to Than Lynn Development Committee, Yangon Division
General Waste with Green Waste	8 December 2023	Landscaping and Plantation	Kg	2800	Waste disposing to Than Lynn Development Committee, Yangon Division
General Waste with Green Waste	3 January 2024	Landscaping and Plantation	Kg	2950	Waste disposing to Than Lynn Development Committee, Yangon Division
Total			Kg	11,500	
Sludge	21 October 2023	Sewage Treatment Plant	Kg	6800	Golden DOWA Eco-System Myanmar Co., Ltd
Sludge	20 November 2023	Sewage Treatment Plant	Kg	7140	Golden DOWA Eco-System Myanmar Co., Ltd
Sludge	21 December 2023	Sewage Treatment Plant	Kg	6920	Golden DOWA Eco-System Myanmar Co., Ltd
Sludge	20 February 2024	Sewage Treatment Plant	Kg	6160	Golden DOWA Eco-System Myanmar Co., Ltd
Total			Kg	27,020	

Remarks: Waste amount is not only in TSEZ-B but also combine with TSEZ-A General Waste. Generate wastes are dried waste and weight value are estimated base on type of Trash collector car. Green Waste (Grass cutting waste) are used in Bio-fertilizer.

Note: Zone-B wastewater treated at Sewage Treatment of TSEZ-A. Above data are sludge generated from Sewage treatment plant of TSEZ-A.

6) (a) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
22 September -2023			+6.298	m	There is no tube well water consumption and Ground level monitor once per month

6) (b) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
20 October -2023			+6.297	m	There is no tube well water consumption and Ground level monitor once per month

6) (c) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
24 November -2023			+6.298	m	There is no tube well water consumption and Ground level monitor once per month

6) (d) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
22 December -2023			+6.298	m	There is no tube well water consumption and Ground level monitor once per month

6) (e) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
26 January -2024			+6.298	m	There is no tube well water consumption and Ground level monitor once per month

6) (f) Ground Subsidence Hydrology (GPS Location 16.67 N, 96.29E)

Duration (Month)	Water Consumption		Ground Level		Note
	Quantity	Unit	Quantity	Unit	
23 February -2024			+6.299	m	There is no tube well water consumption and Ground level monitor once per month

7) Offensive Odor (only operation phase)
Complaints from Residents

- Are there any complaints from residents regarding offensive odor in this monitoring period? ☐ Yes, ☒ No

If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Complaints from Residents	Countermeasures

Situations environmental report from tenants

- Are there any serious issues regarding offensive odor in this monitoring period? ☐ Yes, ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Issues on Soil Contamination	Countermeasures

8) Infectious disease, Working Environment, Accident
Information from contractor (construction phase) or tenants (operation phase)

- Are there any incidents regarding infectious disease, Working Environment, Accident in this monitoring period? ☐ Yes, ☒ No
If yes, please describe the contents of complains and its countermeasures to fill in below the table.

Contents of Incidents	Countermeasures
There is no accident and incident during monitoring period.	

Note: If emergency incidents are occurred, the information shall be reported to the relevant organizations and authorities immediately.

9) Resettlement Works for Project Affected Persons (PAPs) and Common Assets
Information from TSMC

- Please describe the progress and remarkable issues (if any) to fill in below the table.

Resentment Works		Progress in Narrative	Remarkable Issues
Projected Affected Persons	Land Acquisition and Relocation	There was no land acquisition and relocation work between September 2023 and February 2024.	
	Income Restoration Program	- Submitted CV for 6 non-PAPs from Aye Mya Thida village to Golden DOWA Company and 3 non-PAPs got	

		the job and working now from January 2024. - During the month September 2023 to February 2024, there are not specific activities except taking care of job opportunity for PAPs as per the requirement of factories.	
Common Assets	Relocation		

- Are there any grievances submitted, solved and pending regarding resettlement works?
If yes, please describe the contents of grievances to fill in below the table.

☐ Yes, ☒ No

Contents of Grievance	Response/ Countermeasures

10) CSR activities such as Community Support Program

- Are there any CSR activities implemented in this monitoring period?

☒ Yes, ☐ No

If yes, please describe the outline of CSR activities implemented to fill in below the table.

Date	Activities	Description (Location, Participant etc)	Available photos
September 2023 to February 2024	Scholarship/Provision of academic coverages for outstanding students around PACs	Provided the TSEZ Monthly Scholarship/Student Grant for High School Students at Two Highschool around PACs (16 Students) and Medical Student from Shwe Pyouk Village	

20 September 2023	Academic Funds for Students around TSEZ for the equitable access to quality educational opportunities	Provided academic funds for students at two high schools: BEHS Myaing Thar Yar and BEHS Aye Mya Thida	
22 September 2023	Scholarship/Provision of academic coverages for outstanding students around PACs	Engagement and skill development program for State school monthly scholarship (16) students - Excursion activity to Yangon City	
26 October 2023	TSEZ Mid-year CSR Engagement Meeting	Provided the Mid-year CSR engagement meeting which has attended 18 locators from Thilawa SEZ to be strengthen CSR activities for CSR Budget year April 2023-2024	



MJTD

MYANMAR JAPAN THILAWA DEVELOPMENT LIMITED

9 November 2023	TSEZ Kathina Robe Offerings Ceremony	Provided Kathina Robe Offering Ceremony at Kan Oo Monastery, Aye Mya Thida Ward, Kyauk Tan Township	
2-3 December 2023	Year End TSEZ Badminton Tournament 2023	Enhanced and built-up strong relationships among Thilawa SEZ all stakeholders and (20) Locators eagerly participated to the Badminton Tournament	
16-17 December 2023	Year End TSEZ Sepak Takraw Tournament 2023	Enhanced and built-up strong relationships among Thilawa SEZ all stakeholders and (21) Locators eagerly participated to the Sepak Takraw Tournament	



19 January 2024	Renovation and Repair Education Facilities for safe learning environment (School Rectification Work)	School Rectification Work at BEHS Aye Mya Thida: Roof valley modification work, Gutter replacement work, Toilet roofing replacement and Damaged ceiling replacement	BEHS Aye Mya Thida 
2-5 February 2024	Skills Development Program for School going aged children (primary school children) around PACs	Provided the motor skills (handwriting, painting) and intellectual skills (visual memory- memorizations skills) development activity at five primary school around Thilawa SEZ [Total - 302 students of KG and G1]	
6-7-8 February 2024	Food assistance program for financially hardship households around PACs	Provided each 12 kg rice bag for financially hardships (2200) households in accordance with the food assistance program yearly and maintain the good relation with community people	

19-20-21 February 2024	Employee Health Care Program for the Covid-19 Vaccination Booster Dose for TSEZ Employees	COVID-19 Booster Vaccination for TSEZ Locators from February 19 to 21 which administered booster vaccines to 1694 individuals of 37 Locators in Thilawa SEZ	
28 February 2024	Provision of clean drinking water supply to primary school around PACs	Provided 200GPD RO Water Treatment Machine at BEPS Aye Mya Thida (Pha Lan)	
September 2023 to February 2024	Electricity Support to Moe Kyo Swam Monastery	Provided the monthly electricity utility at Moe Kyo Swam Monastery	-

September 2023 to February 2024	Job assistance for vacancy announcement	Delivered over 60 posts of vacancy announcements from Locators of Thilawa SEZ to Thilawa Special Economic Zone Facebook Page	-
------------------------------------	--	---	---

End of Document



Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-A

Water and Waste Water Monitoring Report
August 2023

**WATER QUALITY MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
IN THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(Bi-Monthly Monitoring)

August 2023

Myanmar Koei International Ltd.



TABLE OF CONTENTS

CHAPTER 1: INTRODUCTION	1
1.1 General	1
CHAPTER 2: WATER QUALITY MONITORING	2
2.1 Monitoring Items	2
2.2 Description of Sampling Points	3
2.3 Monitoring Method	4
2.4 Monitoring Period	4
2.5 Monitoring Results	5
CHAPTER 3: CONCLUSION AND RECOMMENDATIONS	9
APPENDIX-1 FIELD SURVEY PHOTOS	A1-1
APPENDIX-2 LABORATORY RESULTS	A2-1

LIST OF TABLES

Table 2.1-1 Monitoring Items for Water Quality	2
Table 2.2-1 Outline of Sampling Points	3
Table 2.3-1 Analytic Method for Water Quality	4
Table 2.4-1 Sampling Time of Each Point	4
Table 2.4-2 Tide Record for Yangon River, Myanmar	4
Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek	6
Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well	7

LIST OF FIGURES

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring	1
--	---

CHAPTER 1: INTRODUCTION

1.1 General

Thilawa Special Economic Zone (SEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report and Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area. As for the monitoring of the water quality, total four sampling points are set for water quality survey, named SW-2, SW-4, SW-7 and GW-2 have been monitored in Thilawa SEZ and its surrounding area in timely manner. Among the four locations, SW-7 is main discharged point of Zone B during the operation stage. Moreover, GW-2 is monitored as a reference of existing tube well located in the monastery compound of Phalan village which is situated next to the southern boundary of the industrial area of Zone B. Location of sampling points for water quality monitoring is shown in Figure 1.1-1.



Source: Google Earth

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring

CHAPTER 2: WATER QUALITY MONITORING

2.1 Monitoring Items

Sampling points and parameters for water quality monitoring are determined to cover the environmental monitoring plan of the ELA report.

Water quality sampling was carried out at four locations. Among the four locations, water flow measurement was carried out at three locations (SW-2, SW-4 and SW-7) where can be measured by current meter. Monitoring items and sampling points are summarized in Table 2.1-1.

Table 2.1-1 Monitoring Items for Water Quality

No.	Parameters	SW-2	SW-4	SW-7	GW-2	Remarks
1	Water Temperature	○	○	○	○	On-site measurement
2	pH	○	○	○	○	On-site measurement
3	DO	○	○	○	○	On-site measurement
4	Suspended Solids	○	○	○	○	Laboratory analysis
5	BOD ₅	○	○	○	○	Laboratory analysis
6	COD _{Cr}	○	○	○	○	Laboratory analysis
7	Color	○	○	○	○	Laboratory analysis
8	Odor	○	○	○	○	Laboratory analysis
9	Oil and Grease	○	○	○	○	Laboratory analysis
10	Total Nitrogen (T-N)	○	○	○	○	Laboratory analysis
11	Total Phosphorus (T-P)	○	○	○	○	Laboratory analysis
12	Total Coliform	○	○	○	○	Laboratory analysis
13	Total Dissolved solids (TDS) (Self-monitoring)	○	○	○	○	Laboratory analysis
14	Iron (Self-monitoring)	○	○	○	○	Laboratory analysis
15	Mercury (Self-monitoring)	○	○	○	○	Laboratory analysis
16	Escherichia Coli (Self-monitoring)	-	-	○	○	Laboratory analysis
17	Flow Rate	○	○	○	-	On-site measurement

Source: Myanmar Koei International Ltd.

2.2 Description of Sampling Points

The outline of sampling points is mentioned in Table 2.2-1. The photos of conducting field survey at each sampling points are mentioned in Appendix-1.

Table 2.2-1 Outline of Sampling Points

No.	Station	Detailed Information
1	SW-2	Coordinate- N - 16° 40' 20.69", E - 96° 17' 18.04"
		Location - Upstream of Shwe Pyauk Creek
		Survey Item - Surface water sampling and water flow rate measurement
2	SW-4	Coordinate- N - 16° 39' 42.84", E - 96° 16' 27.42"
		Location - Downstream of Shwe Pyauk Creek
		Survey Item - Surface water sampling and water flow rate measurement
3	SW-7	Coordinate - N - 16° 40' 13.25", E - 96° 17' 5.66"
		Location - Outlet of retention pond of Zone B before connecting to Shwe Pyauk Creek
		Survey Item - Discharge water sampling and water flow rate measurement
4	GW-2	Coordinate - N - 16° 39' 25.30", E - 96° 17' 15.60"
		Location - In the monastery compound of Phalan village
		Survey Item - Ground water sampling

Source: Myanmar Koen International Ltd.

SW-2 (Reference Point)

SW-2 was collected at the upstream of Shwe Pyauk creek. This sampling point is located in the northeast of Zone B area and at the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northwest and local industrial zone in the east respectively.

SW-4 (Reference Point)

SW-4 was collected at the downstream of Shwe Pyauk creek, after mixing of discharge water from local industrial zone, Thilawa SEZ Zone A and Zone B, which is flowing from east to west and then entering into the Yangon River. The distance is about 2.15 km downstream of SW-2. This sampling point is located in the west of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northeast, local industrial zone in the east and paddy fields in the south and west respectively.

SW-7 (Discharged Point)

SW-7 is main discharged point of Zone B during operation stage. The distance is about 434 m downstream of SW-2. This sampling point is located at outlet of retention pond of Zone B, in the north of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the north and local industrial zone in the east respectively.

GW-2 (Reference of Existing Tube Well)

GW-2 was collected from tube well as ground water sample. It is located in the monastery compound of Phalan village. The surrounding areas are Thilawa SEZ Zone A in the north, Phalan village in the south and fields in the west and local industrial zone in the northeast and operation of Thilawa SEZ Zone B in the east and northeast respectively.

2.3 Monitoring Method

All water samples were collected with cleaned sampling bottles and analyzed by the following standard method as shown in Table 2.3-1. All samples were kept in iced boxes keeping at 2-4 °C and were transported to the laboratory. Among the parameters; water temperature, pH and DO were measured by the on-site instrument "Horiaba, U-52" and water flow rate was also conducted by using the on-site instrument "JFE Digital Current Meter".

Table 2.3-1 Analytic Method for Water Quality

No.	Parameter	Method
1	Water Temperature	Instrument Analysis Method (Horiaba, U-52, Multi Water Quality Checker)
2	pH	Instrument Analysis Method (Horiaba, U-52, Multi Water Quality Checker)
3	Dissolved Oxygen (DO)	Instrument Analysis Method (Horiaba, U-52, Multi Water Quality Checker)
4	Suspended Solids (SS)	APHA 2540D (Dry at 103-105°C Method)
5	BOD ₅	APHA 5210 B (5 days BOD Test)
6	COD _{Cr}	APHA 5220D (Close Reflux Colorimetric Method)
7	Color	APHA 2120C (Spectrophotometric Method)
8	Odor	APHA 2150 B (Threshold Odor Test)
9	Oil and Grease	APHA 5520B (Partition-Gravimetric Method)
10	Total Nitrogen (T-N)	HACH Method 10072 (TNT Persulfate Digestion Method)
11	Total Phosphorous (T-P)	APHA 4500-P E (Ascorbic Acid Method)
12	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)
13	Total Dissolved Solids (TDS)	APHA 2540C (Total Dissolved Solids Dried at 180°C Method)
14	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
15	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
16	Escherichia Coli	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
17	Flow Rate	Detection of Electromagnetic Elements (Real-time measurement by APM 213-D Digital Current Meters)

Source: Myanmar Koei International Ltd.

2.4 Monitoring Period

Water quality and water flow rate monitoring were conducted on 8 August 2023, and sampling time is shown in Table 2.4-1 to avoid tidal effect. The tide record for Yangon River, Myanmar 8 August 2023 is shown in Table 2.4-2.

Table 2.4-1 Sampling Time of Each Point

No.	Station	Sampling Time
1	SW-2	08/08/2023 12:31
2	SW-4	08/08/2023 11:40
3	SW-7	08/08/2023 09:41
4	GW-2	08/08/2023 08:10

Source: Myanmar Koei International Ltd.

Table 2.4-2 Tide Record for Yangon River, Myanmar

Date	Time	Height (m)	Tide Conditions
08/08/2023	04:06	1.43	Low Tide
	09:00	5.89	High Tide
	16:27	1.70	Low Tide
	21:20	5.49	High Tide

Source: Myanmar Port Authority, Tide Table for the Yangon River and Elephant Point, 2023.

2.5 Monitoring Results

Results of water quality monitoring at discharged point, discharged creek are summarized in Table 2.5-1. Analytical results of the laboratory are described in Appendix-2. The results were compared with the target value of effluent water quality discharged to water body stipulated in the EIA report.

2.5.1 Results of Discharged Point and Discharged Creek

As the comparison with the target value, the results of suspended solid (SS), BOD_{50} , total coliform and iron exceeded the target values.

Result of Discharged point

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the heavy rainfall and stormwater runoff can wash contaminants from the surroundings into the retention pond, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, E. Coli analysis was carried out alternatively to identify the health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

Result of Reference Monitoring points (Discharged Creek)

As for the result of SS, results at the surface water monitoring points (SW-4) exceeded the target values. The exceeded results for SS maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

As for the result of BOD_{50} , results at the surface water monitoring point (SW-2) exceeded the target value. The possible reason for exceeded BOD_{50} values maybe due to i) high levels of organic pollution in the water, and ii) high nitrate levels which causes high plant growth and lower DO in the water body.

As for the result of total coliform, results at surface water monitoring points (SW-2) and (SW-4) exceeded the target value due to three expected reasons: i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

As for the result of iron, the result at the monitoring point of surface water monitoring point (SW-2) and (SW-4) exceeded the target value. The possible reason for exceeded values in surface water (SW-2) and (SW-4) maybe due to the influence of natural origin (iron can reach out from the soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.



Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek

No.	Parameters	Unit	SW-2	SW-4	SW-7	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	29	28	28	≤ 35
2	pH	-	6.7	7.1	6.7	6~9
3	Dissolved Oxygen (DO)	mg/l	3.37	4.96	4.43	-
4	Suspended Solid (SS)	mg/l	24	206	58	50
5	BOD ₅	mg/l	63.82	4.54	8.40	30
6	COD _{Cr}	mg/l	114.0	14.7	21.7	125
7	Color	TCU (True Color Unit)	31.70	14.46	26.25	150
8	Odor	TON (Threshold Odor Number)	1	1	1	-
9	Oil and Grease	mg/l	< 3.1	< 3.1	< 3.1	10
10	Total Nitrogen (T-N)	mg/l	3.6	0.6	11.4	80
11	Total Phosphorus (T-P)	mg/l	< 0.05	0.31	0.20	2
12	Total Coliform	MPN/100ml	35000.0	35000.0	42000.0	400
13	Total Dissolved solids (TDS)	mg/l	80	192	126	2000
14	Iron	mg/l	4.060	14.860	3.270	3.5
15	Mercury	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	-	-	24.0	(1000)* (CFU/100ml)
17	Flow Rate	m ³ /s	0.27	0.76	1.03	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at discharged creek, the quality standard for water bath in Japan, (Ministry of Environment, 1997) is set as a reference value for self-monitoring of E. coli for surface water monitoring. However, due to limitation of capacity for analytical laboratory in Myanmar, the method to analyze the "Colony Forming Unit (CFU)" is not available in Myanmar. Therefore, the results of "Most Probable Number (MPN)" are assumed similar to CFU values and compared with reference values. Once the method to analyze the CFU will be available in Myanmar, the analytical method will be changed.

Source: Myanmar-Koer International Ltd.



2.5.2 Result of Reference Tube Well

Result of water quality monitoring at reference tube well monitoring point is shown in Table 2.5-2. As the comparison with the target value, the result of iron exceeded the target value.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 9.182 mg/l in August 2022 and most of the iron concentration results (from April 2019 to August 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (laterite soil), and it can be transported to the low land area by run-off.

Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well

No.	Parameters	Unit	GW-2	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	29	≤ 35
2	pH	-	6.8	6-9
3	Dissolved Oxygen (DO)	mg/l	6.08	-
4	Suspended Solid (SS)	mg/l	4	50
5	BOD ₅	mg/l	7.80	30
6	COD _{Mn}	mg/l	12.2	125
7	Color	TCU (True Color Unit)	29.66	150
8	Odor	TON (Threshold Odor Number)	1	-
9	Oil and Grease	mg/l	< 3.1	10
10	Total Nitrogen (T-N)	mg/l	< 0.5	80
11	Total Phosphorous (T-P)	mg/l	0.65	2
12	Total Coliform	MPN/100ml	23.0	400
13	Total Dissolved solids (TDS)	mg/l	186	2000
14	Iron	mg/l	7.350	5.5
15	Mercury	mg/l	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	< 1.8	(100)* (MPN/100ml)
17	Flow Rate	m ³ /s	-	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at monitoring point for ground water, B1 (irrigation water) of National Technical Regulation on Surface Water Quality in Vietnam (No. QCVN 08:2008/BTNMT) is set as a reference value of self-monitoring for ground water monitoring.

Source: Myanmar Koni International Ltd.



2.5.3 Comparison of Results of Water Quality Exceed the Target Value between Previous Monitoring and August 2023 Monitoring

In order to overview the exceed the target values of the concerned parameters during the present monitoring (August 2023), the results of the exceed parameters with respective sampling points are compared with the previous monitoring results since August 2022.

Regarding the results of the parameter of discharge point, suspended solid amount at SW-7 is higher than the target value in October, December 2022 and April, August 2023. Moreover, total coliform amount at SW-7 is higher than the target value in August 2022 and February, June, August 2023. The concentrations of total coliform at SW-7 are extending from 2300 MPN/100ml to the detection limit (>160000 MPN/100ml). Total coliform concentration at SW-7 is obviously reached to the detection limit in the early and mid-rainy season and it might be the effect of storm water run-off. Moreover, iron concentration at GW-2 is always higher than the target value except the result of April 2023. It is observed that iron concentration at GW-2 is higher throughout monsoon and winter time.

On the other hand, it is observed that some parameters at the reference monitoring points (SW-2 and SW-4) are also higher than the target value. As for the result of SS concentration, the result of SW-4 is higher than the target value during the surveys except April 2023, ranging from 78 to 558 mg/l. It is clear that SS concentrations at SW-4 are higher during rainy season due to the storm water run-off from the surrounding. As for the result of BOD_{50} at SW-2, it is higher than the target value in this monitoring survey (August 2023), but the results are lower than the target value in previous surveys. Although the result of iron at SW-2 is higher than the target value only in August 2022, June and August 2023, iron at SW-4 is higher in five monitoring surveys (August, October, December 2022 and June, August 2023) ranging from 4.376 to 22.626 mg/l. It is revealed that high concentration of iron at SW-4 occurred throughout rainy season till the beginning of winter time. It is obvious that total coliform at SW-2 is higher in six monitoring surveys among seven (ranging from 1300 to >160000 MPN/100ml) while the result at SW-4 is higher in all monitoring surveys (ranging from 4600 to >160000 MPN/100ml). Especially the total coliform amount at SW-2 was reached to the detection limit (>160000 MPN/100ml) in August 2022 and June 2023 as well as at SW-4 in October 2022 and June 2023 respectively. It is possible to say that the present condition of the water quality reflects the background condition of the surrounding environment of Thilawa SEZ.

The expected reasons for the results exceed the target value of concerned parameters are discussed in the upper section of this monitoring report.



CHAPTER 3: CONCLUSION AND RECOMMENDATIONS

As described in Chapter 2 (Section 2.5), the results of suspended solid (SS) at (SW-4 and SW-7), BOD₅ at (SW-2), total coliform at (SW-2, SW-4 and SW-7) and iron at (SW-2 and SW-4), in surface water, and the results of iron at (GW-2) in ground water exceeded the target value in this monitoring period for operation stage of Thilawa SEZ Zone B.

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because there are various kinds of vegetation and creature such as birds, and small animals in and along the retention pond.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, self-monitoring for E. Coli analysis was carried out to identify health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

As for the result of BOD₅, the result at the monitoring point of surface water monitoring point (SW-2) exceeded the target value. The possible reason for exceeded values in surface water (SW-2) maybe due to the high levels of organic pollution in the water and high nitrate levels which causes high plant growth and lower DO in the water body.

As for the result of SS at reference monitoring point (SW-4), total coliform and iron at reference monitoring point (SW-2 and SW-4) exceeded the target values. The exceeded results for SS at (SW-4) maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

The exceeded results for total coliform at (SW-2 and SW-4) maybe due to three expected reasons; i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

The expected reason for exceeding the target value of iron at reference monitoring point (SW-2 and SW-4) may be due to the influence of natural origin (iron can reach out from soil by run-off), the surrounding high land areas is comprised of lateritic soils and it can be transported to the low land area by run-off.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 9.182 mg/l in August 2022 and most of the iron concentration results (from April 2019 to August 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.



As for future subject for main discharged points of Thilawa SEZ Zone B, the following action may be taken to maintain the target value of total coliform and appropriate water quality monitoring:

- To continue monitoring *Escherichia coli* (*E. coli*) level to identify health impact by coliform bacteria.

End of the Document

FOR DISCHARGED POINT OF THILAWA SEZ ZONE B



Surface water sampling and onsite measurement at SW-7

**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**



Surface water sampling and onsite measurement at SW-2



Surface water sampling and onsite measurement at SW-4



Ground water sampling and onsite measurement at GW-2

APPENDIX-2 LABORATORY RESULTS



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**

DDMM

Thilawa Special Economic Zone Development Co., Ltd.
Water Quality Monitoring & Management Division
(Water Quality Monitoring)



Report No. : QM-WQ-20230808
Revision No. : 1
Report Date : 25 August, 2023
Registration No. : 0001-1281

Analysis Report

Client Name : Myanmar Japan Thilawa Development Co., Ltd.
Address : No. 36/A, 1st floor, Shwe Dhe Seik Condominium, The Seik Road, Thilawa Township, Yangon Region
Project Name : Environmental Monitoring Report for Zone A & B
Sample Description :
Sample Name : PML Site 2 (WB)
Sample No. : W-20230808
Water Profile No. : -
Sampling Date : 8 August, 2023
Sampling By : Cassimere
Samples Received Date : 8 August, 2023
Analysis Date : 8-11/08/2023

No.	Parameter	Method	Unit	Result	SDQ
1	pH	APHA 9245C (25°C at 10.1-14.0°C, Potenti)	mg/L	7.8	-
2	BOD (5)	APHA 5211A (5 days BOD Test)	mg/L	64.80	1.80
3	COD (Cr)	APHA 5210 (Closed Reflux Colorimetric Method)	mg/L	114.5	0.5
4	Oil and Grease	APHA 9223B (Gravimetric Grease/Non-Aqueous Method)	mg/L	<0.1	0.1
5	Color	APHA 2270B (Spectrophotometric Method)	PCU	24.75	1.00
6	Total Phosphorus	APHA 9231 (Ascorbic Acid Reduction Spectrophotometric Method)	mg/L	3.6	0.5
7	Total Phosphorus	APHA 9231 (Ascorbic Acid Reduction Spectrophotometric Method)	mg/L	<0.05	0.05
8	TDS	APHA 9240B (Total Dissolved Solids Gravimetric Method)	mg/L	88	-
9	Chromium	APHA 9121B (Inductively Coupled Plasma (ICP) Method)	mg/L	60.008	0.002
10	Mercury	APHA 9120B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.002	0.002
11	Cadmium	APHA 9120B (Inductively Coupled Plasma (ICP) Method)	mg/L	4.000	0.002
12	Total Calcium	APHA 9221B (Standard Total Calcium Determination Technique)	mg/L	9500.8	2.8
13	Chlor	APHA 9150B (Mercuric Nitrate Test)	mg/L	1	0

Remarks : SDQ - Limit of Quantitation
APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Research (AWWA), Standard Methods for the Examination of Water and Wastewater, 19th edition.

Analysed By

[Signature]

Mr. Aye Lay
Manager



Approved By

[Signature]

Chen Aye Lay
Managing Director

Thilawa Special Economic Zone Development Co., Ltd. (TSDC) is a 100% owned subsidiary of Myanmar Japan Thilawa Development Limited (MJTD). MJTD is a 100% owned subsidiary of Myanmar Japan Thilawa Development Limited (MJTD). MJTD is a 100% owned subsidiary of Myanmar Japan Thilawa Development Limited (MJTD).



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY August-2023)**

GC&S

Department of Environmental Conservation
Ministry of Natural Resources and Environmental Conservation
No. 100, Phnom Penh, Cambodia



Report No. : GEM-LAB-202308008
Revision No. : 1
Report Date : 31 August 2023
Application No. : 0002/2023

Analysis Report

Client Name : Myanmar Asia Development LTD (MAD)
Address : No. 10/A, 1st Floor, Island Phnom Penh Condominium, Phnom Penh Road, Tachak Townships, Ngeun, Phnom Penh
Project Name : Environmental Monitoring report for Zone B & C
Sample Description :
 Sample Name : (W) DW + 0000
 Sample No. : W-2208023
 Water Point No. :
Sampling Date : 8 August, 2023
Sampling By : Customer
Sample Received Date : 8 August, 2023
Analysis Date : 8/31/08/2023

No.	Parameter	Method	Unit	Result	LOD
1	pH	APHA 25400 (Dry at 100-105°C Method)	mg/L	7.08	
2	DOO (T)	APHA 5210 B (5 Days BOD Test)	mg/L	4.54	2.00
3	DOO (H)	APHA 5210 B (5 Days BOD Test)	mg/L	14.7	0.1
4	DO and Oxygen	APHA 5210B (Potassium Dichromate Method)	mg/L	13.5	0.1
5	Total	APHA 5210C (Spectrophotometric Method)	mg/L	14.45	2.00
6	Total Nitrogen	NH4N Method 1010 (NMT Nesslerization Digestion Method)	mg/L	0.14	0.1
7	Total Phosphorus	APHA 8000-PP (Ascorbic Acid Method)	mg/L	0.11	0.02
8	TDS	APHA 2540 C (100ml Hoochard Sample dried at 100°C Method)	mg/L	176	-
9	Greenness	APHA 1125 B (Automatically Coupled Reactor (COT) Method)	mg/L	40.000	0.002
10	Yellow	APHA 1125 B (Automatically Coupled Reactor (COT) Method)	mg/L	40.000	0.002
11	Iron	APHA 1125 B (Automatically Coupled Reactor (COT) Method)	mg/L	14.000	0.002
12	Total Coliform	APHA 9221B (Standard Total Coliform Enumeration Technique)	coliforms	10000 CFU	1.0
13	Color	APHA 2120 B (15-volume Color Test)	PCU	1	0

Remark : LOD : Limit of Quantitation

APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By

By: N. Aye (Analyst)
Analyst



Approved By

Aug 21, 2023
Laboratory Director

Report should be read in the context of the report and the laboratory's accreditation.
The laboratory is not responsible for the results of the analysis if the sample is not properly labeled or if the sample is not properly stored.



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY August-2023)**

GC/MS/MS

JICA-GEF/Thilawa SEZ Development Project
Thilawa SEZ Zone B Industrial Area
Thilawa, Yangon Region, Myanmar



Report No. : JTM-CAB-202308001
Revision No. : 1
Report Date : 21 August, 2023
Application No. : 0001-CT01

Analysis Report

Client Name : Myanmar-Japan Thilawa Development Corporation
Address : No. 36/A, 1st Floor, Grand Park South Condominium, The South Road, Tanintharyi Township, Yangon Region
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : HW-001-2-2023
Sample No. : 14-2308001
Water Profile No. :

Sampling Date : 8 August, 2023
Sampling No. : 14-2308001
Sample Received Date : 8 August, 2023
Analysis Date : 21/08/2023

No.	Parameter	Method	Unit	Result	LOG
1	pH	APHA 9245C (Digital 15.0-10.0, 0.1pH)	High	7	—
2	DO (%)	APHA 9245B (5 Days 20°C Test)	High	7.80	0.00
3	DO (O ₂)	APHA 9245C (Clark-type Polarographic Method)	High	12.3	0.7
4	Oil and Grease	APHA 9229B (Petroleum-Ether Extract Method)	High	<1.1	0.1
5	Color	APHA 2120C (Colorimetric Method)	PCU	18.88	0.00
6	Total Suspended Solids (TSS)	APHA 9220B (525 Filter, Gravimetric Method)	High	<0.1	0.1
7	Total Dissolved Solids (TDS)	APHA 9220B (525 Filter, Gravimetric Method)	High	0.02	0.00
8	Hardness	APHA 9241C (Calcium Chloride Titration Method)	High	186	—
9	Calcium	APHA 9241C (Calcium Chloride Titration Method)	High	<0.002	0.002
10	Magnesium	APHA 9241C (Calcium Chloride Titration Method)	High	<0.002	0.002
11	Iron	APHA 9241C (Calcium Chloride Titration Method)	High	0.004	0.001
12	Total Chloride	APHA 9241C (Mercuric Nitrate Titration Method)	High	23.1	1.0
13	Chloride	APHA 9241C (Mercuric Nitrate Titration Method)	High	1	—
14	Fluoride (Free Fluoride)	APHA 9241C (Fluoride Ion Selective Electrode Method)	High	<1.0	0.0

Notes : 1. All units are in mg/L.
2. APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF). Standard Methods for the Examination of Water and Wastewater, 19th edition.

Analyst By

To Be Reviewed
Manager



Supervised By

Aug 21, 2023
Thilawa Director

This report is a confidential document and should not be distributed outside the project area. If you have any questions, please contact the project manager.



Thilawa Special Economic Zone
Zone B– Phase 1,2 & 3 (Operation phase)

Appendix-B

Water and Waste Water Monitoring Report
October 2023

**WATER QUALITY MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
IN THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(Bi-Monthly Monitoring)

October 2023

Myanmar Koei International Ltd.



TABLE OF CONTENTS

CHAPTER 1: INTRODUCTION	1
1.1 General	1
CHAPTER 2: WATER QUALITY MONITORING	2
2.1 Monitoring Items	2
2.2 Description of Sampling Points	3
2.3 Monitoring Method	4
2.4 Monitoring Period	4
2.5 Monitoring Results	5
CHAPTER 3: CONCLUSION AND RECOMMENDATIONS	9
APPENDIX-1 FIELD SURVEY PHOTOS	A1-1
APPENDIX-2 LABORATORY RESULTS	A2-1

LIST OF TABLES

Table 2.1-1 Monitoring Items for Water Quality	2
Table 2.2-1 Outline of Sampling Points	3
Table 2.3-1 Analytic Method for Water Quality	4
Table 2.4-1 Sampling Time of Each Point	4
Table 2.4-2 Tide Record for Yangon River, Myanmar	4
Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek	6
Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well	7

LIST OF FIGURES

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring	1
--	---



CHAPTER 1: INTRODUCTION

1.1 General

Thilawa Special Economic Zone (SEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report and Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area. As for the monitoring of the water quality, total four sampling points are set for water quality survey, named SW-2, SW-4, SW-7 and GW-2 have been monitored in Thilawa SEZ and its surrounding area in timely manner. Among the four locations, SW-7 is main discharged point of Zone B during the operation stage. Moreover, GW-2 is monitored as a reference of existing tube well located in the monastery compound of Phalan village which is situated next to the southern boundary of the industrial area of Zone B. Location of sampling points for water quality monitoring is shown in Figure 1.1-1.



Source: Google Earth

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring

CHAPTER 2: WATER QUALITY MONITORING

2.1 Monitoring Items

Sampling points and parameters for water quality monitoring are determined to cover the environmental monitoring plan of the EIA report.

Water quality sampling was carried out at four locations. Among the four locations, water flow measurement was carried out at two locations (SW-2 and SW-4) where can be measured by current meter. However, water flow measurement cannot be conducted with current meter at one location (SW-7) because water gate is closed. Monitoring items and sampling points are summarized in Table 2.1-1.

Table 2.1-1 Monitoring Items for Water Quality

No.	Parameters	SW-2	SW-4	SW-7	GW-2	Remarks
1	Water Temperature	○	○	○	○	On-site measurement
2	pH	○	○	○	○	On-site measurement
3	Dissolved Oxygen (DO)	○	○	○	○	On-site measurement
4	Suspended Solid (SS)	○	○	○	○	Laboratory analysis
5	BOD ₅	○	○	○	○	Laboratory analysis
6	COD _{Cr}	○	○	○	○	Laboratory analysis
7	Color	○	○	○	○	Laboratory analysis
8	Odor	○	○	○	○	Laboratory analysis
9	Oil and Grease	○	○	○	○	Laboratory analysis
10	Total Nitrogen (T-N)	○	○	○	○	Laboratory analysis
11	Total Phosphorus (T-P)	○	○	○	○	Laboratory analysis
12	Total Coliform	○	○	○	○	Laboratory analysis
13	Total Dissolved solids (TDS) (Self-monitoring)	○	○	○	○	Laboratory analysis
14	Iron (Self-monitoring)	○	○	○	○	Laboratory analysis
15	Mercury (Self-monitoring)	○	○	○	○	Laboratory analysis
16	Escherichia Coli (Self-monitoring)	-	-	○	○	Laboratory analysis
17	Flow Rate	○	○	-	-	On-site measurement

Source: Myanmar Koei International Ltd.

2.2 Description of Sampling Points

The outline of sampling points is mentioned in Table 2.2-1. The photos of conducting field survey at each sampling points are mentioned in Appendix-1.

Table 2.2-1 Outline of Sampling Points

No.	Station	Detailed Information
1	SW-2	Coordinate - N - 16° 40' 20.69", E - 96° 17' 18.04" Location - Upstream of Shwe Pyauk Creek Survey Item - Surface water sampling and water flow rate measurement
2	SW-4	Coordinate - N - 16° 39' 42.84", E - 96° 16' 27.42" Location - Downstream of Shwe Pyauk Creek Survey Item - Surface water sampling and water flow rate measurement
3	SW-7	Coordinate - N - 16° 40' 13.25", E - 96° 17' 5.66" Location - Outlet of retention pond of Zone B before connecting to Shwe Pyauk Creek Survey Item - Discharge water sampling
4	GW-2	Coordinate - N - 16° 39' 25.30", E - 96° 17' 15.60" Location - In the monastery compound of Phalan village Survey Item - Ground water sampling

Source: Myanmar Koei International Ltd.

SW-2 (Reference Point)

SW-2 was collected at the upstream of Shwe Pyauk creek. This sampling point is located in the northeast of Zone B area and at the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northwest and local industrial zone in the east respectively.

SW-4 (Reference Point)

SW-4 was collected at the downstream of Shwe Pyauk creek, after mixing of discharge water from local industrial zone, Thilawa SEZ Zone A and Zone B, which is flowing from east to west and then entering into the Yangon River. The distance is about 2.15 km downstream of SW-2. This sampling point is located in the west of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northeast, local industrial zone in the east and paddy fields in the south and west respectively.

SW-7 (Discharged Point)

SW-7 is main discharged point of Zone B during operation stage. The distance is about 434 m downstream of SW-2. This sampling point is located at outlet of retention pond of Zone B, in the north of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the north and local industrial zone in the east respectively.

GW-2 (Reference of Existing Tube Well)

GW-2 was collected from tube well as ground water sample. It is located in the monastery compound of Phalan village. The surrounding areas are Thilawa SEZ Zone A in the north, Phalan village in the south and fields in the west and local industrial zone in the northeast and operation of Thilawa SEZ Zone B in the east and northeast respectively.

2.3 Monitoring Method

All water samples were collected with cleaned sampling bottles and analyzed by the following standard method as shown in Table 2.3-1. All samples were kept in iced boxes keeping at 2-4 °C and were transported to the laboratory. Among the parameters; water temperature, pH and DO were measured by the on-site instrument "Horiba, U-52" and water flow rate was also conducted by using the on-site instrument "JFE Digital Current Meter".

Table 2.3-1 Analytic Method for Water Quality

No.	Parameter	Method
1	Water Temperature	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
2	pH	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
3	Dissolved Oxygen (DO)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
4	Suspended Solid (SS)	APHA 2540D (Dry at 103-105°C Method)
5	BOD ₅	APHA 5210-B (5 days BOD Test)
6	COD _{Cr}	APHA 5220D (Close Reflux Colorimetric Method)
7	Color	APHA 2120C (Spectrophotometric Method)
8	Odor	APHA 2150-B (Threshold Odor Test)
9	Oil and Grease	APHA 5520B (Partition-Gravimetric Method)
10	Total Nitrogen (T-N)	HACH Method 10072 (TNT Persulfate Digestion Method)
11	Total Phosphorous (T-P)	APHA 4500-P-E (Ascorbic Acid Method)
12	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)
13	Total Dissolved Solids (TDS)	APHA 2540C (Total Dissolved Solids Dried at 180°C Method)
14	Iron	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)
15	Mercury	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)
16	Escherichia Coli	APHA 9221-F (Escherichia Coli Procedure Using Fluorogenic Substrate)
17	Flow Rate	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

Source: Myanmar Koei International Ltd.

2.4 Monitoring Period

Water quality and water flow rate monitoring were conducted on 24 October 2023, and sampling time is shown in Table 2.4-1 to avoid tidal effect. The tide record for Yangon River, Myanmar 24 October 2023 is shown in Table 2.4-2.

Table 2.4-1 Sampling Time of Each Point

No.	Station	Sampling Time
1	SW-2	24/10/2023 13:25
2	SW-4	24/10/2023 13:51
3	SW-7	24/10/2023 09:44
4	GW-2	24/10/2023 09:12

Source: Myanmar Koei International Ltd.

Table 2.4-2 Tide Record for Yangon River, Myanmar

Date	Time	Height (m)	Tide Conditions
24/10/2023	00:17	4.73	High Tide
	07:21	1.96	Low Tide
	12:37	4.85	High Tide
	20:09	1.32	Low Tide

Source: Myanmar Port Authority, Tide Table for the Yangon River and Elephant Point, 2023.

2.5 Monitoring Results

Results of water quality monitoring at discharged point, discharged creek are summarized in Table 2.5-1. Analytical results of the laboratory are described in Appendix-2. The results were compared with the target value of effluent water quality discharged to water body stipulated in the EIA report.

2.5.1 Results of Discharged Point and Discharged Creek

As the comparison with the target value, the results of suspended solid (SS), total coliform and iron exceeded the target values.

Result of Discharged point

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the heavy rainfall and stormwater runoff can wash contaminants from the surroundings into the retention pond, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, E. Coli analysis was carried out alternatively to identify the health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

Result of Reference Monitoring points (Discharged Creek)

As for the result of SS, results at the surface water monitoring points (SW-4) exceeded the target values. The exceeded results for SS maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

As for the result of total coliform, results at surface water monitoring points (SW-2) and (SW-4) exceeded the target value due to three expected reasons: i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

As for the result of iron, the result at the monitoring point of surface water monitoring point (SW-4) exceeded the target value. The possible reason for exceeded value in surface water (SW-4) maybe due to the influence of natural origin (iron can reach out from the soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.



Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek

No.	Parameters	Unit	SW-2	SW-4	SW-7	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	30	30	29	≤ 35
2	pH	-	6.6	6.9	7.2	6-9
3	Dissolved Oxygen (DO)	mg/l	3.39	4.33	6.01	-
4	Suspended Solid (SS)	mg/l	30	102	38	50
5	BOD ₅	mg/l	5.06	4.11	5.44	30
6	COD _{Cr}	mg/l	13.3	9.6	4.4	125
7	Color	TCU (True Color Unit)	19.15	13.94	3.75	150
8	Odor	TON (Threshold Odor Number)	1	1	1	-
9	Oil and Grease	mg/l	< 3.1	< 3.1	< 3.1	10
10	Total Nitrogen (T-N)	mg/l	1.8	< 0.3	< 0.3	80
11	Total Phosphorus (T-P)	mg/l	0.25	0.16	0.05	2
12	Total Coliform	MPN/100ml	35000.0	14000.0	28000.0	400
13	Total Dissolved solids (TDS)	mg/l	96	112	80	2000
14	Iron	mg/l	2.060	12.860	2.270	3.5
15	Mercury	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	-	-	8.3	(1000)* (CFU/100ml)
17	Flow Rate	m ³ /s	0.19	0.31	-	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at discharged creek, the quality standard for water baths in Japan, (Ministry of Environment, 1997) is set as a reference value for self-monitoring of E. coli for surface water monitoring. However, due to limitation of capacity for analytical laboratory in Myanmar, the method to analyze the "Colony Forming Unit (CFU)" is not available in Myanmar. Therefore, the results of "Most Probable Number (MPN)" are assumed similar to CFU values and compared with reference values. Once the method to analyze the CFU will be available in Myanmar, the analytical method will be changed.

Source: Myanmar Koei International Ltd.

2.5.2 Result of Reference Tube Well

Result of water quality monitoring at reference tube well monitoring point is shown in Table 2.5-2. As the comparison with the target value, the result of iron exceeded the target value.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 9.182 mg/l in August 2022 and most of the iron concentration results (from April 2019 to October 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may be due to the influence of natural origin (iron can reach out from soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.

Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well

No.	Parameters	Unit	GW-2	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	28	≤ 35
2	pH	-	6.8	6-9
3	Dissolved Oxygen (DO)	mg/l	6.75	-
4	Suspended Solid (SS)	mg/l	2	50
5	BOD ₅	mg/l	3.76	30
6	COD _{Cr}	mg/l	< 0.7	125
7	Color	TCU (True Color Unit)	39.69	150
8	Odor	TON (Threshold Odor Number)	1	-
9	Oil and Grease	mg/l	< 3.1	10
10	Total Nitrogen (T-N)	mg/l	< 0.5	80
11	Total Phosphorus (T-P)	mg/l	0.62	2
12	Total Coliform	MPN/100ml	6.1	400
13	Total Dissolved solids (TDS)	mg/l	200	2000
14	Iron	mg/l	7.150	3.5
15	Mercury	mg/l	≤ 0.002	0.005
16	Escherichia Coli	MPN/100ml	2.0	(100)* (MPN/100ml)
17	Flow Rate	m ³ /s	-	-

Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at monitoring point for ground water, B1 (irrigation water) of National Technical Regulation on Surface Water Quality in Vietnam (No. QCVN 08: 2008/NTNMT) is set as a reference value of self-monitoring for ground water monitoring.

Source: Myanmar Koei International Ltd.



2.5.3 Comparison of Results of Water Quality Exceed the Target Value between Previous Monitoring and October 2023 Monitoring

In order to overview the exceed the target values of the concerned parameters during the present monitoring (October 2023), the results of the exceed parameters with respective sampling points are compared with the previous monitoring results since October 2022.

Regarding the results of the parameter of discharge point, total coliform amount at SW-7 is higher than the target value in February, June, August and October 2023. The concentrations of total coliform at SW-7 are extending from 2300 MPN/100ml to the detection limit (>160000 MPN/100ml). Total coliform concentration at SW-7 is obviously reached to the detection limit in the early and mid-rainy season, and winter season and it might be the effect of storm water run-off. Moreover, iron concentration at GW-2 is always higher than the target value except the result of April 2023. It is observed that iron concentration at GW-2 is higher throughout monsoon and winter time.

On the other hand, it is observed that some parameters at the reference monitoring points (SW-2 and SW-4) are also higher than the target value. As for the result of SS concentration, the result of SW-4 is higher than the target value during the surveys except April 2023, ranging from 78 to 502 mg/l. It is clear that SS concentrations at SW-4 are higher throughout rainy season due to the storm water run-off from the surrounding. The result of iron at SW-4 is higher in five monitoring surveys (October, December 2022 and June, August, October 2023) ranging from 4.376 to 22.626 mg/l. It is revealed that high concentration of iron at SW-4 occurred throughout rainy season till the beginning of winter time. It is obvious that total coliform at SW-2 is higher in six monitoring surveys among seven (ranging from 1300 to >160000 MPN/100ml) while the result at SW-4 is higher in all monitoring surveys (ranging from 4600 to >160000 MPN/100ml). Especially the total coliform amount at SW-2 was reached to the detection limit (>160000 MPN/100ml) in June 2023 as well as at SW-4 in October 2022 and June 2023 respectively. It is possible to say that the present condition of the water quality reflects the background condition of the surrounding environment of Thilawa SEZ.

The expected reasons for the results exceed the target value of concerned parameters are discussed in the upper section of this monitoring report.



CHAPTER 3: CONCLUSION AND RECOMMENDATIONS

As described in Chapter 2 (Section 2.5), the results of total coliform at (SW-2, SW-4 and SW-7), suspended solid (SS) and iron at (SW-4) in surface water, and the result of iron at (GW-2) in ground water exceeded the target value in this monitoring period for operation stage of Thilawa SEZ Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the heavy rainfall and stormwater runoff can wash contaminants from the surroundings into the retention pond, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, E. Coli analysis was carried out alternatively to identify the health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

The result of total coliform at reference monitoring points (SW-2 and SW-4), SS and iron at reference monitoring point (SW-4) exceeded the target values. The exceeded results for total coliform at (SW-2 and SW-4) maybe due to three expected reasons; i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) heavy rainfall and stormwater runoff can wash contaminants from the surroundings into Shwe Pyauk creek, and this runoff may contain fecal matter and other pollutants, leading to increased coliform levels, and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

The exceeded results for SS at (SW-4) maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

The expected reason for exceeding the target value of iron at reference monitoring point (SW-4) may be due to the influence of natural origin (iron can reach out from soil by run-off), the surrounding high land areas is comprised of lateritic soils and it can be transported to the low land area by run-off.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 9.182 mg/l in August 2022 and most of the iron concentration results (from April 2019 to October 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). Surroundings of the Thilawa SEZ especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off.

As for future subject for main discharged points of Thilawa SEZ Zone B, the following action may be taken to maintain the target value of total coliform and appropriate water quality monitoring:

- To continue monitoring *Escherichia coli* (E. coli) level to identify health impact by coliform bacteria.

End of the Document



APPENDIX-1 FIELD SURVEY PHOTOS



FOR DISCHARGED POINT OF THILAWA SEZ ZONE B



Surface water sampling and onsite measurement at SW-7

**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**



Surface water sampling and onsite measurement at SW-2



Surface water sampling and onsite measurement at SW-4



Ground water sampling and onsite measurement at GW-2

APPENDIX-2 LABORATORY RESULTS



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY October-2023)

FOR DISCHARGED POINT

ADDRESS

JANABOON CHHIN CHHIN CO., LTD.
100/10/1 Thilawa SEZ Zone B, Thilawa District, Yangon Region
Phone No. 09-699-11000, 09-699-11001



Report No. : JPM/AN/2023/019

Revised No. : 1

Report Date : 7 November, 2023

Registration No. : 0001-0001

Analysis Report

Client Name : Myanmar Rail International (TO) (MCI)

Address : No. 35/A, 1st Floor, Grand Pine Gate Condominium (Pine Gate Road, Dagon Township, Yangon Region)

Project Name : Environment Monitoring report for Zone B & C

Sample Description

Sample Name : WW-SW-T-1024

Sampling Date : 24 October, 2023

Sample No. : W-2023108

Sampling No. : Customer

Water Profile No. :

Sample Received Date : 24 October, 2023

Analysis Date : 24/10/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2540 (Use of pH-STAT Method)	mg/l	7.0	-
2	BOD (5d)	APHA 5211 B-5 Class BOD Test	mg/l	2.44	0.05
3	COD (Cr)	APHA 5210 (Open Reflux Titrimetric Method)	mg/l	9.9	0.7
4	Total Solids	APHA 5210B (Filtration Gravimetric Method)	mg/l	<2.1	0.1
5	Color	APHA 2170C Spectrophotometric Method	PCU	0.75	0.05
6	Total Nitrogen	NACH Method 5872 (N-1 Potassium Digestion Method)	mg/l	<0.0	0.0
7	Total Phosphorus	APHA 4500 P-T (Ascorbic Acid Method)	mg/l	0.05	0.01
8	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	80	-
9	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.007	0.001
10	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.007	0.001
11	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	2.275	0.001
12	Total Bacteria	APHA 9222A (Standard Total Culture Fermentation Technique)	MPN/100ml	260000	1.0
13	Oil	APHA 9250 B (Turbidimetric Test)	mg/l	1	0
14	Chlorine Residual	APHA 5221 P Potentiometric Chlorine Residual using Phosphate Buffer/Matrix	MPN/100ml	0.2	0.0

Remark : LOQ- Limit of Quantification

APHA – American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 19th edition

Approved By

M. M. Aye San
Manager



Approved By

Managing Director

JANABOON CHHIN CHHIN CO., LTD.
100/10/1 Thilawa SEZ Zone B, Thilawa District, Yangon Region
Phone No. 09-699-11000, 09-699-11001



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**

DOWA

DOOWA (CAMBODIA) CO., LTD.
1000/10, Road 63, Zone A, Prey Veng District,
Kandal Province, 12170 Cambodia



Report No. : DCH-LAB-20231018
Revision No. : 1
Report Date : 7 November, 2023
Approval No. : 0061-C083

Analysis Report

Client Name : Myanmar Air International (P) (PVT) Ltd.
Address : No. 88/A, 1st Floor, 8888th Phnom Penh Condominium, Phnom Penh Road, Tonle Sap Area, Phnom Penh
Project Name : Environmental Monitoring report for Zone A & B
Service Description :
Sample Name : PRC-TW-2-1024
Sample No. : W-0100108
Batch Profile No. :

Sampling Date : 24 October, 2023
Sampling By : Customer
Sample Received Date : 24 October, 2023
Analysis Date : 24/10/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2540D (Dry at 105.125°C Method)	mg/L	10	
2	DO (O ₂)	APHA 2170 B (3 Days 500 Test)	mg/L	0.08	0.05
3	CO ₂ (O ₂)	APHA 5210 (Open Reflux Colorimetric Method)	mg/L	13.3	6.7
4	Oil and Grease	APHA 5520B (Petroleum Evaporation Method)	mg/L	<3.1	3.1
5	Ca ²⁺	APHA 2110C (Spectrophotometric Method)	TCU	19.15	0.05
6	Total Nitrogen	APHA Method 10013 (TNM Persulfate Digestion Method)	mg/L	1.8	0.5
7	Total Phosphorus	APHA 4500 P-3 (Ascorbic Acid Method)	mg/L	0.25	0.05
8	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/L	90	
9	Chromium	APHA 3110 B (Bismuthate Oxidized Phosphorus (BO) Method)	mg/L	<0.001	0.001
10	Mercury	APHA 3110 B (Oxidation, Purge and Capture (OPC) Method)	mg/L	<0.001	0.001
11	Iron	APHA 3110 B (Oxidation, Purge and Capture (OPC) Method)	mg/L	2.064	0.001
12	Total Carbon	APHA 82314 (High-Temperature Catalytic Oxidation Technique)	mg/L (ppm)	5800.0	1.8
13	DOH	APHA 1150 B (Threshold Color Test)	TCU	1	0

Notes : <LOQ : Limit of Quantitation

APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF). Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed By



Mr. Ph. Apol Luth
Manager



Approved By


Helen Yoon Nov 9, 2023
Marketing Director

DOOWA (CAMBODIA) CO., LTD. IS NOT RESPONSIBLE FOR THE RESULTS OF THE ANALYSIS.
THE ANALYST SHALL SIGN THE ANALYSIS REPORT ONLY, WITHOUT ANY OTHER SIGNATURE OF THE LABORATORY.
DOOWA (CAMBODIA) CO., LTD. IS NOT RESPONSIBLE FOR THE RESULTS OF THE ANALYSIS.



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY October-2023)**

QOWA

Jointly Owned Co. (Pvt) Ltd. (JOC)
1st Floor, Thilawa SEZ Zone B, Myanmar Economic
Special Zone (MSEZ) (2000)



Report No. : JEM-LAB-20231101
Revision No. : 1
Report Date : 7 November, 2023
Application No. : 0001-0001

Analysis Report

Client Name : Myanmar Kasei (Investment) LTD (MKI)
Address : No. 36/A, 1st Floor, Island Hill Sector Commercial, The Saka Road, Thilawa Township, Yangon, Myanmar
Project Name : Investment Monitoring report for Zone B & C
Sample Description :
 Sample Name : HA-09-A-1024
 Sample No. : W-2300187
 Water Profile No. :
 Sampling Date : 24 October, 2023
 Sampling By : Customer
 Sample Received Date : 24 October, 2023
 Analysis Date : 24/10/2023

No.	Parameter	Method	Unit	Result	LDQ
1	DO	APHA 2540 (Dry at 20°C (10°C Method))	mg/l	1.0	
2	BOD-5	APHA 5210 5-D Days (5D Test)	mg/l	4.11	0.01
3	COD-Mn	APHA 5210 (Closed Reflux Colorimetric Method)	mg/l	9.6	0.7
4	Fe and Cu	APHA 5510 (Phosco Gravimetric Method)	mg/l	<0.3	0.1
5	Calc	APHA 5110 (Spectrophotometric Method)	mg/l	17.94	0.02
6	Total Nitrogen	HACH Method 8012 (TRC Phenylhypodiazotization Method)	mg/l	<0.5	0.1
7	Total Phosphorus	APHA 4500-P-3 (Ascorbic Acid Method)	mg/l	0.18	0.02
8	TSS	APHA 5550 (Total Suspended Solids Sieve at 100°C Method)	mg/l	0.12	—
9	Chlorine	APHA 5120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	60.870	0.003
10	Mercury	APHA 5120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	60.862	0.002
11	Iron	APHA 5120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	12.868	0.007
12	Total Calcium	APHA 52110 (Standard Total Calcium Tannimetric Method)	mg/L (ppm)	1400.0	1.0
13	Color	APHA 2150-B (Threshold Color Test)	TCU	1	0

Remarks : LDQ = Limit of Quantitation
 APHA = American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 19th edition

Analysed By

 N. N. Aye San
 Manager



Approved By

 Managing Director

We warrant the accuracy of the analysis results for the sample.
 We warrant that we will not disclose any confidential information of the client without
 the client's written consent.



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Monthly Monitoring in FY October 2023)**

CDMRA

Department of Environmental Conservation
Ministry of Natural Resources and Environmental Conservation
P.O. Box 11, Phnom Penh, Cambodia
Phone: +855 23 770 0000



Report No. : GEM LAB-2023-1023
Revision No. : 1
Report Date : 7 November, 2023
Application No. : 0004/2023

Analysis Report

Client Name : Myanmar Water International (MWT)
Address : No. 16/A, 1st Floor, Grand Pao Sam Condominium (Phnom Penh Road), Tonle Sap Township, Yangon, Myanmar
Project Name : Development Monitoring Report for Zone A & B
Sample Description :
 Sample Name : H2O (Tap Water)
 Sample No. : W-2300188
 Water Profile No. :
 Sampling Date : 04 October, 2023
 Sampling By : Customer
 Sample Received Date : 04 October, 2023
 Analysis Date : 04/10/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2450 (pH at 25°C Method)	mg/L	8	-
2	BOD (5)	APHA 5210 (5 Days BOD Test)	mg/L	3.76	0.05
3	COD (Cr)	APHA 5210 (Open Reflux Colorimetric Method)	mg/L	40.7	0.2
4	Dissolved Oxygen	APHA 9205B (Fischer's Dissolved Oxygen Method)	mg/L	4.1	0.1
5	Calcium	APHA 2110C (Spectrophotometric Method)	mg/L	39.89	0.05
6	Total Nitrogen	APHA 4500-1.0 (N) (Nesslerization Method)	mg/L	0.5	0.1
7	Total Phosphorus	APHA 4500-P (Ascorbic Acid Method)	mg/L	0.02	0.05
8	TDS	APHA 2540 C (Total Dissolved Solids Test at 180°C Method)	mg/L	180	-
9	Chlorine	APHA 8110 B (Inductively Coupled Plasma (ICP) Method)	mg/L	41.00	0.005
10	Mercury	APHA 8110 B (Inductively Coupled Plasma (ICP) Method)	mg/L	48.00	0.005
11	Iron	APHA 8110 B (Inductively Coupled Plasma (ICP) Method)	mg/L	1.00	0.002
12	Total Coliform	APHA 9218B (Standard Total Coliform Fermentation Technique)	MPN/100mL	1.1	1.0
13	Chlor	APHA 8110 B (Threshold Value Test)	mg/L	1	0
14	Perchlorate (ClO ₄)	APHA 8221 F (Extraction and Precipitation Using Fluorogenic Substrate)	MPN/100mL	1.0	1.0

Reference : 1020 – Limit of Quantitation
 APHA – American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 23rd edition

Analysed By :

W. W. Aye Lay
Manager



Approved By :

W. W. Aye Lay
Managing Director

NOTES: 1. ALL OF THE DATA SUBMITTED FOR ANALYSIS
 2. THE ANALYST HAS BEEN TRAINED AND QUALIFIED TO PERFORM THE ANALYSIS OF THE SAMPLES OF
 3. THE ANALYST HAS BEEN TRAINED AND QUALIFIED TO PERFORM THE ANALYSIS OF THE SAMPLES OF



**Thilawa Special Economic Zone
Zone B- Phase 1, 2,3 (Operation phase)**

Appendix-C

**Water and Waste Water Monitoring Report
December 2023**

**WATER QUALITY MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
IN THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(Bi-Annually Monitoring)

December 2023

Myanmar Koei International Ltd.



TABLE OF CONTENTS

CHAPTER 1: INTRODUCTION	1
1.1 General	1
CHAPTER 2: WATER QUALITY MONITORING	2
2.1 Monitoring Items	2
2.2 Description of Sampling Points	3
2.3 Monitoring Method	4
2.4 Monitoring Period	5
2.5 Monitoring Results	6
CHAPTER 3: CONCLUSION AND RECOMMENDATIONS	11
APPENDIX-1 FIELD SURVEY PHOTOS	A1-1
APPENDIX-2 LABORATORY RESULTS	A2-1

LIST OF TABLES

Table 2.1-1 Monitoring Items for Water Quality	2
Table 2.2-1 Outline of Sampling Points	3
Table 2.3-1 Analytic Method for Water Quality	4
Table 2.4-1 Sampling Time of Each Point	5
Table 2.4-2 Tide Record for Yangon River, Myanmar	5
Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek	7
Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well	9

LIST OF FIGURES

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring	1
--	---



CHAPTER 1: INTRODUCTION

1.1 General

Thilawa Special Economic Zone (SEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report and Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area. As for the monitoring of the water quality, total four sampling points are set for water quality survey, named SW-2, SW-4, SW-7 and GW-2 have been monitored in Thilawa SEZ and its surrounding area in timely manner. Among the four locations, SW-7 is main discharged point of Zone B during the operation stage. Moreover, GW-2 is monitored as a reference of existing tube well located in the monastery compound of Phalan village which is situated next to the southern boundary of the industrial area of Zone B. Location of sampling points for water quality monitoring is shown in Figure 1.1-1.



Source: Google Earth

Figure 1.1-1 Location of Sampling Points of Water Quality Monitoring

CHAPTER 2: WATER QUALITY MONITORING

2.1 Monitoring Items

Sampling points and parameters for water quality monitoring are determined to cover the environmental monitoring plan of the EIA report.

Water quality sampling was carried out at four locations. Among the four locations, water flow measurement was carried out at two locations (SW-2 and SW-4) where can be measured by current meter. However, water flow measurement cannot be conducted with current meter at one location (SW-7) water gate was closed during sampling. Monitoring items and sampling points are summarized in Table 2.1-1.

Table 2.1-1 Monitoring Items for Water Quality

No.	Parameters	SW-2	SW-4	SW-7	GW-2	Remarks
1	Water Temperature	○	○	○	○	On-site measurement
2	pH	○	○	○	○	On-site measurement
3	DO	○	○	○	○	On-site measurement
4	Suspended Solids	○	○	○	○	Laboratory analysis
5	BOD ₅	○	○	○	○	Laboratory analysis
6	COD _{Cr}	○	○	○	○	Laboratory analysis
7	Total Coliform	○	○	○	○	Laboratory analysis
8	Oil and Grease	○	○	○	○	Laboratory analysis
9	Total Nitrogen	○	○	○	○	Laboratory analysis
10	Total Phosphorus	○	○	○	○	Laboratory analysis
11	Color	○	○	○	○	Laboratory analysis
12	Odor	○	○	○	○	Laboratory analysis
13	Ammonia	○	○	○	○	Laboratory analysis
14	Total Dissolved Solids	○	○	○	○	Laboratory analysis
15	Mercury	○	○	○	○	Laboratory analysis
16	Zinc	○	○	○	○	Laboratory analysis
17	Arsenic	○	○	○	○	Laboratory analysis
18	Chromium	○	○	○	○	Laboratory analysis
19	Cadmium	○	○	○	○	Laboratory analysis
20	Selenium	○	○	○	○	Laboratory analysis
21	Lead	○	○	○	○	Laboratory analysis
22	Copper	○	○	○	○	Laboratory analysis
23	Barium	○	○	○	○	Laboratory analysis
24	Nickel	○	○	○	○	Laboratory analysis
25	Silver	○	○	○	○	Laboratory analysis
26	Iron	○	○	○	○	Laboratory analysis
27	Cyanide	○	○	○	○	Laboratory analysis
28	Total Cyanide	○	○	○	○	Laboratory analysis
29	Chromium (Hexavalent)	○	○	○	○	Laboratory analysis
30	Fluoride	○	○	○	○	Laboratory analysis
31	Free Chlorine	○	○	○	○	Laboratory analysis
32	Total Residual Chlorine	○	○	○	○	Laboratory analysis
33	Sulphide	○	○	○	○	Laboratory analysis
34	Formaldehyde	○	○	○	○	Laboratory analysis
35	Phenols	○	○	○	○	Laboratory analysis
36	Escherichia Coli	-	-	○	○	Laboratory analysis
37	Flow Rate	○	○	-	-	On-site measurement

Source: Myanmar Kasei International Ltd.

2.2 Description of Sampling Points

The outline of sampling points is mentioned in Table 2.2-1. The photos of conducting field survey at each sampling points are mentioned in Appendix-1.

Table 2.2-1 Outline of Sampling Points

No.	Station	Detailed Information
1	SW-2	Coordinate- N - 16° 40' 20.69", E - 96° 17' 18.04"
		Location - Upstream of Shwe Pyauk Creek
		Survey Item - Surface water sampling and water flow rate measurement
2	SW-4	Coordinate- N - 16° 39' 42.84", E - 96° 16' 27.42"
		Location - Downstream of Shwe Pyauk Creek
		Survey Item - Surface water sampling and water flow rate measurement
3	SW-7	Coordinate - N - 16° 40' 13.25", E - 96° 17' 3.66"
		Location - Outlet of retention pond of Zone B before connecting to Shwe Pyauk Creek
		Survey Item - Discharge water sampling
4	GW-2	Coordinate - N - 16° 39' 25.30", E - 96° 17' 15.60"
		Location - In the monastery compound of Phalan village
		Survey Item - Ground water sampling

Source: Myanmar Koei International Ltd.

SW-2 (Reference Point)

SW-2 was collected at the upstream of Shwe Pyauk creek. This sampling point is located in the northeast of Zone B area and at the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northwest and local industrial zone in the east respectively.

SW-4 (Reference Point)

SW-4 was collected at the downstream of Shwe Pyauk creek, after mixing of discharge water from local industrial zone, Thilawa SEZ Zone A and Zone B, which is flowing from east to west and then entering into the Yangon River. The distance is about 2.15 km downstream of SW-2. This sampling point is located in the west of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the northeast, local industrial zone in the east and paddy fields in the south and west respectively.

SW-7 (Discharged Point)

SW-7 is main discharged point of Zone B during operation stage. The distance is about 434 m downstream of SW-2. This sampling point is located at outlet of retention pond of Zone B, in the north of Zone B area and in the south of Dagon-Thilawa road. The surrounding areas are Zone A in the north and local industrial zone in the east respectively.

GW-2 (Reference of Existing Tube Well)

GW-2 was collected from tube well as ground water sample. It is located in the monastery compound of Phalan village. The surrounding areas are Thilawa SEZ Zone A in the north, Phalan village in the south and fields in the west and local industrial zone in the northeast and operation of Thilawa SEZ Zone B in the east and northeast respectively.

2.3 Monitoring Method

All water samples were collected with cleaned sampling bottles and analyzed by the following standard method as shown in Table 2.3-1. All samples were kept in iced boxes keeping at 2-4 °C and were transported to the laboratory. Among the parameters, water temperature, pH and DO were measured by the on-site instrument "Horiba, U-52" and water flow rate was also measured by using the on-site instrument "JFE Digital Current Meter".

Table 2.3-1 Analytic Method for Water Quality

No.	Parameter	Method
1	Water Temperature	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
2	pH	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
3	Dissolved Oxygen (DO)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
4	Suspended Solids (SS)	APHA 2540 D (Dry at 103-105°C Method)
5	BOD ₅	APHA 5210 B (5 Days BOD Test)
6	COD _{Cr}	APHA 5220 D (Close Reflux Colorimetric Method)
7	Total Coliform	APHA 9221 B (Standard Total Coliform Fermentation Technique)
8	Oil and Grease	APHA 5520 B (Partition-Gravimetric Method)
9	Total Nitrogen (T-N)	HACH Method 10072 (TNT Persulfate Digestion Method)
10	Total Phosphorus (T-P)	APHA 4500-P E (Ascorbic Acid Method)
11	Color	APHA 2120 C (Spectrophotometric Method)
12	Odor	APHA 2150 B (Threshold Odor Test)
13	Ammonia	HACH Method 10295 (Silicolytic TNT Plus Method)
14	Total Dissolved Solids	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
15	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
16	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
17	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
18	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
19	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
20	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
21	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
22	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
23	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
24	Nickel	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
25	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
26	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
27	Cyanide	HACH 8027 (Pyridine-Pyrazolone Method)
28	Total Cyanide	Distillation process: APHA 4500-CN-C. Total Cyanide after Distillation, Determine cyanide Concentration Process: HACH 8027 (Pyridine - Pyrazolone Method)
29	Chromium (Hexavalent)	ISO 11083:1994 (Determination of chromium (VI) Spectrometric method using 1,5-dihydroxynaphthazene)
30	Fluoride	APHA 4110 B (Ion Chromatography with Chemical Suppression of Eluent Conductivity)
31	Free Chlorine	APHA 4500-CL G (DPD-Colorimetric Method)
32	Total Residual Chlorine	APHA 4500-CL G (DPD-Colorimetric Method)
33	Sulphide	HACH 8131 (USEPA Methylene Blue Method)
34	Formaldehyde	HACH 8110 (MBTH Method)
35	Phenols	USEPA Method 420.1 (Phenolics (Spectrophotometric, Manual 4-AP With Distillation))
36	Escherichia Coli	APHA 9221 F (Escherichia Coli Procedure Using Phageogenic Substrate)
37	Flow Rate	Detection of Electromagnetic Elements (Real-time measurement by AFM 213-D Digital Current Meters)

Source: Myanmar Koei International Ltd.



2.4 Monitoring Period

Water quality and water flow rate monitoring were conducted on 5 December 2023, and sampling time is shown in Table 2.4-1 to avoid tidal effect. The tide record for Yangon River, Myanmar 5 December 2023 is shown in Table 2.4-2.

Table 2.4-1 Sampling Time of Each Point

No.	Station	Sampling Time
1	SW-2	05/12/2023 12:15
2	SW-4	05/12/2023 14:03
3	SW-7	05/12/2023 09:45
4	GW-2	05/12/2023 09:04

Source: Myanmar Koo International Ltd.

Table 2.4-2 Tide Record for Yangon River, Myanmar

Date	Time	Height (m)	Tide Conditions
05/12/2023	03:59	1.73	Low Tide
	09:32	4.33	High Tide
	16:42	1.38	Low Tide
	22:26	4.47	High Tide

Source: Myanmar Port Authority, Tide Table for the Yangon River and Elephant Point, 2023.

2.5 Monitoring Results

Results of water quality monitoring at discharged point, discharged creek are summarized in Table 2.5-1. Analytical results of the laboratory are described in Appendix-2. The results were compared with the target value of effluent water quality discharged to water body stipulated in the EIA report.

2.5.1 Results of Discharged Point and Discharged Creek

As the comparison with the target value, the results of pH, suspended solid (SS), total coliform and iron exceeded the target values.

(1) Result of Discharged point

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the contaminants from the surroundings into the retention pond may contain fecal matter and other pollutants, leading to increase coliform levels.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, E. Coli analysis was carried out alternatively to identify the health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

As for the result of iron, the result at the main discharging point of Zone B (SW-7) before discharging to the creek exceeded the target value. The possible reasons may be due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron and iron remains in the natural environment for a long time. Table 2.5-1 shows the results of water quality of the main discharged point of Zone B (SW-7) and reference monitoring points (SW-2 and SW-4). Regarding SW-2 and SW-4, SS concentration are 70 mg/l and 114 mg/l, while iron concentration occur 5.580 mg/l and 6.880 mg/l respectively. It can be clearly seen that the lower suspended solid concentrations generally have lower iron concentrations and higher suspended solid concentrations generally have higher iron concentrations.

(2) Additional Monitoring by MJTD

As of the water quality monitoring results on (December 5, 2023), the iron result exceeded at (SW-7). After receiving the result of iron for December 5, 2023 monitoring, additional water quality monitoring was carried out at the same location on (January 9, 2024) by MJTD for more identification of iron. The Result of additional monitoring is compared with that of December 5, 2023, the additional monitoring result is lower. But comparing with the target value, the additional monitoring result is exceeded. There was construction work by three locators in the Zone B during monitoring and it is speculated that iron concentration in the retention pond can be affected by the construction activities. The result of iron (December 5, 2023) exceeded the target value as the reasons discussed above. The results in previous monitoring months with complied with the target value at (SW-7).

Result of Reference Monitoring points (Discharged Creek)

As for the result of pH, results at the surface water monitoring point (SW-4) exceeded the target value might be due to wastewater discharged that may contains detergents and soap-based products from the local industrial zone outside of Thilawa SEZ.

As for the result of SS, results at the surface water monitoring points (SW-2) and (SW-4) exceeded the target values. The exceeded results for SS maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside

by tidal fluctuation along Shwe Pyauk creek.

As for the result of total coliform, results at surface water monitoring points (SW-2) and (SW-4) exceeded the target value due to three expected reasons: i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) contaminants from the surroundings into the Shwe Pyauk creek may contain fecal matter and other pollutants, leading to increase coliform levels and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

As for the result of iron, the result at the monitoring point of surface water monitoring points (SW-2) and (SW-4) exceeded the target value. The possible reason for exceeded value in surface water (SW-2) and (SW-4) maybe due to the influence of natural origin (iron can reach out from the soil by run-off). Surroundings of the Thilawa SEZ, especially small hilly areas are mainly composed of iron rich soil (lateritic soil), and it can be transported to the low land area by run-off or strong wind.

Table 2.5-1 Results of Water Quality Monitoring at Discharged point and Discharged Creek

Sampling Date			5.12.2023	5.12.2023	5.12.2023	9.1.2024	Target Value (Reference Value for Self- Monitoring)
No.	Parameters	Unit	Regular Monitoring ①	Regular Monitoring ①	Regular Monitoring ①	Additional Monitoring ②	
			SW-2	SW-4	SW-7	SW-7	
1	Water Temperature	°C	29	31	28	-	≤ 35
2	pH	-	7.5	10.0	7.9	-	6-9
3	Dissolved Oxygen (DO)	mg/l	3.57	8.85	4.68	-	-
4	Suspended Solid (SS)	mg/l	70	114	166	-	50
5	BOD ₅	mg/l	17.67	11.69	8.47	-	30
6	COD _{Mn}	mg/l	50.0	30.0	19.4	-	125
7	Total Coliform	MPN/100ml	160000	280000	> 160000	-	400
8	Oil and Grease	mg/l	< 3.1	< 3.1	< 3.1	-	10
9	Total Nitrogen (T-N)	mg/l	2.3	3.8	3.5	-	80
10	Total Phosphorus (T-P)	mg/l	0.31	0.38	0.78	-	2
11	Color	TCU (True Color Unit)	36.03	10.80	10.04	-	150
12	Odor	TON (Threshold Odor Number)	1	3	1.4	-	-
13	Ammonia	mg/l	1.05	0.11	0.74	-	10
14	Total Dissolved Solids	mg/l	366	302	344	-	2000
15	Mercury	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.005
16	Zinc	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	2
17	Arsenic	mg/l	≤ 0.010	≤ 0.010	≤ 0.010	-	0.1
18	Chromium	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.5
19	Cadmium	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.03
20	Selenium	mg/l	≤ 0.010	≤ 0.010	≤ 0.010	-	0.02
21	Lead	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.1
22	Copper	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.5
23	Barium	mg/l	0.186	0.280	0.168	-	1
24	Nickel	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.2
25	Silver	mg/l	≤ 0.002	≤ 0.002	≤ 0.002	-	0.5
26	Iron	mg/l	5.580	6.300	11.680	12.040	3.5



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)

Sampling Date			5.12.2023	5.12.2023	5.12.2023	9.1.2024	Target Value (Reference Value for Self- Monitoring)
No.	Parameters	Unit	Regular Monitoring *)	Regular Monitoring *)	Regular Monitoring *)	Additional Monitoring *)	
			SW-2	SW-4	SW-7	SW-7	
27	Cyanide	mg/l	< 0.002	< 0.002	< 0.002	-	0.1
28	Total Cyanide	mg/l	0.003	0.002	< 0.002	-	1
29	Chromium (Hexavalent)	mg/l	< 0.05	< 0.05	< 0.05	-	0.1
30	Fluoride	mg/l	0.185	1.395	1.000	-	20
31	Free Chlorine	mg/l	< 0.1	< 0.1	< 0.1	-	1
32	Total Residual Chlorine	mg/l	< 0.1	< 0.1	< 0.1	-	0.2
33	Sulphide	mg/l	0.124	0.126	0.515	-	1
34	Formaldehyde	mg/l	0.134	0.094	0.396	-	1
35	Phenols	mg/l	0.010	0.027	0.015	-	0.5
36	Escherichia Coli	MPN/100ml	-	-	6.8	-	(1000)** (CFU/100ml)
37	Flow Rate	m ³ /s	0.003	3.25	-	-	-

Note: Red color means exceeded value than target value.

Note: *) Regular water quality monitoring was carried out in accordance with EIA report. In addition to EIA report, additional water quality monitoring was also carried out on January 9, 2024. As of the water quality monitoring results on December 5, 2023, iron level exceeded at SW-7 than the target value. When the result of December 5, 2023 is compared with that of January 9, 2024, the latter result is lower than the former one.

**Note: Based on the water utilization at discharged creek, the quality standard for water bodies in Japan, (Ministry of Environment, 1993) is set as a reference value for self-monitoring of E. coli for surface water monitoring. However, due to limitation of capacity for analytical laboratory in Myanmar, the method to analyze the "Colony Forming Units (CFU)" is not available in Myanmar. Therefore, the results of "Most Probable Number (MPN)" are assumed similar to CFU values and compared with reference values. Once the method to analyze the CFU will be available in Myanmar, the analytical method will be changed.

Source: Myanmar-Kaesi International Ltd.



2.5.2 Result of Reference Tube Well

Result of water quality monitoring at reference tube well monitoring point is shown in Table 2.5-2. As the comparison with the target value, the result of iron exceeded the target value.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 14.100 mg/l in December 2023 and most of the iron concentration results (from April 2019 to December 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). Moreover, Thilawa SEZ area is mainly composed of iron rich soil (lateritic soil), and it can be saturated in the underlying confined aquifer.

Table 2.5-2 Results of Water Quality Monitoring at Reference Tube Well

No.	Parameters	Unit	GW-2	Target Value (Reference Value for Self-Monitoring)
1	Water Temperature	°C	29	< 35
2	pH	-	6.4	6-9
3	Dissolved Oxygen (DO)	mg/l	6.08	-
4	Suspended Solid (SS)	mg/l	3	50
5	BOD ₅	mg/l	7.68	30
6	COD _{Cr}	mg/l	< 0.7	125
7	Total Coliform	MPN/100ml	140.0	400
8	Oil and Grease	mg/l	< 3.1	10
9	Total Nitrogen (T-N)	mg/l	< 0.5	80
10	Total Phosphorus (T-P)	mg/l	0.65	2
11	Color	TCU (True Color Unit)	74.55	150
12	Odor	TON (Threshold Odor Number)	1	-
13	Ammonia	mg/l	0.21	10
14	Total Dissolved Solids	mg/l	200	2000
15	Mercury	mg/l	< 0.002	0.005
16	Zinc	mg/l	< 0.002	2
17	Arsenic	mg/l	≤ 0.010	0.1
18	Chromium	mg/l	< 0.002	0.5
19	Cadmium	mg/l	≤ 0.002	0.03
20	Selenium	mg/l	≤ 0.010	0.02
21	Lead	mg/l	≤ 0.002	0.1
22	Copper	mg/l	< 0.002	0.5
23	Barium	mg/l	0.100	1
24	Nickel	mg/l	≤ 0.002	0.2
25	Silver	mg/l	≤ 0.002	0.5
26	Iron	mg/l	14.100	3.5
27	Cyanide	mg/l	< 0.002	0.1
28	Total Cyanide	mg/l	< 0.002	1
29	Chromium (Hexavalent)	mg/l	< 0.05	0.1
30	Fluoride	mg/l	0.227	20
31	Free Chlorine	mg/l	< 0.1	1
32	Total Residual Chlorine	mg/l	< 0.1	0.2
33	Sulphide	mg/l	< 0.005	1
34	Formaldehyde	mg/l	< 0.003	1
35	Phenols	mg/l	< 0.002	0.5
36	Escherichia Coli	MPN/100ml	< 1.8	(100)* (MPN/100ml)
37	Flow Rate	m³/s	-	-



Note: Red color means exceeded value than target value.

*Note: Based on the water utilization at monitoring point for ground water, Bi (irrigation water) of National Technical Regulation on Surface Water Quality in Vietnam (No. QCVN 08: 2008/BTHMT) is set as a reference value of self-monitoring for ground water monitoring.

Source: Myanmar Koci International Ltd.

2.5.3 Comparison of Results of Water Quality Exceed the Target Value between Previous Monitoring and December 2023 Monitoring

In order to overview the exceed the target values of the concerned parameters during the present monitoring (December 2023), the results of the exceed parameters with respective sampling points are compared with the previous monitoring results since December 2022.

Regarding the results of the parameter of discharge point, suspended solid amount at SW-7 is higher than the target value in December 2022 and April, August, December 2023. Moreover, total coliform amount at SW-7 is higher than the target value in February, June, August, October and December 2023. The concentrations of total coliform at SW-7 are extending from 2300 MPN/100ml to the detection limit (>160000 MPN/100ml). Total coliform concentration at SW-7 is obviously reached to the detection limit in the early and mid-rainy season, and winter season and it might be the effect of storm water run-off. The result of iron at SW-7 is higher than the target value in this time (December 2023) as well as in December 2022. Noticeably, iron concentration of SW-7 are higher the winter season. Moreover, iron concentration at GW-2 is always higher than the target value except the result of April 2023. It is observed that iron concentration at GW-2 is higher throughout monsoon and winter season.

On the other hand, it is observed that the result of pH at SW-4 is higher than the target value in this monitoring survey (December 2023), but the results are lower than the target value in previous surveys. As for the result of SS concentration, the results at the reference monitoring points (SW-2 and SW-4) are higher than the target value. As for the result of SS concentration, the result of SW-2 is higher in three monitoring surveys (December 2022, June and December 2023) ranging from 70 to 370 mg/l. It is revealed that high concentration of SS at SW-2 occurred at bi-annually monitoring in rainy and winter season. As for the result of SS concentration, the result of SW-4 is higher than the target value during the surveys except April 2023, ranging from 78 to 502 mg/l. It is clear that SS concentrations at SW-4 are higher throughout rainy season due to the storm water run-off from the surrounding and winter season. It is obvious that total coliform at SW-2 is higher in six monitoring surveys among seven (ranging from 1700 to >160000 MPN/100ml) while the result at SW-4 is higher in all monitoring surveys (ranging from 4600 to >160000 MPN/100ml). Especially the total coliform amount at SW-2 and SW-4 were reached to the detection limit (>160000 MPN/100ml) in June 2023. The result of iron at SW-2 and SW-4 are also higher than the target value in four to five monitoring surveys. It is revealed that high concentration of iron at SW-2 occurred during rainy and winter seasons. The result of iron at SW-4 is higher in five monitoring surveys (December 2022 and June, August, October, December 2023) ranging from 6.88 to 22.626 mg/l. It is revealed that high concentration of iron at SW-4 occurred throughout rainy season till the beginning of winter time. It is possible to say that the present condition of the water quality reflects the background condition of the surrounding environment of Thilawa SEZ.

The expected reasons for the results exceed the target value of concerned parameters are discussed in the upper section of this monitoring report.



CHAPTER 3: CONCLUSION AND RECOMMENDATIONS

As described in Chapter 2 (Section 2.5), the results of suspended solid (SS), total coliform and iron at (SW-2, SW-4 and SW-7) and pH at (SW-4) in surface water, and the result of iron at (GW-2) in ground water exceeded the target value in this monitoring period for operation stage of Thilawa SEZ Zone B.

As for the result of SS, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the surface water run-off from bare land in Zone B.

As for the result of total coliform of surface water, result at the main discharging point of Zone B (SW-7) before discharging to the creek, exceeded the target value due to the expected reason; the potential expected reason might be natural bacteria existed in all area of Zone B because the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, and the contaminants from the surroundings into the retention pond may contain fecal matter and other pollutants, leading to increase coliform levels.

Since the composition of the total coliform include bacteria from natural origin, and total coliform do not affect human health directly, E. Coli analysis was carried out alternatively to identify the health impact by coliform bacteria. As for the result of E. Coli of surface water at the main discharging point of Zone B (SW-7), the result was under the reference value. Therefore, although the target value of total coliform was exceeded at the main discharging point of Zone B (SW-7) but it is considered that there is no significant impact on human health.

As for the result of iron, the result at the main discharging point of Zone B (SW-7) before discharging to the creek exceeded the target value. The possible reasons may be due to the influence of natural origin (iron can reach out from soil by run-off). In Yangon, soil is naturally rich in iron and iron remains in the natural environment for a long time. Regarding SW-2 and SW-4, SS concentration are 70 mg/l and 114 mg/l, while iron concentration occur 5.580 mg/l and 6.880 mg/l respectively. It can be clearly seen that the lower suspended solid concentrations generally have lower iron concentrations and higher suspended solid concentrations generally have higher iron concentrations.

As for the result of pH, results at the surface water monitoring point (SW-4) exceeded the target value might be due to wastewater discharged that may contains detergents and soap-based products from the local industrial zone outside of Thilawa SEZ.

The result of total coliform, SS and iron at reference monitoring points (SW-2 and SW-4) exceeded the target values. The exceeded results for total coliform at (SW-2 and SW-4) maybe due to three expected reasons; i) the existing of various kinds of vegetation and aquatic animals, especially fecal contamination from the animals, ii) contaminants from the surroundings into the Shwe Pyauk creek may contain fecal matter and other pollutants, leading to increased coliform levels and iii) incoming tidal water can contain the fecal matter and delivered along Shwe Pyauk creek during flood tide.

The exceeded results for SS at (SW-2 and SW-4) maybe due to two expected reasons; i) delivered from upstream area such as natural origin and wastewater from local industrial zone which is located outside of Thilawa SEZ, and ii) influence by water from the downstream of monitoring points due to backflow by tidal fluctuation along Shwe Pyauk creek.

The expected reason for exceeding the target value of iron at reference monitoring point (SW-2 and SW-4) may be due to the influence of natural origin (iron can reach out from soil by run-off), the surrounding high land areas is comprised of lateritic soils and it can be transported to the low land area by run-off or strong wind.

As for the result of the iron, the result at the monitoring point of reference tube well (GW-2) exceeded the target value. Comparison with previous monitoring results of GW-2 since April 2019, the iron concentration results are ranging from 0.108 mg/l in April 2023 to 14.100 mg/l in December 2023 and most of the iron concentration results (from April 2019 to December 2023) exceeded the target value except the results of August 2019, February and April 2022, and April 2023. Therefore, the possible reasons may due to the influence of natural origin (iron can reach out from soil by run-off). Moreover, Thilawa SEZ area is mainly composed of iron rich soil (lateritic soil), and it can be saturated in the



underlying confined aquifer.

As for future subject for main discharged points of Thilawa SEZ Zone B, the following action may be taken to maintain the target value of total coliform, SS and iron and appropriate water quality monitoring:

- To continue monitoring *Escherichia coli* (E. coli) level to identify health impact by coliform bacteria.
- To monitor the possibility of the overflow from bare land.
- To monitor the possibility of the domestic wastewater from the factories.

End of the Document



FOR DISCHARGED POINT OF THILAWA SEZ ZONE B



Surface water sampling and onsite measurement at SW-7

**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**



Surface water sampling and onsite measurement at SW-2



Surface water sampling and onsite measurement at SW-4



Ground water sampling and onsite measurement at GW-2

APPENDIX-2 LABORATORY RESULTS



FOR DISCHARGED POINT

23-02-2023

CHINA WATER & ELECTRICITY ENGINEERING CONSULTING GROUP CO., LTD.
(Beijing, China)



Report No. : WQA-2023-11-2023

Revision No. : 1

Report Date : 19 December, 2023

Application No. : 0901-0001

Analysis Report

Client Name: Myanmar Water International LTD (MWI)
Address: No. 36/A, 1st Floor, Central Post Office Condominium, 4th Street Road, Tattar Township, Yangon, Myanmar
Project Name: Environment Monitoring Report for Zone A & B
Sample Group Name: W-11-2023
Sample Name: W-11-2023
Sample No: W-11-2023
Water Profile No: W-11-2023
Analysis Date: 19 December, 2023
Sample Received Date: 19 December, 2023
Analytical Date: 19/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	388	-
2	BOD (5)	APHA 5210 B (5-Days BOD Test)	mg/l	9.87	0.00
3	COD (Cr)	APHA 5220D (Close Reflux Colorimetric Method)	mg/l	29.4	0.7
4	Total Calcium	APHA 9221B (Standard Titr Calcium Determination Technique)	mg/l	110000	1.9
5	Oil and Grease	APHA 9520B (Petroleum-Grease Method)	mg/l	43.1	3.1
6	Color	APHA 2130C (Spectrophotometric Method)	PCU	10.56	0.07
7	Total Nitrogen	HR-1 Method 50372 (POT Resubstrate Digestion Method)	mg/l	3.5	0.5
8	Total Phosphorus	APHA 4500-P-P (Ascorbic Acid Method)	mg/l	0.18	0.05
9	Ammonia	HR-1 Method 50355 (Nesslerize NIT-Rite Method)	mg/l	0.14	0.02
10	TDS	APHA 2540-C (Total Dissolved Solids Gravimetric Method)	mg/l	344	-
11	Iron	APHA 3150-B (Thionitrite Color Test)	mg/l	1.4	0.1
12	Mercury	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
13	Zinc	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
14	Arsenic	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.010	0.010
15	Chromium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
16	Cadmium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
17	Selenium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.010	0.010
18	Copper	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
19	Lead	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
20	Barium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.156	0.022

**LAB
GEM**

Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)

D-014-04

(Signature and Stamp of the Analyst)
Name: Cherry Kait Thiri
Position: Assistant Manager



No.	Parameter	Method	Unit	Result	LOQ
21	Nitrate	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	±0.003	0.002
22	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	±0.003	0.002
23	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	24.880	0.002
24	Cyanide	HACH 8027 (Preliminary - Persulfate Method)	mg/l	±0.002	0.002
25	Total Cyanide	Oxidation Process: APHA 4500-CN-C, Total Cyanide after Oxidation, Determine Cyanide Concentration Process: HACH 8027 (Preliminary - Persulfate Method)	mg/l	±0.002	0.002
26	Ammonium Nitrogen (NH ₄ -N)	ISO 11883:1994 (Determination of ammonium(VI) Spectrophotometric method using 1,5-diphenylcarbazide)	mg/l	±0.05	0.05
27	Fluoride	APHA 8020-C (or) Directly with Chemical Suppression of Fluoride Conductivity	mg/l	1.588	0.014
28	Free Chlorine	APHA 4500-CL-G (DPD Colorimetric Method)	mg/l	±0.1	0.1
29	Total Residual Chlorine	APHA 4500-CL-G (DPD Colorimetric Method)	mg/l	±0.1	0.1
30	Sulfate	HACH 8131 (U.S.EPA Methylene Blue Method)	mg/l	0.115	0.005
31	Formaldehyde	HACH 8110 (MBTH Method)	mg/l	0.158	0.005
32	Bacteriophage Coli	APHA 9221-B Bacteriophage Coli Procedure Using Phagegen [®] Substrate	no./100ml	5.8	1.8
33	Phenol	APHA Method 400-1 (Reaction Spectrophotometric, Period 4000 with Catalyst)	mg/l	0.015	0.002

Notes:

(LOQ) - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA (2005), Color Unit - 1CU (one Color Unit) One PCU is equivalent to one million unit absorbance at 2.5 cm

Analysed By

Cherry Kait Thiri
Assistant Manager



Approved By

W. M. Aye Lin
Manager

(Signature and Stamp of the Analyst)
Name: Cherry Kait Thiri
Position: Assistant Manager





GOLDEN DOWA ECO-SYSTEM MYANMAR CO., LTD.
Lot No E1, Thilawa SEZ Zone A, Yangon Region, Myanmar.
Phone No Fax No: (+95) 1 2509051



motivate our planet
Doc No: GEM-LB-R006/200/AD
Page 1 of 1

Report No. : GEM-LAB-202401036
Revision No. : 1
Report Date : 17 January, 2024
Application No. : 0001-C001

Analysis Report

Client Name : MJTD Co.Ltd
Address : 1st Floor, Administration Complex, Thilawa Special Economic Zone, Yangon.
Project Name : -
Sample Description :
Sample Name : SW-2(Environment)
Sample No. : W-2401055
Waste Profile No :
Sampling Date : 9 January, 2024
Sampling By : Customer
Sample Received Date : 9 January, 2024
Analytical Date : 9-17/01/2024

No.	Parameter	Method	Unit	Result	LOQ
1	Iron	APHA 2120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	12.040	0.002

Remark : LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed By:


Ni Ni Aye Lwin
Manager



Approved By :


Hsiao Yochia Jan 19, 2024
Managing Director

REPORT RESULT IS ONLY OF THE SAMPLE SUBMITTED FOR ANALYSIS.
THIS ANALYSIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, WITHOUT WRITTEN APPROVAL OF THE UNDERSIGNED OF
GOLDEN DOWA ECO-SYSTEM MYANMAR CO., LTD.



**FOR REFERENCE MONITORING POINTS FOR COMPARISON WITH DISCHARGED
POINTS AND BASELINE OF DISCHARGED CREEK**

01/12/2023

Copyright © 2023 by Myanmar Environmental
Development Co., Ltd. (MED)



Report No.: CEM-LAB-202312001

Revision No.: 1

Report Date: 19 December, 2023


Application No.: 0001-CED

Analysis Report

Client Name: Myanmar Environmental Development Co., Ltd. (MED)
Address: No. 30/A, 1st Floor, Grand Piro Sati Condominium, Piro Sati Road, Fenny Township, Yangon, Myanmar
Project Name: Environment Monitoring report for Zone A & B
Sample Description:
Sample Name: WQ-GW-2-1201
Sample No: W-212011
Sample Profile No:

Sampling Date: 5 December, 2023
Sampling By: Customer
Sample Received Date: 5 December, 2023
Analysis Date: 19/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	70	
2	BOD (5)	APHA 5210-B (5 Days BOD Test)	mg/l	17.67	0.00
3	COD (Cr)	APHA 5220D (Dissolved Oxygen Colorimetric Method)	mg/l	50.0	0.0
4	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)	MPN/100ml	100000	0.0
5	Oil and Grease	APHA 9520B (Partition Gravimetric Method)	mg/l	<1.1	1.1
6	Color	APHA 2120C (Spectrophotometric Method)	PCU	36.01	0.00
7	Total Nitrogen	HACH Method 10032 (TN- Persulfate Digestion Method)	mg/l	2.1	0.5
8	Total Phosphorus	APHA 4500-P-E (Ascorbic Acid Method)	mg/l	0.31	0.05
9	Arsenic	HACH Method 10205 (Selenite Tri Sulfoxide Method)	mg/l	0.05	0.02
10	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	366	
11	Odor	APHA 150-B (Threshold Odor Test)	TCU	5	0
12	Mercury	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13	Zinc	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
14	Arsenic	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
15	Chromium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
16	Cadmium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
17	Selenium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.01
18	Lead	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19	Copper	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20	Barium	APHA 3120-B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.186	0.002



Myanmar Environmental Development Co., Ltd. (MED)
10th Floor, Grand Piro Sati Condominium, Piro Sati Road, Fenny Township, Yangon, Myanmar
www.myanmarenvironmental.com



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)

01/04/24

(Signature of the Analyst)
Name: [Signature]
Date: 01/04/24



No.	Parameter	Method	Unit	Result	LOQ
23	Iron	APHA 3100 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
22	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
24	Zinc	APHA 3100 B (Inductively Coupled Plasma (ICP) Method)	mg/l	5.580	0.002
24	Cyanide	HACH 8027 (Pyridine - Pyrazole Method)	mg/l	<0.002	0.002
25	Total Cyanide	Dissolution Process APHA 4500-CN C, Total Cyanide after Dissolution, Determine Cyanide Concentration Process: HACH 8027 (Pyridine - Pyrazole Method)	mg/l	0.002	0.002
26	Hexavalent Chromium (Cr VI)	ISO 11093:1994 (Determination of chromium(VI) Spectrometric method using 1,5-diphenylcarbazide)	mg/l	<0.05	0.05
27	Fluoride	APHA 8120 (Ion Chromatography with Chloride Suppressor of Fluoride Ionselective)	mg/l	0.180	0.014
28	Free Chlorine	APHA 4500 CL G (DPD Colorimetric Method)	mg/l	<0.1	0.1
29	Total Residual Chlorine	APHA 4500 CL G (DPD Colorimetric Method)	mg/l	<0.1	0.1
30	Sulfide	HACH 8131 (USEPA Methylene Blue Method)	mg/l	0.124	0.005
31	Formaldehyde	HACH 8110 (MBTH Method)	mg/l	0.134	0.003
32	Phenols	USEPA Method 421.1 (Phenols (spectrophotometric, Reagent Addition) Distillation)	mg/l	0.010	0.002

Remarks

LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 2120B (Fe): Color Unit = 702 Hue Unit (unit), the 702 is equivalent to the Hue unit and the 702 is the 702 unit.

Analysed by


Chany Minn, BSc
Assistant Manager



Approved by


H. H. Aye Lynn, BSc, MSc
Manager

(Signature of the Analyst)
Name: [Signature]
Date: 01/04/24



**Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)**

02/12/2023

Environmental Monitoring Laboratory (EM-LAB)
Unit 11, Tower 11/12, Capital Square, Thilawa
Thilawa Industrial Zone, Yangon, Myanmar



Report No.: EM-LAB-2023/2023

Revision No.: 1

Report Date: 19 December, 2023

Application No.: 0001-C001

Analysis Report

Client Name: Myanmar Kobi International LTD (MKT)
Address: No. 16/A, 15th Floor, Grand Hla Sen Condominium, Hla Sen Road, Tattawa Township, Yangon, Myanmar
Project Name: Environment Monitoring report for Zone A & B
Sample Description: Sewage Effluent
Sample Name: MKT-SW-A-1202
Sample No.: W-23/2019
Water Profile No.:
Sampling Date: 5 December, 2023
Sampling By: Customer
Sample Received Date: 5 December, 2023
Analysis Date: 5-19/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/L	114	-
2	BOD (3)	APHA 5210 B (5 Days BOD Test)	mg/L	51.59	0.08
3	COD (Cr)	APHA 5210D (Closed Reflux Colorimetric Method)	mg/L	38.0	0.7
4	Total Coliform	APHA 8210 B (Standard Total Coliform Fermentation Technique)	mpn/100ml	20000/B	1.8
5	Oil and Grease	APHA 5520B (Petroleum Gravitimetric Method)	mg/L	<0.1	1.1
6	Color	APHA 2120C (Spectrophotometric Method)	PCU	10.80	0.00
7	Total Nitrogen	HACH Method 10072 (TKN Persulfate Digestion Method)	mg/L	0.8	0.5
8	Total Phosphorus	APHA 4500-P F (Ascorbic Acid Method)	mg/L	0.34	0.05
9	Ammونيا	HACH Method 10295 (Distillate TNT Plus Method)	mg/L	0.11	0.02
10	TDS	APHA 2540 C (Total Dissolved Solids Tared at 180°C Method)	mg/L	302	-
11	Odor	APHA 2150 B (Threshold Odor Test)	ODS	3	0
12	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
13	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
14	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.010	0.010
15	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
16	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
17	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.01
18	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
19	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
20	Manganese	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.080	0.002

**LAB
GEM**

Environmental Monitoring Laboratory (EM-LAB)
Unit 11, Tower 11/12, Capital Square, Thilawa
Thilawa Industrial Zone, Yangon, Myanmar



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)

CONTENTS

WATER QUALITY MONITORING REPORT FOR
DEVELOPMENT OF INDUSTRIAL AREA IN THILAWA SEZ ZONE B
(BI-ANNUALLY MONITORING IN FY DECEMBER - 2023)



No.	Parameter	Method	Unit	Result	LOQ
21	Asbestos	APHA 21.22 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
22	Boron	APHA 21.22 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
23	Cadmium	APHA 21.22 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.000	0.002
24	Cyanide	HACH 8027 (Prindles - Potassium Method)	mg/l	<0.002	0.002
25	Total Cyanide	Oxidation Process (APHA 4500-CN-C, Total Cyanide after Distillation, Determination: Colorimetric Concentration Process, HACH 8027 (Prindles - Potassium Method)	mg/l	0.002	0.002
26	Hexavalent Chromium (Cr(VI))	ISO 11063:2004 (Determination of chromium(VI) Spectrometric method using 1,5-diphenylcarbazide)	mg/l	<0.01	0.05
27	Fluoride	APHA 4110 B (Ion Chromatography with Chemoselective of Fluoride Electrode)	mg/l	1.295	0.204
28	Total Chlorine	APHA 4500-Cl-G (DPD Colorimetric Method)	mg/l	<0.1	0.1
29	Total Residual Chlorine	APHA 4500-Cl-G (DPD Colorimetric Method)	mg/l	<0.1	0.1
30	Sulfide	HACH 8131 (DIFEA Methylene Blue Method)	mg/l	0.120	0.006
31	Formaldehyde	HACH 8110 (PBTH Method)	mg/l	0.004	0.001
32	Phenols	APHA 8190 A (4-Amino-2,6-Dimethylphenol Method)	mg/l	0.007	0.001

Notes:

LOQ = Limit of Quantitation

APHA = American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 21.22B.820, Total (As + TC) (As+Total As) (As+TC) is equivalent to one Asbestos unit and is only PL Cr units

Analysed By:

Cherry Nyein Thun
Assistant Manager



Approved By:

N. M. Aye Linn, Dec. 29, 2023
Manager

This report is valid only if accompanied by the original sample.
This report is valid only if accompanied by the original sample.
This report is valid only if accompanied by the original sample.



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Bi-Annually Monitoring in FY December - 2023)

DD&WA

JAPAN THILAWA DEVELOPMENT LIMITED
10th Floor, 10th Floor, Grand Pric Sea Condominium, Phra Sam Road, Thilawa Township, Yangon, Myanmar



Region No. GDM-LAB-202312023
Revision No. 1.1
Report Date 19 December, 2023
Application No. 0001-C001

Analysis Report

Client Name Myanmar Kael International LTD (PPL)
Address No. 36/A, 3rd Floor, Grand Pric Sea Condominium, Phra Sam Road, Thilawa Township, Yangon, Myanmar
Project Name Environment Monitoring report for Zone A & B
Sample Description
Sample Name HQ-GW-2-1203
Sample No W-111201R
Water Profile No.
Received Date 5 December, 2023
Issued By Customer
Sample Received Date 5 December, 2023
Analytical Date 5-19/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	2	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	7.66	0.20
3	COD (Cr)	APHA 5220D (Open Reflux Colorimetric Method)	mg/l	<0.2	0.1
4	Total Calcium	APHA 5211B (Standard Total Calcium Fermentation Test/Reagent)	mg/l	140.8	1.4
5	Oil and Grease	APHA 5530B (Filtration Gravimetric Method)	mg/l	<1.1	1.1
6	Color	APHA 1540C (Spectrophotometric Method)	PCU	14.55	0.00
7	Total Nitrogen	HACH Method 10021 (TNT Persulfate Digestion Method)	mg/l	<0.5	0.5
8	Total Phosphorus	APHA 4500 P C (Ascorbic Acid Method)	mg/l	0.66	0.05
9	Arsenite	HACH Method 10205 (Silylating Reagent Method)	mg/l	0.24	0.10
10	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	300	-
11	pH	APHA 2150 A (Freeze-dried Color Test)	pH	1	0
12	Mercury	APHA 3125 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13	Zinc	APHA 3126 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
14	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
15	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
16	Calcium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
17	Selenium	APHA 3126 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
18	Lead	APHA 3129 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19	Copper	APHA 3126 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20	Barium	APHA 3126 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.100	0.002

LAB
GEM

JAPAN THILAWA DEVELOPMENT LIMITED
10th Floor, 10th Floor, Grand Pric Sea Condominium, Phra Sam Road, Thilawa Township, Yangon, Myanmar



Water Quality Monitoring Report for Development of Industrial Area in Thilawa SEZ Zone B
(Be Annually Monitoring in FY December - 2023)

Continued

MOLAY CHAN MYINT
General Manager
Thilawa SEZ Development Co., Ltd.



No.	Parameter	Method	Unit	Result	LOQ
21	Nickel	APHA 8000 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
22	Silver	APHA 8120 B (Electrode Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
23	Iron	APHA 8100 B (Inductively Coupled Plasma (ICP) Method)	mg/L	14.100	0.002
24	Cadmium	APHA 8001 (Positive - Gravimetric Method)	mg/L	<0.001	0.001
25	Total Cyanide	Distillation Process APHA 8100 C- C, Total Cyanide after Distillation, Selenium Cyanide Concentration Process (HACH DR27 (ph) dye - Potentiometric Method)	mg/L	<0.002	0.002
26	Ammonia Nitrogen (NH ₄ ⁺)	ISO 11083 (NHA Condensation of chromophoric) Spectrometry method using 1,2-diphenylhydrazide)	mg/L	<0.10	0.00
27	Fluoride	APHA 8100 (Ion Chromatography with Chloride Suppression of Fluoride Conductivity)	mg/L	0.227	0.014
28	Free Chlorine	APHA 8000 D-5 (DPD (colorimetric Method)	mg/L	<0.1	0.1
29	Total Residual Chlorine	APHA 8000 D-5 (DPD Colorimetric Method)	mg/L	<0.1	0.1
30	Sulphide	HACH 8133 HACHDR Method: Blue Method)	mg/L	<0.005	0.006
31	Formaldehyde	HACH 8110 (Phenyl Method)	mg/L	<0.001	0.001
32	Biochemical Oxygen Demand (BOD ₅)	APHA 8221 F Incubation Cell Procedure Using Potentiometric Substrate	mg/L	<1.0	1.0
33	Chemical Oxygen Demand (COD)	APHA 8221 F Incubation Cell Procedure Using Potentiometric Substrate	mg/L	<0.002	0.002

Remarks

LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the State Environmental Protection (SEPA), Standard Methods for the Examination of Water and Wastewater, 22nd edition.

APHA 8100 BOD₅ Code (HACH DR27 (ph) dye - Potentiometric) is equivalent to standard method used by the EPA.

Analysed By:

[Signature]

Chen Nyein Thiri
Assistant Manager



Approved By:

[Signature]

W. Aye Lay
Manager

Thilawa SEZ Development Co., Ltd.
General Manager
Thilawa SEZ Development Co., Ltd.



**Thilawa Special Economic Zone
Zone B– Phase 1,2 & 3 (Operation phase)**

Appendix-D

Air Quality Monitoring Report

December 2023

**AIR QUALITY MONITORING
REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

**December 2023
Myanmar Koei International Ltd.**



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN.....	1
1.1 General.....	1
1.2 Outlines of Monitoring Plan.....	1
CHAPTER 2: AIR QUALITY MONITORING.....	2
2.1 Monitoring Item.....	2
2.2 Monitoring Location.....	2
2.3 Monitoring Period.....	2
2.4 Monitoring Method.....	3
2.5 Monitoring Results.....	3
CHAPTER 3: CONCLUSION AND RECOMMENDATION.....	8
APPENDIX-1 HOURLY AIR RESULTS.....	A1-1
APPENDIX-2 CERTIFICATE OF CALIBRATION.....	A2-1

LIST OF TABLES

Table 1.2-1 Outlines of Air Quality Monitoring Plan.....	1
Table 2.5-1 Air Quality Monitoring Result (Daily Average).....	3
Table 2.5-2 Total Exceeded Hours.....	6
Table 2.5-3 Summary of Wind Direction at AQ-1.....	7

LIST OF FIGURES

Figure 2.2-1 Location of Air Quality Monitoring Point.....	2
Figure 2.4-1 Status of Air Quality Monitoring Point.....	3
Figure 2.5-1 Wind Status at AQ-1.....	4
Figure 2.5-2 Wind Rose Diagram of AQ-1.....	5



CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd. (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, air quality had been monitored from 11 December 2023 to 18 December 2023 as follows;

Table 1.2-1 Outlines of Air Quality Monitoring Plan

Monitoring Date	Monitoring Item	Parameters	Number of Point	Duration	Monitoring Methodology
From 11 December to 18 December, 2023	Air Quality	CO, NO ₂ , PM _{2.5} , PM ₁₀ and SO ₂	1	7 Days	On site measurement by Haz-Scanner Environmental Perimeter Air Station (EPAS)

Source: Myanmar Koci International Ltd.



CHAPTER 2: AIR QUALITY MONITORING

2.1 Monitoring Item

The parameters for air quality monitoring were CO, NO₂, PM_{2.5}, PM₁₀ and SO₂.

2.2 Monitoring Location

The air quality measurement equipment, "Haz-Scanner Environmental Perimeter Air Station (EPAS)" was set up at the south of the Thilawa SEZ Zone B, N: 16°39'24.20", E: 96°17'15.80", inside the monastery compound of Phalan village. As the monitoring point (AQ-1) is adjacent to the southern boundary of Thilawa SEZ Zone B, it is surrounded by Thilawa SEZ Zone B in the north and east. In the south and west of AQ-1, the residential houses of Phalan village and the fields are occurred respectively. Besides, Thilawa SEZ Zone A is distanced about 2 km north of AQ-1 as well as the Thilawa Industrial Zone is about 1 km northeast. Due to the air quality monitoring is carried out at above location which is closed to the residential houses of Phalan village, the possible emission sources are exhaust gas and dust emissions from the fuel-burning equipment and other tasks of construction activities of Zone B but also from the daily human activities in Phalan village. The location of air quality monitoring is shown in the Figure 2.2-1.



Figure 2.2-1 Location of Air Quality Monitoring Point

2.3 Monitoring Period

Air quality monitoring was conducted seven consecutive days from 11 December, 2023 to 18 December, 2023.

2.4 Monitoring Method

Monitoring of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ were conducted by referring to the recommendation of the United States Environmental Protection Agency (U.S. EPA). The Haz-Scanner EPAS was used to collect ambient air pollutants. The EPAS measures automatically every one minute and directly reads and records onsite for CO, NO₂, PM_{2.5}, PM₁₀ and SO₂. Wind data are analyzed by using the WRPLOT View (Ver. 8.0.2); in which calm wind is defined below 0.5 m/s. The status of air quality monitoring is shown in Figure 2.4-1.



Source: Myanmar Kooi International Ltd.

Figure 2.4-1 Status of Air Quality Monitoring Point

2.5 Monitoring Results

The daily average value of air quality monitoring results of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ are described in Table 2.5-1. Comparing with the target value of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ prescribed in EIA report for Thilawa SEZ development project Zone B, seven days average concentration of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ were within target value. However, daily average concentration of PM_{2.5} for three days, and that of PM₁₀ and SO₂ for two days were exceeded the target value. When compared with the PM₁₀ daily average value of environmental standards by Ministry of Environment Japan (MOEJ) which is 35 µg/m³ (0.035 mg/m³), the exceeded values are complied with MOEJ's target values.

Table 2.5-1 Air Quality Monitoring Result (Daily Average)

Date	CO mg/m ³	NO ₂ mg/m ³	PM _{2.5} mg/m ³	PM ₁₀ mg/m ³	SO ₂ mg/m ³
11~12 December, 2023	0.166	0.041	0.024	0.036	0.016
12~13 December, 2023	0.233	0.066	0.026	0.058	0.023
13~14 December, 2023	0.179	0.082	0.027	0.062	0.027
14~15 December, 2023	0.257	0.092	0.024	0.041	0.019
15~16 December, 2023	0.198	0.078	0.029	0.047	0.018
16~17 December, 2023	0.159	0.096	0.023	0.034	0.019
17~18 December, 2023	0.251	0.095	0.021	0.031	0.020
7 Days Average Value	0.200	0.078	0.025	0.044	0.020
Target Value	0.26	0.1	0.025	0.05	0.02

Note: Red color indicates the exceeded value for PM_{2.5}, PM₁₀ and SO₂.

The target value of CO, NO₂ and SO₂ were converted from ppm units to mg/m³. The conversion equation are as follows:

1. (CO, mg/m³) = (CO, ppm) * (Molecular Weight of CO, 28) / 24.45 at 25°C and 1 atm condition

2. (NO₂, mg/m³) = (NO₂, ppm) * (Molecular Weight of NO₂, 46) / 24.45 at 25°C and 1 atm condition

3. (SO₂, mg/m³) = (SO₂, ppm) * (Molecular Weight of SO₂, 64) / 24.45 at 25°C and 1 atm condition

Source: Myanmar Kooi International Ltd.

Wind direction and wind speed were measured at AQ-1. Hourly average values of measured wind direction and wind speed data are described in Appendix-1. Frequency of wind direction at AQ-1 and its wind rose diagram are described in Figure 2.5-1 and Figure 2.5-2. According to the wind rose analysis, the prevailing wind direction during monitoring was Northeast (NE) and the least frequency wind direction was

Southwest (SW). During the monitoring period, while the maximum wind speed was 1.0 m/s, the average speed is 0.09 m/s. The calm wind is 83.93%, whereas the calm wind is defined below 0.5 m/s. As the average wind speed is lower than the defined calm wind, it is assumed that the wind was calm during the monitoring period.



Source: Myanmar E&E International Ltd.

Figure 2.5-1 Wind Status at AQ-1




Figure 2.5-2 Wind Rose Diagram of AQ-1



There were no construction activities during this monitoring period.

Overall summary of total exceeded hours of particulate matters and SO₂ during the seven days monitoring period are shown in Table 2.5-2. According to the daily average values, Day 2, Day 3 and Day 5 values of PM_{2.5} as well as the values of Day 2 and Day 3 of PM₁₀ and SO₂ are higher than the target value.

When compared with the target value, the total exceeded hours during 7-days consecutive monitoring for PM_{2.5} were 96 hours, observing from evening till early morning on Day 2, Day 3 and Day 5. For PM₁₀, the total exceeded hours during 7-days consecutive monitoring were 70 hours, those hours were observed from evening till early morning on Day 2 and Day 3. For SO₂, the total exceeded hours during 7-days consecutive monitoring were 52 hours and those exceeded hours occurred from afternoon to evening on Day 2 and Day 3.

According to the wind data, the wind was prominently blowing from North-Northeast (NNE) and East-Northeast (ENE) directions during night on Day 2. On Day 3, the prominent wind direction during night were Northeast (NE) and Northwest (NW). During day time on Day 5, the prominent wind directions were North (N) and North-Northeast (NNE). (see Appendix 1)

According to the summary of wind direction at AQ-1, most of the prominent wind were blowing from Northwest (NW) and Northeast (NE) quadrants, observing more than 70% of total wind direction (Table 2.5-3).

Possible emission sources for PM_{2.5} and PM₁₀ are affected from natural origin such as dust from unpaved land area from outside of Zone B and transportation in and around the monitoring area.

Possible emission sources for SO₂ are affected from the combustion of fuel for vehicles from nearby roads, daily human activities in residential area (cooking by wood or charcoal, open burning, etc.), operation activities of Thilawa Port, operation activities of local industrial zone and operation activities of Zone B.

In the evening and night during winter, the air becomes cold, dense and moving slower than in day time. Consequently, cold air can trap the particulate matter or pollutants, and remaining in place for longer time, causing the high concentration of pollutants during night. Moreover, Planetary Boundary Layer, a section of atmosphere from 0 to about 1.5 km from above sea level, becomes shallow during night and there will be less space for pollution particle to move around, causing them to get more concentrated.

Table 2.5-2 Total Exceeded Hours

	Parameters	Total Exceeded Hours
Day 1 – Day 7	PM _{2.5}	96
	PM ₁₀	70
	SO ₂	52

Source: Myanmar Kyori International Ltd.

Table 2.5-3 Summary of Wind Direction at AQ-1

Wind Direction	All Day	Day Time	Evening Time	Night Time
N	19.0%	10.7%	3.0%	5.4%
NNE	18.5%	6.5%	3.0%	8.9%
NE	6.5%	4.8%	1.2%	0.6%
ENE	5.4%	4.2%	1.2%	0.0%
E	1.8%	1.8%	0.0%	0.0%
ESE	2.4%	2.4%	0.0%	0.0%
SE	3.6%	1.8%	1.8%	0.0%
SSE	4.2%	3.6%	0.6%	0.0%
S	6.5%	3.0%	0.0%	3.6%
SSW	4.8%	0.0%	0.0%	4.8%
SW	1.2%	1.2%	0.0%	0.0%
WSW	1.8%	0.0%	0.6%	1.2%
W	2.4%	1.2%	0.6%	0.6%
WNW	3.0%	1.2%	0.6%	1.2%
NW	9.5%	4.2%	0.0%	5.4%
NNW	9.5%	3.6%	0.0%	6.0%
Total	100.0%	50.0%	12.5%	37.5%

Source: Myanmar Koei International Ltd



CHAPTER 3: CONCLUSION AND RECOMMENDATION

The result of seven days average air quality of CO, NO₂, PM_{2.5}, PM₁₀ and SO₂ during seven days monitoring did not exceed the target value, thus there are no impacts on the surrounding environments. However, daily average concentration of PM_{2.5} for three days, and that of PM₁₀ and SO₂ for two days were exceeded the target value. When compared with the PM_{2.5} daily average value of environmental standards by Ministry of Environment Japan (MOEJ) which is 35 µg/m³ (0.035 mg/m³), the exceeded values are complied with MOEJ's target values.

When compared with the target value, the total exceeded hours during 7-days consecutive monitoring for PM_{2.5} were 96 hours, observing from evening till early morning on Day 2, Day 3 and Day 5. For PM₁₀, the total exceeded hours during 7-days consecutive monitoring were 70 hours, those hours were observed from evening till early morning on Day 2 and Day 3.

Possible emission sources for PM_{2.5} and PM₁₀ are affected from natural origin such as dust from unpaved land area from outside of Zone B and transportation in and around the monitoring area.

According to US Environmental Protection Agency (EPA) and WHO's health effect of particulate matter, there is no evidence of safe level of exposure or a threshold below which no adverse health effects occur. Exposure to PM_{2.5} and PM₁₀ reduces the life expectancy of the population of the Region by about 8.6 months on average. Short term (hours, days) exposure to PM_{2.5} and PM₁₀ can aggravate lung disease, causing asthma attacks and acute bronchitis, and may also increase susceptibility to respiratory infections. In people with heart disease, short term exposures have been linked to heart attacks and arrhythmias. However, healthy children and adults have not been reported to suffer serious effects from short term exposures. Long term exposures (months, years) have been associated with problems such as reduced lung function and the development of chronic bronchitis and even premature death. Even though the daily average values exceeded the target values, it does not exceed the level I guideline for alert by MOEJ which is equal to or less than 70 µg/m³ (0.07 mg/m³). Therefore, it can be considered to have no serious health impact and it is not necessary to avoid outside activities, however, it is desirable for high sensitive receptors to pay attention to their health condition considering the potential impact.

For SO₂, the total exceeded hours during 7-days consecutive monitoring were 52 hours and those exceeded hours occurred from afternoon to evening on Day 2 and Day 3.

Possible emission sources for SO₂ are affected from the combustion of fuel for vehicles from nearby roads, daily human activities in residential area (cooking by wood or charcoal, open burning, etc.), operation activities of Thilawa Port, operation activities of local industrial zone and operation activities of Zone B.

In the public health statement SO₂ reported by ATSDR (Agency for Toxic Substances and Disease Registry) in US, 100 ppm (261.8 mg/m³) SO₂ is considered immediately dangerous to life and health (short term). Lung function changes observed when 0.4 to 3 ppm (1.05mg/m³ to 7.85 mg/m³) exposure for 20 years or more (long term). Therefore, although the target value of SO₂ was exceeded during monitoring period but it is considered that there is no significant impact on human health.

As for future subject for air quality monitoring in Zone B, the following action may be taken to achieve the target level:

- 1) To control the speed limit of all machinery & vehicle (25km/hr) on site to avoid excessive dust creation and to minimize air pollution by the exhaust fumes.
- 2) To conduct the proper operation (stop idling while no operation).
- 3) To implement the regular maintenance of machine used for operation activities.

The periodical monitoring will be necessary to grasp the environmental conditions in operation stage of Thilawa SEZ Zone B. The mitigation measures for environmental management will be considered in collected periodical environmental data and has to be reviewed in future.

Date	Time	CO	NO _x	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
		mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
		Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
11 December, 2023	11:00 ~ 11:59	0.231	0.019	0.009	0.013	0.032	0.40	98	E
11 December, 2023	12:00 ~ 12:59	0.167	0.018	0.020	0.032	0.036	0.43	11	N
11 December, 2023	13:00 ~ 13:59	0.624	0.022	0.010	0.024	0.019	0.45	354	N
11 December, 2023	14:00 ~ 14:59	0.202	0.020	0.022	0.032	0.021	0.45	81	E
11 December, 2023	15:00 ~ 15:59	0.133	0.018	0.010	0.023	0.021	1.00	140	SE
11 December, 2023	16:00 ~ 16:59	0.099	0.014	0.012	0.025	0.028	0.15	110	ESE
11 December, 2023	17:00 ~ 17:59	0.146	0.012	0.028	0.034	0.023	0.20	167	SSE
11 December, 2023	18:00 ~ 18:59	0.277	0.041	0.027	0.032	0.010	0.05	173	S
11 December, 2023	19:00 ~ 19:59	0.269	0.070	0.033	0.038	0.005	0.02	45	NE
11 December, 2023	20:00 ~ 20:59	0.145	0.047	0.028	0.032	0.015	0.00	267	W
11 December, 2023	21:00 ~ 21:59	0.157	0.053	0.018	0.023	0.017	0.00	254	WSW
11 December, 2023	22:00 ~ 22:59	0.134	0.027	0.015	0.023	0.018	0.00	254	WSW
11 December, 2023	23:00 ~ 23:59	0.167	0.026	0.022	0.026	0.015	0.00	211	SSW
12 December, 2023	00:00 ~ 00:59	0.217	0.038	0.029	0.034	0.016	0.00	204	SSW
12 December, 2023	01:00 ~ 01:59	0.183	0.042	0.033	0.043	0.015	0.00	204	SSW
12 December, 2023	02:00 ~ 02:59	0.027	0.018	0.038	0.056	0.015	0.00	204	SSW
12 December, 2023	03:00 ~ 03:59	0.067	0.013	0.040	0.068	0.014	0.00	203	SSW
12 December, 2023	04:00 ~ 04:59	0.107	0.027	0.040	0.077	0.016	0.00	203	SSW
12 December, 2023	05:00 ~ 05:59	0.117	0.042	0.031	0.067	0.017	0.00	203	SSW
12 December, 2023	06:00 ~ 06:59	0.150	0.078	0.042	0.074	0.014	0.00	203	SSW
12 December, 2023	07:00 ~ 07:59	0.247	0.178	0.030	0.039	0.005	0.05	214	SW
12 December, 2023	08:00 ~ 08:59	0.076	0.140	0.025	0.035	0.000	0.18	324	NW
12 December, 2023	09:00 ~ 09:59	0.017	0.025	0.008	0.013	0.000	0.27	18	NNE
12 December, 2023	10:00 ~ 10:59	0.030	0.019	0.009	0.010	0.002	0.43	11	N
Max		0.624	0.178	0.042	0.077	0.036			
Avg		0.166	0.041	0.024	0.036	0.016			
Min		0.017	0.012	0.008	0.010	0.000			



Date	Time			CO	NO _x	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
				mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
				Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
12 December, 2023	11:00	~	11:59	0.217	0.018	0.007	0.010	0.023	0.52	23	NNE
12 December, 2023	12:00	~	12:59	0.863	0.012	0.008	0.016	0.053	0.57	74	ENE
12 December, 2023	13:00	~	13:59	0.401	0.017	0.006	0.034	0.047	0.35	85	E
12 December, 2023	14:00	~	14:59	0.305	0.018	0.009	0.029	0.043	0.58	49	NE
12 December, 2023	15:00	~	15:59	0.365	0.021	0.015	0.020	0.037	0.53	175	S
12 December, 2023	16:00	~	16:59	0.300	0.025	0.036	0.065	0.032	0.40	162	SSE
12 December, 2023	17:00	~	17:59	0.116	0.058	0.029	0.058	0.036	0.13	172	S
12 December, 2023	18:00	~	18:59	0.434	0.151	0.042	0.061	0.029	0.13	128	SE
12 December, 2023	19:00	~	19:59	0.579	0.104	0.028	0.051	0.013	0.10	64	ENE
12 December, 2023	20:00	~	20:59	0.429	0.120	0.025	0.042	0.017	0.07	76	ENE
12 December, 2023	21:00	~	21:59	0.118	0.087	0.028	0.051	0.018	0.00	9	N
12 December, 2023	22:00	~	22:59	0.078	0.065	0.032	0.062	0.018	0.03	21	NNE
12 December, 2023	23:00	~	23:59	0.052	0.084	0.033	0.071	0.018	0.00	23	NNE
13 December, 2023	00:00	~	00:59	0.116	0.064	0.041	0.095	0.020	0.03	34	NE
13 December, 2023	01:00	~	01:59	0.097	0.004	0.025	0.058	0.019	0.22	189	S
13 December, 2023	02:00	~	02:59	0.019	0.004	0.027	0.068	0.018	0.03	174	S
13 December, 2023	03:00	~	03:59	0.060	0.025	0.028	0.077	0.020	0.00	170	S
13 December, 2023	04:00	~	04:59	0.089	0.022	0.031	0.091	0.017	0.00	170	S
13 December, 2023	05:00	~	05:59	0.125	0.017	0.037	0.107	0.019	0.00	170	S
13 December, 2023	06:00	~	06:59	0.108	0.135	0.046	0.117	0.044	0.00	170	S
13 December, 2023	07:00	~	07:59	0.324	0.219	0.035	0.089	0.014	0.02	158	SSE
13 December, 2023	08:00	~	08:59	0.249	0.238	0.027	0.045	0.000	0.07	67	ENE
13 December, 2023	09:00	~	09:59	0.017	0.018	0.009	0.013	0.000	0.32	258	N
13 December, 2023	10:00	~	10:59	0.130	0.015	0.007	0.011	0.000	0.30	15	NNE

Max	0.863	0.238	0.046	0.117	0.053
Avg	0.233	0.066	0.026	0.056	0.023
Min	0.017	0.004	0.006	0.010	0.000



Date	Time	CO	NO ₂	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
		mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
		Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
13 December, 2023	11:00 ~ 11:59	0.328	0.022	0.007	0.011	0.015	0.47	289	WNW
13 December, 2023	12:00 ~ 12:59	0.165	0.013	0.008	0.031	0.040	0.53	341	NNW
13 December, 2023	13:00 ~ 13:59	0.318	0.020	0.028	0.050	0.059	0.35	65	ENE
13 December, 2023	14:00 ~ 14:59	0.351	0.019	0.023	0.029	0.048	0.40	307	NW
13 December, 2023	15:00 ~ 15:59	0.357	0.015	0.024	0.056	0.074	0.56	277	W
13 December, 2023	16:00 ~ 16:59	0.175	0.043	0.027	0.074	0.082	0.63	229	SW
13 December, 2023	17:00 ~ 17:59	0.075	0.034	0.025	0.050	0.043	0.27	32	NNE
13 December, 2023	18:00 ~ 18:59	0.170	0.121	0.032	0.068	0.043	0.05	25	NNE
13 December, 2023	19:00 ~ 19:59	0.403	0.138	0.035	0.078	0.012	0.05	31	NNE
13 December, 2023	20:00 ~ 20:59	0.348	0.097	0.029	0.060	0.004	0.03	35	NE
13 December, 2023	21:00 ~ 21:59	0.003	0.052	0.030	0.059	0.014	0.02	135	SE
13 December, 2023	22:00 ~ 22:59	0.216	0.139	0.039	0.082	0.016	0.00	324	NW
13 December, 2023	23:00 ~ 23:59	0.079	0.124	0.040	0.089	0.016	0.00	307	NW
14 December, 2023	00:00 ~ 00:59	0.048	0.011	0.026	0.056	0.016	0.02	307	NW
14 December, 2023	01:00 ~ 01:59	0.078	0.005	0.025	0.052	0.016	0.02	307	NW
14 December, 2023	02:00 ~ 02:59	0.071	0.015	0.032	0.064	0.017	0.00	324	NW
14 December, 2023	03:00 ~ 03:59	0.097	0.068	0.028	0.083	0.017	0.02	315	NW
14 December, 2023	04:00 ~ 04:59	0.076	0.084	0.033	0.096	0.018	0.12	307	NW
14 December, 2023	05:00 ~ 05:59	0.087	0.099	0.027	0.118	0.018	0.00	307	NW
14 December, 2023	06:00 ~ 06:59	0.151	0.138	0.034	0.110	0.016	0.00	307	NW
14 December, 2023	07:00 ~ 07:59	0.293	0.337	0.027	0.124	0.040	0.03	312	NW
14 December, 2023	08:00 ~ 08:59	0.299	0.243	0.029	0.076	0.000	0.10	319	NW
14 December, 2023	09:00 ~ 09:59	0.005	0.105	0.026	0.042	0.000	0.28	352	N
14 December, 2023	10:00 ~ 10:59	0.090	0.020	0.008	0.012	0.000	0.32	358	N

Max	0.403	0.337	0.040	0.124	0.082
Avg	0.179	0.082	0.027	0.065	0.027
Min	0.003	0.005	0.007	0.011	0.000



Date	Time			CO	NO ₂	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
				mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
				Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
14 December, 2023	11:00	-	11:59	2.297	0.023	0.008	0.013	0.004	0.50	6	N
14 December, 2023	12:00	-	12:59	0.272	0.023	0.007	0.011	0.024	0.53	70	ENE
14 December, 2023	13:00	-	13:59	0.297	0.027	0.012	0.025	0.028	0.60	174	S
14 December, 2023	14:00	-	14:59	0.241	0.026	0.012	0.032	0.037	0.78	114	ESE
14 December, 2023	15:00	-	15:59	0.064	0.030	0.036	0.057	0.030	0.73	168	SSE
14 December, 2023	16:00	-	16:59	0.063	0.014	0.026	0.094	0.030	0.42	161	SSE
14 December, 2023	17:00	-	17:59	0.069	0.053	0.030	0.064	0.026	0.17	117	ESE
14 December, 2023	18:00	-	18:59	0.232	0.068	0.023	0.055	0.020	0.14	138	SE
14 December, 2023	19:00	-	19:59	0.218	0.154	0.019	0.036	0.010	0.07	16	NNE
14 December, 2023	20:00	-	20:59	0.194	0.085	0.026	0.036	0.015	0.00	0	N
14 December, 2023	21:00	-	21:59	0.180	0.098	0.036	0.045	0.018	0.00	0	N
14 December, 2023	22:00	-	22:59	0.278	0.149	0.032	0.040	0.018	0.02	0	N
14 December, 2023	23:00	-	23:59	0.169	0.048	0.019	0.028	0.016	0.00	0	N
15 December, 2023	00:00	-	00:59	0.171	0.052	0.023	0.036	0.016	0.00	0	N
15 December, 2023	01:00	-	01:59	0.164	0.059	0.031	0.046	0.017	0.05	344	NNW
15 December, 2023	02:00	-	02:59	0.255	0.055	0.034	0.055	0.017	0.00	332	NNW
15 December, 2023	03:00	-	03:59	0.103	0.013	0.039	0.058	0.016	0.00	332	NNW
15 December, 2023	04:00	-	04:59	0.085	0.061	0.035	0.051	0.016	0.10	332	NNW
15 December, 2023	05:00	-	05:59	0.045	0.216	0.026	0.042	0.016	0.08	332	NNW
15 December, 2023	06:00	-	06:59	0.102	0.207	0.037	0.053	0.019	0.00	331	NNW
15 December, 2023	07:00	-	07:59	0.033	0.596	0.035	0.052	0.018	0.05	314	NW
15 December, 2023	08:00	-	08:59	0.090	0.100	0.015	0.036	0.014	0.20	28	NNE
15 December, 2023	09:00	-	09:59	0.032	0.022	0.009	0.013	0.015	0.28	7	N
15 December, 2023	10:00	-	10:59	0.030	0.029	0.008	0.012	0.015	0.43	335	NNW

Max	2.297	0.596	0.039	0.094	0.037
Avg	0.237	0.092	0.024	0.041	0.019
Min	0.030	0.013	0.007	0.011	0.004



Date	Time	CO	NO ₂	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
		mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
		Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
15 December, 2023	11:00 – 11:59	0.115	0.025	0.007	0.012	0.011	0.42	349	N
15 December, 2023	12:00 – 12:59	0.263	0.018	0.008	0.012	0.021	0.45	3	N
15 December, 2023	13:00 – 13:59	0.431	0.026	0.010	0.018	0.026	0.42	3	N
15 December, 2023	14:00 – 14:59	0.404	0.034	0.009	0.025	0.032	0.42	354	N
15 December, 2023	15:00 – 15:59	0.267	0.036	0.022	0.033	0.039	0.33	33	NNE
15 December, 2023	16:00 – 16:59	0.409	0.032	0.035	0.066	0.034	0.20	245	NNW
15 December, 2023	17:00 – 17:59	0.238	0.057	0.042	0.067	0.025	0.07	293	WNW
15 December, 2023	18:00 – 18:59	0.196	0.120	0.035	0.061	0.032	0.00	1	N
15 December, 2023	19:00 – 19:59	0.323	0.124	0.025	0.056	0.016	0.00	15	NNE
15 December, 2023	20:00 – 20:59	0.279	0.104	0.042	0.077	0.025	0.05	15	NNE
15 December, 2023	21:00 – 21:59	0.160	0.093	0.028	0.060	0.007	0.00	15	NNE
15 December, 2023	22:00 – 22:59	0.186	0.099	0.028	0.041	0.013	0.00	15	NNE
15 December, 2023	23:00 – 23:59	0.163	0.117	0.032	0.048	0.012	0.00	15	NNE
16 December, 2023	00:00 – 00:59	0.186	0.119	0.044	0.058	0.019	0.00	15	NNE
16 December, 2023	01:00 – 01:59	0.193	0.115	0.041	0.058	0.016	0.00	15	NNE
16 December, 2023	02:00 – 02:59	0.091	0.112	0.036	0.037	0.007	0.00	15	NNE
16 December, 2023	03:00 – 03:59	0.046	0.119	0.029	0.066	0.017	0.00	15	NNE
16 December, 2023	04:00 – 04:59	0.072	0.095	0.047	0.080	0.013	0.00	15	NNE
16 December, 2023	05:00 – 05:59	0.060	0.097	0.052	0.085	0.010	0.08	15	NNE
16 December, 2023	06:00 – 06:59	0.134	0.104	0.046	0.060	0.009	0.02	15	NNE
16 December, 2023	07:00 – 07:59	0.262	0.105	0.028	0.044	0.010	0.02	15	NNE
16 December, 2023	08:00 – 08:59	0.160	0.051	0.014	0.027	0.012	0.12	41	NE
16 December, 2023	09:00 – 09:59	0.036	0.028	0.009	0.011	0.012	0.28	73	ENE
16 December, 2023	10:00 – 10:59	0.067	0.034	0.007	0.010	0.013	0.50	66	ENE

Max	0.431	0.124	0.052	0.083	0.039
Avg	0.198	0.078	0.029	0.047	0.018
Min	0.036	0.018	0.007	0.010	0.007

Date	Time	CO		NO _x		PM _{2.5}		PM ₁₀		SO _x		Wind Speed	Wind Direction	
		mg/m ³		mg/m ³		mg/m ³		mg/m ³		mg/m ³		m/s	Deg.	Direction
		Hourly		Hourly		Hourly		Hourly		Hourly		Hourly	Hourly	Hourly
16 December, 2023	11:00 – 11:59	0.055		0.026		0.007		0.010		0.013		0.50	52	NE
16 December, 2023	12:00 – 12:59	0.090		0.017		0.007		0.013		0.020		0.55	43	NE
16 December, 2023	13:00 – 13:59	0.148		0.031		0.007		0.017		0.031		0.62	51	NE
16 December, 2023	14:00 – 14:59	0.190		0.038		0.007		0.015		0.029		0.48	7	N
16 December, 2023	15:00 – 15:59	0.119		0.032		0.009		0.026		0.023		0.42	354	N
16 December, 2023	16:00 – 16:59	0.094		0.016		0.023		0.034		0.031		0.20	321	NW
16 December, 2023	17:00 – 17:59	0.158		0.085		0.056		0.074		0.037		0.00	113	ESE
16 December, 2023	18:00 – 18:59	0.181		0.169		0.074		0.109		0.046		0.05	265	W
16 December, 2023	19:00 – 19:59	0.211		0.174		0.054		0.098		0.023		0.18	293	WNW
16 December, 2023	20:00 – 20:59	0.217		0.175		0.062		0.105		0.019		0.10	354	N
16 December, 2023	21:00 – 21:59	0.387		0.182		0.039		0.049		0.003		0.07	353	N
16 December, 2023	22:00 – 22:59	0.179		0.189		0.029		0.032		0.009		0.17	353	N
16 December, 2023	23:00 – 23:59	0.223		0.183		0.033		0.035		0.009		0.05	353	N
17 December, 2023	00:00 – 00:59	0.132		0.177		0.043		0.046		0.012		0.02	353	N
17 December, 2023	01:00 – 01:59	0.129		0.174		0.021		0.026		0.017		0.00	21	NNE
17 December, 2023	02:00 – 02:59	0.039		0.156		0.008		0.013		0.015		0.05	20	NNE
17 December, 2023	03:00 – 03:59	0.115		0.041		0.008		0.013		0.018		0.28	354	N
17 December, 2023	04:00 – 04:59	0.089		0.051		0.008		0.014		0.014		0.22	34	NNE
17 December, 2023	05:00 – 05:59	0.108		0.079		0.008		0.012		0.017		0.32	25	NNE
17 December, 2023	06:00 – 06:59	0.106		0.095		0.009		0.015		0.014		0.33	10	N
17 December, 2023	07:00 – 07:59	0.127		0.157		0.009		0.019		0.017		0.23	334	NW
17 December, 2023	08:00 – 08:59	0.102		0.028		0.007		0.013		0.017		0.46	332	NNW
17 December, 2023	09:00 – 09:59	0.073		0.032		0.007		0.010		0.011		0.33	14	NNE
17 December, 2023	10:00 – 10:59	0.063		0.026		0.007		0.011		0.008		0.40	359	N

Max	0.387	0.189	0.074	0.109	0.046
Avg	0.139	0.096	0.023	0.034	0.019
Min	0.039	0.016	0.007	0.010	0.003



Date	Time	CO	NO _x	PM _{2.5}	PM ₁₀	SO ₂	Wind Speed	Wind Direction	
		mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³	m/s	Deg.	Direction
		Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly	Hourly
17 December, 2023	11:00 ~ 11:59	0.122	0.025	0.012	0.023	0.012	0.55	17	NNE
17 December, 2023	12:00 ~ 12:59	0.349	0.033	0.007	0.012	0.017	0.65	39	NE
17 December, 2023	13:00 ~ 13:59	0.564	0.042	0.007	0.013	0.035	0.48	54	NE
17 December, 2023	14:00 ~ 14:59	0.554	0.030	0.007	0.020	0.033	0.47	37	NE
17 December, 2023	15:00 ~ 15:59	0.661	0.018	0.018	0.025	0.040	0.42	355	N
17 December, 2023	16:00 ~ 16:59	0.449	0.035	0.030	0.046	0.041	0.20	333	NNW
17 December, 2023	17:00 ~ 17:59	0.336	0.063	0.047	0.062	0.042	0.10	177	S
17 December, 2023	18:00 ~ 18:59	0.359	0.173	0.057	0.086	0.031	0.03	162	SSE
17 December, 2023	19:00 ~ 19:59	0.489	0.193	0.047	0.087	0.023	0.05	142	SE
17 December, 2023	20:00 ~ 20:59	0.078	0.240	0.041	0.068	0.005	0.00	141	SE
17 December, 2023	21:00 ~ 21:59	0.360	0.227	0.042	0.051	0.011	0.00	150	SSE
17 December, 2023	22:00 ~ 22:59	0.368	0.249	0.056	0.038	0.011	0.02	247	WSW
17 December, 2023	23:00 ~ 23:59	0.257	0.209	0.036	0.043	0.020	0.15	272	W
18 December, 2023	00:00 ~ 00:59	0.240	0.189	0.010	0.021	0.014	0.08	298	WNW
18 December, 2023	01:00 ~ 01:59	0.029	0.042	0.008	0.012	0.017	0.17	287	WNW
18 December, 2023	02:00 ~ 02:59	0.041	0.053	0.009	0.014	0.010	0.28	0	N
18 December, 2023	03:00 ~ 03:59	0.086	0.084	0.010	0.018	0.018	0.37	345	NNW
18 December, 2023	04:00 ~ 04:59	0.098	0.075	0.008	0.011	0.015	0.23	345	NNW
18 December, 2023	05:00 ~ 05:59	0.099	0.066	0.009	0.012	0.011	0.17	340	NNW
18 December, 2023	06:00 ~ 06:59	0.107	0.081	0.008	0.015	0.014	0.15	344	NNW
18 December, 2023	07:00 ~ 07:59	0.124	0.094	0.009	0.013	0.014	0.25	330	NNW
18 December, 2023	08:00 ~ 08:59	0.153	0.017	0.007	0.012	0.015	0.28	357	N
18 December, 2023	09:00 ~ 09:59	0.051	0.014	0.007	0.012	0.014	0.40	33	NNE
18 December, 2023	10:00 ~ 10:59	0.057	0.019	0.007	0.010	0.018	0.52	70	ENE

Max	0.661	0.249	0.057	0.087	0.042
Avg	0.251	0.093	0.021	0.031	0.020
Min	0.029	0.014	0.007	0.010	0.005



APPENDIX-2 CERTIFICATE OF CALIBRATION





SYSTEM HEALTH CHECK REPORT

Information

Instrument	Fluorocrom
Model	EPAN
Serial number	001100
Unit Sensor	CO ₂ /H ₂ O/NO ₂ /SO ₂ /PM ₁₀ PM _{2.5} & RH/WS/WEB/LOG
Company	Myanmar Koe International LTD
Date	Sep-23

Check List

Physical Check	OK
Supply Voltage Check	OK
PM ₁₀ /PM _{2.5} Air Flow Check	OK
SO ₂ & RH/WS/WS sensor Check	OK
NO Sensor Health Check	Malfunction
CO ₂ /H ₂ O/NO ₂ Sensor Health Check	Still Good
External Battery Voltage Check	OK
Data Logging Check	OK
Data Downloading Check	OK

Recommend

- Need to replace new acid gas analyzer (schedule is 6 months)
- Need to replace internal filter (schedule is 6 months)
- Need to perform factory calibration or field calibration (schedule is 12 months)

Performed by
Phuc Saw Phoo
Technical Service Engineer
NANOVA CO., LTD

Approved by
Min Ooi
Technical Service Manager
NANOVA CO., LTD

Singapore: 22-A, Sheng Seng Street, Serangoon Tower B, Tel: +65 (7) 232-9957, 232-9952
 Bangkok: 24 / 20, Zoukhaeng Seng Seng, 104 Phayathai Road, Pyramont, Tel: 06-2 470-8002
 Thailand: 33 Samsat, Samsat 33/34, Charnok Thaksin Tower B, Tel: 09 432-6666
 Email: info@nanova.co.th, service@nanova.co.th
 Myanmar: 09 401 380000, 09 401 380000



**Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)**

Appendix-E

**Noise and Vibration Monitoring Report
December 2023**

**NOISE AND VIBRATION
MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

**December 2023
Myanmar Koei International Ltd.**



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN	1
1.1 General	1
1.2 Outlines of Monitoring Plan	1
CHAPTER 2: NOISE AND VIBRATION LEVEL MONITORING	2
2.1 Monitoring Item	2
2.2 Monitoring Location	2
2.3 Monitoring Method	3
2.4 Monitoring Results	4
CHAPTER 3: CONCLUSION AND RECOMMENDATION	10

LIST OF TABLES

Table 1.2-1 Outlines of Noise and Vibration Level Monitoring	1
Table 2.1-1 Monitoring Parameters for Noise and Vibration Level	2
Table 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1	4
Table 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2	4
Table 2.4-3 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-1	5
Table 2.4-4 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-2	5
Table 2.4-5 Results of Vibration Levels (L_{v10}) Monitoring at NV-1	7
Table 2.4-6 Results of Vibration Levels (L_{v10}) Monitoring at NV-2	7
Table 2.4-7 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-1	8
Table 2.4-8 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-2	8

LIST OF FIGURES

Figure 2.2-1 Location of Noise and Vibration Level Monitoring Points	2
Figure 2.3-1 Status of Noise and Vibration Level Monitoring at NV-1 and NV-2	3
Figure 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1	6
Figure 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2	6
Figure 2.4-3 Results of Vibration Levels (L_{v10}) Monitoring at NV-1	9
Figure 2.4-4 Results of Vibration Levels (L_{v10}) Monitoring at NV-2	9



CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd., (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented monitoring various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, noise and vibration levels had been monitored from 11 December 2023 to 12 December 2023 as follows;

Table 1.2-1 Outlines of Noise and Vibration Level Monitoring

Monitoring Date	Monitoring Item	Parameters	Number of Points	Duration	Monitoring Methodology
12 December 2023	Noise Level	L_{Aeq} (dB)	1 (NV-1)	8 hours	On-site measurement by "Rion NL-42 sound level meter"
11 December 2023	Noise Level	L_{Aeq} (dB)	1 (NV-2)	8 hours	On-site measurement by "Rion NL-42 sound level meter"
12 December 2023	Vibration Level	L_{v10} (dB)	1 (NV-1)	8 hours	On-site measurement by "Vibration Level Meter- VM-53A"
11 December 2023	Vibration Level	L_{v10} (dB)	1 (NV-2)	8 hours	On-site measurement by "Vibration Level Meter- VM-53A"

Source: Myanmar Koen International Ltd.



CHAPTER 2: NOISE AND VIBRATION LEVEL MONITORING

2.1 Monitoring Item

The noise and vibration level monitoring items are shown in Table 2.1-1.

Table 2.1-1 Monitoring Parameters for Noise and Vibration Level

No.	Item	Parameter
1	Noise	A-weighted loudness equivalent (LAeq)
2	Vibration	Vibration level, vertical, percentile (L _{vn})

Source: Myanmar Koei International Ltd.

2.2 Monitoring Location

Noise and vibration levels were measured in the northeast corner of the Thilawa SEZ Zone B, namely NV-1 (N: 16°40'18.22", E: 96°17'18.18") for traffic noise concerned and inside the monastery compound of Phalan village, adjacent to the southern boundary of the Thilawa SEZ Zone B, as NV-2 (N: 16°39'24.90", E: 96°17'16.70") for sensitive area noise level. The location of the noise and vibration monitoring points are shown in Figure 2.2-1.



Figure 2.2-1 Location of Noise and Vibration Level Monitoring Points

NV-1

NV-1 is located in front of temporary gate of operation site of Thilawa SEZ Zone B and next to Thilawa Development Road. The surrounding area are Zone A in the northwest, local industrial zone in the east respectively. Possible sources of noise and vibration is generated from construction activities and road traffic.

NV-2

NV-2 is located inside the monastery compound of Phalan village, adjacent to the southern boundary of the Thilawa SEZ Zone B and surrounded by the residential houses of Phalan village in the south and the fields in west. Thilawa SEZ Zone A is distanced about 2 km north of NV-2 and local industrial zone about 1 km northeast respectively. Possible sources of noise and vibration is generated from construction activities from Zone B and daily human activities from nearby Phalan village.

2.3 Monitoring Method

Noise level was measured by "Rion NL-42 sound level meter" and automatically records every 10 minutes in a memory card. The vibration level meter, VM-53A (Rion Co., Ltd., Japan), was accompanied by a 3-axis accelerometer PV-83C (Rion Co., Ltd.) and it was placed on solid soil ground. Vertical vibration (Z axis), L_v, was measured every 10 minutes within the adaptable range of (10-70) dB at NV-1 and NV-2 and recorded to a memory card.

The measurement period of noise and vibration was 8 hours for each monitoring point. The status of the noise and vibration level monitoring on NV-1 and NV-2 are shown in Figure 2.3-1.



Source: Myanmar Kooi International Ltd

Figure 2.3-1 Status of Noise and Vibration Level Monitoring at NV-1 and NV-2

2.4 Monitoring Results

Noise Monitoring Results

Noise monitoring results are separated as daytime (6:00 AM to 10:00 PM) and evening time (10:00 PM to 6:00 AM) time frames for NV-1 and daytime (7:00 AM to 7:00 PM), evening time (7:00 PM to 10:00 PM) and night time (10:00 PM to 7:00 AM) time frames for NV-2 respectively. Noise measurement was carried out for 8-hour as working time (8:00 AM to 4:00 PM) at the designated locations instead of 24-hours due to the safety reason and risk avoidance. The monitoring results are summarized in Table 2.4-1 and Table 2.4-2. Hourly noise level (L_{Aeq}) monitoring results at NV-1 and NV-2 are shown in Table 2.4-3 and Table 2.4-4. Figure 2.4-1 and Figure 2.4-2 show the results of noise level (L_{Aeq}) at NV-1 and NV-2. Comparing with the target value of noise level in operation stage prescribed in EIA report for Thilawa SEZ development project Zone B, all results were under the target values.

Table 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1

Date	(Traffic Noise Level) Equivalent Noise Level (L_{Aeq} , dB)	
	Day Time (6:00 AM – 10:00 PM)	Night Time (10:00 PM – 6:00 AM)
12 December, 2023	60	-
Target Value	75	70

Note: Target value is applied to the noise standard along main road stipulated in the Noise Regulation Law (Japan) (Law No. 98 of 1968, Latest Amendment by Law No.91 of 2000).

Source: Myanmar Koei International Ltd.

Table 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2

Date	(A side next to sensitive area such as monastery, hospital and school) Equivalent Noise Level (L_{Aeq} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
11 December, 2023	50	-	-
Target Value	60	55	50

Note: Target value is applied to the noise level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Koei International Ltd.

Table 2.4-3 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-1

Table 2.7.2. Hourly Noise Level (L_{Aeq}) Monitoring Records at PPA					
Date	Time	Result L_{Aeq} (dB)	Each Category L_{Aeq} (dB)	Target Value L_{Aeq} (dB)	Remark
12 December, 2023	6:00-7:00	-	60	75	No construction Activities
	7:00-8:00	-			
	8:00-9:00	62			
	9:00-10:00	60			
	10:00-11:00	61			
	11:00-12:00	62			
	12:00-13:00	59			
	13:00-14:00	60			
	14:00-15:00	60			
	15:00-16:00	60			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-			
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-	-	70	
	23:00-24:00	-			
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			

Source: Myanmar Koei International Ltd.

Table 2.4-4 Hourly Noise Level (L_{Aeq}) Monitoring Results at NV-2

Date	Time	(L_{Aeq} , dB)	(L_{Aeq} , dB) Each Category	(L_{Aeq} , dB) Target Value	Remark
11 December, 2023	7:00-8:00	-	50	60	No construction Activities
	8:00-9:00	46			
	9:00-10:00	46			
	10:00-11:00	43			
	11:00-12:00	39			
	12:00-13:00	45			
	13:00-14:00	40			
	14:00-15:00	55			
	15:00-16:00	55			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	-	55	
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-	-	50	
	23:00-24:00	-			
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koei International Ltd.




Figure 2.4-1 Results of Noise Levels (L_{Aeq}) Monitoring at NV-1




Figure 2.4-2 Results of Noise Levels (L_{Aeq}) Monitoring at NV-2

Vibration Monitoring Results

Vibration monitoring results are separated as daytime (7:00 AM to 7:00 PM), evening time (7:00 PM to 10:00 PM) and night time (10:00 PM to 7:00 AM) time frames respectively for both NV-1 and NV-2. Vibration measurement was carried out for 8-hour as working time (8:00 AM to 4:00 PM) at the designated locations instead of 24-hours due to the safety reason and risk avoidance. The results of vibration level (L_{v10}) monitoring at NV-1 and NV-2 are shown in Table 2.4-5 and Table 2.4-6. Hourly vibration level (L_{v10}) monitoring results at NV-1 and NV-2 are shown in Table 2.4-7 and Table 2.4-8. Figure 2.4-3 and Figure 2.4-4 showed the graph of vibration level monitoring results at NV-1 and NV-2. By comparing with the target vibration level in operation stage in EIA report for Thilawa SEZ development project Zone B, all of results were under the target values.

Table 2.4-5 Results of Vibration Levels (L_{v10}) Monitoring at NV-1

Date	(Office, commercial facilities and factories) Equivalent Vibration Level (L_{v10} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
11 December, 2023	38	-	-
Target Value	70	65	65

Note: Target value is applied to the vibration level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Kwei International Ltd.

Table 2.4-6 Results of Vibration Levels (L_{v10}) Monitoring at NV-2

Date	(Residential houses and monastery) Equivalent Vibration Level (L_{v10} , dB)		
	Day Time (7:00 AM – 7:00 PM)	Evening Time (7:00 PM – 10:00 PM)	Night Time (10:00 PM – 7:00 AM)
11 December, 2023	22	-	-
Target Value	65	60	60

Note: Target value is applied to the vibration level during the operation stage in the EIA Report for Thilawa SEZ Development Project (Industrial Area of Zone B).

Source: Myanmar Kwei International Ltd.



Table 2.4-7 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-1

Date	Time	Result L ₁₀ (dB)	Each Category L ₁₀ (dB)	Target Value L ₁₀ (dB)	Remark
12 December, 2023	7:00-8:00	-	38	70	No construction Activities
	8:00-9:00	39			
	9:00-10:00	38			
	10:00-11:00	39			
	11:00-12:00	37			
	12:00-13:00	36			
	13:00-14:00	37			
	14:00-15:00	39			
	15:00-16:00	39			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	-	65	
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-	-	65	
	23:00-24:00	-			
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koei International Ltd.

Table 2.4-8 Results of Hourly Vibration Levels (L_{v10}) Monitoring at NV-2

Date	Time	Result L _{eq} (dB)	Each Category L _{eq} (dB)	Target Value L _{eq} (dB)	Remark
11 December, 2023	7:00-8:00	-	22	65	No construction Activities
	8:00-9:00	22			
	9:00-10:00	24			
	10:00-11:00	24			
	11:00-12:00	22			
	12:00-13:00	19			
	13:00-14:00	21			
	14:00-15:00	23			
	15:00-16:00	23			
	16:00-17:00	-			
	17:00-18:00	-			
	18:00-19:00	-			
	19:00-20:00	-	-	60	
	20:00-21:00	-			
	21:00-22:00	-			
	22:00-23:00	-	-	60	
	23:00-24:00	-			
	24:00-1:00	-			
	1:00-2:00	-			
	2:00-3:00	-			
	3:00-4:00	-			
	4:00-5:00	-			
	5:00-6:00	-			
	6:00-7:00	-			

Source: Myanmar Koei International Ltd.




Figure 2.4-3 Results of Vibration Levels (L_{A10}) Monitoring at NV-1




Figure 2.4-4 Results of Vibration Levels (L_{A10}) Monitoring at NV-2

CHAPTER 3: CONCLUSION AND RECOMMENDATION

By Comparing with the target value of noise and vibration level in operation stage prescribed in EIA report for Thilawa SEZ development project Zone B, all results were under the target values at NV-1 and NV-2. Thus, there is no negative impact on noise and vibration from operation activities of Zone B to the surrounding environment.

In conclusion of this environmental monitoring, there are no specific noise and vibration impacts to the surrounding area of industrial area of Thilawa SEZ Zone B during the monitoring period.

**Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)**

Appendix-F

Traffic Volume Monitoring Report

December 2023

**TRAFFIC VOLUME MONITORING REPORT
FOR DEVELOPMENT OF INDUSTRIAL AREA
THILAWA SEZ ZONE B
(PHASE 1, 2 & 3 OPERATION STAGE)**

(BI-ANNUALLY MONITORING)

December 2023

Myanmar Koei International Ltd.



TABLE OF CONTENTS

CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN	1
1.1 General.....	1
1.2 Outlines of Monitoring Plan	1
CHAPTER 2: TRAFFIC VOLUME MONITORING	2
2.1 Monitoring Item	2
2.2 Monitoring Location	3
2.3 Monitoring Method.....	4
2.4 Monitoring Results.....	4
CHAPTER 3: CONCLUSION AND RECOMMENDATION.....	6

LIST OF TABLES

Table 1.2-1 Outlines of Traffic Volume Monitoring	1
Table 2.1-1 Monitoring Parameters for Traffic Volume.....	2
Table 2.1-2 Classification of Vehicles Types	2
Table 2.4-1 Summary of Traffic Volume Recorded at TV-1.....	4
Table 2.4-2 Hourly Traffic Volume Results at TV-1 (From Phalan Village to Dagon-Thilawa Road)	5
Table 2.4-3 Hourly Traffic Volume Results at TV-1 (From Dagon-Thilawa Road to Phalan Village)	5

LIST OF FIGURES

Figure 2.2-1 Location of Traffic Volume Monitoring Point.....	3
Figure 2.3-1 Status of Traffic Volume Monitoring at TV-1	4



CHAPTER 1: OUTLINES AND SUMMARY OF MONITORING PLAN

1.1 General

Thilawa Special Economic Zone (TSEZ) is located in southern district of Yangon region and about 23 km southeast of Yangon city. As the developer of Thilawa SEZ, Myanmar Japan Thilawa Development Ltd., (MJTD) has a responsibility to carry out regular environmental monitoring in the industrial area of Zone B in accordance with the approved Environmental Impact Assessment (EIA) report with Environmental Management Plan (EMP). MJTD has implemented the monitoring for various environmental items with the specified time frame to know the environmental conditions in and around the area.

1.2 Outlines of Monitoring Plan

To assess the environmental condition under the operation of industrial area in and around Thilawa SEZ Zone B, Traffic volume monitoring was carried out for 8-hours as working time (8:00 to 16:00) at one designated location instead of 24 hours due to the safety reason and risk avoidance. Traffic volume had been monitored on 12 December 2023 as follows;

Table 1.2-1 Outlines of Traffic Volume Monitoring

Monitoring Date	Monitoring Item	Parameter	Number of Point	Duration	Monitoring Methodology
12 December 2023	Traffic Volume	-	1 (TV-1)	8 hours	Manual Count

Source: Myanmar Kazi International Ltd.



CHAPTER 2: TRAFFIC VOLUME MONITORING

2.1 Monitoring Item

The traffic volume monitoring item are shown in Table 2.1-1. All vehicles were classified into four types as detailed in Table 2.1-2.

Table 2.1-1 Monitoring Parameters for Traffic Volume

No.	Item	Parameter
1.	Traffic volume	Number of Vehicle (4 Types)

Source: Myanmar Koei International Ltd.

Table 2.1-2 Classification of Vehicles Types

No.	Classification		Description
1	Two-wheeled vehicle and motorcycle sidecar		Motorbike, Motorcycle sidecar (Taxi)
2	Four-wheeled light vehicle		Pick-up car, Jeep, Taxi, Saloon car, Light truck (under 2 tons)
3	Heavy vehicle		Medium bus, Express, Big bus, medium truck, Heavy truck such as 2 axles, 3 axles and more than 4 axles and Trailer (over 4.5 tons)
4	Others		Tractor

Note: In vehicle classification, two-wheeled vehicle and motorcycle sidecar are included in Number 1. A motorcycle sidecar is a modified motorcycle for local purpose use.

Source: Myanmar Koei International Ltd.

2.2 Monitoring Location

Traffic volume was recorded at the northeast corner of the Thilawa SEZ Zone B, monitoring point (TV-1); N: 16°40'17.90", E: 96°17'18.20". The location of the traffic volume survey monitoring is shown in Figure 2.2-1.



Source: Myanmar Kori International Ltd.


Figure 2.2-1 Location of Traffic Volume Monitoring Point

TV-1

TV-1 is located in front of main gate of operation site of Thilawa SEZ Zone B and next to Thilawa Development Road. The surrounding area are Zone A in the northwest and local industrial zone in the east respectively.

2.3 Monitoring Method

The traffic volume monitoring was conducted for 8 hours at the same time as the traffic noise and vibration level monitoring. Traffic volume monitoring was conducted to count the number of vehicles moving from Phalan village to Dagon-Thilawa Road and from Dagon-Thilawa Road to Phalan village in each direction. Manual count method was used and data was recorded using tally sheets. The status of the traffic volume monitoring at TV-1 is shown in Figure 2.3-1.



Source: Myanmar Ksei International Ltd.

Figure 2.3-1 Status of Traffic Volume Monitoring at TV-1

2.4 Monitoring Results

The traffic volume monitoring results are summarized in Table 2.4-1. Hourly quantity of each type of vehicle were recorded. Table 2.4-1 shows that the number of 4-wheel light vehicles are distinctly and highly utilized in weekdays. The number of heavy vehicle moving from Phalan village to Dagon-Thilawa Road is three and half times lower than that of 4-wheel light vehicles and heavy vehicle moving from Dagon-Thilawa Road to Phalan village is also four times lower than that of 4-wheel light vehicles.

Table 2.4-1 Summary of Traffic Volume Recorded at TV-1

Survey Point	Direction	Date	Weekday	2-wheel Vehicles and motorcycle sidecar	4-wheel Light Vehicles	Heavy Vehicles	Others	Total
TV-1	Phalan village to Dagon-Thilawa road	12 December 2023	Tuesday	269	545	158	18	990
	Dagon-Thilawa road to Phalan village			251	652	171	15	1,089

Source: Myanmar Ksei International Ltd.

The summary monitoring results of hourly traffic volume at TV-1 is shown in Table 2.4-2 and Table 2.4-3 respectively. Comparing the result of each direction in the morning as 8:00 to 9:00, traffic volume from Dagon-Thilawa Road to Phalan village is higher than that of opposite direction. Similarly, in the afternoon as 15:00 to 16:00, traffic volume from Dagon-Thilawa Road to Phalan village is also higher than that of opposite direction. It may be possible commuting vehicles are moving from Dagon-Thilawa Road to Phalan village in the morning and afternoon during the monitoring period.

Table 2.4-2 Hourly Traffic Volume Results at TV-1 (From Phalan Village to Dagon-Thilawa Road)

From	To	Classification Type of vehicles				Total
		Two-wheeled vehicle and motorcycle sidcar	Four-wheeled light vehicle	Heavy vehicle	Others	
8:00	9:00	56	63	23	3	147
9:00	10:00	32	50	11	0	93
10:00	11:00	32	63	20	4	130
11:00	12:00	32	75	19	0	126
12:00	13:00	29	82	14	3	128
13:00	14:00	26	82	20	3	131
14:00	15:00	32	64	18	3	117
15:00	16:00	30	62	24	2	118
Total		269	543	158	18	990

Source: Myanmar Koei International Ltd

Table 2.4-3 Hourly Traffic Volume Results at TV-1 (From Dagon-Thilawa Road to Phalan Village)

From	To	Classification Type of vehicles				Total
		Two-wheeled vehicle and motorcycle sidcar	Four-wheeled light vehicle	Heavy vehicle	Others	
8:00	9:00	53	119	24	4	200
9:00	10:00	28	55	17	2	102
10:00	11:00	26	85	22	1	134
11:00	12:00	39	78	16	2	135
12:00	13:00	25	93	16	1	135
13:00	14:00	19	83	17	4	123
14:00	15:00	30	71	35	1	137
15:00	16:00	31	68	24	0	123
Total		251	652	171	15	1,089

Source: Myanmar Koei International Ltd



CHAPTER 3: CONCLUSION AND RECOMMENDATION

The results of the traffic volume show that the number of 4-wheel light vehicles are distinctly and highly utilized in this monitoring period. The number of heavy vehicles is three and half times and four times significantly lower than that of 4-wheel light vehicles for each direction. It seems that commuting vehicles are more utilized during this monitoring period as compared with construction related vehicles (Heavy vehicles).

The continuous monitoring will be necessary to grasp the traffic volume data in operation stage of Thilawa SEZ Zone B. Once enough traffic volume data is collected, the mitigation measures for traffic volume management will be considered in future.

**Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)**

Appendix-G

**Waste Disposal Record
(September 2023 to February 2024)**

Solid Waste

Item	Date	Generated from	Unit	Value	Disposed to
General Waste with Green Waste	28 September 2023	Landscaping and Plantation	Kg	2850	Waste disposing to Than Lynn Development Committee, Yangon Division
General Waste with Green Waste	1 November 2023		Kg	2900	
General Waste with Green Waste	8 December 2023		Kg	2800	
General Waste with Green Waste	3 January 2024		Kg	2950	
Total			Kg	11,500	
Item	Date	Generated from	Unit	Value	Disposed to
Sludge	21 October 2023	Sewage Treatment Plant	Kg	6800	Golden DOWA Eco- System Myanmar Co., Ltd
Sludge	20 November 2023		Kg	7140	
Sludge	21 December 2023		Kg	6920	
Sludge	20 February 2024		Kg	6160	
Total			Kg	27,020	

Remarks: Waste amount is not only in TSEZ-B but also combine with TSEZ-A General Waste. Generate wastes are dried waste and weight value are estimated base on type of Trash collector car. Green Waste (Grass cutting waste) are used in Bio-fertilizer.

Note: Zone-B wastewater treated at Sewage Treatment Plant of TSEZ-A. Above data are sludge generated from Sewage treatment plant of TSEZ-A.



ခွဲလွှဲပြောင်း/လက်ခံရခြင်း

စွဲကြောင်းအရာ :
..... Letter for Dumping Service Charges

ခွဲပေါင်း(ကတိန်) : Thonny

ခွဲပေါင်း(စာဖြင့်) : Severdy Thonnyed Kyat

၁.၇.၂၀၂၃


(လွှဲပြောင်းပေးသူ)


(လက်ခံသူ)

တမည် : န.မောင်.ကျော်.မိုး

ရာထူး : ၁.၁. အထောက်အကူ ပြုစုရေးရာ

နေရာ : ၂.၂.၂.၂.

ရက်စွဲ : ၀၁.၀၇.၂၀၂၃

တမည် :
ရာထူး : ၀. ဦးစီးမှု(သန့်)

နေရာ : (မြို့နယ်စည်ပင်သာယာရေးအဖွဲ့)

ရက်စွဲ : သန့်လှိုင်မြို့





စွန့်လွှဲခြောင်း/လက်ခံခြင်း

စွန့်လွှဲကြောင်းအရာ

မှ... မှိုက်ခွက်...အား... Dumping Service Charges

ငွေပေါင်း(ဝဘန်း)။ ၃၀၀၀၀/-

ရာ ငွေပေါင်း(သိန်း)။ Seventy Thousand Kyats

၂၀၁၉.၁၁.၂၃


(လွှဲပြောင်းရေးသူ)


(လက်ခံသူ)

အမည် Myint Khin Myint

အမည်

ရာထူး ဦး ရဲအောင်မိုး

ရာထူး ဦးစီးချုပ်(သန်)

နေရာ ITFZ

နေရာ မြောက်ဗဟိုပရိဘောဂရေးရာဌာန

မှတ်စွဲ ၈၃-၂၁၈-၉၀၂၃

မှတ်စွဲ သန်လျင်မြို့





ငွေလွှဲခြောင်း/လက်ခံခြင်း

စွဲကြောင်းကရာ :
Payung For Dumping Service Charges

၂။ ငွေပေါင်း(ဝဘန်း) : အဝဝပိ/.....

၃။ ငွေပေါင်း(စာဖြင့်) : Seventy Thousand Kyats.....

3.၇.ကဏ္ဍ


(စွဲကြောင်းကရာ)


(လက်ခံသူ)

စာမည် : Mr. A. H. P. P.
ရာထူး : ... Senior Officer ...
နေရာ : ... N. Z.
ရက်စွဲ : ... ၁၁.၀၁.၂၀၂၃ ...

စာမည် :
ရာထူး :
နေရာ :
ရက်စွဲ :
.....



Manifest		A-Slip		* Waste generator Copy
Date of issuance	(Day Month, Year) 9 Oct 2023	Issue	(Handwritten Sign) Hoo Ni Ton Aung 	
Number of issuance	0001 2310 0007			
Connections	Waste generator	Transportation company	Waste service company	
Company Name	GEM MTD	GEM	GEM	
Tel				
Waste	Kind	Name	Style of packing	
	☒ Non-hazardous	SIP Dehydrated Sludge		
	☐ Hazardous	Quantity(Unit)	Remark	
	☐ Other			
Customer code	000*	Waste Profile code	NHV-100E	
Trace	PIC(Handwritten Sign)		Date of Completion	
Transportation company	(Handwritten Sign) AG 100 Lin AG 3K.8896		(Day Month, Year)	
Waste service company	(Handwritten Sign)		(Day Month, Year)	
Designed by GOLDER DOWA ECO-SYSTEM MYANMAR CO., LTD.			GRM-SL-2 0102 00	

12003



Manifest				A- Slip		* Waste generator Code	
Date of issuance		(Date Month Year)		E 08 Nov 2023			
Number of issuance		0007 2311 0001		Issuer		(Personal Sign) Hon. Ni Tun Aung Shw	
Contractors		Waste generator		Transportation company		Waste service company	
Company Name		MJD		GEM		GEM	
Tel							
Waste	Kind	Name		Style of packing			
	☒ Non-Hazardous	Slip Dehydrated Sludge					
	☐ Hazardous	Quantity (Unit)					
	☐ Others					Remark	
Customer code		0007		Waste Profile code		NHN - 1006	
Trace		PIC (Name & Sign)		Date of Completion			
Transportation company		(Handwritten) Pg 100 Dn Pg 3K.8896		(Date Month Year)			
Waste service company		(Handwritten)		(Date Month Year)			
Designed by GOLDEN DOWA ECO - SYSTEM MYANMAR CO., LTD.							
(GEM-SL-R 0106/00)							



Manifest		C-104		Transportation to Burmese	
Date of issuance	12/12/2013	Issue	Permit No. 1006		
Number of manifest	0001		1006		
Contractors	Water provider	Transportation company		Water service company	
Contract Name	M-103	C-104		C-104	
SI					
Name	Kind	Name		Style of packing	
	Material	Sludge			
	Quantity	Quantity (kg)		Batch	
	Others	4,500 kg			
Customer code	0001	Water Provider code		MIN - 1006	
From	To (Name & Sign)		Date of Completion		
Transportation company	10/12/13		10/12/13		
Water service company	10/12/13		10/12/13		
Designed by GOLDEN DEWA ECO - SYSTEM MYANMAR CO., LTD. DEWA NO. 1 (1006)					



1/11/2024

Manifest				C-Slip		Transportation company or Waste transporter	
Date of issuance	9 Feb 2024			Invoice	160 N. H. T. A. 103 Shu		
Number of invoice	0001 8902 0001						
Company Name	Waste generator		Transportation company		Waste service company		
Tel	MJD		GEM		GEM		
Waste	Kind	Name			Style of packing		
	☒ Non-Hazardous	SIP Saturated Sludge					
	☐ Hazardous	Quantity (Unit)			Remark		
		6140 kg					
Customer code	0001			Waste Profile code	NHN-1006		
Transportation company	PIC (Date & Sign)			Date of Completion			
Waste service company	13 20 24 13			13 11.2.24			
Signature			Signature				
G. Phawin Huan							
Designed by GOLDEN DOWA ECO-SYSTEM MYANMAR CO., LTD							
GEM-SC-R-0102-00							



Solid Waste

Item	Date	Generated from	Unit	Value	Disposed to
General Waste with Green Waste	28 September 2023	Landscaping and Plantation	Kg	2850	Waste disposing to Than Lynn Development Committee, Yangon Division
General Waste with Green Waste	1 November 2023		Kg	2900	
General Waste with Green Waste	8 December 2023		Kg	2800	
General Waste with Green Waste	3 January 2024		Kg	2950	
Total			Kg	11,500	
Item	Date	Generated from	Unit	Value	Disposed to
Sludge	21 October 2023	Sewage Treatment Plant	Kg	6800	Golden DOWA Eco- System Myanmar Co., Ltd
Sludge	20 November 2023		Kg	7140	
Sludge	21 December 2023		Kg	6920	
Sludge	20 February 2024		Kg	6160	
Total			Kg	27,020	

Remarks: Waste amount is not only in TSEZ-B but also combine with TSEZ-A General Waste. Generate wastes are dried waste and weight value are estimated base on type of Trash collector car. Green Waste (Grass cutting waste) are used in Bio-fertilizer.

Note: Zone-B wastewater treated at Sewage Treatment Plant of TSEZ-A. Above data are sludge generated from Sewage treatment plant of TSEZ-A.

Thilawa Special Economic Zone
Zone B- Phase 1,2 & 3 (Operation phase)

Appendix-H

Sewage Treatment Plant Monitoring Record
September 2023 to February 2024

Monthly STP Water Analysis Results

Month	Date	Zone A (Inlet)-1			Zone A (Inlet)-2			Outlet -1							Outlet-2								
		SS	BOD	T-P	SS	BOD	T-P	SS	BOD	T-N	T-P	Oil	T-Cod	E-Cod	Free Chlorine	SS	BOD	T-N	T-P	Oil	T-Cod	E-Cod	Free Chlorine
Parameter		Max 200	Max 200	Max	Max 200	Max 200	Max	Max 20	Max 20	Max 80	Max 2	Max 10	Max 400	Max 1000	Max 1	Max 10	Max 20	Max 80	Max 2	Max 10	Max 400	Max 1000	Max 1
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	MG/1000L	MG/1000L	mg/L	ppm	ppm	ppm	ppm	ppm	MG/1000L	MG/1000L	mg/L
Sep-05-09-23		-	-	-	25	123	2.61	7	7.9	11.6	0.66	0.1	179	179	0.81	50	17	15.3	1.11	0.1	1	<1	0.51
Sep-12-09-23		27	81	0.659	-	-	-	9	8.8	11.1	0.711	0	1	<1	0.82	30	7	8.6	0.824	0	1	1	0.04
Sep-18-09-23		-	-	-	45	201	1.81	20	20	7.8	1.00	0	179	178	0.83	30	8	8.7	1.18	0.2	337	337	0.18
Sep-27-09-23		48	147	1.55	-	-	-	3	8.6	11.3	0.659	0	399	<1	0.81	30	19	14.3	0.960	0.4	<1	<1	0.68
Oct-03-10-23		-	-	-	13	105	0.879	6	8.4	8.7	0.713	0	1	<1	0.81	30	8.8	3.8	0.733	0	<1	<1	0.1
Oct-11-10-23		98	108	0.987	-	-	-	30	8.3	8.8	0.699	0.1	<1	<1	0.83	5	1.7	6	0.688	0	<1	<1	1.02
Oct-17-10-23		-	-	-	139	225	2.81	3	7.8	7.2	0.483	0	<1	<1	1.76	4	8.3	11.2	0.343	0.3	<1	<1	1
Oct-26-10-23		23	89	1.3	-	-	-	3	8.4	12.3	0.711	0.1	<1	<1	0.52	3	7.4	7.3	0.88	0	<1	<1	0.22
Nov-01-11-23		47	96	1.96	-	-	-	30	7.4	15.1	0.858	0.1	<1	<1	0.1	3	7.6	6	1.64	0	<1	<1	0.62
Nov-08-11-23		-	-	-	17	102	1.82	5	6.4	10.9	0.68	0	<1	<1	0.11	7	7.1	4.1	0.889	0	338	82	0.02
Nov-15-11-23		33	83	1.34	-	-	-	3	6.7	6	0.607	0.1	<1	<1	0.89	4	8.8	10.2	0.874	0.3	<1	<1	0.01
Nov-21-11-23		-	-	-	13	-	2.88	6	8.6	19.3	0.739	0.1	1	1	0.81	8	7	11	1.18	0	1	1	0.01
Nov-28-11-23		60	-	1.52	-	-	-	5	7.7	14.5	0.889	0	1	<1	0.81	8	7.7	8.3	0.845	0.1	<1	<1	0.01
Dec-05-12-23		-	-	-	88	117	1.58	3	8.3	13.4	1.18	0	<1	<1	0.11	10	1.6	6.2	1.18	0	<1	<1	0.28
Dec-12-12-23		-	-	-	33	83	1.49	5	6.4	16.3	0.881	0.3	<1	<1	0.87	10	7.8	14	1.42	0.1	1	1	0.01
Dec-19-12-23		89	153	2.81	-	-	-	4	7.2	17.3	1.61	0	1	<1	0.84	6	6	10.1	1.45	0	<1	<1	0.09
Dec-26-12-23		-	-	-	35	88	1.49	1	8.8	21.4	0.739	0	<1	<1	0.88	4	8.1	16	1.68	0	<1	<1	0.76
Jan-02-01-24		12	95	0.61	-	-	-	5	8.1	16.8	0.99	0.1	<1	<1	0.92	11	1.7	14.2	1.64	0	<1	<1	0.04
Jan-09-01-24		-	-	-	43	23	3	3	4.9	15.1	0.907	0	<1	<1	1.54	4	6.3	12.8	1.01	0.1	1	<1	0.08
Jan-16-01-24		27	123	1.68	-	-	-	10	6.7	8.3	1.07	0	1	<1	0.81	15	7	18.2	0.799	0.2	<1	<1	0.05
Jan-23-01-24		-	-	-	31	114	1.29	5	8.8	13.2	1.15	0.1	46	<1	0.82	15	9.5	1.3	1.36	0	340	340	0.04
Jan-31-01-24		10	-	4.31	-	-	-	4	9.4	1.2	0.1	<1	<1	<1	0.56	7	-	8.4	0.97	0.8	<1	<1	0.13
Feb-06-02-24		-	-	-	89	147	0.82	5	6.3	12.6	0.888	0	<1	<1	0.29	7	6.5	9.8	1.14	0.1	81	81	0.05
Feb-13-02-24		10	81	2.94	-	-	-	39	8.8	11.3	1.48	0.1	<1	<1	0.77	3	8.2	8.3	1.8	0	1	<1	0.28
Feb-20-02-24		-	-	-	43	17	1.81	4	5.8	20.8	1	0	<1	<1	0.25	10	1.3	13.8	1.02	0	1	<1	0.08
Feb-27-02-24		90	94	2.64	-	-	-	22	6.6	16.9	1.04	0.3	1	<1	0.45	10	8.8	12.8	1.44	0.1	198	198	0.02



MUTD-FRM-WAT

Month	Date	Outlet - 1																Outlet - 2																
		Iron	Manganese	Zinc	Aluminum	Chromium	Cadmium	Selenium	Cobalt	Copper	Barium	Nickel	Silver	Vanadium	Total Cyanide	Mercury	Fluoride	Phosphate	Iron	Manganese	Zinc	Aluminum	Chromium	Cadmium	Selenium	Cobalt	Copper	Barium	Nickel	Silver	Vanadium	Total Cyanide	Mercury	Fluoride
Sample		Max 0.05	Max 0.1	Max 0.1	Max 0.1	Max 0.01	Max 0.01	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.01	Max 0.1	Max 0.1	Max 0.01	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1	Max 0.1
Unit		ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	
Test	05-05-23	1	< 0.001	0.004	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.31	0.001	1	<0.001	0.002	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
Ref	21-10-23	1	<0.001	<0.001	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.42	<0.001	2	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
Ref	08-11-23	1.4	<0.001	<0.001	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.42	<0.001	1.4	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
Ref	05-12-23	1	<0.001	<0.001	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.42	<0.001	1	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
Ref	01-03-24	1	<0.001	<0.001	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.42	<0.001	1	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	
Ref	08-02-24	1	<0.001	0.126	<0.01	<0.002	<0.001	<0.01	<0.001	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	<0.002	1.42	<0.001	1	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	<0.001	



MJTD-FRM-WAT-M-032

Month	Date	Table 1															Table 2																				
		Gold	Mercury	Zinc	Lead	Chromium	Cadmium	Selenium	Total	Copper	Barium	Aluminum	Iron	Calcium	Total	Residual Chromium (ppm)	Mercury	Barium	Aluminum	Iron	Calcium	Selenium	Total	Copper	Barium	Aluminum	Iron	Calcium	Total	Residual Chromium (ppm)	Mercury	Barium	Aluminum	Iron	Calcium		
January		Max 0.005	Max 1	Max 0.1	Max 0.2	Max 0.01	Max 0.01	Max 0.1	Max 0.2	Max 1	Max 0.2	Max 1	Max 1	Max 1	Max 0.1	Max 0.2	Max 0.5	Max 0.005	Max 1	Max 0.1	Max 0.2	Max 0.01	Max 0.01	Max 0.1	Max 0.2	Max 1	Max 1	Max 1	Max 0.1	Max 0.2	Max 0.5	Max 0.005	Max 1	Max 0.1	Max 0.2	Max 0.01	Max 0.01
Jan	01-01-21	70%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	12%	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	ppm	
Feb	11-02-21	0	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.01	< 0.01	< 0.001	< 0.01	< 0.001	1	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.001	< 0.001	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01	< 0.01		
Apr	04-01-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001		
Dec	05-02-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	8	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001		
Jan	01-02-21	2	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.01	< 0.01	< 0.001	< 0.01	< 0.001	10	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001		
Feb	06-02-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	12	< 0.001	< 0.01	< 0.01	< 0.001	< 0.001	< 0.01	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001	< 0.001		



Monitoring Parameters Result for STP

Month	Date	Data B - Inlet										Data A - Inlet-1										Data A - Inlet-2										Outlet-1						Outlet-2					
		TS	BOD	TS	TS	DO	Spends	Formaldehyde	Free Chlorine	Color	Iron	Ammonia	TS	DO	Spends	Formaldehyde	Free Chlorine	Color	Iron	Ammonia	TS	DO	Spends	Formaldehyde	Free Chlorine	Color	Iron	Ammonia	Spends	Formaldehyde	Total Chlorine	Color	Iron	Ammonia	Spends	Formaldehyde	Total Chlorine	Color	Iron	Ammonia			
Standard		Max 200	Max 100	Max 5	Max 5	Max 10	Max 0.2	Max 0	Max 1	100	Max 0.5	Max 0	Max 50	Max 0	Max 0	Max 0	Max 1	Max 1	100	Max 0.5	Max 0	Max 50	Max 0	Max 0	Max 0	Max 1	Max 1	100	Max 0.5	Max 0	Max 100	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	Max 0	
Unit		mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	TCU	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L		
Jan	01-01-21	-	-	-	-	-	-	-	-	-	-	-	8	0.2	0.0	0.000	0.00	0.00	0.01	0.00	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Feb	01-02-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
Mar	01-03-21	20	20	0.07	0.0	0.0	0.000	0.000	0	10.00	0.000	0.0	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Apr	01-04-21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
May	01-05-21	0.7	0.7	0.07	0.0	0.0	0.000	0.000	0.00	10.00	0.00	0.00	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
Jun	01-06-21	27	27	0.47	0.0	0.0	0.000	0.000	0.01	10.00	0.00	0.00	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		



Thilawa Special Economic Zone
Zone B– Phase 1,2 & 3 (Operation phase)

Appendix-I

Chemical consumption at Water Sending Station at TSEZ-B

Sludge Generated from Sewage Treatment Plant at TSEZ-A

Water Supply Volume to TSEZ-B

September 2023 to February 2024

Chemical consumption in WSS	
Month- Year	NaOCl (Liters)
Mar-23	629.94
Apr-23	418.93
May-23	601.08
Jun-23	763.06
Jul-23	221.88
Aug-23	264.21
Sep-23	474.00
Oct-23	529.00
Nov-23	764.00
Dec-23	666.00
Jan-24	427.00
Feb-24	412.00
Total	6,171.10

Note: Above chemical consumption volume are used in Water Sending Station (WSS).



Generate Sludge Volume

Date	Items	Generated from	Volume (Kg)
Mar-23	Sludge	Sewage Treatment Plant at Zone-A	11380
Apr-23	Sludge	Sewage Treatment Plant at Zone-A	5830
May-23	Sludge	Sewage Treatment Plant at Zone-A	11940
Jun-23	Sludge	Sewage Treatment Plant at Zone-A	0
Jul-23	Sludge	Sewage Treatment Plant at Zone-A	6920
Aug-23	Sludge	Sewage Treatment Plant at Zone-A	6900
Sep-23	Sludge	Sewage Treatment Plant at Zone-A	0
Oct-23	Sludge	Sewage Treatment Plant at Zone-A	6800
Nov-23	Sludge	Sewage Treatment Plant at Zone-A	7140
Dec-23	Sludge	Sewage Treatment Plant at Zone-A	6920
Jan-24	Sludge	Sewage Treatment Plant at Zone-A	0
Feb-24	Sludge	Sewage Treatment Plant at Zone-A	6160
Total			69980

Note: TSEZ-B wastewater are treated at Sewage Treatment Plant at Zone-A.



Water Supply Volume in Zone-B

Months - Year	Zone B Locator Water Volume (m3)	Outsource Customer V power (m3)	Total Water Volume (m3)
Mar-23	37761	1045	38806
Apr-23	25100	212	25312
May-23	35272	227	35499
Jun-23	30690	213	30903
Jul-23	20462	318	20780
Aug-23	14357	242	14599
Sep-23	33762	280.12	34042
Oct-23	20036	227.12	20263
Nov-23	34087	227.12	34314
Dec-23	38082	227.12	38309
Jan-24	30931	211.98	31143
Feb-24	31373	160.56	31540
Total			163888

Note: Above mention water supply are distributed from Water Sending Station (WSS)



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(နှစ်လတစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ သြဂုတ်လ
မြန်မာ့အံ့အင်တာနေရှင်နယ်လီမိတက်



မာတိကာ

အခန်း ၁ နိဒါန်း	၀
၁.၁ ယေဘုယျ မော်ပြချက်	၁
အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း	၃
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များမော်ပြချက်	၄
၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း	၆
၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ	၇
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၇
အခန်း ၃ နီဂုံးချုပ် နှင့် အကြံပြုချက်များ	၁၄
နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဇာတ်ပုံများ	က ၁-၁
နောက်ဆက်တွဲ ၂ မာတိခွဲခန်းရလဒ်များ	က ၂-၁

ဇယားများစာရင်း

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ	၄
ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ	၆
ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်	၇
ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း	၇
ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၈
ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်	၁၁

ပုံများစာရင်း

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်ရေနမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ ...၂



အခန်း ၁ နိဒါန်း

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်း နှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကိုသိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအား ရေနမူနာယူရာတွင် သီလဝါအထူးစီးပွားရေးဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ ဓုဓုပေါင်းနေရာ လေးနေရာ၊ နာမည်အားဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တို့တွင် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ်ကာလတွင် အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ တောင်ဘက်နယ်နိမိတ်အနီး ဖလမ်းကျွေတွင်တည်ရှိသော ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းရှိ ရေတွင်းအားရည်ညွှန်းနိုင်ရန် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာယူသော နေရာများ၏ တည်နေရာများကို ပုံ ၁.၁-၁ တွင် ဖော်ပြထားပါသည်။





မှတ်စု: စုစည်းထား

ပုံ ၁.၁-၁ ရေအရင်းအမြစ်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက် ရေကမ္ဘာ့ရယူသောနေရာများ၏ တည်နေရာပြပုံ

အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေကမ္ဘာ့ရယူသောနေရာများနှင့် ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters)ကို ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းဆိုင်ရာ အစီအရင်ခံစာပါ ပတ်ဝန်းကျင်ဆိုင်ရာ စောင့်ကြည့်လေ့လာမှု အစီအစဉ်အား ဖြည့်စွက်ရန်အလို့ငှာ ဆောင်ရွက်ထားပါသည်။

ရေအရည်အသွေးကမ္ဘာ့စစ်တမ်းရယူမှုအား နေရာလေးနေရာတွင် ဆောင်ရွက်ခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ ရေစီးဆင်းမှုတိုင်းတာခြင်းကို ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာနိုင်သော နေရာသုံးနေရာ ဖြစ်သည့် မြေပေါ်ရေကမ္ဘာ့ရယူသည့်နေရာ-၂ (SW-2)၊ မြေပေါ်ရေကမ္ဘာ့ရယူသည့်နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေကမ္ဘာ့ရယူသည့်နေရာ-၇ (SW-7) တို့တွင် တိုင်းတာခဲ့ပါသည်။ စောင့်ကြည့်လေ့လာသော ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters)နှင့် ရေကမ္ဘာ့ရယူသောနေရာများကို ဇယား ၂.၁-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	မြေပေါ်ရေ ကမ္ဘာ့ရယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ ကမ္ဘာ့ရယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ ကမ္ဘာ့ရယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေကမ္ဘာ့ရယူသည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁	ရေအပူချိန် (Water Temperature)	၀	၀	၀	၀	ရေကမ္ဘာ့ရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၂	ရေဗေဒနီကိန်း (pH)	၀	၀	၀	၀	ရေကမ္ဘာ့ရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၃	ပျော်ဝင်အောက်စီဂျင် (DO)	၀	၀	၀	၀	ရေကမ္ဘာ့ရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၄	ဆိုင်းကြွအနယ်များ (Suspended Solids)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၅	ဒီဇင်ဒြပ်ဖြူခြွေရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၆	ဓာတ်နည်းမြင် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{mn})	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၇	အရောင် (Color)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၈	အနံ့ (Odor)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၉	ဆီနှင့်အမဲဆီ (Oil and Grease)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၁	ဖော့စဖော့ရက်စုစုပေါင်း (Total Phosphorus)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၂	ကိုလီဖော့စ်စုစုပေါင်း (Total Coliform)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူသည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁၃	ပျော်ဝင်အနည်နုစုပေါင်း (Total Dissolved Solids) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၄	သံဆာတ် (Iron) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၅	ပြဒါးဓာတ် (Mercury) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၆	ရမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖော့င်းဘက်တီးရီးယား (Escherichia Coli) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	-	-	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၇	စီးဆင်းနှုန်း (Flow Rate)	၀	၀	၀	-	ရေနမူနာရယူသည့်နေရာတွင်တိုက်ရိုက်တိုင်းတာခြင်း

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်

ရေနမူနာရယူသည့်နေရာများကို ဇယား ၂.၂-၁ တွင် ဖော်ပြထားပါသည်။ ရေနမူနာရယူသည့်နေရာ တစ်ခုစီတွင် စစ်တမ်းရယူခဲ့သည့်မှတ်တမ်းပုံများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားသည်။

ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ

စဉ်	တည်နေရာ	အသေးစိတ်အချက်အလက်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ကိုညွှန်မိုက် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၀' ၂၀.၆၉"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၈.၈၄" တည်နေရာ - ရွှေပျောက်ချောင်းအထက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ကိုညွှန်မိုက် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၄၂.၈၄"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၆' ၂၇.၄၂" တည်နေရာ - ရွှေပျောက်ချောင်းအောက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ကိုညွှန်မိုက် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၀' ၁၃.၂၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၅.၆၆" တည်နေရာ - ရွှေပျောက်ချောင်းသို့ ဖရောက်မီ ဇုန်အပိုင်း (ခ)၏ ရေထိန်းကန်ရှိ ထွက်ပေါက် ရေနမူနာရယူသော အမျိုးအစား - ခွံတုတ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (GW-2)	ကိုညွှန်မိုက် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၂၅.၃၀"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၅.၆၀" တည်နေရာ - ဗလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းအရပ်အတွင်း ရေနမူနာရယူသော အမျိုးအစား - မြေအောက်ရေရယူခြင်း

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)အား ရွှေပျောက်ချောင်း၏ အထက်ပိုင်းတွင် ရယူခဲ့ခြင်းဖြစ်သည်။ အဆိုပါအမှတ်သည် ဇုန်အပိုင်း(ခ)ဧရိယာ၏ အရှေ့မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနောက်မြောက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့က အသီးသီး ဝန်းရံလျက် ရှိသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

ပြည်တွင်းစက်မှုဇုန်၊ သီလဝါ ဇုန်အပိုင်း(က) နှင့် ဇုန်အပိုင်း(ခ)ရှိ လုပ်ငန်းခွင်များမှ စွန့်ထုတ်လိုက်သောရေများပေါင်းစည်းရောနှောသွားသောနေရာ ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရယူခဲ့ခြင်းဖြစ်သည်။ ရွှေပျောက်ချောင်းသည် အရှေ့မှအနောက်သို့စီးဆင်းပြီး ရန်ကုန်မြစ် အတွင်းသို့ စီးဝင်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) သည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ချောင်းအောက်ပိုင်း ၂.၁၅ ကီလိုမီတာအကွာတွင် တည်ရှိပါသည်။ အဆိုပါ ရေနမူနာရယူသည့်နေရာသည် ဇုန်အပိုင်း(ခ) ဧရိယာ၏ အနောက်ဘက်တွင်တည်ရှိပြီး ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင်တည်ရှိပါသည်။ ပတ်ဝန်းကျင်အနီးအနားတွင် အရှေ့မြောက်ဘက်တွင် ဇုန်အပိုင်း (က)၊ အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်၊ တောင်ဘက်နှင့် အနောက်ဘက်တို့တွင် စပါးခင်းတို့ အသီးသီးတည်ရှိပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) (စွန့်ထုတ်ရေထွက်ပေါက်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထိုနေရာသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ချောင်းအောက်ပိုင်း၊ အကွာအဝေးအားဖြင့် ၄၃၄ မီတာ အကွာတွင် တည်ရှိပါသည်။ နမူနာရယူသည့်နေရာမှာ ဇုန်အပိုင်း(ခ) ရေထိန်းကန်၏ထွက်ပေါက်၊ ဇုန်အပိုင်း(ခ) ဧရိယာ၏ မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်းမကြီး၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) (မူလတည်ရှိနေသောရေတွင်းအား ရည်ညွှန်းခြင်း)

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား တူးဖော်ထားသောရေတွင်းမှ ရယူခဲ့ပါသည်။ အဆိုပါ ရေတွင်းသည် ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းတွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (က)၊ တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ၊ အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်နှင့် အရှေ့နှင့်အရှေ့မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ)တို့ အသီးသီးတည်ရှိနေပါသည်။



၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ရေနမူနာများကို ရယူပြီး သန့်စင်ထားသောဖန်ပုလင်းညှို့များဖြင့် သိမ်းဆည်းပြီး ဇယား ၂.၃-၁ တွင် ဖော်ပြထားသော နည်းလမ်းများဖြင့် စာတံခွဲခန်း၌ စစ်ဆေးပါသည်။ ရေနမူနာများကို ရေခဲပုံးများဖြင့် ၂-၄ဒီဂရီ ဆဲလ်စီးရပ်တွင် သိမ်းဆည်းထားပြီး စာတံခွဲခန်းသို့ ပို့ဆောင်ပါသည်။ တိုင်းတာသည့် ရေအရည်အသွေး အမျိုးအစားများ၌ ရေအပူချိန်၊ ချဉ်ဖန်ကိန်း နှင့် ပျော်ဝင်အောက်စီဂျင်တို့အား ရေအရည်အသွေး တိုင်းတာသောစက်ကိရိယာ (Horiba U-52)ကို အသုံးပြု၍ ရေနမူနာရယူသည့်နေရာ၌ပင် တိုက်ရိုက်တိုင်းတာခဲ့ပါသည်။ ထို့အပြင်ရေစီးဆင်းမှုနှုန်းကိုလည်း ဒီဂျစ်တယ်ရေစီးနှုန်းတိုင်းကိရိယာ (JFE Digital Current Meter)ဖြင့် ရေနမူနာရယူသည့်နေရာ၌ တိုင်းတာခဲ့ပါသည်။

ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁	ရေအပူချိန် (Water Temperature)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၂	ချဉ်ဖန်ကိန်း (pH)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၄	ဆိုင်ကြွေအနယ် (Suspended Solids)	APHA 2540 D (Dry at 103-105°C Method)
၅	စီဝန်ညှို့ဖြင့် ဖြိုခွဲရန် ဆောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	APHA 5210 B (5 Days BOD Test)
၆	ဓာတ်နည်းဖြင့် ဖြိုခွဲရန် ဆောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	APHA 5220D (Close Reflux Colorimetric Method)
၇	အရောင် (Color)	APHA 2120C (Spectrophotometric Method)
၈	အနံ့ (Odor)	APHA 2150 B (Threshold Odor Test)
၉	ဆီနှင့် အမဲဆီ (Oil and Grease)	APHA 5520B (Partition-Gravimetric Method)
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	HACH Method 10072 (TNT Persulfate Digestion Method)
၁၁	ဖော့စဖောရပ်စ်စုစုပေါင်း (Total Phosphorus)	APHA 4500-P E (Ascorbic Acid Method)
၁၂	ကိုလိုဖောင်း နမူနာပေါင်း (Total Coliform)	APHA 9221B (Standard Total Coliform Fermentation Technique)
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
၁၄	သံမဏိ (Iron)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၅	မြွေဆေး (Mercury)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ဘက်တီးရီးယား (Escherichia Coli)	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

မူရင်း ဖြန့်ချိထုတ်ဝေမှုအတွက် အသုံးပြုရန်

၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ

ရေအရည်အသွေးနှင့် ဓရဇီးဆင်းမှုနှုန်း စောင့်ကြည့်လေ့လာမှုအား ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် ဆောင်ရွက်ခဲ့ပြီး ဒီရေအောက်အကျကြောင့် ဖြစ်ပေါ်လာနိုင်သော သက်ရောက်မှုများကိုရှောင်ရှားနိုင်ရန် အောက်ပါ ဇယား ၂.၄-၁ အတိုင်း ရေနမူနာရယူခဲ့သည်။ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ် အတွက်ဒီရေ မှတ်တမ်းကို ဇယား ၂.၄-၂ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်

စဉ်	ရေနမူနာရယူသည့်နေရာ	ရေနမူနာရယူသည့်အချိန်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၂ နာရီ : ၃၀ မိနစ်)
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၁ နာရီ : ၄၀ မိနစ်)
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၀၉ နာရီ : ၄၀ မိနစ်)
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၀၈ နာရီ : ၀၀ မိနစ်)

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်ရှယ်လီမိတက်

ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

ရက်စွဲ	အချိန်	အမြင့်	ဒီရေအမြေအနေ
ဩဂုတ်လ ၈ ရက်နေ့ ၂၀၂၃ ခုနှစ်	၀၄:၀၆	၁.၄၃	ဒီရေအကျ
	၀၉:၀၀	၅.၈၉	ဒီရေအောက်
	၁၆:၂၇	၁.၇၀	ဒီရေအကျ
	၂၁:၂၀	၅.၄၉	ဒီရေအောက်

မှတ်ချက်- မြန်မာအိတ်ကမ်းအားထာဝရ ၂၀၂၃ ခုနှစ်အတွက် ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စွန့်ထုတ်ရေထွက်ပေါက်၊ စွန့်ထုတ်ရေရောက်ရှိသောချောင်းနှင့် ရည်ညွှန်းရေတွင်းရှိ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားသည်။ ဓာတ်ခွဲခန်းဆန်းစစ်မှု ရလဒ်များကို နောက်ဆက်တွဲ-၂ တွင် ဖော်ပြထားသည်။ ရလဒ်များကို ပတ်ဝန်းကျင်ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသည့် ရေအရည်အသွေး ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ထားပါသည်။

၂.၅.၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိရလဒ်များ

ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ဆိုင်းကြွအနယ်များ၊ ဇီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင်လိုအပ်ချက်(၅-ရက်)၊ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

စွန့်ထုတ်ရေထွက်ပေါက်ရှိ ရေအရည်အသွေးရလဒ်များ

ဆိုင်းကြွအနယ်များ၏ ရလဒ်များအနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် စုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ် ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ စုန်အပိုင်း(ခ)ရှိ မြေလွှတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် စုန်အပိုင်း(ခ)၏ အဓိက စွန့်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်ချေအလားအလာရှိသည့် အကြောင်းရင်းများမှာ အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများကွင်းလည်ကျက်စားခြင်းကြောင့် စုန်အပိုင်း(ခ)

အတွင်းရှိမြေများတွင် သဘာဝမှတက်တီးရီးယားများပါဝင်ပြီး အထူးသဖြင့် တိရစ္ဆာန်များထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း နှင့် မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် ပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည် ရေထိန်းကန်ထဲသို့ စီးဝင်စေပြီး၊ ၎င်းစွန့်ပစ်အညစ်အကြေးများ ပါဝင်နေသော စီးဆင်းရေများနှင့် အခြားအညစ်အကြေးများတို့သည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းဇုန်ပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှတက်တီးရီးယားများပါဝင်ပြီး ကိုလီဖောင်းဇုန်ပေါင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား ဓာတ်ခွဲစမ်းသပ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli) ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းဇုန်ပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

စောင့်ကြည့်လေ့လာသည့်ရည်ညွှန်းအမှတ်များ၏ရေအရည်အသွေးရလဒ်များ(စွန့်ထုတ်ရေရောက်ရှိသောချောင်း)

ဆိုင်းကြွအနည် ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) သဘာဝအလျှောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ (၂) ရွှေပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ဒီဝန်နည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင်လိုအပ်ချက် (၅-ရက်) ၏ ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) ရေထုထဲတွင် အောက်နစ်ညစ်ညမ်းမှု ပမာဏများနေခြင်းကြောင့် လည်းကောင်း၊ (၂) ရေထုထဲတွင် နိုက်ထရိုဂျင်ပမာဏလွန်ကဲခြင်းကြောင့် အပင်များကြီးထွားကာပျော် ဝင်အောက်စီဂျင် လျော့နည်းလာခြင်းတို့ကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းဇုန်ပေါင်း ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်းနှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များမှ ထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများကို ရွှေ့ပျောက်ချောင်းသို့ ရောက်ရှိစေနိုင်ပြီး၊ ၎င်းစွန့်ပစ်အညစ်အကြေးများ ပါဝင်နေသော စီးဆင်းရေများနှင့် အခြားအညစ်အကြေးများတို့သည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေ့ပျောက်ချောင်းတလျှောက် တိုးဝင်လာသောဒီရေများတွင် စွန့်ပစ်အညစ်အကြေးများ ပါဝင်နိုင်ခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါအထူးစီးပွားရေးဇုန်၏



ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂရမ်မြေဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းနေရုံမျှကြောင့် ၎င်းမြေသားများသည် မြေနှိမ့်ပိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

**ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး
စောင့်ကြည့်လေ့လာမှုရလဒ်များ**

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	စည်မှန်စွာတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် စည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၂၉	၂၀	၂၈	≤ ၃၅
၂	ချွန်ဖန်ကိန်း(pH)	-	၆.၇	၇.၁	၆.၇	၆ - ၉
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/l	၃.၃၇	၄.၉၆	၄.၄၃	-
၄	ဆိတ်ကြွယ်မှု (Suspended Solids)	mg/l	၂၄	၂၀၆	၅၈	၅၀
၅	ဇီဝအောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	mg/l	၆၃.၈၂	၄.၅၄	၈.၄၀	၃၀
၆	ဓာတုအောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	mg/l	၁၁၄.၀	၁၄.၇	၂၁.၇	၁၂၅
၇	အရောင် (Color)	TCU (True Color Unit)	၃၁.၇၀	၁၄.၄၆	၂၆.၂၅	၁၅၀
၈	အနံ့ (Odor)	TQN (Threshold Odor Number)	၁	၁	၁	-
၉	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/l	≤ ၃.၁	≤ ၃.၁	≤ ၃.၁	၁၀
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/l	၃.၆	၀.၆	၁၁.၄	၈၀
၁၁	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/l	≤ ၀.၀၅	၀.၃၁	၀.၂၀	၂
၁၂	ကိုလီဖော့မ်း နမူနာပေါင်း (Total Coliform)	MPN/100ml	၃၅၀၀၀.၀	၃၅၀၀၀.၀	၉၂၀၀၀.၀	၄၀၀
၁၃	ပျော်ဝင်အရည်စုစုပေါင်း (Total Dissolved Solids)	mg/l	၈၀	၁၉၂	၁၂၆	၂၀၀၀
၁၄	သံဓာတ် (Iron)	mg/l	၄.၈၆၀	၁၄.၈၆၀	၃.၂၇၀	၃၅
၁၅	မြွေဆိမ့် (Mercury)	mg/l	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	၀.၀၀၅

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဆောင်း ဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml (SW)	-	-	၂၄၀	(၁၀၀၀)* (CFU/၁၀၀ml)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	m ³ /s	၈.၂၇	၈.၇၆	၁.၀၃	-

မှတ်ချက်။ အစီရင်ခံစာပြင်ဆင်ပြီးနောက်အသိပေးသည့်သတ်မှတ်ထားသည့်တန်ဖိုးအထက်ကျော်လွန်သောရေကိုမူလီလီပါသည်။

*မှတ်ချက်။ နမူနာယူရက်အတွက်လက်သောက်ရေအရင်းအမြစ် အသုံးပြုမှုမပါမီတည်ရှိ လှုပ်နှံနိုင်စွမ်း မျိုးရေစန့်ချိန်ညှိမှု (ပတ်ဝန်းကျင်ဆိုင်ရာဝန်ကြီးဌာန၊ ၁၉၉၇)ကို ဝမ်းကိုက်ရောဂါဖြစ်စေသော ကိုလီဆောင်းဘက်တီးရီးယား(E.coli)၏ ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ထားပါသည်။ သို့သော်လည်း မြန်မာနိုင်ငံရှိ ဆက်သွယ်ရေးစာအုပ်
လုပ်ဆောင်နိုင်မှု ကန့်သတ်ချက်များကြောင့် စီအက်စ်ယူတန်ဖိုး "Colony Forming Unit (CFU)" အား တိုင်းတာ၍မရပါ။ ထို့ကြောင့် အမေရိကန် "Most Probable Number (MPN)" ရလဒ်များကို စီအက်စ်ယူတန်ဖိုးနှင့် တူညီလည်ဟုယူဆပြီး ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ပါသည်။ မြန်မာနိုင်ငံတွင် စီအက်စ်ယူတန်ဖိုးကို သုံးသပ်နိုင်သည်နှင့် တစ်ပြိုင်နက် သုံးသပ်သည့်နည်းလမ်းများ ပြောင်းလဲမည်ဖြစ်သည်။

မှရပြီး၊ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတာကို

၂.၅.၂ ရည်ညွှန်းရေတွင်း၏ရလဒ်

ရည်ညွှန်းရေတွင်းစောင့်ကြည့်လေ့လာသောနေရာ၌ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရလဒ်များကို
ဇယား ၂.၅-၂ တွင်ဖော်ပြထားသည်။ ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာတွင် သံဓာတ်သည် ရည်မှန်းတန်ဖိုးထက်
ကျော်လွန်နေကြောင်း တွေ့ရသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ်
ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင်
စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင်
၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဩဂုတ်လ၊ ၂၀၂၂ခုနှစ် တွင် ၉.၁၈၂ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ
၂၀၁၉ခုနှစ်၊ ဖော်ဖော်ဝါရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍
သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ ဩဂုတ်လ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက်
ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ
သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု ကြောင့်ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ
ထွက်လာနိုင်ပါသည်။)။ အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည်
သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂစ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည်
မြေနှိပ်ပိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။



၂.၅-၃ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှင့် ၂၀၂၃ ခုနှစ် ဩဂုတ်လ တွင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ
၏ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ အရည်အသွေးများ နှိုင်းယှဉ်ခြင်း

ယခု စောင့်ကြည့်လေ့လာနေစဉ်ကာလ (ဩဂုတ် ၂၀၂၃) အတွင်း ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ
အရည်အသွေးများအား မြင့်သုံးသပ်ကြည့်ရန်အတွက် ၂၀၂၂ ခုနှစ် ဩဂုတ်လ ကတည်းကရရှိသော
စောင့်ကြည့်မှုရလဒ်များနှင့် နှိုင်းယှဉ်ထားပါသည်။

စွန့်ထုတ်လိုက်သောနေရာများ၏ ရေအရည်အသွေးရလဒ်များနှင့် ပတ်သက်၍ စောင့်ကြည့်ရာတွင်
မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ဆိုင်းကြွအနည်ရလဒ်သည် အောက်တိုဘာလ၊ ဒီဇင်ဘာလ ၂၀၂၂ နှင့်
ဧပြီလ၊ ဩဂုတ်လ ၂၀၂၃ တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ ထို့အပြင် မြေပေါ်ရေနမူနာယူသည့်
နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် ဩဂုတ်လ ၂၀၂၂ နှင့် မေမော်ဝါရီလ၊ ဇွန်လ၊
ဩဂုတ်လ ၂၀၂၃ တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏
ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် ၂၃၀၀ MPN/၁၀၀ml မှ စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀၀
MPN/၁၀၀ml)ထိ ရှိပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်
တန်ဖိုးသည် မိုးရာသီအစနှင့် အလယ်တွင် စမ်းသပ်နိုင်သောပမာဏ ထိ သိသာထင်ရှားစွာ မြင့်မားနေပြီး
စီးဆင်းရေ၏ သက်ရောက်မှုကြောင့် ဖြစ်နိုင်သည်ဟု သုံးသပ်ရပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့်
နေရာ-၂ (GW-2) ၏ သံဓာတ်တန်ဖိုးသည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍ စစ်တမ်းကောက်ယူထားသော
ကျန်လများအားလုံးသည် ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2)
၏ သံဓာတ်တန်ဖိုးသည် မိုးဦးရာသီ နှင့် ဆောင်းရာသီတို့တွင် မြင့်မားနေသည်ကို သိသိသာသာတွေ့မြင်ရ ပါသည်။

အခြားတစ်ဖက်တွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄
(SW-4)တို့ရှိ ရလဒ်အမျိုးမျိုးသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။
မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ ဆိုင်းကြွအနည်ရလဒ်သည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍
စစ်တမ်းကောက်ယူထားသော ကျန်လများတွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပြီး ၇၈ မှ ၅၅၈ mg/l
ထိတန်ဖိုးအပိုင်းအခြား အတွင်းရှိနေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင်ရှိသော
ဆိုင်းကြွအနည်ရလဒ်များသည် မိုးရာသီအတွင်း ပတ်ဝန်းကျင်မှရေများ စီးဆင်းမှုကြောင့် ရလဒ်များ
မြင့်တက်နေခြင်းဖြစ်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ဇီဝနည်းဖြင့်ဖြည့်ရန်
အောက်စီဂျင်လိုအပ်ချက် (၅-ရက်) ရလဒ်သည် ယခု စောင့်ကြည့်လေ့လာသော ကာလ ဩဂုတ် ၂၀၂၃ တွင်
ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရသော်လည်း ယခင်စောင့်ကြည့်လေ့လာခဲ့သော
ကာလများတွင် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းနေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂
(SW-2) ၏ သံဓာတ်တန်ဖိုးသည် ဩဂုတ်လ ၂၀၂၂၊ ဇွန်လ နှင့် ဩဂုတ်လ ၂၀၂၃တို့တွင်သာ ရည်မှန်းတန်ဖိုးထက်
မြင့်မားနေသော်လည်း၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးသည် (ဩဂုတ်လ၊
အောက်တိုဘာလ၊ ဒီဇင်ဘာလ ၂၀၂၂ နှင့် ဇွန်လ၊ ဩဂုတ်လ ၂၀၂၃) စောင့်ကြည့်လေ့လာနေသော ကာလ(၅)လ တွင်
မြင့်မားနေပြီး သံဓာတ်တန်ဖိုး အပိုင်းအခြားသည် ၄-၃၇၆ မှ ၂၂.၆၂၆ mg/l အတွင်းရှိပါသည်။
မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးမြင့်မားမှုသည် မိုးရာသီ တလျှောက်လုံးမှ
ဆောင်းရာသီအစတိုင်အောင် ဖြစ်ပေါ်နေကြောင်း တွေ့ရှိရသည်။ သိသာထင်ရှားစွာမြင့် မြေပေါ်ရေနမူနာယူသည့်
နေရာ-၂ (SW-2) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှုစစ်တမ်း (၇)လအတွက်
(၆)လသည် (၁၃၀၀မှ >၁၆၀၀၀၀ MPN/100ml အပိုင်းအခြားအတွင်း) ရလဒ်တန်ဖိုးထက် မြင့်နေပြီး
မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှု
ကာလအားလုံးတွင် (၄၆၀၀ မှ >၁၆၀၀၀၀ MPN/100ml အပိုင်းအခြားအတွင်း) ရည်မှန်းတန်ဖိုးထက်



မြင့်မားနေကြောင်း တွေ့ရှိရသည်။ အထူးသဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် ဩဂုတ်လ ၂၀၂၂ နှင့် ဇွန်လ ၂၀၂၃ တွင် စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀ MPN/100ml) ထိရောက်ရှိခဲ့ပြီး၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် အောက်တိုဘာလ ၂၀၂၂ နှင့် ဇွန်လ ၂၀၂၃ တွင် စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀ MPN/100ml)ထိ အသီးသီး ရောက်ရှိခဲ့ပါသည်။ ယခုလက်ရှိ ရေအရည်အသွေးများ၏ ရလဒ်များအခြေအနေသည် သီလဝါအထူးစီးပွားရေးဇုန် ယခင်နှင့်ယခုလက်ရှိကာလ လည်ပတ်မှု၏ ပတ်ဝန်းကျင်အခြေနေများကို ထင်ဟပ်နေသည်ဟု ဆိုနိုင်ပါသည်။

ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည့် သက်ဆိုင်ရာရေအရည်အသွေးအမျိုးအစားများအတွက် ပြစ်နိုင်သော အကြောင်းပြချက်များအား ဤ အစီရင်ခံစာ၏ အရှေ့ပိုင်းရှင်းလင်းချက်တွင် ဖော်ပြထားပါသည်။



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

အခန်း ၂ (အပိုင်း ၂.၅) တွင်ဖော်ပြထားသကဲ့သို့ သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ် ကာလ စောင့်ကြည့်လေ့လာသောအချိန်အတွင်း မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ဆိုင်းကြွအနည်းများ၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) တွင် ဇီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် သံဓာတ်များ နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တွင် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။

ဆိုင်းကြွအနယ် ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ရေထိန်းကန် အတွင်းနှင့် အပြင်တလျှောက်တွင် အပင်များနှင့်ငှက်များ၊ တိရစ္ဆာန်ငယ်များ ကျင်လည်ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ)၏ ဧရိယာတွင် သဘာဝအလျောက် ဘက်တီးရီးယားများ ရှိနေသောကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး စုစုပေါင်းကိုလီဖောင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား မာတ်ခွဲစမ်းသပ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

ဇီဝနည်းဖြင့်ဖြိုခွဲရန် အောက်စီဂျင်လိုအပ်ချက် (၅-ရက်) ၏ ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) ရှိ ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိကအကြောင်းအရာများမှာ ရေထုထဲတွင် အော်ဂဲနစ်ညစ်ညမ်းမှု ပမာဏများနေခြင်း နှင့် ရေထုထဲတွင် နိုက်ထရိုဂျင်ပမာဏ လွန်ကဲခြင်းကြောင့် အပင်များကြီးထွားကာ ပျော်ဝင်အောက်စီဂျင်လျော့နည်းလာခြင်း တို့ဖြစ်သည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ဆိုင်းကြွအနယ်၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်း စုစုပေါင်း နှင့် သံဓာတ် ရလဒ်အနေဖြင့် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ဆိုင်းကြွအနယ်၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ရခြင်းမှာ (၁) သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ (၂) ရွှေ့ပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်းနှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များမှ ထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများကို ရွှေ့ပျောက်ချောင်းသို့ ရောက်ရှိစေနိုင်ပြီး၊ ၎င်းစွန့်ပစ်အညစ်အကြေးများ ပါဝင်နေသောစီးဆင်းရေများနှင့် အခြားအညစ်အကြေးများတို့သည် ကိုလီဖောင်းပဝင်မှုအား မြှင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေ့ပျောက်ချောင်းတလျှောက် တိုးဝင်လာသောဒီရေများတွင် စွန့်ပစ်အညစ်အကြေးများ ပါဝင်နိုင်ခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် သံဓာတ် ၏ ရလဒ် များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပြီး (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှထွက်လာနိုင်ပါသည်) ပတ်ဝန်းကျင်ရှိတောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသော မြေဆီလွှာ(ဂဝံမြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုခိုဝိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင် ၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဩဂုတ်လ၊ ၂၀၂၂ခုနှစ် တွင် ၉.၁၈၂ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ ၂၀၁၉ခုနှစ်၊ ဖော်ဖော်ဝါရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍ သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ ဩဂုတ်လ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု ကြောင့်ဖြစ်နိုင်ပါသည် (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်)။ အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂဝံမြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုခိုဝိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

အနာဂတ်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ၏ အဓိကစွန့်ထုတ်ရေ ထွက်ရှိသောနေရာများမှ ထွက်ရှိလာသော ရေအရည်အသွေးများဖြစ်သည့် ကိုလီဖောင်းစုစုပေါင်း၏ သင့်တော်သော ရည်မှန်းအဆင့် ရရှိနိုင်ရန် အောက်ပါဆောက်လုပ်ချက်များကို လုပ်ဆောင်သင့်ပါသည်။

- ကိုလီဖောင်းဘက်တီးရီးယားများ၏ ကျန်းမာရေးအပေါ်သက်ရောက်မှုကို သိရှိနိုင်ရန် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E. Coli) ကိုဆက်လက်စောင့်ကြည့်ရန် လုပ်ဆောင်သင့်ပါသည်။

ဤတွင်စာတမ်းပြီးဆုံးပါသည်။



နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဓာတ်ပုံများ



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ရှိ စွန့်ထုတ်ရေနမူနာယူယူသည့်နေရာ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၌ ရေနမူနာယူခြင်းနှင့်တိုင်းတာခြင်း

စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏ အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

နောက်ဆက်တွဲ ၂ ဓာတ်ခွဲခန်းရလဒ်များ



သီလဝတီဆေးကုရေးဆေးရုံနှင့်အပိုင်(ခ)ရှိစက်မှုနှင့်မြို့ပြတိုးတက်ရေးအဖွဲ့အစည်းဆောင်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတာခံကြိုက် ဆောင်ကြည့်လေ့လာခြင်း ပြေတိုက် ၂၀၂၃ ခုနှစ်)

စွန့်ထုတ်ရေထွက်ရှိရာနေရာ

0212666

Lab. No. 0212666
Date: 01/08/2023
Time: 09:00 AM



Report No. : 0212666
Revision No. : 1
Report Date : 01 August 2023
Approval No. : 0212666

Analysis Report

Client Name : Myanmar Rail Corporation (MRC)
Address : No. 20/1, 1st Floor, North Myanmar Corporation, The 2nd Road, North Township, Yangon Region
Project Name : Environmental Monitoring report for Zila Sub B
Sample Description :
Sample Name : WWT 01
Sample No. : WWT 01
Field No. : WWT 01

Reference : 01 August 2023

Sampling By : Customer

Sample Received Date : 01 August 2023

Report Date : 01 August 2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540C (20/4 at 100°C Method)	mg/L	38	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/L	8.45	0.20
3	COD (Cr)	APHA 5220A (Open Reflux Carotimeter Method)	mg/L	21.7	0.2
4	Ts and Tss	APHA 5210B (Gravimetric Method)	mg/L	67.1	0.1
5	Calc	APHA 2110C (Spectrophotometric Method)	mg/L	88.25	0.05
6	Total Nitrogen	APHA 4500-02 (Catalytic Reduction Method)	mg/L	11.4	0.5
7	Total Phosphorus	APHA 4500-07 (Ascorbic Acid Method)	mg/L	0.27	0.05
8	TDS	APHA 2540C (Total Dissolved Solids (TDS) Method)	mg/L	149	-
9	Fluoride	APHA 4500-F (Ferrochrome Coupled Plasma (CFP) Method)	mg/L	0.2052	0.005
10	Ammonia	APHA 4500-N (Nesslerization Coupled Plasma (CFP) Method)	mg/L	0.002	0.002
11	Iron	APHA 4500-Fe (Catalytic Coupled Plasma (CFP) Method)	mg/L	5.175	0.005
12	Total Coliform	APHA 9220B (Standard Plate Counting Technique)	MPN/100mL	14000.0	1.0
13	Salinity	APHA 9220B (Thermocouple Method)	mg/L	1	0
14	Enterobacteriaceae	APHA 9220B (Enterobacteriaceae Counting using Enterobacter Substrate)	MPN/100mL	24.0	1.0

Symbol : LOQ - Limit of Quantitation

Method : American Public Health Association (APHA), The American Water Works Association (AWWA), and the British Standards Institution (BSI), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By :
N/A
Technician
Manager



Approved By :
N/A
Aug 01, 2023
Signature

Water Quality Control and Management Department
Environmental Monitoring and Assessment Division
Environmental Monitoring and Assessment Unit



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း၊ ခရိုင်စက်မှုဇုန်၌ ပြိုတိုက်တက်မှုအတွက် ရေစနစ် အသေးစား စောင့်ကြည့်လေ့လာမှု အစီရင်ခံစာ
(နှစ်လတာကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း အြာတ်လ ၂၀၂၃ ခုနှစ်)

**စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ရောင်း၏
အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ**

2023/08/08

ANALYSIS REPORT FOR MONITORING OF
WATER QUALITY IN THE INDUSTRIAL ZONE
(2023/08/08)



Report No. : 019-AM-23258037
Revision No. : 1
Report Date : 21 August, 2023
Application No. : 0003-0003

Analysis Report

Client Name : Myanmar Water International LTD (MWI)
Address : No. 16/A, 1st Floor, Shanti Plaza Condominium, Phawbada Road, Tamar Township, Yangon Region
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : pH, DO, BOD
Sample No. : W-230808
Water Profile No. :
Sampling Date : 8 August, 2023
Sampling By : Customer
Sample Received Date : 8 August, 2023
Analysis Date : 8-21/08/2023

No.	Parameter	Method	Unit	Result	LOD
1	pH	APHA 2540C (Dry at 103-101°C Method)	mg/l	7.4	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	23.80	0.05
3	DO (5)	APHA 5200A (DO probe method) (membrane method)	mg/l	11.14	0.2
4	TSS and Suspended	APHA 5200B (gravimetric-gravimetric method)	mg/l	49.2	0.1
5	Color	APHA 5210C (spectrophotometric method)	PCU	11.14	0.05
6	Total Nitrogen	HACH Method 38712 (TNB Fermentation-Digestion Method)	mg/l	1.8	0.5
7	Total Phosphorus	APHA 5200 F-2 (Ascorbic Acid Method)	mg/l	<0.05	0.05
8	TDS	APHA 5210 C (Total Dissolved Solids dried at 103°C Method)	mg/l	80	-
9	Chlorine	APHA 5210 B (Dichloromethyl Coupled Plasmic (DCT) Method)	mg/l	48.382	0.001
10	Fluoride	APHA 5210 B (Dichloromethyl Coupled Plasmic (DCT) Method)	mg/l	48.382	0.001
11	Iron	APHA 5210 B (Dichloromethyl Coupled Plasmic (DCT) Method)	mg/l	4.000	0.001
12	Total Calcium	APHA 5210 B (Standard Total Calcium Fermentation Technique)	mg/l (ppm)	10.66.0	1.0
13	Oil	APHA 5210 B (Threshold Oil Test)	mg/l	-	0

Remarks : LOD : Limit of Quantitation

APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF). Standard Methods for the Examination of Water and Wastewater, 22nd edition.

Analysed By

Ms. Aye Linn
Analyst



Approved By

Ms. Aye Linn
Managing Director

ANALYSIS REPORT FOR MONITORING OF
WATER QUALITY IN THE INDUSTRIAL ZONE
(2023/08/08)



သီလဝါအထူးစီးပွားရေးနှင့်အိတ်ဒ်(ခ)စိုက်ပျိုးရေးနှင့်မြို့တိုးတက်မှုအတွက်ရေအရင်းအမြစ်ဆောင်ကြည်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ် ဆောင်ကြည်လေ့လာခြင်း ဩဂုတ်လ ၂၀၂၃ ခုနှစ်)

SCW-8

Water and Environmental Engineering Ltd.
No. 16/A, 1st Floor, Grand Proton Condo, P.O. Box 1666, Thimphu, Bhutan
Phone No: 9753 12345



Report No. : WEM-LAB-2023-000004
Revision No. : 1
Report Date : 21 August, 2023
Ref: SCW-8

Analysis Report

Client Name : Pashmar Nam International LTD (PNI)
Address : No. 16/A, 1st Floor, Grand Proton Condo, P.O. Box 1666, Thimphu, Bhutan
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : RSLW-4 (RSL)
Sample No. : W-20001/4
Water Profile No. :
Sampling Date : 6 August, 2023
Sampling By : Customer
Sample Received Date : 6 August, 2023
Analysis Date : 6-11/08/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2590 (Dry et. 10-14.0) Method	mg/l	7.8	—
2	Hardness	APHA 5110 F (2-1400 MG/l) Method	mg/l	4.34	0.05
3	Calcium	APHA 5220 (Titrimetric Calcium Method)	mg/l	54.7	0.7
4	Chloride	APHA 5220 (Mercuric Chloride Method)	mg/l	4.3	3.3
5	Lead	APHA 5110 (Spectrophotometric Method)	mg/l	14.06	0.05
6	Copper	APHA 5110 (Spectrophotometric Method)	mg/l	0.6	0.5
7	Total Phosphorus	APHA 4500-P (Ascorbic Acid Method)	mg/l	0.05	0.05
8	TDS	APHA 2540-C (Total Dissolved Solids Gravimetric Method)	mg/l	984	—
9	Chlorine	APHA 5110-B (Inductively Coupled Plasma (ICP) Method)	mg/l	45.000	0.007
10	Mercury	APHA 5110-B (Inductively Coupled Plasma (ICP) Method)	mg/l	40.000	0.004
11	Iron	APHA 5110-B (Inductively Coupled Plasma (ICP) Method)	mg/l	14.000	0.002
12	Total Coliform	APHA 8210 (Standard Total Coliform Enumeration Technique)	MPN/100ml	10000.0	1.0
13	DO	APHA 2130-B (Electrode (DO) Test)	mg/l	7	0

Notes :
LOQ : Limit of Quantitation
APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Treatment Federation (WTF), Standard Methods for the Examination of Water and Wastewater, 21st edition.

Analyst By

By the Analyst

Signature



Approved By

Aug 21, 2023

Approving Director

Report No. WEM-LAB-2023-000004
This report is the property of Water and Environmental Engineering Ltd. and is not to be reproduced or used in any form without the written permission of the company.



သီလဝါအထူးစီးပွားရေးနှင့် အဝတ် (သန့်စက်မှုနှင့်) ပြုတ်တက်မှုအတွက် အရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတာစံကြမ်း၊ စောင့်ကြည့်လေ့လာခြင်း ပြုစုတ်လ ၂၀၂၃ ခုနှစ်)

EDQM/02

International Union of Pure and Applied Chemistry
100-10-17, Avenue de l'Industrie & Transport, 91000 Evry-Courcouronnes
France (tél. 01 69 20 00 00) (fax 01 69 20 00 01)



Report No. : GEM-LAB-20230801
Revision No. : 1
Report Date : 01 August, 2023
Supervisor No. : 0001-001

Analysis Report

Client Name : Myanmar Water International (MWTI)
Address : No. 30/4, 1st Floor, Grand One Sam Commercial, 9th, New Road, Tachin Township, Yangon, Myanmar
Project Name : Environment Monitoring report for Zarka A & B
Sample Description :
Sample Name : RW1 CW-2 (SB)
Sample No. : 01200001
Sample Profile No. :
Sampling Date : 8 August, 2023
Sampling By : Customer
Sample Received Date : 8 August, 2023
Analysis Date : 8-11-08-2023

No.	Parameter	Method	Unit	Result	LOQ
1	PH	APHA 2140 (25°C at 175-100°C Method)	mg/l	7	
2	DOC (C)	APHA 5210 (C) (Ascar 6000 Test)	mg/l	7.80	0.30
3	DOC (O)	APHA 5210 (C) (Ascar 6000 Test)	mg/l	11.2	0.1
4	Oil and Grease	APHA 5420B (Petroleum-Oxidation Method)	mg/l	<3.1	0.1
5	Copper	APHA 2110 (Spectrophotometric Method)	mg/l	26.00	0.01
6	Total Nitrogen	APHA 4500-N (C) (Nesslerized Ammonia Method)	mg/l	<0.1	0.01
7	Total Phosphorus	APHA 4500-P (C) (Molybdenum Blue Method)	mg/l	0.00	0.01
8	TSS	APHA 2540 (C) (Total Suspended Solids (TSS) at 100°C Method)	mg/l	0.00	
9	Electron	APHA 1110 (C) (Inductively Coupled Plasma (ICP) Method)	mg/l	41.00	0.001
10	Mercury	APHA 1631 (C) (Inductively Coupled Plasma (ICP) Method)	mg/l	40.00	0.001
11	Iron	APHA 1020 (C) (Inductively Coupled Plasma (ICP) Method)	mg/l	1.30	0.001
12	Total Calcium	APHA 2200 (C) (Standard Total Calcium Determination Technique)	mg/100ml	23.6	1.0
13	Sulfate	APHA 1020 (C) (Inductively Coupled Plasma (ICP) Method)	mg/l	1	0
14	Escherichia Coli	APHA 9223 (C) (Membrane Filter Technique Using Fluorogenic Substrate)	MPN/100ml	<1.0	1.0

Remark : LOQ : Limit of Quantitation
APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 21st ed. 2011.

Analysed By :

No. 11 Ave Lab
Manager



Approved By :

Aug 21, 2023
Manager

Report generated by the system on 08/11/2023 at 10:00 AM
The results shown on this report are the results of the analysis performed by the laboratory and are not a guarantee of the quality of the sample or the results of the analysis.



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(နှစ်လတစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ အောက်တိုဘာလ
မြန်မာ့အံ့အင်တာနေရှင်နယ်လီမိတက်



မာတိကာ

အခန်း ၁ နိဒါန်း	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်	၁
အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း	၃
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်	၄
၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း	၆
၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ	၇
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၇
အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ	၁၃
နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဇာတ်ပုံများ	က၁-၁
နောက်ဆက်တွဲ ၂ မာတ်ခွဲခန်းရလဒ်များ	က၂-၁

ဇယားများစာရင်း

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၃
ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ	၄
ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ	၆
ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်	၇
ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း	၇
ဇယား ၂.၅-၁ ဇွန်ထုတ်ရေထွက်ပေါက်နှင့်ဇွန်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၉
ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်	၁၀

ပုံများစာရင်း

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်ရေနမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ ...	၂
--	---



အခန်း ၁ နိဒါန်း

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ ဧကီမူမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်း နှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကိုသိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအား ရေနမူနာရယူရာတွင် သီလဝါအထူးစီးပွားရေးဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ စုစုပေါင်းနေရာ လေးနေရာ၊ နာမည်အားဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တို့တွင် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ) လှုပ်ငန်းလည်ပတ်နေသည့်ကာလတွင် အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ တောင်ဘက်နယ်နိမိတ်အနီး ဖလမ်းကျွေရွာတွင်တည်ရှိသော ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းရှိ ရေတွင်းအားရည်ညွှန်းနိုင်ရန် စောင့်ကြည့်လေ့လာခဲ့သည်။ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသော နေရာများ၏ တည်နေရာများကို ပုံ ၁.၁-၁ တွင် ဖော်ပြထားပါသည်။





မှတ်စု: ရုပ်ပုံအမှတ်

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ

အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသောနေရာများနှင့် ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters)ကို ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းဆိုင်ရာ အစီအရင်ခံစာပါ ပတ်ဝန်းကျင်ဆိုင်ရာ စောင့်ကြည့်လေ့လာမှု အစီအစဉ်အား ခြုံငုံမိစေရန်အလို့ငှာ ဆောင်ရွက်ထားပါသည်။

ရေအရည်အသွေးနမူနာစစ်တမ်းရယူမှုအား နေရာလေးနေရာတွင် ဆောင်ရွက်ခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ ရေစီးဆင်းမှုတိုင်းတာခြင်းကို ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာနိုင်သော နေရာနှစ်နေရာ ဖြစ်သည့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) တို့တွင် တိုင်းတာခဲ့ပါသည်။ သို့သော်လည်း ရေတံခါးများ ပိတ်ထားသောကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7)တွင် ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာခဲ့ခြင်း မလုပ်ခဲ့ပါ။ စောင့်ကြည့်လေ့လာသော ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters) နှင့် ရေနမူနာရယူသောနေရာများကို ဇယား ၂.၁-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူ သည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁	ရေအပူချိန် (Water Temperature)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၂	ရည်ပန်ကိန်း (pH)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၃	လျော်ဂင်အောက်စီဂျင် (DO)	၀	၀	၀	၀	ရေနမူနာရယူသည့်နေရာ တွင်တိုက်ရိုက်တိုင်းတာ ခြင်း
၄	ဆိုင်ကြွယ်မှုများ (Suspended Solids)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၅	အီလက်ထရိုနစ် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၆	ဓာတ်အုတ်ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၇	အရောင် (Color)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၈	အနံ့ (Odor)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၉	ဆီနှင့်အမဲဆီ (Oil and Grease)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း
၁၁	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	၀	၀	၀	၀	ဓာတ်ခွဲစမ်းသပ်ခြင်း

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	မှတ်ချက်
၁၂	ကိုလီဖောင်းနုစုပေါင်း (Total Coliform)	•	•	•	•	စာတံခွဲစမ်းသပ်ခြင်း
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	•	•	•	•	စာတံခွဲစမ်းသပ်ခြင်း
၁၄	သံဓာတ် (Iron) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	•	•	•	•	စာတံခွဲစမ်းသပ်ခြင်း
၁၅	မြွေဓာတ် (Mercury) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	•	•	•	•	စာတံခွဲစမ်းသပ်ခြင်း
၁၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား (Escherichia Coli) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	•	•	•	•	စာတံခွဲစမ်းသပ်ခြင်း
၁၇	စီးဆင်းနှုန်း (Flow Rate)	•	•	•	•	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း

မှတ်ချက်။ ပြန်မာသို့အံအင်တာနေရှင်နယ်လီမီတာကို

၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်

ရေနမူနာရယူသည့်နေရာများကို ဇယား ၂.၂-၁ တွင် ဖော်ပြထားပါသည်။ ရေနမူနာရယူသည့်နေရာ တစ်ခုစီတွင် စစ်တမ်းရယူခဲ့သည့်မှတ်တမ်းပုံများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားသည်။

ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ

စဉ်	တည်နေရာ	အသေးစိတ်အချက်အလက်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ကိုညွှန်နီတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၈' ၂၀.၆၉"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၈.၈၄" တည်နေရာ - ရွှေပျောက်ချောင်းအထက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ကိုညွှန်နီတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၄၂.၈၄"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၆' ၂၇.၄၂" တည်နေရာ - ရွှေပျောက်ချောင်းအောက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ကိုညွှန်နီတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၈' ၁၃.၂၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၅.၆၆" တည်နေရာ - ရွှေပျောက်ချောင်းသို့ မရောက်မီ နန့် အပိုင်း (ခ)၏ ရေတိမ်ကန်ရှိ ထွက်ပေါက် ရေနမူနာရယူသော အမျိုးအစား - ခွံန့်ထုတ်ရေရယူခြင်း
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (GW-2)	ကိုညွှန်နီတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၂၅.၃၈"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၅.၆၀" တည်နေရာ - မလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝဏီအတွင်း ရေနမူနာရယူသော အမျိုးအစား - မြေအောက်ရေရယူခြင်း

မှတ်ချက်။ ပြန်မာသို့အံအင်တာနေရှင်နယ်လီမီတာကို



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)အား ရွှေပျောက်ချောင်း၏ အထက်ပိုင်းတွင် ရယူခဲ့ခြင်းဖြစ်သည်။ အဆိုပါအမှတ်သည် ဇုန်အပိုင်း(ခ)ဧရိယာ၏ အရှေ့မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနောက်မြောက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့က အသီးသီး ဝန်းရံလျက် ရှိသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

ပြည်တွင်းစက်မှုဇုန်၊ သီလဝါ ဇုန်အပိုင်း(က) နှင့် ဇုန်အပိုင်း(ခ)ရှိ လုပ်ငန်းခွင်များမှ စွန့်ထုတ်လိုက်သောရေများပေါင်းစည်းရောနှောသွားသောနေရာ ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရယူခဲ့ခြင်းဖြစ်သည်။ ရွှေပျောက်ချောင်းသည် အရှေ့မှအနောက်သို့စီးဆင်းပြီး ရန်ကုန်မြစ် အတွင်းသို့ စီးဝင်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) သည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ချောင်းအောက်ပိုင်း ၂.၁၅ ကီလိုမီတာအကွာတွင် တည်ရှိပါသည်။ အဆိုပါ ရေနမူနာရယူသည့်နေရာသည် ဇုန်အပိုင်း(ခ) ဧရိယာ၏ အနောက်ဘက်တွင်တည်ရှိပြီး ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင်တည်ရှိပါသည်။ ပတ်ဝန်းကျင်အနီးအနားတွင် အရှေ့မြောက်ဘက်တွင် ဇုန်အပိုင်း (က)၊ အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်၊ တောင်ဘက်နှင့် အနောက်ဘက်တို့တွင် ပေါင်းခင်းတို့ အသီးသီးတည်ရှိပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) (စွန့်ထုတ်ရေထွက်ပေါက်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထိုနေရာသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ချောင်းအောက်ပိုင်း၊ အကွာအဝေးအားဖြင့် ၄၃၄ မီတာ အကွာတွင် တည်ရှိပါသည်။ နမူနာရယူသည့်နေရာမှာ ဇုန်အပိုင်း(ခ) ရေထိန်းကန်၏ထွက်ပေါက်၊ ဇုန်အပိုင်း(ခ) ဧရိယာ၏ မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်းမကြီး၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) (မူလတည်ရှိနေသောရေတွင်းအား ရည်ညွှန်းခြင်း)

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား တူးဖော်ထားသောရေတွင်းမှ ရယူခဲ့ပါသည်။ အဆိုပါ ရေတွင်းသည် ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းတွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (က)၊ တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ၊ အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်နှင့် အရှေ့နှင့်အရှေ့မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ)တို့ အသီးသီးတည်ရှိနေပါသည်။



၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ရေနမူနာများကို ရယူပြီး သန့်စင်ထားသောဖန်ပုလင်းညှို့များဖြင့် သိမ်းဆည်းပြီး နောက် ၂.၃-၁ တွင် ဖော်ပြထားသော နည်းလမ်းများဖြင့် စာတံခွဲခန့်၌ စစ်ဆေးပါသည်။ ရေနမူနာများကို ရေခဲပုံးများဖြင့် ၂-၄ ဒီဂရီ ဆဲလ်စီးယပ်တွင် သိမ်းဆည်းထားပြီး စာတံခွဲခန့်သို့ ပို့ဆောင်ပါသည်။ တိုင်းတာသည့် ရေအရည်အသွေး အမျိုးအစားများ၌ ရေအပူချိန်၊ ချဉ်ဖန်ကိန်း နှင့် ပျော်ဝင်အောက်စီဂျင်တို့အား ရေအရည်အသွေး တိုင်းတာသောစက်ကီရိယာ (Horiba U-52) ကို အသုံးပြု၍ ရေနမူနာရယူသည့်နေရာ၌ပင် တိုက်ရိုက်တိုင်းတာခဲ့ပါသည်။ ထို့အပြင်ရေစီးဆင်းမှုနှုန်းကိုလည်း ဒီဂျစ်တယ်ရေစီးနှုန်းတိုင်းကီရိယာ (JFE Digital Current Meter) ဖြင့် ရေနမူနာရယူသည့်နေရာ၌ တိုင်းတာခဲ့ပါသည်။

ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁	ရေအပူချိန် (Water Temperature)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၂	ချဉ်ဖန်ကိန်း (pH)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၄	ဆိုင်ကြွေအနယ် (Suspended Solids)	APHA 2540 D (Dry at 103-105°C Method)
၅	နီမနည်ဖြင့်ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	APHA 5210 B (5 Days BOD Test)
၆	ဓာတ်နည်ဖြင့်ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	APHA 5220D (Close Reflux Colorimetric Method)
၇	အရောင် (Color)	APHA 2120C (Spectrophotometric Method)
၈	အနံ့ (Odor)	APHA 2150 B (Threshold Odor Test)
၉	ဆီနှင့် အမဲဆီ (Oil and Grease)	APHA 5520B (Partition-Gravimetric Method)
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	HACH Method 10072 (TNT Persulfate Digestion Method)
၁၁	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	APHA 4500-P E (Ascorbic Acid Method)
၁၂	ကိုလီဖော့မ်း စုစုပေါင်း (Total Coliform)	APHA 9221B (Standard Total Coliform Fermentation Technique)
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
၁၄	သံဓာတ် (Iron)	APHA 3120 B [Inductively Coupled Plasma (ICP) Method]
၁၅	ပြွေးဓာတ် (Mercury)	APHA 3120 B [Inductively Coupled Plasma (ICP) Method]
၁၆	ခမ်းကိုက်ရောဂါကိုဖြစ်စေသော ဘက်တီးရီးယား (Escherichia Coli)	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

ခရိုင်၊ မြို့နယ်နှင့်အင်တာနေရှင်နယ်ကီတက်

၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ

ရေအရည်အသွေးနှင့် ရေစီးဆင်းမှုနှုန်း စောင့်ကြည့်လေ့လာမှုအား အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် ဆောင်ရွက်ခဲ့ပြီး ဒီရေအောက်အကျကြောင့် ဖြစ်ပေါ်လာနိုင်သော သက်ရောက်မှုများကိုရှောင်ရှားနိုင်ရန် အောက်ပါ ဇယား ၂.၄-၁ အတိုင်း ရေစန့်မှုနာရယူခဲ့သည်။ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ် အတွက်ဒီရေ မှတ်တမ်းကို ဇယား ၂.၄-၂ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်

စဉ်	ရေစန့်မှုနာရယူသည့်နေရာ	ရေစန့်မှုနာရယူသည့်အချိန်
၁	မြေပေါ်ရေစန့်မှုနာရယူသည့် နေရာ-၂ (SW-2)	အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၃ နာရီ : ၂၅ မိနစ်)
၂	မြေပေါ်ရေစန့်မှုနာရယူသည့် နေရာ-၄ (SW-4)	အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၃ နာရီ : ၅၁ မိနစ်)
၃	မြေပေါ်ရေစန့်မှုနာရယူသည့် နေရာ-၇ (SW-7)	အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၉ နာရီ : ၄၄ မိနစ်)
၄	မြေအောက်ရေစန့်မှုနာရယူသည့် နေရာ-၂ (GW-2)	အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၉ နာရီ : ၁၂ မိနစ်)

မှတ်။ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်တိမ်တက်

ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

ရက်စွဲ	အချိန်	ထမြင့်	ဒီရေအခြေအနေ
အောက်တိုဘာလ ၂၄ ရက်နေ့ ၂၀၂၃ ခုနှစ်	၀၈:၁၇	၄.၇၃	ဒီရေအောက်
	၀၇:၂၁	၁.၉၆	ဒီရေအကျ
	၁၂:၃၇	၄.၈၅	ဒီရေအောက်
	၂၀:၀၉	၁.၃၂	ဒီရေအကျ

မှတ်။ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်တိမ်တက်၊ ၂၀၂၃ ခုနှစ်အတွက် ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စွန့်ထုတ်ရေထွက်ပေါက်၊ စွန့်ထုတ်ရေရောက်ရှိသောချောင်းနှင့် ရည်ညွှန်းရေတွင်းရှိ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားသည်။ ဓာတ်ခွဲခန်းဆန်းစစ်မှု ရလဒ်များကို နောက်ဆက်တွဲ-၂ တွင် ဖော်ပြထားသည်။ ရလဒ်များကို ပတ်ဝန်းကျင်ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသည့် ရေအရည်အသွေး ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ထားပါသည်။

၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိရလဒ်များ

ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ဆိုင်းကြွအနယ်များ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

စွန့်ထုတ်ရေထွက်ပေါက်ရှိ ရေအရည်အသွေးရလဒ်များ

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ စွန့်ထုတ်ခင် ဇန်နဝါရီလ(ခ)၏ အဓိက စွန့်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေစန့်မှုနာရယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများကျင်လည် ကျက်စားခြင်းကြောင့် ဇန်နဝါရီလ(ခ) အတွင်းရှိမြေများတွင် သဘာဝမှ ဘက်တီးရီးယားများပါဝင်ပြီး အထူးသဖြင့် တိရစ္ဆာန်များထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း နှင့် မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် ပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည်

ရေထိန်းကန်ထဲသို့စီးဝင်စေပြီး၊ ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး ကိုလီဖောင်းစုစုပေါင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား ဓာတ်ခွဲစမ်းသပ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli) ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

စောင့်ကြည့်လေ့လာသည့်ရည်ညွှန်းအမှတ်များ၏ရေအရည်အသွေးရလဒ်များ(စွန့်ထုတ်ရေရောက်ရှိသောချောင်း)

ဆိုင်းကြံအနည် ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) သဘာဝအလျှောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးစနစ် ပြင်ပရှိ ပြည်တွင်းစက်မှုစနစ်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့် လည်းကောင်း၊ (၂) ရွှေပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအောက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်းနှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များမှ ထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) မိုးသည်ထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများကို ရွှေပျောက်ချောင်းသို့ ရောက်ရှိစေနိုင်ပြီး၊ ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေပျောက်ချောင်းတလျှောက် တီးဝင်လာသောဒီရေများတွင် ပါရှိလာနိုင်သောအညစ်အကြေးများ ပါဝင်နိုင်ခြင်းကြောင့်လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါအထူးစီးပွားရေးစနစ်၏ ပတ်ဝန်းကျင်ရှိတောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသော မြေဆီလွှာ(ဂစ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေနှိမ့်ပိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။



ဇယား ၂-၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ရောင်းမှရေအရည်အသွေး
စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	ရည်မှန်းချက် (ကိုယ်လုံး စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၃၀	၃၀	၂၉	≤ ၃၅
၂	ဆွပ်ဖန်ကိန်း(pH)	-	၆.၆	၆.၉	၇.၂	၆ - ၉
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/l	၃.၃၉	၄.၃၃	၆.၈၁	-
၄	ဆိုင်ကြဲအနယ် (Suspended Solids)	mg/l	၃၀	၁၀၂	၃၈	၅၀
၅	စီဝန်ညှပ်ဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ခုက်) (BOD ₅)	mg/l	၅.၈၆	၄.၁၁	၅.၄၄	၃၀
၆	ဆာပွန်ဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	mg/l	၁၃.၃	၉.၆	၄.၄	၁၂၅
၇	အရောင် (Color)	TCU (True Color Unit)	၁၉.၁၅	၁၃.၉၄	၃.၇၅	၁၅၀
၈	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	၁	၁	-
၉	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/l	< ၃.၁	< ၃.၁	< ၃.၁	၁၈
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/l	၁.၈	< ၀.၅	< ၀.၅	၈၀
၁၁	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/l	၀.၂၅	၀.၁၆	၀.၀၅	၂
၁၂	ကိုလီဖောင်း ဓုစုပေါင်း (Total Coliform)	MPN/100ml	၃၅၀၀၈.၀	၁၄၀၀၀.၀	၂၈၀၀၀.၀	၄၀၀
၁၃	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	mg/l	၉၆	၁၁၂	၈၀	၂၀၀၀
၁၄	သံမဏိ (Iron)	mg/l	၂.၀၆၀	၁၂.၈၆၀	၂.၂၇၀	၃၅
၁၅	မြွှာမဏိ (Mercury)	mg/l	၄၀.၀၀၂	၄၀.၀၀၂	၄၀.၀၀၂	၀.၀၀၅
၁၆	ရက်စက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်း ထက်ဝီရီးယား (Escherichia Coli)	MPN/100ml (SW)	-	-	၈.၃	(၁၀၀၀)* (CFU/၁၀၀ml)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	m³/s	၀.၁၉	၀.၃၁	-	-

မှတ်ချက်၊ အစီရင်ခံစာပြုစုထားသောတန်ဖိုးများသည်သတ်မှတ်ထားသည့်တန်ဖိုးများထက်ကျော်လွန်နေသည်ကိုဆိုလိုပါသည်။
 *မှတ်ချက်၊ နမူနာတိုက်ရိုက်စစ်ဆေးမှုရလဒ်များကို အသုံးပြုမူဝါဒတည်၍ ရှုမနီဒီဇ၏ ချိုးချစ်ချိန်စံနှုန်း၊ ပတ်ဝန်းကျင်ဆိုင်ရာစံကြမ်း(၁၊ ၁၉၉၅)ကို ဝေဖန်ကော်မရှင်ကော်မရှင်စေသော ကိုလီဖော်နီးယားတိုက်တီယား(E.coli)၏ ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ထားပါသည်။ သို့သော်လည်း မြန်မာနိုင်ငံရှိ ဓာတ်ခွဲခန်းများ၏ လုပ်ဆောင်နိုင်မှု ကန့်သတ်ချက်များကြောင့် စီအက်ဂီယူတန်ဖိုး "Colony Forming Unit (CFU)" အား တိုင်းတာချိန်မှစ၍ ထို့ကြောင့် အမိမိအန့် "Most Probable Number (MPN)" ရလဒ်များကို စီအက်ဂီယူတန်ဖိုးနှင့် တူညီသည်ဟုယူဆပြီး ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ပါသည်။ မြန်မာနိုင်ငံတွင် စီအက်ဂီယူတန်ဖိုးကို သုံးသပ်နိုင်သည်နှင့် တစ်ပြိုင်နက် သုံးသပ်သည့်နည်းလမ်းများ ပြောင်းလဲမည်ဖြစ်သည်။
 *မှတ်ချက်၊ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်ဝယ်မီတာ

၂.၅.၂ ရည်ညွှန်းရေတွင်း၏ ရလဒ်

ရည်ညွှန်းရေတွင်းစောင့်ကြည့်လေ့လာသောနေရာ၌ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရလဒ်များကို ဇယား ၂.၅-၂ တွင်ဖော်ပြထားသည်။ ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာတွင် သံဓာတ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင် ၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဩဂုတ်လ၊ ၂၀၂၂ခုနှစ် တွင် ၉.၁၈၂ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ ၂၀၁၉ခုနှစ်၊ မော်မော်တီရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍ သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ အောက်တိုဘာလ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှဲစားမှု၊ ကြောင့်ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂစ်မြေ)ဖြင့် အဓိကစွဲစည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေနှိမ့်ဝိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၂၈	≤ ၃၅
၂	ချဉ်ဖန်ကိန်း (pH)	-	၆.၈	၆-၉
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/l	၆.၇၅	-
၄	ဆိုင်ကြွအနယ် (Suspended Solid)	mg/l	၂	၅၀
၅	စီစနည်းဖြင့် ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	mg/l	၃.၇၆	၃၀
၆	ဓာတ်နည်းဖြင့် ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{Cr})	mg/l	၁၀.၇	၁၂၅
၇	အရောင် (Color)	TCU (True Color Unit)	၃၉.၆၉	၁၅၀



သီလဝါအသွေးစီးပွားရေးနှင့်ဆိုင်ရာ(ခ)မြို့စက်မှုနှင့်မြို့ပြတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း အောက်တိုဘာလ ၂၀၂၃ ခုနှစ်)

ရက်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၈	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	-
၉	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/l	၁၃.၁	၁၀
၁၀	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/l	၁၀.၅	၈၀
၁၁	ဖော့စဖောရပ်စ်စုစုပေါင်း (Total Phosphorus)	mg/l	၀.၆၂	၂
၁၂	ကိုလီဖောင်းစုစုပေါင်း (Total Coliform)	MPN/100ml	၆.၁	၄၀၀
၁၃	ပျော်ဝင်အရည်စုစုပေါင်း (Total Dissolved Solids)	mg/l	၂၀၀	၂၀၀၀
၁၄	သံဆာတ် (Iron)	mg/l	၇.၇၅၀	၃.၅
၁၅	ပြဒါးဆာတ် (Mercury)	mg/l	၁၀.၀၀၂	၀.၀၀၅
၁၆	ဝမ်းကွဲကိရောက်(ကိုဖြစ်စေသော)ကိုလီဖောင်း ဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml	၂.၀	(၁၀၀)* (MPN/100ml)
၁၇	စီးဆင်းနှုန်း (Flow Rate)	m ³ /s	-	-

မှတ်ချက်: အနီရောင်ဖြင့်ဖော်ပြထားသောတန်ဖိုးများသည် သတ်မှတ်ထားသည့်တန်ဖိုးများထက်အလွန်နိမ့်နေသည်ကိုဆိုလိုပါသည်။

*မှတ်ချက်: မြေအောက်ရေစောင့်ကြည့်လေ့လာသောနေရာတွင် ရေအသုံးပြုမှုပေါ်မူတည်၍ နိမ့်ကျနေနိုင်ပါသည်။ မြေအောက်ရေအရည်အသွေးတိုင်ရာ အမျိုးအစားနှင့်လည်းကောင်း၊ ဗီ (ဆည်ပြင်အရ) (No. QCVMB: 2003/STNMT) ကိုမြေအောက်ရေကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ပါသည်။

မှရင်း၊ မြန်မာ့သမ္မတနိုင်ငံတော်နေ့ရက်နယ်လီမီတာက

၂၅-၃ ယခင်စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှင့် ၂၀၂၃ ခုနှစ် အောက်တိုဘာလ တွင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ ၏ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ အရည်အသွေးများ နှိုင်းယှဉ်ခြင်း

ယခု စောင့်ကြည့်လေ့လာနေစဉ်ကာလ (အောက်တိုဘာ ၂၀၂၃) အတွင်း ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ အရည်အသွေးများအား မြိုင်သုံးသပ်ကြည့်ရန်အတွက် ၂၀၂၂ ခုနှစ် အောက်တိုဘာလ ကတည်းကရရှိသော စောင့်ကြည့်မှုရလဒ်များနှင့် နှိုင်းယှဉ်ထားပါသည်။

စွန့်ထုတ်လိုက်သောနေရာများ၏ ရေအရည်အသွေးရလဒ်များနှင့် ပတ်သက်၍ စောင့်ကြည့်ရာတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် မေမော်ဝါရီလ၊ ဇွန်လ၊ ဩဂုတ်လ နှင့် အောက်တိုဘာလ ၂၀၂၃ တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် ၂၃၀၀ MPN/၁၀၀ml မှ စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀၀ MPN/၁၀၀ml)ထိ ရှိပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ် တန်ဖိုးသည် မိုးရာသီအစနှင့် အလယ်တွင် စမ်းသပ်နိုင်သောပမာဏ ထိ သိသာထင်ရှားစွာ မြင့်မားနေပြီး စီးဆင်းရေ၏ သက်ရောက်မှုကြောင့် ဖြစ်နိုင်သည်ဟု သုံးသပ်ရပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ သံဆာတ်တန်ဖိုးသည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍ စစ်တမ်းကောက်ယူထားသော ကျန်လများအားလုံးသည် ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေပါသည်။



မြေအောက်ရေနေမှုနာယူသည့် နေရာ-၂ (GW-2) ၏ သံဓာတ်တန်ဖိုးသည် မိုးရာသီ နှင့် ဆောင်းရာသီ တလျှောက်လုံးတွင် မြင့်မားနေသည်ကို သိသိသာသာတွေ့မြင်ရပါသည်။

အခြားတစ်ဖက်တွင် မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4)တို့ရှိ ရလဒ်အချို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) ၏ ဆိုင်းကြွအနည်ရလဒ်သည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍ စစ်တမ်းကောက်ယူထားသော ကျန်လများတွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပြီး၊ ၇၈ မှ ၅၀၂ mg/l လီတန်ဖိုးအပိုင်းအခြား အတွင်းရှိနေပါသည်။ မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) တွင်ရှိသော ဆိုင်းကြွအနည်ရလဒ်များသည် မိုးရာသီအတွင်း ပတ်ဝန်းကျင်မှရေများ စီးဆင်းမှုကြောင့် ရလဒ်များ မြင့်တက်နေခြင်းဖြစ်သည်။ မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးသည် စောင့်ကြည့်လေ့လာနေသော ကာလ(၅)လ (အောက်တိုဘာလ၊ ဒီဇင်ဘာလ ၂၀၂၂ နှင့် ဇွန်လ၊ ဩဂုတ်လ၊ အောက်တိုဘာလ ၂၀၂၃) တွင် မြင့်မားနေပြီး၊ သံဓာတ်တန်ဖိုး အပိုင်းအခြားသည် ၄၃၇၆ မှ ၂၂၆၂၆ mg/l အတွင်းရှိပါသည်။ မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးမြင့်မားမှုသည် မိုးရာသီ တလျှောက်လုံးမှ ဆောင်းရာသီအစတိုင်အောင် ဖြစ်ပေါ်နေကြောင်း တွေ့ရှိရသည်။ သိသာထင်ရှားစွာဖြင့် မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၂ (SW-2)၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှုစစ်တမ်း (၇)လအနက် (၆)လသည် (၁၃၀၀မှ >၁၆၀၀၀၀ MPN/100ml အပိုင်းအခြားအတွင်း) ရလဒ်တန်ဖိုးထက် မြင့်နေပြီး မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှု ကာလအားလုံးတွင် (၄၆၀၀ မှ >၁၆၀၀၀၀ MPN/100ml အပိုင်းအခြားအတွင်း) ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေကြောင်း တွေ့ရှိရသည်။ အထူးသဖြင့် မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၂ (SW-2)၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် ဇွန်လ ၂၀၂၃ တွင် စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀၀ MPN/100ml) ထိရောက်ရှိခဲ့ပြီး မြေပေါ်ရေနေမှုနာယူသည့် နေရာ-၄ (SW-4) ၏ ကိုလီဖောင်း စုစုပေါင်းရလဒ်များသည် အောက်တိုဘာလ ၂၀၂၂ နှင့် ဇွန်လ ၂၀၂၃ တို့တွင် စမ်းသပ်နိုင်သောပမာဏသို့ အသီးသီး ရောက်ရှိခဲ့ပါသည်။ ယခုလက်ရှိ ရေအရည်အသွေးများ၏ ရလဒ်များအခြေအနေသည် သီလဝါအထူးစီးပွားရေးဇုန် ယခင်နှင့်ယခုလက်ရှိကာလ လည်ပတ်မှု၏ ပတ်ဝန်းကျင်အခြေအနေများကို ထင်ဟပ်နေသည်ဟု ဆိုနိုင်ပါသည်။

ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည့် သက်ဆိုင်ရာရေအရည်အသွေးအမျိုးအစားများအတွက် ဖြစ်နိုင်သော အကြောင်းပြချက်များအား ဤ အစီရင်ခံစာ၏ အရှေ့ပိုင်းရင်းလင်းချက်တွင် ဖော်ပြထားပါသည်။



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

အခန်း ၂ (အပိုင်း ၂.၅) တွင်ဖော်ပြထားသကဲ့သို့ သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ် ကာလ စောင့်ကြည့်လေ့လာသောအချိန်အတွင်း မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ဆိုင်းကြွအနည်းများ နှင့် သံဓာတ်များ၊ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တွင် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိက စွန့်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများကျင်လည် ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ) အတွင်းရှိမြေများတွင် သဘာဝမှ ဘက်တီးရီးယားများပါဝင်ပြီး အထူးသဖြင့် တိရစ္ဆာန်များထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း နှင့် မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် ပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည် ရေထိန်းကန်ထဲသို့ စီးဝင်စေပြီး ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး စုစုပေါင်းကိုလီဖောင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား ဓာတ်ခွဲခန်းသစ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်း စုစုပေါင်း၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ဆိုင်းကြွအနည်း နှင့် သံဓာတ် တို့၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များထွက်ရှိသော စွန့်ပစ် အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) မိုးသည်းထန်စွာရွာသွန်းခြင်းနှင့် စီးဆင်းရေများသည် အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများကို ရွှေ့ပျောက်ချောင်သွှေချောက်ရှိစေနိုင်ပြီး ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေ့ပျောက်ချောင်းတလျှောက် တိုးဝင်လာသောဒီရေများတွင် ပါရှိလာနိုင်သောအညစ်အကြေးများ ပါဝင်နိုင်ခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ဆိုင်းကြွအနယ်၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ (၁) သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သောရေများကြောင့်လည်းကောင်း၊ (၂) ရွှေပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် သံဓာတ် ၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ သံဓာတ်အရင်းအမြစ်၏ လွှမ်းမိုးမှုကြောင့် ဖြစ်နိုင်ပြီး (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှထွက်လာနိုင်ပါသည်) ပတ်ဝန်းကျင်ရှိတောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသော မြေဆီလွှာ(ဂရပ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုခိုဝိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင် ၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဩဂုတ်လ၊ ၂၀၂၂ခုနှစ် တွင် ၉.၁၈၂ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ ၂၀၁၉ခုနှစ်၊ ဖော်ဖော်ဝါရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍ သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ အောက်တိုဘာလ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု ကြောင့်ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂရပ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုခိုဝိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

အနာဂတ်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ၏ အဓိကစွန့်ထုတ်ရေ ထွက်ရှိသောနေရာများမှ ထွက်ရှိလာသော ရေအရည်အသွေးများဖြစ်သည့် ကိုလီဖောင်းစုစုပေါင်း၏ သင့်တော်သော ရည်မှန်းအဆင့် ရရှိနိုင်ရန် အောက်ပါဆောက်လုပ်ချက်များကို လုပ်ဆောင်သင့်ပါသည်။

- ကိုလီဖောင်းဘက်တီးရီးယားများ၏ ကျွန်းမာရေးအပေါ်သက်ရောက်မှုကို သိရှိနိုင်ရန် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E. Coli) ကိုဆက်လက်စောင့်ကြည့်ရန် လုပ်ဆောင်သင့်ပါသည်။

ဤတွင်စာတမ်းပြီးဆုံးပါသည်။



နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဇယားများ



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ရှိ စက်မှုဇုန်အရေအတွက်ယူသည့်နေရာ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏ အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

နောက်ဆက်တွဲ ၂ ဓာတ်ခွဲခန်းရလဒ်များ



စွန့်ထုတ်ရေတွက်ရှိရာနေရာ

၀၀၀၀၀၀

100% (100% of the total sample size)
100% (100% of the total sample size)



Report No. : 001-001-001-001
Report No. : 1
Report Date : 7 November, 2023
Application No. : 001-001

Analysis Report

Client Name : Myanmar Steel International LTD (MSI)
Address : No. 30A, 1st Floor, Central Myanmar Cement, Phaw-San Road, Dagon Township, Yangon Region
Project Name : Environmental Monitoring report for Steel & S.S.
Sample Description :
Sample Name : MS-001-001
Sample No. : 001-001-001
Water Matrix No. :
Sampling Date : 24 October, 2023
Sampling By : Customer
Sample Received Date : 24 October, 2023
Analysis Date : 04/11/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2550C (25°C at 100-110°C Method)	mg/L	7.0	...
2	DO (%)	APHA 2550C (15 Days DO Test)	mg/L	2.49	0.01
3	COO (O2)	APHA 2550C (Chemical Reflux Colorimetric Method)	mg/L	0.0	0.1
4	Oil and Grease	APHA 2550B (Petroleum Oxidation Method)	mg/L	0.1	1.1
5	Color	APHA 2150C (Spectrophotometric Method)	PCU	0.05	0.00
6	Total Nitrogen	APHA 2550C (TN Test Reflux Colorimetric Method)	mg/L	0.1	0.1
7	Total Phosphorus	APHA 2550C (Phosphomolybdate Method)	mg/L	0.05	0.05
8	TSS	APHA 2550C (TSS Gravimetric Test at 100°C Method)	mg/L	0.0	...
9	Chlorine	APHA 2550B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.000	0.001
10	Mercury	APHA 2550B (Inductively Coupled Plasma (ICP) Method)	mg/L	0.000	0.001
11	Iron	APHA 2550B (Inductively Coupled Plasma (ICP) Method)	mg/L	2.170	0.001
12	Total Carbon	APHA 2550B (Standard Total Carbon Determination Method)	mg/L	2800.0	0.0
13	Fluoride	APHA 2550B (Fluoride Ion Test)	mg/L	1	0
14	Bacterial Coli	APHA 2550B (Bacterial Coli Test Using Fluorogenic Substrate)	MPN/100mL	0.1	0.0

Remarks : LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By :

Ms. Aye Linn

Manager



Reviewed By :

Ms. Aye Linn
Manager

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)ရှိစက်မှုဇုန်၌ဖြိုတိုက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း အောက်တိုဘာလ ၂၀၂၃ ခုနှစ်)

**စွန့်ထုတ်ရေတွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏
အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ**

DISCLAIM

Lab Gem (Burma) Environmental Co., Ltd.
Unit 11, Phase(2) South Nagar Square, Myanmar
Mawbata Road, Yangon, Myanmar



Report No. : LGP-LAB-2023-1009
Revision No. : 1
Report Date : 7 November, 2023
Application No. : 2023-0701

Analysis Report

Client Name : Myanmar Gas International Ltd (MGI)
Address : No. 38/4, 1st Floor, 103rd Pho San Condominium, 103 San Road, Tumen Township, Yangon, Myanmar
Project Name : Environmental Monitoring Report for Zone A & B
Sample Description :
Sample Name : WQ GW 2 / 1009
Sample No. : W-20231009
Water Profile No. :
Sampling Date : 24 October, 2023
Sampling By : Customer
Sample Received Date : 24 October, 2023
Analytical Date : 24/10/23 (2023)

No.	Parameter	Method	Unit	Result	LOQ
1.	pH	APHA 2540 (25 ± 0.1°C, 10°C Method)	mg/L	8.0	
2.	DOC (%)	APHA 5210 (5.0 L/min, 800 °C)	mg/L	0.06	0.05
3.	DO (%)	APHA 5210 (Closed Reflux Colorimetric Method)	mg/L	11.2	0.1
4.	Oil and Grease	APHA 5520 (Petroleum-Ether Extraction Method)	mg/L	<0.1	1.4
5.	Cadmium	APHA 3120 (Spectrophotometric Method)	mg/L	0.45	0.05
6.	Total Nitrogen	NACH Method 0007 (191 Persulfate Digestion Method)	mg/L	1.8	0.05
7.	Total Phosphorus	APHA 4500 P-3 (Ascorbic Acid Method)	mg/L	0.25	0.05
8.	TSS	APHA 2540 (Total Dissolved Solids Gravimetric Method)	mg/L	58	
9.	Copper	APHA 3110 (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
10.	Mercury	APHA 3120 (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
11.	Lead	APHA 3110 (Inductively Coupled Plasma (ICP) Method)	mg/L	0.002	0.002
12.	Total Coliform	APHA 9220 (Standard Total Culture Enumeration Technique)	MPN/100ml	50000	1.4
13.	Chlorine	APHA 7110 (Diazotization Test)	TDN	1	1

Remarks : LOQ : Limit of Quantitation
APHA : American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analyst By :

R. M. Aye (Analyst)
Manager



Approved By :

R. M. Aye (Manager)
Managing Director

REMARK: This report is only for the sample submitted for analysis.
This report and sample shall not be reproduced, copied, or used without written permission of the Laboratory or the Client.



သီလဝါအထူးစီးပွားရေးဇုန်သမိုင်း (ခ) မျိုးစက်မှုဇုန်ဖြ့်ဖြူးတိုင်ဝက်မှုအတွက်ခရုအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(နှစ်လတာစံကြမ်း၊ စောင့်ကြည့်လေ့လာခြင်း အောက်တိုဘာလ ၂၀၂၃ ခုနှစ်)

EXFORM

ANALYSIS REPORT FORM (REV. 01)
ANALYSIS REPORT FORM (REV. 01)
(Form No. 1 (Rev. 01) (2023))



Report No. : GPM-LAB-2023-1020
Revision No. : 1
Report Date : 7 November, 2023
Registration No. : 0011-C081

Analysis Report

Client Name : Myanmar Gas International LTD (MGIL)
Address : Bldg. 38/A, 1st Floor, Grand Phaya-Son Condominium, Phaya-Son Road, Tamarine Compound, Yangon, Myanmar
Project Name : Environmental Monitoring Report for Zone A & B
Sample Description :
Sample Name : MB-C08-2-1020
Sample No. : 20231019
Water Profile No. :
Sampling Date : 04 October, 2023
Sampling By : Customer
Sample Received Date : 04 October, 2023
Analysis Date : 04/10/2023-17/10/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	2	
2	BOD (5)	APHA 5211 B (5 Days BOD Test)	mg/l	0.76	0.04
3	COD (Cr)	APHA 5101D (Open Reflux Titrimetric Method)	mg/l	40.7	0.7
4	Oil and Grease	APHA 5530B (Petroleum Oxidation Method)	mg/l	4.3	0.1
5	Color	APHA 2130C (Spectrophotometric Method)	PCU	99.69	0.01
6	Total Nitrogen	ISO 15705 Method 3B01 (NBT Phenyl-Hypodiazotization Method)	mg/l	40.5	0.5
7	Total Phosphorus	APHA 4500-P T (Ascorbic Acid Method)	mg/l	0.62	0.05
8	TDS	APHA 2540 C (Total Dissolved Solids Gravimetric Method)	mg/l	238	
9	Chloride	APHA 3120 B (Mercurimetric Coupled Plasma (ICP) Method)	mg/l	20.363	0.001
10	Mercury	APHA 3120 B (Mercurimetric Coupled Plasma (ICP) Method)	mg/l	20.300	0.001
11	Iron	APHA 3120 B (Mercurimetric Coupled Plasma (ICP) Method)	mg/l	1.350	0.001
12	Total Calcium	APHA 9220A (Standard Total Calcium Determination Technique)	mg/100ml	8.1	1.0
13	Dissolved Oxygen	APHA 9140 B (Hach-DREL/2000 DO Method)	%	1	0
14	Escherichia Coli	APHA 9221 F Escherichia Coli Presumptive Using Membrane Filtration	MPN/100ml	2.0	1.0

Remarks : LOQ = Limit of Quantitation

APHA = American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed By

Dr. Myo Aye

Analyst



Approved By

Nov 7, 2023

Project Director

Report generated by the system. All data are subject to change without notice. The system is not responsible for any errors or omissions. The system is not a substitute for professional advice. The system is not a substitute for professional advice.



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့အံ့အင်တာနေရှင်နယ်လီမိတက်



မာတိကာ

အခန်း ၁ နိဒါန်း.....	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်	၁
အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း.....	၃
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား.....	၃
၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်.....	၅
၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း.....	၇
၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ	၉
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၉
အခန်း ၃ နီဂုံးချုပ် နှင့် အကြံပြုချက်များ.....	၁၈
နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းစာတံပုံများ	က၁-၁
နောက်ဆက်တွဲ ၂ ဇာတ်ခွဲခန်းရလဒ်များ.....	က၂-၁

ဇယားများစာရင်း

ဇယား ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား.....	၃
ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ	၅
ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ.....	၇
ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်	၉
ဇယား ၂.၄-၂ ပြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း.....	၉
ဇယား ၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၁၂
ဇယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်	၁၄

ပုံများစာရင်း

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက်ရေနမူနာရယူသောနေရာများ၏ တည်နေရာပြပုံ ...	၂
--	---



အခန်း ၁ နိဒါန်း

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်း နှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကိုသိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့်လေ့လာမှုများကို ရေဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအား ရေနမူနာရယူရာတွင် သီလဝါအထူးစီးပွားရေးဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ စုစုပေါင်းနေရာ လေးနေရာ၊ နာမည်အားဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တို့တွင် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ်ကာလတွင် အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ တောင်ဘက်နယ်နိမိတ်အနီး ဗလမ်းကျေးရွာတွင်တည်ရှိသော ဘုန်းကြီးကျောင်းပရဟိတအတွင်းရှိ ရေတွင်းအားရည်ညွှန်းနိုင်ရန် စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသော နေရာများ၏ တည်နေရာများကို ပုံ ၁.၁-၁ တွင် ဖော်ပြထားပါသည်။



သီလဝါအတွင်းလွှာအရေစုနှစ်အပိုင်း (ခ) ရှိစက်မှုစုနိမ့် ဖြစ်တိုးတက်မှုအတွက် ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း နိုဗင်ဘာလ ၂၀၂၃ ခုနှစ်)



မှတစ်ဆင့် ရုပ်ပုံအတို

ပုံ ၁.၁-၁ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအတွက် ရေစုနိမ့်စုနိမ့်သောနေရာများ၏ တည်နေရာပြပုံ

အခန်း ၂ ရေအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုအတွက် ရေနမူနာရယူသောနေရာများနှင့် ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters)ကို ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းဆိုင်ရာ အစီအရင်ခံစာပါ ပတ်ဝန်းကျင်ဆိုင်ရာ စောင့်ကြည့်လေ့လာမှု အစီအစဉ်အား ဖြည့်မီစေရန်အလို့ငှာ ဆောင်ရွက်ထားပါသည်။

ရေအရည်အသွေးနမူနာစစ်တမ်းရယူမှုအား နေရာလေးနေရာတွင် ဆောင်ရွက်ခဲ့ပါသည်။ ထိုနေရာ လေးနေရာမှ ရေစီးဆင်းမှုတိုင်းတာခြင်းကို ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာနိုင်သော နေရာနှစ်နေရာ ဖြစ်သည့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) တို့တွင် တိုင်းတာခဲ့ပါသည်။ သို့သော်လည်း ရေတံခါးများ ပိတ်ထားသောကြောင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၇ (SW-7) တွင် ရေစီးနှုန်းတိုင်းကိရိယာဖြင့် တိုင်းတာခဲ့ခြင်း မလုပ်ခဲ့ပါ။ စောင့်ကြည့်လေ့လာသော ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ(Parameters) နှင့် ရေနမူနာရယူသောနေရာများကို စာယာ ၂.၁-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။

စာယာ ၂.၁-၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစား (Parameters)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေ နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေနမူနာယူ သည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁	ရေအပူချိန် (Water Temperature)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၂	ချွပ်မန်ကိန်း (pH)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၃	ပျော်ဝင်အောက်စီဂျင် (DO)	၁	၁	၁	၁	ရေနမူနာရယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း
၄	ဆိုင်ကြွအနယ်များ (Suspended Solids)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၅	စီဝန်ညှစ်ဖြင့်ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၆	ဓာတ်နည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{cr})	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၇	ကိုလိုဖောင်းစုစုပေါင်း (Total Coliform)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၈	ဆီနှင့်အမဲဆီ (Oil and Grease)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၉	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၀	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၁	အရောင် (Color)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၂	အနံ့ (Odor)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၃	အမိုးနီးယား (Ammonia)	၁	၁	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း



သီလဝါအထူးစီးပွားရေးစနစ်သမိုင်း(ခ)စိုက်ပျိုးမှုစနစ်(ပို့ဆောင်ကုန်များအတွက်ရေးအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

စဉ်	ရေးအရည်အသွေး တိုင်းတာသည့် အမျိုးအစား (Parameters)	မြေပေါ်ရေး နမူနာယူသည့် နေရာ-၂ (SW-2)	မြေပေါ်ရေး နမူနာယူသည့် နေရာ-၄ (SW-4)	မြေပေါ်ရေး နမူနာယူသည့် နေရာ-၇ (SW-7)	မြေအောက် ရေဖျက်နာယူ သည့်နေရာ-၂ (GW-2)	မှတ်ချက်
၁၄	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၅	ဗျူးမာဇာတ် (Mercury)	၁	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၆	သွပ် (Zinc)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၇	အာဆီနစ် (Arsenic)	၁	၁	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၈	ခရိုမီယမ် (Chromium)	၁	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၁၉	ကက်ဒမီယမ် (Cadmium)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၀	ဆယ်လီနီယမ် (Selenium)	၁	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၁	ခဲ (Lead)	၀	၁	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၂	ကြေးနီ (Copper)	၁	၀	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၃	ဇေရီယမ် (Barium)	၀	၀	၁	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၄	နစ်ကယ် (Nickel)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၅	ဓင (Silver)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၆	သံဆာတ် (Iron)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၇	ဆိုက်ယာနိုက် (Cyanide)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၈	ဆိုက်ယာနိုက်စုစုပေါင်း (Total Cyanide)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၂၉	ခရိုမီယမ် (Chromium Hexavalent)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၀	ဖလူရိုက် (Fluoride)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၁	မလိုကလိုရင်း (Free Chlorine)	၀	၀	၁	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၂	ကြွင်းကျန်သောကလိုရင်းစုစုပေါင်း (Total Residual Chlorine)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၃	ဆာလဖိုင် (Sulphide)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၄	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	၀	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၅	ဖီနော (Phenols)	၁	၀	၀	၀	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၆	ခမ်းကိုက်ဆေးပျက်ကြွက်ဆေးပျက် ကိုလီဖော့စ်ဘက်တီးရီးယား (Escherichia Coli) (ကိုယ်တိုင်စောင့်ကြည့်လေ့လာခြင်း)	-	-	၀	၁	ဓာတ်ခွဲခန်းသပ်ခြင်း
၃၇	ရေစီးဆင်းနှုန်း	၀	၁	-	-	ရေစုစုနမူနာယူသည့်နေရာတွင် တိုက်ရိုက်တိုင်းတာခြင်း

မှတ်ချက်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတာ



၂.၂ ရေနမူနာရယူသည့်နေရာများ၏တည်နေရာနှင့်အချက်အလက်များဖော်ပြချက်

ရေနမူနာရယူသည့်နေရာများကို ဇယား ၂.၂-၁ တွင် ဖော်ပြထားပါသည်။ ရေနမူနာရယူသည့်နေရာ တစ်ခုစီတွင် စစ်တမ်းရယူခဲ့သည့်မှတ်တမ်းပုံများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၂-၁ ရေနမူနာရယူသည့်နေရာများ

စဉ်	တည်နေရာ	အသေးစိတ်အချက်အလက်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ကိုညွှန်နိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၈' ၂၀.၆၉"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၈.၈၄" တည်နေရာ - ရွှေပျောက်ချောင်းအောက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ကိုညွှန်နိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၄၂.၈၄"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၆' ၂၇.၄၂" တည်နေရာ - ရွှေပျောက်ချောင်းအောက်ပိုင်း ရေနမူနာရယူသော အမျိုးအစား - မြေပေါ်ရေရယူခြင်းနှင့်ရေစီးနှုန်းတိုင်းတာခြင်း
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ကိုညွှန်နိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၄၈' ၁၃.၂၅"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၅.၆၆" တည်နေရာ - ရွှေပျောက်ချောင်းသို့ မရောက်မီ နှစ် အပိုင်း (ခ)၏ ရေညိန်အောက်ရှိ ထွက်ပေါက် ရေနမူနာရယူသော အမျိုးအစား - ရွှေပျောက်ရေရယူခြင်း
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (GW-2)	ကိုညွှန်နိတ် - မြောက်လတ္တီတွဒ် - ၁၆° ၃၉' ၂၅.၃၀"၊ အရှေ့လောင်ဂျီတွဒ် - ၉၆° ၁၇' ၁၅.၆၀" တည်နေရာ - ဖလမ်းကျရွာရှိ ဘုန်းကြီးကျောင်းပရဝတ်အတွင်း ရေနမူနာရယူသော အမျိုးအစား - မြေအောက်ရေရယူခြင်း

ဗဟိုမြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတာ

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)အား ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် ရယူခဲ့ခြင်းဖြစ်သည်။ အဆိုပါအမှတ်သည် ဇုန်အပိုင်း(ခ)ဧရိယာ၏ အရှေ့မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနောက်မြောက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့က အသီးသီး ဝန်းရံလျက် ရှိသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) (ရေအရည်အသွေး ရည်ညွှန်းအမှတ်)

ပြည်တွင်းစက်မှုဇုန် သီလဝါ ဇုန်အပိုင်း(က) နှင့် ဇုန်အပိုင်း(ခ)ရှိ လုပ်ငန်းခွင်များမှ စွန့်ထုတ်လိုက်သောရေများပေါင်းစည်းရောနှောသွားသောနေရာ ရွှေပျောက်ချောင်း၏ အောက်ပိုင်းတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရယူခဲ့ခြင်းဖြစ်သည်။ ရွှေပျောက်ချောင်းသည် အရှေ့မှအနောက်သို့စီးဆင်းပြီး ရန်ကုန်မြစ် အတွင်းသို့ စီးဝင်သည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) သည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ချောင်းအောက်ပိုင်း ၂၁၅ ကီလိုမီတာအကွာတွင် တည်ရှိပါသည်။ အဆိုပါ ရေနမူနာယူသည့်နေရာသည် ဇုန်အပိုင်း(ခ) ဧရိယာ၏ အနောက်ဘက်တွင်တည်ရှိပြီး ဒဂုံ-သီလဝါလမ်း၏ တောင်ဘက်တွင်တည်ရှိပါသည်။ ပတ်ဝန်းကျင်အနီးအနားတွင် အရှေ့မြောက်ဘက်တွင် ဇုန်အပိုင်း (က)၊ အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်၊ တောင်ဘက်နှင့် အနောက်ဘက်တို့တွင် စပါးခင်းတို့ အသီးသီးတည်ရှိပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) (စွန့်ထုတ်ရေထွက်ပေါက်)

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) သည် ဇုန်အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်ပါသည်။ ထိုနေရာသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ချောင်းအောက်ပိုင်း၊ အကွာအဝေးအားဖြင့် ၄၃၄ မီတာ အကွာတွင် တည်ရှိပါသည်။ နမူနာရယူသည့်နေရာမှာ ဇုန်အပိုင်း(ခ) ရေထိန်းကန်၏ထွက်ပေါက်၊ ဇုန်အပိုင်း(ခ) ဧရိယာ၏ မြောက်ဘက်နှင့် ဒဂုံ-သီလဝါလမ်းမကြီး၏ တောင်ဘက်တွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် ဇုန်အပိုင်း(က) နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) (မူလတည်ရှိနေသောရေတွင်းအား ရည်ညွှန်းခြင်း)

မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) အား တူးဖော်ထားသောရေတွင်းမှ ရယူခဲ့ပါသည်။ အဆိုပါ ရေတွင်းသည် ဖလမ်းကျေးရွာရှိ ဘုန်းကြီးကျောင်းပရဝဏ်အတွင်းတွင် တည်ရှိပါသည်။ အနီးအနားပတ်ဝန်းကျင်၌ မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (က)၊ တောင်ဘက်တွင် ဖလမ်းကျေးရွာ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ၊ အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်နှင့် အရှေ့နှင့်အရှေ့မြောက်ဘက်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ)တို့ အသီးသီးတည်ရှိနေပါသည်။



၂.၃ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ရေနမူနာများကို ရယူပြီး သန့်စင်ထားသောဖန်ဂုလင်းညှို့များဖြင့် သိမ်းဆည်းပြီး ဇယား ၂.၃-၁ တွင် ဖော်ပြထားသော နည်းလမ်းများဖြင့် စာတံခွဲခန်း၌ စစ်ဆေးပါသည်။ ရေနမူနာများကို ရေခဲပုံးများဖြင့် ၂-၄ ဒီဂရီ ဆဲလ်စီးယပ်တွင် သိမ်းဆည်းထားပြီး စာတံခွဲခန်းသို့ ပို့ဆောင်ပါသည်။ တိုင်းတာသည့် ရေအရည်အသွေး အမျိုးအစားများ၌ ရေအပူချိန်၊ ချဉ်ဖန်ကိန်း နှင့် ပျော်ဝင်အောက်စီဂျင်တို့အား ရေအရည်အသွေး တိုင်းတာသောဇက်ကီရီယာ (Horiba U-52) ကို အသုံးပြု၍ ရေနမူနာရယူသည့်နေရာ၌ပင် တိုက်ရိုက်တိုင်းတာခဲ့ပါသည်။ ထို့အပြင်ရေစီးဆင်းမှုနှုန်းကိုလည်း ဒီဂျစ်တယ်ရေစီးနှုန်းတိုင်းကီရီယာ (JFE Digital Current Meter) ဖြင့် ရေနမူနာရယူသည့်နေရာ၌ တိုင်းတာခဲ့ပါသည်။

ဇယား ၂.၃-၁ ရေအရည်အသွေးစစ်ဆေးသည့် နည်းလမ်းများ

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၁	ရေအပူချိန် (Water Temperature)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၂	ချဉ်ဖန်ကိန်း (pH)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	Instrument Analysis Method (Horiba, U-52, Multi Water Quality Checker)
၄	ဆိုင်းကြွေအနယ် (Suspended Solids)	APHA 2540 D (Dry at 103-105°C Method)
၅	စီဝန်ညှို့ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	APHA 5210 B (5 Days BOD Test)
၆	မာတုနည်းဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{cr})	APHA 5220D (Close Reflux Colorimetric Method)
၇	ကိုလီဖော်မီး နုနပေါင်း (Total Coliform)	APHA 9221B (Standard Total Coliform Fermentation Technique)
၈	ဆီနှင့် အမ်းဆီ (Oil and Grease)	APHA 5520B (Partition-Gravimetric Method)
၉	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	HACH Method 10072 (TNT Persulfate Digestion Method)
၁၀	ဖော့စဖောရပ်စ်စုစုပေါင်း (Total Phosphorus)	APHA 4500-P-E (Ascorbic Acid Method)
၁၁	အရောင် (Color)	APHA 2120C (Spectrophotometric Method)
၁၂	အနံ့ (Odor)	APHA 2150 B (Threshold Odor Test)
၁၃	အမိုးနီးယား (Ammonia)	HACH Method 10205 (Siliclylate TNT Plus Method)
၁၄	ပျော်ဝင်အနည်စုစုပေါင်း (Total Dissolved Solids)	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)
၁၅	ပြွန်ဓာတ် (Mercury)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၆	ဩဇာ (Zinc)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၇	အာဆီနစ် (Arsenic)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၈	ခရိုမီယမ် (Chromium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၁၉	ကက်သမီယမ် (Cadmium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၀	ဆယ်လီနီယမ် (Selenium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)

သီလဝါအထူးစီးပွားရေးစနစ်အပိုင်း(ခ)ရှိစက်မှုစနစ်၊ ခြုံငုံတိုက်တွက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

စဉ်	အမျိုးအစားများ	နည်းလမ်း
၂၁	ခဲ (Lead)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၂	ကြေးနီ (Copper)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၃	ဗေရီယမ် (Barium)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၄	နစ်ကယ် (Nickel)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၅	ငွေ (Silver)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၆	သံမဏိ (Iron)	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)
၂၇	ဆိုဒီယာဆိုင်း (Cyanide)	HACH 8027 (Pyridine-Pyrazalone Method)
၂၈	ဆိုဒီယာဆိုင်းစုစုပေါင်း (Total Cyanide)	Distillation process: APHA 4500-CN-C. Total Cyanide after Distillation, Determine cyanide Concentration Process: HACH 8027 (Pyridine - Pyrazalone Method)
၂၉	ခရိုမီယမ် (Chromium Hexavalent)	ISO 11083:1994 (Determination of chromium (VI) Spectrometric method using 1,5-diphenylcarbazide)
၃၀	ဖလူအိုရိုက် (Fluoride)	APHA 4110-B (Ion Chromatography with Chemical Suppression of Eluent Conductivity)
၃၁	မရိုကလိုရင်း (Free Chlorine)	APHA 4500-CL G (DPD Colorimetric Method)
၃၂	ကြွင်းကျန်သောကလိုရင်းစုစုပေါင်း (Total Residual Chlorine)	APHA 4500-CL G (DPD Colorimetric Method)
၃၃	ဆာလဖိုင်း (Sulphide)	HACH 8131 (USEPA Methylene Blue Method)
၃၄	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	HACH 8110 (MBTH Method)
၃၅	ဖီနော (Phenols)	USEPA Method 420.1 (Phenolics (Spectrophotometric, Manual 4 AAP With Distillation))
၃၆	ဝမ်းကိုက်ရောဂါကိုဖြစ်စေသော ဇက်ဝီဇီးယား (Escherichia Coli)	APHA 9221 F (Escherichia Coli Procedure Using Fluorogenic Substrate)
၃၇	စီးဆင်းနှုန်း (Flow Rate)	Detection of Electromagnetic Elements (Real-time measurement by AEM 213-D Digital Current Meters)

မှတ်ချက်- ပြန်စစ်ဆေးရန်အတွက် နယ်လီမီတာ



၂.၄ စောင့်ကြည့်လေ့လာသည့်ကာလ

ရေအရည်အသွေးနှင့် ရေစီးဆင်းမှုနှုန်း စောင့်ကြည့်လေ့လာမှုအား ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် ဆောင်ရွက်ခဲ့ပြီး ဒီရေအတက်အကျကြောင့် ဖြစ်ပေါ်လာနိုင်သော သက်ရောက်မှုများကိုရှောင်ရှားနိုင်ရန် အောက်ပါ ဇယား ၂.၄-၁ အတိုင်း ရေနမူနာရယူခဲ့သည်။ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် အတွက်ဒီရေ မှတ်တမ်းကို ဇယား ၂.၄-၂ တွင်ဖော်ပြထားပါသည်။

ဇယား ၂.၄-၁ နေရာတစ်ခုချင်းစီအတွက် နမူနာရယူသည့်အချိန်

စဉ်	ရေနမူနာရယူသည့်နေရာ	ရေနမူနာရယူသည့်အချိန်
၁	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၂ (SW-2)	ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၂ နာရီ : ၁၅ မိနစ်)
၂	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၄ (SW-4)	ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၁၄ နာရီ : ၀၃ မိနစ်)
၃	မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7)	ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၀၉ နာရီ : ၄၅ မိနစ်)
၄	မြေအောက်ရေနမူနာရယူသည့် နေရာ-၂ (GW-2)	ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် (၀၉ နာရီ : ၀၄ မိနစ်)

မှူင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီတာက်

ဇယား ၂.၄-၂ မြန်မာနိုင်ငံ၊ ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

ရက်စွဲ	အချိန်	အမြင့်	ဒီရေအခြေအနေ
ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်	၀၃:၅၉	၁.၇၃	ဒီရေအတက်
	၀၉:၃၂	၄.၃၃	ဒီရေအကျ
	၁၆:၄၂	၁.၃၈	ဒီရေအတက်
	၂၂:၂၆	၄.၄၇	ဒီရေအကျ

မှူင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီတာက် ၂၀၂၃ ခုနှစ်အတွက် ရန်ကုန်မြစ်၏ ဒီရေမှတ်တမ်း

၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စွန့်ထုတ်ရေထွက်ပေါက်၊ စွန့်ထုတ်ရေရောက်ရှိသောချောင်းနှင့် ရည်ညွှန်းရေတွင်းရှိ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားသည်။ မာတ်ခွဲခန်းဆန်းစစ်မှု ရလဒ်များကို နောက်ဆက်တွဲ-၂ တွင် ဖော်ပြထားသည်။ ရလဒ်များကို ပတ်ဝန်းကျင်ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသည့် ရေအရည်အသွေး ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ထားပါသည်။

၂.၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့် စွန့်ထုတ်ရေရောက်ရှိသောချောင်းတွင်းရှိရလဒ်များ

ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ချဉ်ပန်ကိန်း၊ ဆိုင်းကြွအနယ်များ ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်းတွေ့ရသည်။

(၁) စွန့်ထုတ်ရေထွက်ပေါက်ရှိ ရေအရည်အသွေးရလဒ်များ

ဆိုင်းကြွအနယ်များ၏ ရလဒ်များအနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇန်နဝါရီလ(ခ)၏ အဓိကစွန့်ထုတ် ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇန်နဝါရီလ(ခ)ရှိ မြေလွှတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇန်နဝါရီလ(ခ)၏ အဓိက စွန့်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာရယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနုသတ္တဝါများကျင်လည် ကျက်စားခြင်းကြောင့် ဇန်နဝါရီလ(ခ) အတွင်းရှိနေရာများတွင် အာဇာနည်



ဘက်တီးရီးယားများပါဝင်ပြီး အထူးသဖြင့် တိရစ္ဆာန်များမှထွက်ရှိသော ဇွန်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း၊ ပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည် ရေထိန်းကန်ထဲသို့စီးဝင်စေပြီး ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏ဇွန်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး ကိုလီဖောင်းစုစုပေါင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နှည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား ဓာတ်ခွဲစမ်းသပ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli)ရလဒ်အရ မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ ဓန့်ထုတ်ခင် ဇွန်အပိုင်း(ခ)၏ အဓိကဇွန်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်သောအကြောင်းအရာများမှာ သဘာဝ မြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ကြောင့်ဖြစ်နိုင်ပါသည်။ ရန်ကုန်မြို့ ၏မြေဆီလွှာသည် သဘာဝအားဖြင့်သံဓာတ်ကြွယ်ဝပြီး သံဓာတ်သည် သဘာဝပတ်ဝန်းကျင်တွင် အချိန်ကြာမြင့်စွာ တည်ရှိနေပါသည်။ ဇွန်အပိုင်း(ခ)၏ အဓိက ဇွန်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များ နှင့် စောင့်ကြည့်လေ့လာသည့်ရည်ညွှန်းအမှတ်များ၏ မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များအား ဇယား ၂.၅-၁ တွင် ဖော်ပြထားပါသည်။ မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေစုစုစာယူသည့် နေရာ-၄ (SW-4) တို့နှင့် ပတ်သတ်၍ ဆိုင်းကြွအနည်း၏ ရလဒ်များမှာ ၇၀ mg/l နှင့် ၁၁၄ mg/l တို့ ရှိကြပြီး သံဓာတ်၏ ရလဒ်များမှာ ၅.၅၈၀ mg/l နှင့် ၆.၈၈၀ mg/l တို့ အသီးသီး ရှိကြပါသည်။ ဆိုင်းကြွအနည်း၏ ရလဒ်နည်းလျှင် သံဓာတ်တည်ရှိမှုနည်းပါးပြီး ဆိုင်းကြွအနည်းများ၏ ရလဒ်များလျှင် သံဓာတ်တည်ရှိမှုမြင့်မားကြောင်း သိသာထင်ရှားစွာ တွေ့မြင်နိုင်ပါသည်။

(၂) မြန်မာ့ဂျပန်သီလဝါဖွံ့ဖြိုးရေးလီမိတက်၏ ထပ်မံစောင့်ကြည့်လေ့လာမှု

ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် တိုင်းတာခဲ့သော ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များအရ သံဓာတ်ရလဒ်သည် မြေပေါ်ရေစုစုစာယူသည့် နေရာ ၇ (SW-7)တွင် ကျော်လွန်နေသည်ကို တွေ့ရပါသည်။ ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ် စောင့်ကြည့်လေ့လာမှုအတွက် သံဓာတ်ရလဒ်အား လက်ခံရရှိပြီးသည့်နောက် သံဓာတ်၏ရလဒ်များ ပိုမိုတိကျသိရှိရန် ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုကို မြန်မာ့ဂျပန်သီလဝါဖွံ့ဖြိုးရေးလီမိတက်မှ ဇန်နဝါရီလ ၉ ရက်နေ့ ၂၀၂၄ ခုနှစ်တွင် တည်သောနေရာ၌ ရေစုစုစာကောက်ယူ၍ ထပ်မံဆောင်ရွက်ခဲ့ပါသည်။ ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်၏ ရလဒ်များကို ထပ်မံတိုင်းတာခဲ့သော ရလဒ်နှင့် နှိုင်းယှဉ်ရာတွင် ထပ်မံရရှိသော သံဓာတ်ရလဒ်မှာ နည်းနေသည်ကို တွေ့ရှိရပါသည်။ သို့သော်လည်း ရည်မှန်းတန်ဖိုးနှင့်နှိုင်းယှဉ်ရာတွင် ထပ်မံတိုင်းတာခဲ့သော ရလဒ်သည်ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။ ထိုသို့ ကျော်လွန်ခြင်းမှာ ဇွန်အပိုင်း(ခ)၏ စက်ရုံလုပ်ငန်း သုံးခုမှ ဆောက်လုပ်ရေးလုပ်ငန်းများ လုပ်ဆောင်နေခြင်း နှင့် ဆောက်လုပ်ရေးလုပ်ငန်းများမှ ထွက်လာသော သံဓာတ်များသည် ရေထိန်းကန်အတွင်းသို့ စီးဝင်မှုများကြောင့်



သံဓာတ်ရလဒ်များ ကျော်လွန်နေခြင်း ဖြစ်နိုင်ပါသည်။ ဒီဇင်ဘာလ ၅ ရက်နေ့၊ ၂၀၂၃ ခုနှစ်တွင် တိုင်းတာခဲ့သော သံဓာတ်ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ အထက်တွင်ရှင်းပြခဲ့သည့် အကြောင်းပြချက်ကြောင့် ဖြစ်ပါသည်။ ယခင် စောင့်ကြည့်လေ့လာမှု ကာလရလဒ်များသည် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ တွင် ရည်မှန်းတန်ဖိုးအတွင်းတွင် ရှိပါသည်။

စောင့်ကြည့်လေ့လာသည့်ရည်ညွှန်းအမှတ်များ၏ရေအရည်အသွေးရလဒ်များ(စွန့်ထုတ်ရေရောက်ရှိသောချောင်း)

ချဉ်းမန်ကိန်းတန်ဖိုးရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့်နေရာ-၄ (SW-4) တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်မှာ သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိပြည်တွင်းစက်မှုဇုန်မှ ဆပ်ပြာနှင့်ဆပ်ပြာ အခြေခံထုတ်ကုန်များ ပါဝင်သည့် စွန့်ပစ်ရေများ စွန့်ထုတ်လိုက်ခြင်းကြောင့် ဖြစ်နိုင်ပါသည်။

ဆိုင်းကြွအနည် ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သော ရေများကြောင့်လည်းကောင်း၊ (၂) ရွှေပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်းနှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များမှ ထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည် ရွှေပျောက်ချောင်းသို့ စီးဆင်းပြီး ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေပျောက်ချောင်းတလျှောက် တိုးဝင်လာသောဒီရေများတွင် ပါရှိလာနိုင်သောအညစ်အကြေးများကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်။ ဖြစ်နိုင်သောအဓိက အကြောင်းအရာများမှာ သဘာဝ သံဓာတ် အရင်းအမြစ်၏ လွှမ်းမိုးမှု ကြောင့် ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါအထူးစီးပွားရေးဇုန် ၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသော မြေဆီလွှာ(ဂစ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုခိုပိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။



ဇယား ၂-၅-၁ စွန့်ထုတ်ရေထွက်ပေါက်နှင့်စွန့်ထုတ်ရေရောက်ရှိသော ချောင်းမှရေအရည်အသွေး
စောင့်ကြည့်လေ့လာမှုရလဒ်များ

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (parameters)	ယူနစ်	၅-၁၂-၂၀၂၃	၅-၁၂-၂၀၂၃	၅-၁၂-၂၀၂၃	၅-၁၂-၂၀၂၃	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင်စောင့်ကြည့်လေ့ လာခြင်း အတွက် ရည်ညွှန်းတန်ဖိုး)
			ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း “၁” ပြေပေါ်ရေနေမှု မှာယူသည့် နေရာ-၂ (SM-2)	ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း “၁” ပြေပေါ်ရေနေမှု မှာယူသည့် နေရာ-၄ (SM-4)	ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း “၁” ပြေပေါ်ရေနေမှု မှာယူသည့် နေရာ-၇ (SM-7)	ထပ်တိုး စောင့်ကြည့် လေ့လာခြင်း “၁” ပြေပေါ်ရေနေမှု မှာယူသည့် နေရာ-၇ (SM-7)	
၁	ရေအပူချိန် (Water Temperature)	°C	၂၉	၃၀	၂၈	-	၃၂၅
၂	ဆွဲဆဲစိုက်နှုန်း (pH)	-	၇.၅	၈.၈	၇.၉	-	၆-၉
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/l	၃.၅၇	၈.၈၅	၄.၆၈	-	-
၄	မိုက်ကြွေအမှုန် (Suspended Solid)	mg/l	၇၈	၁၀၄	၃၆၆	-	၅၀
၅	နီဝနည်ဖြင့် ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (ဗျူမက်) (BOD ₅)	mg/l	၁၇.၆၇	၁၁.၆၉	၈.၄၇	-	၃၀
၆	ဓာတ်နည်ဖြင့် ဖြည့်ရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{mn})	mg/l	၅၀.၀	၃၀.၀	၁၉.၄	-	၁၂၅
၇	ကိုလိုဖောင်း စုစုပေါင်း (Total Coliform)	MPN/100ml	၁၆၀၀၀၀	၁၀၀၀၀၀	၁၆၀၀၀၀	-	၄၀၀
၈	ဆီနှင့် အပိဆီ (Oil and Grease)	mg/l	< ၃.၀	< ၃.၀	< ၃.၀	-	၁၈
၉	နိုက်ထရိုဂျင် စုစုပေါင်း (Total Nitrogen)	mg/l	၂.၃	၃.၈	၃.၅	-	၈၀
၁၀	ဖော့စဖော့ရက် စုစုပေါင်း (Total Phosphorus)	mg/l	၀.၃၁	၀.၃၈	၀.၇၈	-	၂
၁၁	အရောင် (Color)	TCU (True Color Unit)	၃၆.၀၃	၁၀.၈၀	၁၀.၈၄	-	၁၅၀
၁၂	အနံ့ (Odor)	TON (Threshold Odor Number)	၁	၃	၁.၄	-	-
၁၃	အမိုးနီးယား (Ammonia)	mg/l	၁.၀၅	၀.၁၁	၀.၇၄	-	၁၀
၁၄	ပျော်ဝင်အရည် စုစုပေါင်း (Total Dissolved Solids)	mg/l	၃၆၆	၃၀၂	၃၄၄	-	၂၀၀၀
၁၅	ဗြဲဝါဆာတ် (Mercury)	mg/l	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	-	၀.၀၀၅
၁၆	ဗျပ် (Zinc)	mg/l	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	-	၂
၁၇	အာဆီနစ် (Arsenic)	mg/l	≤ ၀.၀၁၀	≤ ၀.၀၁၀	≤ ၀.၀၁၀	-	၀.၁
၁၈	ခရိုမီယမ် (Chromium)	mg/l	≤ ၀.၁၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	-	၀.၅
၁၉	ကက်သီယမ် (Cadmium)	mg/l	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	-	၀.၀၃
၂၀	ဆယ်လီနီယမ် (Selenium)	mg/l	≤ ၀.၀၁၀	≤ ၀.၀၁၀	≤ ၀.၀၀၀	-	၀.၀၂
၂၁	မီ (Lead)	mg/l	≤ ၀.၀၀၂	≤ ၀.၀၀၂	≤ ၀.၀၀၂	-	၀.၁



သီလဝါအတွက် ပတ်ဝန်းကျင်ဆေးစစ်မှု နမူနာများ ပြုစုပေးသည့် အချက်အလက်များကို အကျဉ်းချုပ်ဖော်ပြသော အချက်အလက်များကို အောက်ဖော်ပြပါဇယားတွင် ဖော်ပြထားပါသည်။ (တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

နမူနာအမျိုးအမည်နှင့် နမူနာ			၅-၁၂-၂၀၂၃	၆-၁၂-၂၀၂၃	၇-၁၂-၂၀၂၃	၈-၁၂-၂၀၂၃	ရလဒ်များကို ဖော်ပြသော ဇယား (တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း၊ ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)
စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အချက်အလက်များ (parameters)	ယူနစ်	ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း "၁" ပြေပေါ်ရေမှ နမူနာယူသည့် နေရာ-၂ (SW-2)	ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း "၁" ပြေပေါ်ရေမှ နမူနာယူသည့် နေရာ-၄ (SW-4)	ပုံမှန် စောင့်ကြည့် လေ့လာခြင်း "၁" ပြေပေါ်ရေမှ နမူနာယူသည့် နေရာ-၇ (SW-7)	ထပ်တိုး စောင့်ကြည့် လေ့လာခြင်း "၁" ပြေပေါ်ရေမှ နမူနာယူသည့် နေရာ-၇ (SW-7)	
၂၁	ကြေးနီ (Copper)	mg/l	< ၀.၀၀၅	< ၀.၀၀၅	< ၀.၀၀၅	-	၀.၅
၂၃	ဗေရီယမ် (Barium)	mg/l	၀.၁၀၆	၀.၂၈၀	၀.၁၆၈	-	၁
၂၄	နီကယ် (Nickel)	mg/l	< ၀.၀၀၅	< ၀.၀၀၅	< ၀.၀၀၅	-	၀.၂
၂၅	ဓွတ် (Silver)	mg/l	< ၀.၀၀၅	< ၀.၀၀၅	< ၀.၀၀၅	-	၀.၅
၂၆	သံသတ္တ (Iron)	mg/l	၅.၅၈၀	၆.၈၈၀	၃.၁၆၈၀	၁၂.၀၅၀	၃.၅
၂၇	ဆိုင်းယာနိုက်ဒ် (Cyanide)	mg/l	< ၀.၀၀၅	< ၀.၀၀၅	< ၀.၀၀၅	-	၀.၁
၂၈	ဆိုင်းယာနိုက်ဒ် စုစုပေါင်း (Total Cyanide)	mg/l	၀.၀၀၅	၀.၀၀၅	< ၀.၀၀၅	-	၁
၂၉	ခရိုမီယမ် (Hexavalent Chromium)	mg/l	< ၀.၀၅	< ၀.၀၅	< ၀.၀၅	-	၀.၁
၃၀	ဖလူရိုက် (Fluoride)	mg/l	၀.၁၈၅	၁.၃၉၅	၁.၀၀၀	-	၂၀
၃၁	ဖလိုရိုက် (Free Chlorine)	mg/l	< ၀.၁	< ၀.၁	< ၀.၁	-	၁
၃၂	ကြွင်းကျန်သော ကလိုရိုက် (Total Residual Chlorine)	mg/l	< ၀.၁	< ၀.၁	< ၀.၁	-	၀.၂
၃၃	ဆာလဖိုင် (Sulphide)	mg/l	၀.၁၂၄	၀.၁၂၆	၀.၅၀၅	-	၁
၃၄	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	mg/l	၀.၀၃၄	၀.၀၉၄	၀.၃၃၆	-	၁
၃၅	ဖီနော (Phenols)	mg/l	၀.၀၀၀	၀.၀၂၅	၀.၀၀၅	-	၀.၅
၃၆	ပစ်ကောက်ရောင်ခြင်းရှိသော ကိုလီဖော်ဒါး ဘက်တီးရီးယား (Escherichia Coli)	MPN/100ml	-	-	၆.၈	-	(၁၀၀၀)*** (CFU/၁၀၀ml)
၃၇	စီးဆင်းနှုန်း (Flow Rate)	m³/s	၀.၀၀၃	၂.၂၅	-	-	-

မှတ်ချက်။ အနီရောင်ခြင်းမရှိသော အောက်ဖော်ပြပါအချက်များသည် သတ်မှတ်ထားသည့် တန်ဖိုးများထက် ကျော်လွန်နေသည်ကို ဆိုလိုပါသည်။

မှတ်ချက်။ "၁" ပုံမှန်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုကို ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှု အစီအစဉ်အောက်တွင် ဆောင်ရွက်ခဲ့ပါသည်။ ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှု အစီအစဉ်အောက်တွင် မြေပေါ်ရေမှ နမူနာယူသည့် နေရာများကို ထပ်မံ၍ ဆောင်ရွက်ခဲ့ပါသည်။ ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် တိုင်းတာခဲ့သော ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှုများသည် ပြေပေါ်ရေမှ နမူနာယူသည့် နေရာ-၇ (SW-7) တွင် ရေညစ်ညမ်းမှုထက် ကျော်လွန် နေသည်ကို တွေ့ရှိရပါသည်။ ဒီဇင်ဘာလ ၅ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် တိုင်းတာခဲ့သော ရေအရည်အသွေးများနှင့် ခန့်မှန်းချက် ၉ ရက်နေ့ ၂၀၂၃ ခုနှစ်တွင် တိုင်းတာခဲ့သော ရေအရည်အသွေးများကို နှိုင်းယှဉ်ရာတွင် ရေကို ထပ်တိုးတိုင်းတာခဲ့သော ရေသည် ပထမတိုင်းတာခဲ့သော ရေထက် ရေညစ်ညမ်းမှု ပိုမိုမြင့်မားပါသည်။

***မှတ်ချက်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။

မှတ်ချက်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။ နမူနာယူရာနေရာတွင် ကိုလီဖော်ဒါး ဘက်တီးရီးယား (E. coli) ကို ရေညစ်ညမ်းမှုအခြေသတ်မှတ်ထားပါသည်။



၂.၅.၂ ရည်ညွှန်းရေတွင်း၏ ရလဒ်

ရည်ညွှန်းရေတွင်းစောင့်ကြည့်လေ့လာသောနေရာ၌ ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရလဒ်များကို စာယား ၂.၅-၂ တွင်ဖော်ပြထားသည်။ ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာတွင် သံဓာတ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင် ၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဒီဇင်ဘာလ၊ ၂၀၂၃ခုနှစ် တွင် ၁၄.၁၀၀ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ ၂၀၁၉ခုနှစ်၊ ဖော်ဖော်ဝါရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍ သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ ဒီဇင်ဘာလ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု ကြောင့်ဖြစ်နိုင်ပါသည်။ (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်။) အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂစ်မြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းသံဓာတ်များသည် မြေအောက်ရေအောင်းလွှာအတွင်းသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

စာယား ၂.၅-၂ ရည်ညွှန်းရေတွင်း၏ ရေအရည်အသွေးစောင့်ကြည့်တန်ဖိုးရလဒ်

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာ ခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁	ရေအပူချိန် (Water Temperature)	°C	၂၉	≤ ၃၅
၂	ရည်ပန်းကိန်း (pH)	-	၆.၄	၆ - ၉
၃	ပျော်ဝင်အောက်စီဂျင် (Dissolved Oxygen)	mg/l	၆.၁၈	-
၄	ဆိုင်ကြဲအနယ် (Suspended Solid)	mg/l	၂	၅၀
၅	စီနနည်ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (၅-ရက်) (BOD ₅)	mg/l	၇.၆၈	၃၀
၆	ဓာတုနည်ဖြင့် ဖြိုခွဲရန် အောက်စီဂျင် လိုအပ်ချက် (COD _{cr})	mg/l	< ၀.၇	၁၂၅
၇	ကိုလီဖော်မီဆူပေါင်း (Total Coliform)	MPN/ 100ml	၁၄၀.၀	၄၀၀
၈	ဆီနှင့် အမဲဆီ (Oil and Grease)	mg/l	< ၃.၁	၁၀
၉	နိုက်ထရိုဂျင်စုစုပေါင်း (Total Nitrogen)	mg/l	< ၀.၅	၈၀
၁၀	ဖော့စဖောရက်စုစုပေါင်း (Total Phosphorus)	mg/l	၀.၆၅	၂
၁၁	အရောင် (Color)	TCU (True Color Unit)	၇၄.၅၅	၁၅၀
၁၂	အနံ့ (Odor)	TON (Threshold Odor Number)	၀	-



သီပေါမြို့အတွင်းရှိ ရေအရင်းအမြစ် (ခ) ရှိမကုန်မှုစနစ်ဖြင့် ပြုပြင်ဆင်ဆင်မှုအတွက် ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

စဉ်	ရေအရည်အသွေး တိုင်းတာသည့် အမျိုးအစားများ (Parameters)	ယူနစ်	မြေအောက်ရေ နမူနာယူသည့် နေရာ-၂ (GW-2)	ရည်မှန်းတန်ဖိုး (ကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်ညွှန်းတန်ဖိုး)
၁၃	အမိုးနီးယား (Ammonia)	mg/l	၀.၂၁	၁၀
၁၄	စပွတ်ဝင်အရည်စုစုပေါင်း (Total Dissolved Solids)	mg/l	၂၀၀	၂၀၀၀
၁၅	ပြွန်စင်္ဂတ် (Mercury)	mg/l	≤ ၀.၀၀၂	၀.၀၀၅
၁၆	ဗွန် (Zinc)	mg/l	≤ ၀.၀၀၂	၂
၁၇	အာဆီနစ် (Arsenic)	mg/l	≤ ၀.၀၁၀	၀.၁
၁၈	ခရိုမီယမ် (Chromium)	mg/l	≤ ၀.၀၀၂	၀.၅
၁၉	ကက်ဒမီယမ် (Cadmium)	mg/l	≤ ၀.၀၀၂	၀.၀၃
၂၀	ဆယ်လီနီယမ် (Selenium)	mg/l	≤ ၀.၀၁၀	၀.၀၂
၂၁	ပဲ (Lead)	mg/l	≤ ၀.၀၀၂	၀.၁
၂၂	မကြေးနီ (Copper)	mg/l	≤ ၀.၀၀၂	၀.၅
၂၃	ဗေရီယမ် (Barium)	mg/l	၀.၁၀၀	၁
၂၄	နစ်ကယ် (Nickel)	mg/l	≤ ၀.၀၀၂	၀.၂
၂၅	ဓန (Silver)	mg/l	≤ ၀.၀၀၂	၀.၅
၂၆	သံမဏိ (Iron)	mg/l	၀၄.၁၈၈	၃.၀
၂၇	ဆိုရိုယာဆိုက် (Cyanide)	mg/l	≤ ၀.၀၀၂	၀.၁
၂၈	ဆိုရိုယာဆိုက်စုစုပေါင်း (Total Cyanide)	mg/l	≤ ၀.၀၀၂	၁
၂၉	ခရိုမီယမ် (Chromium Hexavalent)	mg/l	≤ ၀.၀၅	၀.၁
၃၀	ဖလူရိုက် (Fluoride)	mg/l	၀.၂၂၇	၂၀
၃၁	ဖလိုကလိုရင်း (Free Chlorine)	mg/l	≤ ၀.၁	၁
၃၂	ကြွင်းကျန်ဆောက်လိုရင်းစုစုပေါင်း (Total Residual Chlorine)	mg/l	≤ ၀.၁	၀.၂
၃၃	ဆာလဖိုင် (Sulphide)	mg/l	≤ ၀.၀၀၅	၁
၃၄	ဖော်မယ်ဒီဟိုက် (Formaldehyde)	mg/l	≤ ၀.၀၀၃	၁
၃၅	ဖီနော (Phenols)	mg/l	≤ ၀.၀၀၂	၀.၅
၃၆	ပစ်ကောက်ရောဂါကိုဖြစ်စေသော ကိုလီဖော်မီလာတီးရီးယား (Escherichia Coli)	MPN/100ml	≤ ၁.၈	(၁၀၀)* (MPN/100ml)
၃၇	စီးဆင်းနှုန်း (Flow Rate)	m ³ /s	-	-

မှတ်ချက်: အနီရောင်ဖြင့် ဖော်ပြထားသောတန်ဖိုးများသည် သတ်မှတ်ထားသည့်တန်ဖိုးများထက် မကွာလွန်နေသည်ကို ဆိုလိုပါသည်။
 *မှတ်ချက်: မြေအောက်ရေစောင့်ကြည့်လေ့လာသောနေရာတွင် ရေအသုံးပြုမှုပေါ်မူတည်၍ ဒီဇင်ဘာလနှင့် ဖြေအောက်ရေအရည်အသွေးဆိုင်ရာ အချို့သောနည်းပညာစည်းမျဉ်းတွင် B1 (ဆည်မြောင်းစု) (No. QCVN08: 2028/BTNMT) ကိုမြေအောက်ရေကိုယ်တိုင် စောင့်ကြည့်လေ့လာခြင်းအတွက် ရည်မှန်းတန်ဖိုးအဖြစ်သတ်မှတ်ပါသည်။
 မူရင်း ဖြန့်ချိထုတ်ဝေမှုအရင်းအမြစ်



၂.၅-၃ ယခင်စောင့်ကြည့်လေ့လာမှုရလဒ်များ နှင့် ၂၀၂၃ ခုနှစ် ဒီဇင်ဘာလ တွင် စောင့်ကြည့်လေ့လာမှုရလဒ်များ ၏ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ အရည်အသွေးများ နှိုင်းယှဉ်ခြင်း

ယခု စောင့်ကြည့်လေ့လာနေစဉ်ကာလ (ဒီဇင်ဘာ ၂၀၂၃) အတွင်း ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသော ရေ အရည်အသွေးများအား ခြုံငုံသုံးသပ်ကြည့်ရန်အတွက် ၂၀၂၂ ခုနှစ် ဒီဇင်ဘာလ ကတည်းကရရှိသော စောင့်ကြည့်မှုရလဒ်များနှင့် နှိုင်းယှဉ်ထားပါသည်။

စွန့်ထုတ်လိုက်သောနေရာများ၏ ရေအရည်အသွေးရလဒ်များနှင့် ပတ်သက်၍ စောင့်ကြည့်ရာတွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ဆိုင်းကြွအနည်ရလဒ်တန်ဖိုးသည် ဒီဇင်ဘာလ ၂၀၂၂ နှင့် ဧပြီလ၊ ဩဂုတ်လ၊ ဒီဇင်ဘာလ ၂၀၂၃ တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ ထို့အပြင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် မေဖော်မီရိုလ၊ စွန့်လ၊ ဩဂုတ်လ၊ အောက်တိုဘာလ နှင့် ဒီဇင်ဘာလ ၂၀၂၃ တို့တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်တန်ဖိုးသည် ၂၃၀၀ MPN/၁၀၀ml မှ စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀၀ MPN/၁၀၀ml)ထိ ရှိပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ် တန်ဖိုးသည် မိုးရာသီအစ၊ အလယ် နှင့် ဆောင်းရာသီတို့တွင် စမ်းသပ်နိုင်သောပမာဏထိ သိသာထင်ရှားစွာ မြင့်မားနေပြီး စီးဆင်းရေ၏ သက်ရောက်မှုကြောင့် ဖြစ်နိုင်သည်ဟု သုံးသပ်ရပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ သံဓာတ်တန်ဖိုးသည် ဒီဇင်ဘာလ ၂၀၂၂ တွင် ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေသကဲ့သို့ ဒီဇင်ဘာလ ၂၀၂၃ တွင်လည်း ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေပါသည်။ ထို့အပြင် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ သံဓာတ်တန်ဖိုးသည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍ စစ်တမ်းကောက်ယူထားသော ကျန်လများအားလုံးသည် ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေပါသည်။ မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ သံဓာတ်တန်ဖိုးသည် မိုးဇွဲရာသီ နှင့် ဆောင်းရာသီ တလျှောက်လုံးတွင် မြင့်မားနေသည်ကို သိသိသာသာတွေ့မြင်ရ ပါသည်။

အခြားတစ်ဖက်တွင် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ရှိ ချဉ်းနီကိန်းရလဒ်သည် ဒီဇင်ဘာလ ၂၀၂၃ တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ သို့သော်လည်း ယခင် စစ်တမ်းကောက်ယူထားသော လများသည် ရည်မှန်းတန်ဖိုးအောက် လျော့နည်းကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့၏ ဆိုင်းကြွအနည်ရလဒ်သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဆိုင်းကြွအနည်ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)တွင် ဒီဇင်ဘာလ ၂၀၂၂၊ စွန့်လ နှင့် ဒီဇင်ဘာလ ၂၀၂၃ တို့တွင် ၇၀ မှ ၃၇၀ mg/l ထိတန်ဖိုးအပိုင်းအခြား အတွင်းရှိနေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၏ ဆိုင်းကြွအနည်ရလဒ်မြင့်မားမှုသည် မိုးရာသီနှင့် ဆောင်းရာသီတွင် တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာမှုအရ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း ထင်ရှားစွာတွေ့ရှိရပါသည်။ ဆိုင်းကြွအနည်ရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ ဆိုင်းကြွအနည်ရလဒ်သည် ဧပြီလ ၂၀၂၃ ၏ ရလဒ်မှလွဲ၍ စစ်တမ်းကောက်ယူထားသော ကျန်လများတွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပြီး ၇၀ မှ ၅၀၂ mg/l ထိတန်ဖိုးအပိုင်းအခြား အတွင်းရှိနေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင်ရှိသော ဆိုင်းကြွအနည်ရလဒ်များသည် မိုးရာသီအတွင်း ပတ်ဝန်းကျင်မှရေများ စီးဆင်းမှုကြောင့် မိုးရာသီတလျှောက်လုံးနှင့် ဆောင်းရာသီတွင် ရလဒ်များ မြင့်တက်နေခြင်းဖြစ်သည်။ သိသာထင်ရှားစွာဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှုစစ်တမ်း (၇)လအနက် (၆)လသည် (၁၇၀၀မှ >၁၆၀၀၀၀ MPN/100ml အပိုင်းအခြားအတွင်း) ရလဒ်တန်ဖိုးထက် မြင့်နေပြီး မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ ကိုလီဖောင်းစုစုပေါင်းရလဒ်များသည် စောင့်ကြည့်လေ့လာမှု ကာလအားလုံးတွင် (၄၆၀၀ မှ >၁၆၀၀၀၀



MPN/100ml အပိုင်းအခြားအတွင်း) ရည်မှန်းတန်ဖိုးထက် မြင့်မားနေကြောင်း တွေ့ရှိရသည်။ အထူးသဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့၏ ကိုလိုဖောင်းစုပေါင်းရလဒ်များသည် ဇွန်လ ၂၀၂၃ တွင် စမ်းသပ်နိုင်သောပမာဏ (>၁၆၀၀၀၀ MPN/100ml) ထိရောက်ရှိခဲ့ပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့၏ သံဓာတ်ရလဒ်များသည် စောင့်ကြည့်လေ့လာမှု ကာလ လေးကြိမ်မှ ငါးကြိမ်ထိတိုင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၏ သံဓာတ်တန်ဖိုးသည် မိုးရာသီနှင့် ဆောင်းရာသီ အတွင်းတွင် သိသာထင်ရှားစွာ မြင့်တက်နေသည်ကိုတွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးသည် စောင့်ကြည့်လေ့လာနေသော ကာလ(၅)လ (ဒီဇင်ဘာလ ၂၀၂၂ နှင့် ဇွန်လ၊ ဩဂုတ်လ၊ အောက်တိုဘာလ၊ ဒီဇင်ဘာလ ၂၀၂၃) တွင် မြင့်မားနေပြီး၊ သံဓာတ်တန်ဖိုး အပိုင်းအခြားသည် ၆.၈၈ မှ ၂၂.၆၂၆ mg/l အတွင်းရှိပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၏ သံဓာတ်တန်ဖိုးမြင့်မားမှုသည် မိုးရာသီ တလျှောက်လုံးမှ ဆောင်းရာသီအစတိုင်အောင် ဖြစ်ပေါ်နေကြောင်း တွေ့ရှိရသည်။ ယခုလက်ရှိ ရေအရည်အသွေးများ၏ ရလဒ်များအခြေအနေသည် သီလဝါအထူးစီးပွားရေးဇုန် ယခင်နှင့်ယခုလက်ရှိကာလ လည်ပတ်မှု၏ ပတ်ဝန်းကျင်အခြေအနေများကို ထင်ဟပ်နေသည်ဟု ဆိုနိုင်ပါသည်။

ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည့် သက်ဆိုင်ရာရေအရည်အသွေးအမျိုးအစားများအတွက် ဖြစ်နိုင်သော အကြောင်းပြချက်များအား ဤ အစီရင်ခံစာ၏ အရှေ့ပိုင်းရှင်းလင်းချက်တွင် ဖော်ပြထားပါသည်။



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

အခန်း ၂ (အပိုင်း ၂.၅) တွင်ဖော်ပြထားသကဲ့သို့ သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ) လုပ်ငန်းလည်ပတ်နေစဉ် ကာလ စောင့်ကြည့်လေ့လာသောအချိန်အတွင်း မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2)၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တို့တွင် ဆိုင်းကြွအနည်း ကိုလီဖောင်းစုစုပေါင်း နှင့် သံဓာတ်၊ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင်ချဉ်ဖန်ကိန်း နှင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) တွင် သံဓာတ် စသည်တို့သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေပါသည်။

ဆိုင်းကြွအနည်းများ၏ ရလဒ်များအနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ် ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ ဇုန်အပိုင်း(ခ)ရှိ မြေလွှတ်များမှ မြေမျက်နှာပြင် စီးဆင်းရေများ ကြောင့် ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိက စွန့်ထုတ်ရေထွက်ပေါက်ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်းမှာ အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများကျင်လည် ကျက်စားခြင်းကြောင့် ဇုန်အပိုင်း(ခ) အတွင်းရှိမြေများတွင် သဘာဝမှ ဘက်တီးရီးယားများပါဝင်ပြီး အထူးသဖြင့် တိရစ္ဆာန်များမှထွက်ရှိသော စွန့်ပစ်အညစ်အကြေးများကြောင့် လည်းကောင်း နှင့် ပတ်ဝန်းကျင်မှ အညစ်အကြေးများသည် ရေထိန်းကန်ထဲသို့စီးဝင်စေပြီး ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြှင့်တက်စေခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ကိုလီဖောင်းစုစုပေါင်း၏ ဖြစ်တည်မှုတွင် သဘာဝမှဘက်တီးရီးယားများပါဝင်ပြီး ကိုလီဖောင်းစုစုပေါင်းသည် လူတို့၏ကျန်းမာရေးကို တိုက်ရိုက်ထိခိုက်မှု မရှိသော်ငြားလည်း ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားထဲမှ ကျန်းမာရေးအပေါ် သက်ရောက်မှု ရှိ/မရှိသိစေရန် တစ်နည်းအားဖြင့် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်း ဘက်တီးရီးယား အမျိုးအစားတစ်မျိုး (E Coli) အား ဓာတ်ခွဲစမ်းသပ်လေ့လာခဲ့ပါသည်။ ဤဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E Coli) ရလဒ်အရ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ၏ တန်ဖိုးသည် ရည်မှန်းတန်ဖိုးအောက် နည်းပါးကြောင်းတွေ့ရှိရပါသည်။ ထို့ကြောင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) တွင် ကိုလီဖောင်းစုစုပေါင်းသည် ရည်မှန်းတန်ဖိုးထက် များနေသော်လည်း လူ၏ကျန်းမာရေးကို ထိခိုက်နိုင်သည့် သက်ရောက်မှုမရှိနိုင်ကြောင်း သတ်မှတ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် ချောင်းတွင်းသို့ မစွန့်ထုတ်ခင် ဇုန်အပိုင်း(ခ)၏ အဓိကစွန့်ထုတ်ရေထွက်ပေါက် ဖြစ်သော မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) ရှိ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ ဖြစ်နိုင်သောကြောင်းအရာများမှာ သဘာဝ မြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ကြောင့်ဖြစ်နိုင်ပါသည်။ ရန်ကုန်မြို့ ၏မြေဆီလွှာသည် သဘာဝအားဖြင့်သံဓာတ်ကြွယ်ဝပြီး သံဓာတ်သည် သဘာဝပတ်ဝန်းကျင်တွင် အချိန်ကြာမြင့်စွာ တည်ရှိနေပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့နှင့် ပတ်သတ်၍ ဆိုင်းကြွအနည်း၏ ရလဒ်များမှာ ၇၀ mg/l နှင့် ၁၁၄ mg/l တို့ ရှိကြပြီး သံဓာတ်၏ ရလဒ်များမှာ ၅.၅၈၀ mg/l နှင့် ၆.၈၈၀ mg/l တို့ အသီးသီး ရှိကြပါသည်။ ဆိုင်းကြွအနည်းများ၏ ရလဒ်နည်းလျှင် သံဓာတ်တည်ရှိမှုနည်းပါးပြီး ဆိုင်းကြွအနည်းများ၏ ရလဒ်များလျှင် သံဓာတ်တည်ရှိမှုမြင့်မားကြောင်း သိသာထင်ရှားစွာ တွေ့မြင်နိုင်ပါသည်။



ချဉ်းမနီကိန်းတန်ဖိုးရလဒ်အနေဖြင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တွင် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်မှာ သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိပြည်တွင်းစက်မှုဇုန်မှ ဆပ်ပြာနှင့်ဆပ်ပြာ အခြေခံထုတ်ကုန်များ ပါဝင်သည့် စွန့်ပစ်ရေများ စွန့်ထုတ်လိုက်ခြင်းကြောင့် ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်း စုစုပေါင်း ဆိုင်းကြွအနယ် နှင့် သံဓာတ် တို့၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရပါသည်။ မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ကိုလီဖောင်းစုစုပေါင်း၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ (၁) အမျိုးမျိုးသော အပင်များပေါက်ရောက်ခြင်း နှင့် ရေနေသတ္တဝါများ ကျင်လည်ကျက်စားခြင်း၊ အထူးသဖြင့် တိရစ္ဆာန်များမှထွက်ရှိသော စွန့်ပစ် အညစ်အကြေးများကြောင့် လည်းကောင်း၊ (၂) ပတ်ဝန်းကျင်မှ စီးဆင်းရေများသည် အနီးပတ်ဝန်းကျင်မှ အညစ်အကြေးများကို ရွှေ့ပျောက်ချောင်းသို့ရောက်ရှိစေနိုင်ပြီး၊ ၎င်းစီးဆင်းရေများတွင် ပါဝင်သော တိရစ္ဆာန်များ၏စွန့်ပစ်အညစ်အကြေးများနှင့် အခြားအညစ်အကြေးများသည် ကိုလီဖောင်းပါဝင်မှုအား မြှင့်တက်စေနိုင်ခြင်းကြောင့် လည်းကောင်း၊ ၃) ဒီရေတက်ချိန်တွင် ရွှေ့ပျောက်ချောင်းတလျှောက် တိုးဝင်လာသောဒီရေများတွင် ပါရှိလာနိုင်သောအညစ်အကြေးများကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် ဆိုင်းကြွအနယ်၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ (၁) သဘာဝအလျောက် ချောင်းအထက်ပိုင်းမှ စီးဆင်းလာခြင်းနှင့် သီလဝါအထူးစီးပွားရေးဇုန် ပြင်ပရှိ ပြည်တွင်းစက်မှုဇုန်မှ စွန့်ထုတ်လိုက်သောရေများကြောင့်လည်းကောင်း၊ (၂) ရွှေ့ပျောက်ချောင်းတလျှောက် ချောင်းအောက်ဘက်ရှိ ရေများသည် ဒီရေအတက်အကျကြောင့် အထက်သို့ ပြန်လည်စီးဝင်လာခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) နှင့် မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) တို့တွင် သံဓာတ် ၏ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးများထက် ကျော်လွန်ခြင်းမှာ သံဓာတ်အရင်းအမြစ်၏ လွှမ်းမိုးမှုကြောင့် ဖြစ်နိုင်ပြီး (သံဓာတ်သည် ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်) ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသော မြေဆီလွှာ(ဂဝံမြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းမြေသားများသည် မြေခိုမိုပိုင်းဒေသများသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။

သံဓာတ်ရလဒ်အနေဖြင့် မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) သည် ရည်မှန်းတန်ဖိုးထက် အနည်းငယ် ကျော်လွန်နေပါသည်။ ဧပြီလ၊ ၂၀၁၉ ခုနှစ်ကတည်းက မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ၏ ယခင် စောင့်ကြည့်လေ့လာမှုရလဒ်များနှင့် နှိုင်းယှဉ်သောအခါတွင် သံဓာတ်ရလဒ်များသည် ဧပြီလ၊ ၂၀၂၃ခုနှစ်တွင် ၀.၁၀၈ မီလီဂရမ်/လီတာ မှ ဒီဇင်ဘာလ၊ ၂၀၂၃ခုနှစ် တွင် ၁၄.၁၀၀ မီလီဂရမ်/လီတာ အတွင်းရှိပါသည်။ ဩဂုတ်လ ၂၀၁၉ခုနှစ်၊ ဖော်ဖော်ဝါရီလ နှင့် ဧပြီလ၊ ၂၀၂၂ခုနှစ် နှင့် ဧပြီလ၊ ၂၀၂၃ခုနှစ် တို့၏ သံဓာတ်ပါဝင်မှုရလဒ်မှလွဲ၍ သံဓာတ်ပါဝင်မှုရလဒ် အများစု (ဧပြီလ၊ ၂၀၁၉ခုနှစ် မှ ဒီဇင်ဘာလ၊ ၂၀၂၃ခုနှစ်အထိ)သည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရသည်။ ထို့ကြောင့် ဖြစ်နိုင်ချေရှိသော အကြောင်းအရာများမှာ သဘာဝမြေဆီလွှာမှ သံဓာတ် အရင်းအမြစ် လွှမ်းမိုးမှု ကြောင့်ဖြစ်နိုင်ပါသည် (သံဓာတ်သည်ရေစီးဆင်းမှုကြောင့် မြေဆီလွှာအတွင်းမှ ထွက်လာနိုင်ပါသည်)။ အထူးသဖြင့် သီလဝါ အထူးစီးပွားရေးဇုန်၏ ပတ်ဝန်းကျင်ရှိ တောင်ကုန်းငယ်များသည် သံဓာတ်ကြွယ်ဝသောမြေဆီလွှာ (ဂဝံမြေ)ဖြင့် အဓိကဖွဲ့စည်းထားပြီး စီးဆင်းရေများကြောင့် ၎င်းသံဓာတ်များသည် မြေအောက်ရေအောင်းလွှာအတွင်းသို့ ရောက်ရှိသွားသောကြောင့် ဖြစ်နိုင်ပါသည်။



အနာဂတ်တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ၏ အဓိကစွန့်ထုတ်ရေ ထွက်ရှိသောနေရာများမှ ထွက်ရှိလာသော ရေအရည်အသွေးများဖြစ်သည့် ကိုလီဖောင်းစုစုပေါင်း၏ ရည်မှန်းတန်ဖိုးနှင့် သင့်လျော်သော ရေအရည်အသွေး စောင့်ကြည့်လေ့လာမှု ရရှိနိုင်ရန် အောက်ပါဆောင်ရွက်ချက်များကို လုပ်ဆောင်သင့်ပါသည်။

- ကိုလီဖောင်းဘက်တီးရီးယားများ၏ ကျန်းမာရေးအပေါ်သက်ရောက်မှုကို သိရှိနိုင်ရန် ဝမ်းကိုက်ရောဂါကို ဖြစ်စေသော ကိုလီဖောင်းဘက်တီးရီးယား(E. Coli) ကိုဆက်လက်စောင့်ကြည့်ရန်။
- မြေလွတ်များမှ မြေမျက်နှာပြင်ရေများစီးဆင်းမှု အခြေအနေကို စောင့်ကြည့်လေ့လာသည့် လုပ်ဆောင်ချက်များကို လုပ်ဆောင်ရန်။
- ဧကန်မှုများမှ ထွက်လာသော စွန့်ပစ်ရေများအား စောင့်ကြည့်လေ့လာသည့် လုပ်ဆောင်ချက်များကို လုပ်ဆောင်သင့်ပါသည်။

ဤတွင်စာတမ်းပြီးဆုံးပါသည်။



နောက်ဆက်တွဲ ၁ ရေနမူနာရယူသည့် မှတ်တမ်းဓာတ်ပုံများ



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း (ခ) ရှိ စွန့်ထုတ်ရေနမူနာယူသည့်နေရာ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၇ (SW-7) မှ ရေနမူနာယူခြင်းနှင့်တိုင်းတာခြင်း

စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏ အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၂ (SW-2) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေပေါ်ရေနမူနာယူသည့် နေရာ-၄ (SW-4) ၌ ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း



မြေအောက်ရေနမူနာယူသည့် နေရာ-၂ (GW-2) ရေနမူနာရယူခြင်းနှင့်တိုင်းတာခြင်း

နောက်ဆက်တွဲ ၂ စာတ်ခွဲခန်းရလဒ်များ



စွန့်ထုတ်ရေထွက်ရှိရာနေရာ

03/12/2023

Environmental Protection Agency
Ministry of Natural Resources and Environmental Conservation



Report No. : GEM-LAB-210212023
Revision No. : 1
Report Date : 18 December, 2023
Application No. : 0603-C001

Analysis Report

Client Name Myanmar Kay International LTD (MKI)
Address No. 38/A, 3rd Floor, Grand Plo Sen Condominium, Plo Sen Road, Tamar Township, Yangon, Myanmar
Project Name Environment Monitoring report for Zone A & B
Sample Description
Sample Name H&I-DW-7-1201
Sample No. W-2112017
Water Profile No. -
Received Date 5 December, 2023
Sample to Customer
Sample Received Date 5 December, 2023
Analytical Date 5-18/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540 (Dry at 103-105°C Method)	mg/l	388	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	6.47	0.01
3	COD (Cr)	APHA 5220 (Closed Reflux Colorimetric Method)	mg/l	19.4	0.7
4	Total Coliform	APHA 5221B (Standard Total Coliform Fermentation Test/negative)	number	<100000	1.0
5	Total Sulfide	APHA 5520 (Purden - Gasometric Method)	mg/l	<2.4	0.1
6	Color	APHA 2120C (Spectrophotometric Method)	PCU	10.94	0.00
7	Total Nitrogen	WACH Method 10012 (TNF Persulfate Digestion Method)	mg/L	3.3	0.1
8	Total Phosphorus	APHA 4500-P E (Ascorbic Acid Method)	mg/l	0.79	0.05
9	Arsenic	WACH Method 10205 (Silverplate TNT Plus Method)	mg/l	0.76	0.02
10	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	344	-
11	Chlor	APHA 2130 B (Threshhold Chlor Test)	TCU	1.4	0
12	Mercury	APHA 3130 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
14	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
15	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
16	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
17	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
18	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.188	0.002

THIS REPORT IS ONLY VALID FOR THE SAMPLES ANALYZED.
NO GUARANTEE SHALL BE MADE FOR THE RESULTS OBTAINED BY THIS ANALYSIS WHEN THE SAMPLES ARE NOT REPRESENTATIVE OF THE POPULATION.
LABORATORY: GEM



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း (ခ) ကိုစက်မှုဇုန်ဖြိုတိုက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း ခုနစ်တစ်ကြိမ် ၂၀၂၃ ခုနှစ်)

01/08/24

Water Quality Monitoring Report
for the Industrial Effluent
Monitoring and Control System



No.	Parameter	Method	Unit	Result	LOQ
01	Water	APHA 5120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
02	Salinity	APHA 5120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
03	Iron	APHA 5120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	31.680	0.002
04	Cyanide	HACH 8007 (Fenoxide - Pyrazole Method)	mg/l	<0.003	0.002
05	Total Cyanide	Distillation Process APHA 4500-CN- C, Total Cyanide after Distillation, Determination Cyanide Concentration Process HACH 8007 (Fenoxide - Pyrazole Method)	mg/l	<0.004	0.002
06	Hexavalent Chromium (Cr6+)	ISO 11063 (1994) (Determination of chromium(VI) Spectrometric method using 1,5-diphenylcarbazide)	mg/l	<0.05	0.05
07	Fluoride	APHA 4500 F (Ion Chromatography with Chemical Suppression of Fluoride Conductivity)	mg/l	1.000	0.014
08	Free Chlorine	APHA 4500 Cl, G (DPD Colorimetric Method)	mg/l	<0.1	0.1
09	Total Residual Chlorine	APHA 4500 Cl, G (DPD Colorimetric Method)	mg/l	<0.1	0.1
10	Sulphide	HACH 8131 (LCEPA Methylene Blue Method)	mg/l	0.515	0.005
11	Formaldehyde	HACH 8110 (MBTH Method)	mg/l	0.395	0.003
12	Biochemical Oxidation	APHA 5211 P (5-days incubation at 20°C using H ₂ O ₂ as substrate)	mg/l	6.9	6.9
13	Phosphate	APHA 4500 P (Ascorbic Acid Reduction Spectrophotometric Method)	mg/l	0.015	0.002

Remark

LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), The American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 5120 B (ICP) Total Iron - ICP/MS Total Iron only. The ICP is independent of the matrix and not for Fe-Cu and

Analysed By

Cherry Myint Thant
Assistant Manager



Approved By

H. H. Aye Win
Manager

Water Quality Monitoring and Control System
for the Industrial Effluent Monitoring and Control System
at the Industrial Effluent Monitoring and Control System



DOWA

GOLDEN DOWA ECO-SYSTEM MYANMAR CO., LTD.
Lot No.01, Thilawa SEZ Zone A, Yangon Region, Myanmar
Phone No./Fax No. (+95) 1 2308051



Indicate our plant
Doc.No: GEM-18-R0005/000/011
Page:1 of 1

Report No. : GEM-LAB-202401036

Revision No. : 1

Report Date : 17 January, 2024

Application No. : 0001-C001

Analysis Report

Client Name : MJTD Co Ltd

Address : 1st Floor, Administration Complex, Thilawa Special Economic Zone, Yangon.

Project Name : -

Sample Description

Sample Name : SW-3(Environment)

Sampling Date : 9 January, 2024

Sample No. : W-2401085

Sampling By : Customer

Waste Profile No :

Sample Received Date : 9 January, 2024

Analytical Date : 9-17/01/2024

No.	Parameter	Method	Unit	Result	LOQ
1	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	12.040	0.002

Remark : LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

Analysed By:

Ni Ni Aye Lwin
Manager



Approved By :

Htet Aye Yomo Jan. 27, 2024
Managing Director

REPORT RESULT IS ONLY OF THE SAMPLE SUBMITTED FOR ANALYSIS.
THIS ANALYSIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL, WITHOUT WRITTEN APPROVAL OF THE LABORATORY OF
GOLDEN DOWA ECO-SYSTEM MYANMAR CO., LTD.



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)မြို့စက်မှုဇုန်နှင့်မြို့သတိုးတက်မှုအတွက်ရေးအစည်းအသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

စွန့်ထုတ်ရေထွက်ရှိသောနေရာများနှင့် စွန့်ထုတ်ရေရောက်ရှိနိုင်သည့်ချောင်း၏ အခြေခံအချက်အလက်များကို နှိုင်းယှဉ်ရန်အတွက် ရည်ညွှန်းစောင့်ကြည့်လေ့လာသည့် နေရာများ

07700000

Myanmar Koen International (P) Ltd (MKI)
Environmental & Engineering
No. 16/A, 1st Floor, Grand Phe Sam Condominium, Phe Sam Road, Tander Township, Rangoon, Myanmar




Report No.: MKI-LAB-001/1/2023
Revision No.: 1
Report Date: 29 December, 2023
Application No.: 0001-0301

Analysis Report

Client Name: Myanmar Koen International (P) Ltd (MKI)
Address: No. 16/A, 1st Floor, Grand Phe Sam Condominium, Phe Sam Road, Tander Township, Rangoon, Myanmar
Project Name: Environment Monitoring report for Zone A & B
Sample Description:
Sample Name: MKI-SAM-2-1205
Sample No.: WJ212014
Water Profile No.:
Sampling Date: 3 December, 2023
Sampling By: Customer
Sample Received Date: 5 December, 2023
Analytical Date: 5-18/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	79	-
2	BOD (5)	APHA 5210 B (5 Days BOD Test)	mg/l	17.67	0.00
3	COD (Cr)	APHA 5220D (Dichloro Reflux Colorimetric Method)	mg/l	50.0	0.7
4	Total Coliform	APHA 9221B (Standard Total Coliform Fermentation Technique)	mpn/100ml	100000	1.8
5	Oil and Grease	APHA 5520B (Filtration-Gravimetric Method)	mg/l	<0.3	0.3
6	Color	APHA 2120C (Spectrophotometric Method)	PCU	36.00	0.00
7	Total Nitrogen	HACH Method 10072 (TNB Persulfate Digestion Method)	mg/l	2.3	0.5
8	Total Phosphorus	APHA 4500-F (Ascorbic Acid Method)	mg/l	0.31	0.05
9	Amonia	HACH Method 10005 (Nesslerize TNB Plus Method)	mg/l	1.05	0.00
10	TDS	APHA 2540 C (Total Dissolved Solids Filter at 180°C Method)	mg/l	366	-
11	Color	APHA 2120 B (Threshold Color Test)	PCU	1	0
12	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
14	Arasenit	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
15	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
16	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
17	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.01
18	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.399	0.002



Myanmar Koen International (P) Ltd (MKI)
Environmental & Engineering
No. 16/A, 1st Floor, Grand Phe Sam Condominium, Phe Sam Road, Tander Township, Rangoon, Myanmar



သီပေါတံအလှူအတန်းများနှင့်ဆိုင်ရာ (ခ)ရိုက်ကူးမှုနှင့်မြို့တော်တက်မှုအတွက်ရေအရည်အသွေးဆောင်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ် ဆောင်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

000004-04

Water Resource Management Unit
Department of Natural Resources
Ministry of Natural Resources and Environmental Conservation



No.	Parameter	Method	Unit	Result	LOQ
21	Nickel	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
22	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.002	0.002
23	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	5.568	0.002
24	Cyanide	HACH 8007 (Pyridine-Pyrazolone Method)	mg/l	<0.002	0.002
25	Total Cyanide	Distillation Process (APHA 4500-CN-E, Total Cyanide after Distillation, Determine Cyanide Concentration Process (HACH 8007 (Pyridine-Pyrazolone Method)	mg/l	0.002	0.002
26	Hexachlorobenzene (HCB)	ISO 11083:1994 (Determination of chromium(VI) Spectrophotometric method using 1,5-dichloroquinone)	mg/l	<0.05	0.05
27	Fluoride	APHA 4500-F (Ion Chromatography with Chemical Suppression of Fluoride / Ion Chromatography)	mg/l	0.183	0.014
28	Free Chlorine	APHA 4500-CL-2 (DPD Colorimetric Method)	mg/l	<0.1	0.1
29	Total Residual Chlorine	APHA 4500-CL-2 (DPD Colorimetric Method)	mg/l	<0.1	0.1
30	Sulfate	HACH 8131 (Barium Methopropyl Blue Method)	mg/l	0.124	0.005
31	Formaldehyde	HACH 8110 (MBTH Method)	mg/l	0.124	0.003
32	Phenols	APHA Method 8211 (Phenol (4-aminodiphenylamine, Resorcinol Method Solution)	mg/l	0.012	0.002

Remark

LOQ = Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF). Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 2120B-63: Color Unit = TCU (True Color Unit). One TCU is equivalent to one Pt-Co unit and to one PC-Co unit.

Analysed By

Cherry Hsiao Hsiao
Assistant Manager



Approved By

Mr. Aye Linn
Manager

Water Resource Management Unit
Department of Natural Resources
Ministry of Natural Resources and Environmental Conservation



သီလဝါဆေးရုံစီးပွားရေးဇုန်အပိုင်း (ခ)ရှိစက်မှုဇုန်မှ ပြိုကျတိုက်ခတ်မှုအတွက် ရေအရင်းအမြစ်ဆောင်ကြည့်စစ်ချက်မှဆွေးနွေးရန်မိန့်ခွင့်
(တစ်နှစ် နှစ်ကြိမ်၊ ဆောင်ကြည့်စစ်ချက်ပြုင်း နိုဗင်ဘာလ ၂၀၂၃ ခုနှစ်)

01/12/2023

ANALYSIS REPORT
ANALYSIS REPORT
ANALYSIS REPORT



Report No. : GEM-LAB-2023/2023

Reason No. : 1

Report Date : 1/8 December, 2023

Application No. : 0001-C001

Analysis Report

Client Name : Myanmar Rose International LTD (MRO)
Address : No. 35/A, 1st Floor, Crystal Plaza South Condominium, Plot 35B Road, Tarnier Township, Yangon, Myanmar
Project Name : Environmental Monitoring report for Zone A & B
Sample Description :
Sample Name : H2O-SW-A-1205
Sample No. : 0-21122023
Water Profile No. :
Sampling Date : 5 December, 2023
Sampling By : Customer
Sample Received Date : 5 December, 2023
Analysis Date : 5-10/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1	pH	APHA 2540D (Dry at 105-105°C Method)	mg/l	6.4	—
2	DO (%)	APHA 5210 B (5-Days DOG Test)	mg/l	11.89	0.00
3	COB (G)	APHA 5220D (Closed Reflux Colorimetric Method)	mg/l	10.1	0.2
4	Total Calcium	APHA 9211B (Standard Total Calcium Fermentation Technique)	mg/100ml	28000.0	1.8
5	Oil and Grease	APHA 1533B (Particulate-Gravimetric Method)	mg/L	<3.1	3.1
6	Color	APHA 2120C (Nephelometric Method)	PCU	16.80	0.00
7	Total Nitrogen	NACH Method (007) (TNT Persulfate Digestion Method)	mg/l	3.8	0.5
8	Total Phosphorus	APHA 4500 P L (Ascorbic Acid Method)	mg/l	0.38	0.05
9	Amonia	NACH Method (0009) (Nite plate TNT Plus Method)	mg/l	0.51	0.02
10	TDS	APHA 2540 C (Total Dissolved Solids Dried at 180°C Method)	mg/l	302	—
11	Odor	APHA 2150 B (Threshold Odor Test)	TCN	3	6
12	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.003	0.002
14	Arsonic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.018	0.012
15	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
16	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/L	<0.002	0.002
17	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.01
18	Cuall	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20	Barium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.260	0.043

ANALYSIS REPORT
ANALYSIS REPORT
ANALYSIS REPORT



သီလဝါအထူးစီးပွားရေးနှင့်အပိုင်း(ခ)မြို့နယ်မှစုန်ဖွံ့ဖြိုးတိုးတက်မှုအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ မှစ၍)

02/04/2023

See appendix for more information on...
02/04/2023 02:00 PM Report Date: 02/04/2023
Page No. 1 of 1 (1/1) (1/1)



No.	Parameter	Method	Unit	Result	LOQ
21	Nickel	APHA 31.22 B (Inductively Coupled Plasma - ICP Method)	mg/L	<0.002	0.002
22	Silver	APHA 31.25 B (Inductively Coupled Plasma - ICP Method)	mg/L	<0.002	0.002
23	Iron	APHA 31.23 B (Inductively Coupled Plasma - ICP Method)	mg/L	0.885	0.002
24	Cyanide	HACH 8027 (Pyridine - Persulfate Method)	mg/L	<0.002	0.002
25	Total Cyanide	Distillation Process: APHA 4500-CN-1C Total Cyanide after Distillation, Determining Cyanide Concentration Process: HACH 8027 (Pyridine - Persulfate Method)	mg/L	0.002	0.002
26	Hexavalent Chromium (Cr ⁶⁺)	ISO 11883:1994 (Determination of Chromium(VI) Spectrophotometric method using 1,5-diphenylarsinate)	mg/L	<0.05	0.05
27	Phosphate	APHA 4500-P (Ascorbic Acid Method with Chemical Suppression of Interference)	mg/L	1.395	0.014
28	Free Chlorine	APHA 4500-CL-G (DPD Colorimetric Method)	mg/L	<0.1	0.1
29	Total Residual Chlorine	APHA 4500-CL-G (DPD Colorimetric Method)	mg/L	<0.1	0.1
30	Sulphide	HACH 8131 (USEPA Methylene Blue Method)	mg/L	0.124	0.005
31	Formaldehyde	HACH 8110 (MBTH Method)	mg/L	0.094	0.003
32	Phenol	APHA Method 420.1 (Phenol (Spectrophotometric) Method 4AMP With Distillation)	mg/L	0.007	0.003

Remark

LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 2110B.820: Color Unit - PCU (True Color Unit). One PCU is equivalent to one Hazen unit and 15 one Pt-Co unit

Analyzed by

Cherry Myint Thin
Assistant Manager



Approved by

M. Th. Aye Lwin
Manager

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်(ခ)ရိုက်ကူးဇုန်ဖြန့်ဖြူးတိုက်ပွားအတွက်ရေအရည်အသွေးစောင့်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ်၊ စောင့်ကြည့်လေ့လာခြင်း ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

02026/4

Quality Policy: We are committed to providing high quality services to our customers and to the continuous improvement of our processes.



Report No. : QM-LAB-2023-2023

Revision No. : 1

Report Date : 17 December, 2023

Application No. : 0001-CD01

Analysis Report

Client Name: Myanmar Retail International (P) (MRI)
Address: No. 34/A, 1st Floor, Grand Plaza Res Condominium, Pao Sein Road, Tamae Township, Yangon, Myanmar.
Project Name: Government Monitoring report for Zone A & B
Sample Description: Milk-Gar 2-1235
Sample Name: M-2312018
Master Profile No.:
Issued On: 5 December, 2023
Issued To: Customer
Sample Received Date: 5 December, 2023
Analytical Date: 5-19/12/2023

No.	Parameter	Method	Unit	Result	LOQ
1.	SS	APHA 2540D (Dry at 103-105°C Method)	mg/l	3	-
2.	BOD (5)	APHA 5211 B (5 Days BOD Test)	mg/l	1.68	0.00
3.	COD (Cr)	APHA 5220D (Class Reflux Colorimetric Method)	mg/l	<0.7	0.7
4.	Total Coliform	APHA 9211B (Standard Total Coliform Fermentation Technique)	mpn/100ml	140.0	1.0
5.	Oil and Grease	APHA 9520B (Partition Gravimetric Method)	mg/l	<0.1	0.1
6.	Color	APHA 2120C (Spectrophotometric Method)	PCU	14.55	0.00
7.	Total Nitrogen	HACH Method 10072 (TNB Persulfate Digested Method)	mg/l	<0.5	0.5
8.	Total Phosphorus	APHA 4500-P E (Ascorbic Acid Method)	mg/l	0.00	0.00
9.	Ammonia	HACH Method 30285 (Salicylate TNT Plus Method)	mg/l	0.21	0.02
10.	TDS	APHA 2540 C (Total Dissolved Solids dried at 100°C Method)	mg/l	200	-
11.	Odor	APHA 2150 B (Threshold Odor Test)	TCU	3	0
12.	Mercury	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
13.	Zinc	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
14.	Arsenic	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
15.	Chromium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
16.	Cadmium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
17.	Selenium	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.010	0.010
18.	Lead	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
19.	Copper	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
20.	Manganese	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	0.100	0.002

LAB
GEM

Myanmar Testing & Inspection Co., Ltd. (MTI) is a leading provider of quality assurance services in Myanmar. We are committed to providing high quality services to our customers and to the continuous improvement of our processes.



သီလဝါဆေးရုံစီးပွားရေးဇုန်အိုင်(၁)မြို့စက်မှုဇုန်မှ ဖြိုတိုက်မှုအတွက် ရေအရည်အသွေးဆိုင်ကြည့်လေ့လာမှုအစီရင်ခံစာ
(တစ်နှစ် နှစ်ကြိမ် ဆောင်ကြည့်လေ့လာခြင်း အင်တာလပ် ၂၀၂၃ ခုနှစ်)

01/04/23

01/04/23
01/04/23
01/04/23



No.	Parameter	Method	Unit	Result	LOQ
21	Nickel	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
22	Silver	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	<0.002	0.002
23	Iron	APHA 3120 B (Inductively Coupled Plasma (ICP) Method)	mg/l	24.038	0.002
24	Cyanide	HACh 8027 (Pyridine - Pyrazolone Method)	mg/l	<0.002	0.002
25	Total Cyanide	Distillation Process/ APHA 4520-CB-C, Total Cyanide after Distillation, Potassium Cyanide Concentration/HACh 8027 (Pyridine - Pyrazolone Method)	mg/l	<0.002	0.002
26	Hexavalent Chromium (Cr6+)	ISO 11063:1994 (Determination of chromate(VI) Spectrophotometric method using L-3-diphenylcarbazide)	mg/l	<0.05	0.05
27	Fluoride	APHA 4110 B (Ion Chromatography with Chemical Suppression of Suppression)	mg/l	8.227	0.014
28	Free Chlorine	APHA 4500-Cl ₂ G (DPO Colorimetric Method)	mg/l	<0.1	0.1
29	Total Residual Chlorine	APHA 4500-Cl ₂ G (DPO Colorimetric Method)	mg/l	<0.1	0.1
30	Sulfide	HACh 8124 (LSBPA Methylene Blue Method)	mg/l	<0.005	0.005
31	Formaldehyde	HACh 8110 (MBCH Method)	mg/l	<0.004	0.002
32	Escherichia Coli	APHA 9221 F Escherichia Coli Preset (Using Phosphoric Acid)	mpn/100ml	<1.8	1.8
33	Phosphate	APHA Method 4500-P (Phosphomolybdate, Molybdate with Salicylate)	mg/l	<0.002	0.002

Remark

LOQ - Limit of Quantitation

APHA - American Public Health Association (APHA), the American Water Works Association (AWWA), and the Water Environment Federation (WEF), Standard Methods for the Examination of Water and Wastewater, 22nd edition

APHA 2120B (Cr6+): Color Unit - 1CU/100ml Color Unit. One CU is equivalent to one Hg2+ unit and to one PtCl6- unit.

Analysed By

Cherry Myint Thin
Assistant Manager



Approved By

Win Aye Linn
Manager

Report shall remain confidential and shall not be disclosed to any third party without the prior written consent of the Laboratory. The data in this report shall not be used for any purpose other than that for which it was generated. The Laboratory shall not be held responsible for any loss or damage caused by the use of the data in this report.



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ် နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့ဆိုင် အင်တာနေရှင်နယ် လီမိတက်



ဇယားကဏ္ဍ

အခန်း ၁ စောင့်ကြည့်လေ့လာသောအစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၂
၂.၃ စောင့်ကြည့်လေ့လာသည့်ကာလ	၃
၂.၄ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း	၃
၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ	၄
အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ	၁၀
နောက်ဆက်တွဲ-၁ ဘာရီယမ်မျှလေထုအရည်အသွေးတန်ဖိုး	ကဏ္ဍ-၁
နောက်ဆက်တွဲ-၂ လေထုအရည်အသွေးတိုင်းတာသည့်စက်ကို စံကိုက်ညီထားသောလက်မှတ်	ကဏ္ဍ-၁

ဇယားများစာရင်း

ဇယား ၁.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာမှုရလဒ် (နေ့စဉ်ပျမ်းမျှ)	၅
ဇယား ၂.၅-၂ ကျော်လွန်သောအချိန်ရစုစုပေါင်း	၉
ဇယား ၂.၅-၃ နေရာ-၁ (AQ-1) ၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်	၉

ပုံများစာရင်း

ပုံ ၂.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၃
ပုံ ၂.၄-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအခြေအနေ	၄
ပုံ ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1) ၏ လေတိုက်ခတ်သည့်အရပ် အခြေအနေ	၆
ပုံ ၂.၅-၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1) ၏ လေတိုက်နှုန်းနှင့် လေလမ်းကြောင်းပြပုံ (Wind Rose Diagram)	၇



အခန်း ၁ စောင့်ကြည့်လေ့လာသောအစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာ စီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက်စောင့်ကြည့် လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန် လုပ်ငန်း လည်ပတ် နေခြင်းကြောင့် စက်မှုဇုန်အတွင်း နှင့် အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၃ခုနှစ်၊ ဒီဇင်ဘာလ ၁၁ ရက်နေ့ မှ ဒီဇင်ဘာလ ၁၈ ရက်နေ့ အထိ လေထုအရည်အသွေးအား စောင့်ကြည့်လေ့လာခဲ့သည်။

ဇယား ၁.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာ သည့် ရက်စွဲ	စောင့်ကြည့်လေ့ လာမှုအမျိုးအစား	တိုင်းတာသော အမျိုးအစားများ	တိုင်းတာသောနေရာ အရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
၁၁ရက် ဒီဇင်ဘာလ - ၁၈ရက် ဒီဇင်ဘာလ ၂၀၂၃ခုနှစ်	လေထုအရည် အသွေး	ကာဗွန်မိုနောက်ဆိုက်(CO) နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO ₂)၊ အမှုန်အမွှား (PM _{2.5})၊ အမှုန်အမွှား (PM ₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂)	၁	၇ ရက်	ပတ်ဝန်းကျင်လေအရည်အသွေး တိုင်းတာသည့်စက်ကိရိယာ (Haz-Scanner EPAS) ဖြင့် ဖြေပြင်တွင်ကျင်းဆင်းတိုင်းတာ ခြင်း

မှတ်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်



အခန်း ၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့်အမျိုးအစား

လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသော အမျိုးအစားများမှာ ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) တို့ဖြစ်သည်။

၂.၂ စောင့်ကြည့်လေ့လာသည့်တည်နေရာ

ပတ်ဝန်းကျင်လေထုအရည်အသွေးတိုင်းတာသည့် စက်ကိရိယာဖြစ်သည့် "Haz-Scanner Environmental Perimeter Air Station (EPAS)" အား သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ တောင်(S)ဘက်၊ မြောက်လတ္တီတွဒ် ၁၆°၃၉'၂၄.၂၀"၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၅.၈၀"၊ ဖလမ်းကျွန်း၊ ဖလမ်းရွာဦး ကျောင်းဝန်းထဲတွင် တပ်ဆင်ထားသည်။ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)သည် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ တောင်(S) ဘက် နယ်နိမိတ်နှင့် နီးကပ်သကဲ့သို့ မြောက်(N) နှင့် အရှေ့(E) ဘက်တို့တွင် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)တို့ဖြင့် ဝန်းရံထားသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)၏ တောင်(S) နှင့် အနောက်(W)ဘက်တွင် ဖလမ်းကျွန်းရှိလူနေအိမ်များနှင့် လယ်ကွင်းများ အသီးသီး တည်ရှိနေသည်ကို တွေ့ရှိရပါသည်။ ထို့အပြင် သီလဝါ အထူးစီးပွားရေးဇုန် အပိုင်း(က)သည် လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)၏ မြောက်(N)ဘက် ၂ ကီလိုမီတာခန့် ကွာဝေးသကဲ့သို့ ပြည်တွင်းသီလဝါ စီးပွားရေးဇုန် သည် အရှေ့မြောက်(NE)ဘက် ၁ ကီလိုမီတာခန့် အကွာတွင်ရှိပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာမှုကို ဖလမ်းကျွန်းရှိ လူနေအိမ်များနှင့် အနီးဆုံးနေရာဖြစ်သော အထက်ပါနေရာ၌ ဆောင်ရွက်ခဲ့သည်။ အဓိကလေထုညစ်ညမ်းမှုကို ဖြစ်နိုင်သောစွန့်ထုတ်ဓာတ်ငွေ့များ ထုတ်လွှတ်ရာ အရင်းအမြစ်များမှာ ဆောက်လုပ်ရေးလုပ်ငန်းစဉ်များမှ ဖုန်များထွက်ရှိခြင်း၊ သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ ဆောက်လုပ်ရေးလုပ်ငန်းသုံး ယာဉ်များ၊ စက်ပစ္စည်းများနှင့် ဖလမ်းကျွန်းရှိ နေထိုင်သူများ၏ နေ့စဉ်လုပ်ငန်းဆောင်တာများကြောင့် ဖြစ်နိုင်ပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့် လေ့လာသောနေရာကို ပုံ ၂.၂-၁ တွင်ပြသထားပါသည်။





မူရင်း ပုံအတိုင်း

ပုံ ၂.၂-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့်တည်နေရာ

၂.၃ စောင့်ကြည့်လေ့လာသည့်ကာလ

လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာမှုကို ၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ ၁၁ ရက်နေ့မှ ဒီဇင်ဘာလ ၁၈ ရက်နေ့အထိ (၇)ရက် ဆက်တိုက် ဆောင်ရွက်ခဲ့သည်။

၂.၄ စောင့်ကြည့်လေ့လာသည့်နည်းလမ်း

ပတ်ဝန်းကျင်လေထုအရည်အသွေး စံနမူနာယူခြင်းနှင့် ဆန်းစစ်လေ့လာခြင်းများကို အမေရိကန် ပတ်ဝန်းကျင်ဆိုင်ရာ ထိန်းသိမ်းရေးအေဂျင်စီ (U.S. EPA) ၏ အကြံပြုချက်များကို ကိုးကား၍ ကာဗွန်မိုနောက်ဆိုက် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂)တို့အား စောင့်ကြည့်လေ့လာမှုများ လုပ်ဆောင်ခဲ့သည်။ ပတ်ဝန်းကျင်လေထုအရည်အသွေးကို စောင့်ကြည့်တိုင်းတာ၍ အချက်အလက်ရယူရန်အတွက် Haz-Scanner Environmental Perimeter Air Station (EPAS)ကို အသုံးပြုခဲ့ပါသည်။ လေထုအရည်အသွေး အမျိုးအစား၏ အချက်အလက်များဖြစ်သော (ကာဗွန်မိုနောက်ဆိုက် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂)) ကို တစ်မိနစ်တိုင်း အလိုအလျောက်တိုင်းတာ၍ မှတ်တမ်းတင်



သိမ်းဆည်းထားပါသည်။ WRPLOT View (Ver. 8.0.2) ကို အသုံးပြု၍ လေတိုက်ခတ်သည့်အချက်အလက်များကို ခွဲခြမ်းစိတ်ဖြာခဲ့ပြီး ၎င်းတွက်ချက်မှုတွင် တစ်စက္ကန့်လေတိုက်နှုန်း ၀.၅ မီတာ အောက်ရောက်လျှင် လေငြိမ်သည်ဟု သတ်မှတ်ထားပါသည်။ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာသော အခြေအနေကို ပုံ ၂.၄-၁ တွင် ပြသထားပါသည်။



ပုရင်စ ပြန်ဟန်အဆင်တာနေရှင်နယ်လီမီတာ

ပုံ ၂.၄-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအခြေအနေ

၂.၅ စောင့်ကြည့်လေ့လာမှုရလဒ်များ

ကာဗွန်မိုနောက်ဆိုက် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂) တို့၏ လေထုအရည်အသွေး စောင့်ကြည့်လေ့လာမှုရလဒ်များမှ နေ့စဉ်ပျမ်းမျှ တန်ဖိုးများကို ဇယား ၂.၅-၁ တွင် ဖော်ပြထားပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်ရေးစီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင်ပါရှိသည့် ကာဗွန်မိုနောက်ဆိုက် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂) တို့၏ ရည်မှန်းတန်ဖိုးနှင့် နှိုင်းယှဉ်ရာ၌ ကာဗွန်မိုနောက်ဆိုက် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂) တို့၏ (၇)ရက်ပျမ်းမျှတန်ဖိုးများသည် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းနေသည်ကို တွေ့ရှိရသည်။ သို့သော်လည်း ရက်(၃)ရက်၏ နေ့စဉ် အမှုန်အမွှား (PM_{2.5}) ပါဝင်နှုန်းပျမ်းမျှတန်ဖိုးနှင့် ရက် (၂)ရက်၏ နေ့စဉ် အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုက် (SO₂) ပါဝင်နှုန်း ပျမ်းမျှတန်ဖိုးတို့သည် ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ အမှုန်အမွှား (PM_{2.5}) ၏ နေ့စဉ် ပျမ်းမျှတန်ဖိုးအား ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ကြီးကြီးကြွကြွ (MOEL) ၏ ပတ်ဝန်းကျင်စံတန်ဖိုး ၃၅ $\mu\text{g}/\text{m}^3$ (၀.၀၃၅ mg/m^3) နှင့် နှိုင်းယှဉ်ရာ၌ ကျော်လွန်နေသော တန်ဖိုးများသည် ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင် ထိခိုက်မှုဆန်းစစ်ကြီးကြွကြွ (MOEL) ၏ ပတ်ဝန်းကျင်စံတန်ဖိုး နှင့် ကိုက်ညီကြောင်း တွေ့ရှိရသည်။



ဇယား ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာမှုရလဒ် (နေ့စဉ်ပျမ်းမျှ)

နေ့စွဲ	ကာဗွန်မိုနောက်ဆိုက် (CO)	နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO ₂)	အမှုန်အမွှား (PM ₁₀)	အမှုန်အမွှား (PM _{2.5})	ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂)
	mg/m ³	mg/m ³	mg/m ³	mg/m ³	mg/m ³
၁၁-၁၂ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၁၆၆	၀.၀၄၁	၀.၀၂၄	၀.၀၃၆	၀.၀၁၆
၁၂-၁၃ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၂၃၃	၀.၀၆၆	၀.၀၂၆	၀.၀၅၆	၀.၀၂၃
၁၃-၁၄ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၁၇၉	၀.၀၈၂	၀.၀၂၇	၀.၀၆၅	၀.၀၂၇
၁၄-၁၅ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၂၃၇	၀.၀၉၂	၀.၀၂၄	၀.၀၄၁	၀.၀၁၉
၁၅-၁၆ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၁၉၈	၀.၀၇၈	၀.၀၂၉	၀.၀၄၇	၀.၀၁၈
၁၆-၁၇ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၁၃၉	၀.၀၉၆	၀.၀၂၃	၀.၀၃၄	၀.၀၁၉
၁၇-၁၈ ဒီဇင်ဘာလ၊ ၂၀၂၃	၀.၂၅၁	၀.၀၉၅	၀.၀၂၁	၀.၀၃၁	၀.၀၂၀
(၇)ရက် ပျမ်းမျှတန်ဖိုး	၀.၂၀၁	၀.၀၇၈	၀.၀၂၅	၀.၀၄၄	၀.၀၂၀
ရည်မှန်းတန်ဖိုး	၁၀.၂၆	၀.၁	၀.၀၂၅	၀.၀၅	၀.၀၂

မှတ်ချက်: CO, NO₂ နှင့် SO₂ တို့၏ ရည်မှန်းတန်ဖိုးများကို (ppm) ယူနစ်မှ (mg/m³) ယူနစ်သို့ ပြောင်းလဲထားပါသည်။ ပြောင်းလဲမှုညွှန်းချိုးမှာ အောက်ပါအတိုင်း ဖြစ်ပါသည်။

(၁) $CO, mg/m^3 = (CO, ppm) * (CO \text{ မော်လီကျူးအလေးချိန် (၂၈) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ)}$

(၂) $NO_2, mg/m^3 = (NO_2, ppm) * (NO_2 \text{ မော်လီကျူးအလေးချိန် (၄၆) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ)}$

(၃) $SO_2, mg/m^3 = (SO_2, ppm) * (SO_2 \text{ မော်လီကျူးအလေးချိန် (၆၄) / ၂၄.၄၅ (အပူချိန် ၂၅ ဒီဂရီစင်တီဂရိတ်နှင့် ၁ atm အခြေအနေ)}$

မှတ်ချက်: ဖြန့်ဖြူးမှုဆိုင်ရာအချက်အလက်များကို

လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)တွင် လေတိုက်ခတ်ရာအရပ်နှင့် လေတိုက်နှုန်းကို တိုင်းတာခဲ့ပါသည်။ တိုင်းတာထားသော လေတိုက်ခတ်ရာအရပ်နှင့် လေတိုက်နှုန်းတို့၏ တစ်နာရီပျမ်းမျှ တန်ဖိုးများကို နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားပါသည်။ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1)၏ လေတိုက်ခတ်ရာအရပ် အကြိမ်အရေအတွက်အား ပုံ ၂.၅-၁ နှင့် ပုံ ၂.၅-၂ တို့တွင် ပြသထားပါသည်။ လေတိုက်ခြင်းဆိုင်ရာ အချက်အလက်များ ခွဲခြမ်းစိတ်ဖြာမှုအရ စောင့်ကြည့် လေ့လာနေစဉ်အတွင်း လေတိုက်ခတ်သည့် အကြိမ်အရေအတွက် အများဆုံးအရပ်မှာ အရှေ့မြောက် (NE) မှဖြစ်ပြီး အကြိမ်အရေအတွက် အနည်းဆုံး လေတိုက်ခတ်ရာအရပ်မှာ အနောက်တောင် (SW) အရပ်မှ ဖြစ်သည်။ စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း အမြင့်ဆုံးလေတိုက်နှုန်းမှာ တစ်စက္ကန့်လျှင် ၁.၀ မီတာ ဖြစ်ပြီး ပျမ်းမျှလေတိုက်နှုန်းမှာ တစ်စက္ကန့်လျှင် ၀.၀၉ မီတာ ဖြစ်သည်။ တစ်စက္ကန့်လေတိုက်နှုန်း ၀.၅ မီတာ အောက်ရောက်လျှင် လေငြိမ်သည်ဟု သတ်မှတ်သည့်အတွက် လေငြိမ်သည့်ရာခိုင်နှုန်းသည် ၈၃.၉၃ ရာခိုင်နှုန်း ရှိပါသည်။ ပျမ်းမျှလေတိုက်နှုန်းသည် သတ်မှတ်ထားသည့် လေငြိမ်သည့်နှုန်းအောက် ရှိနေသောကြောင့် စောင့်ကြည့်လေ့လာသည့် ကာလအတွင်းတွင် လေငြိမ်နေသည်ဟု ယူဆနိုင်ပါသည်။





ပူရိစ မြန်မာနိုင်ငံအင်တာနေရှင်ဒုသလီမိတက်

ပုံ ၂.၅-၁ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1) ၏ လေထုတိုက်ဖတ်သည့်အရပ်
အခြေအနေ

သီလင်းလေလှေစီးပွားရေးနှင့်အပိုင်း(ခ)မြို့တော်မှစုန်ဖွဲ့ပြီးတိုင်းတက်မယ့်အတွက်လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းသည်ပတ်နေ့စဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ ဒီဇင်ဘာလ ၂၀၂၃ခုနှစ်)



မှရင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

ဇုံ ၂၅-၂ လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (AQ-1) ၏ လေတိုက်နှုန်းနှင့်
လေလမ်းကြောင်းပြပုံ (Wind Rose Diagram)



စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ဆောက်လုပ်ရေးလုပ်ငန်းများဆောင်ရွက်ခြင်းမရှိပါ။

အမှုန်အမွှားများ နှင့် နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO₂) တို့၏ စောင့်ကြည့်လေ့လာသည့် (၇)ရက်အတွင်း ကျော်လွန်နေသော အချိန်စုစုပေါင်း ခြုံငုံသုံးသပ်ချက်များကို ဇယား ၂.၅-၂ တွင် ဖော်ပြထားပါသည်။ တိုင်းတာထားသော နေ့စဉ် ပျမ်းမျှတန်ဖိုးများအရ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO₂)၏ ဒုတိယနေ့ နှင့် တတိယနေ့တို့၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုးရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသကဲ့သို့ အမှုန်အမွှား (PM₁₀) ၏ ဒုတိယနေ့၊ တတိယနေ့ နှင့် ပဉ္စမနေ့တို့၏ နေ့စဉ်ပျမ်းမျှတန်ဖိုးရလဒ်များသည်လည်း ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။

ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်သောအခါတွင် အမှုန်အမွှား (PM₁₀) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၉၆) နာရီ ဖြစ်ပြီး ဒုတိယနေ့၊ တတိယနေ့ နှင့် ပဉ္စမနေ့ တို့တွင် ညနေအချိန်မှ မနက်စောစောအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။ အမှုန်အမွှား (PM₁₀) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၇၀) နာရီ ဖြစ်ပြီး ဒုတိယနေ့ နှင့် တတိယနေ့ တို့တွင် ညနေအချိန်မှ မနက်စောစောအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။ ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO₂) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၅၂) နာရီ ဖြစ်ပြီး ဒုတိယနေ့ နှင့် တတိယနေ့ တို့တွင် နေ့လည်အချိန်မှ ညနေအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။

လေတိုက်ခတ်သည့် အချက်အလက်များအရ ဒုတိယနေ့တွင် ညပိုင်းအချိန်အတွင်း မြောက်-အရှေ့မြောက် (NNE) နှင့် အရှေ့-အရှေ့မြောက် (ENE) တို့မှ သိသာထင်ရှားစွာ တိုက်ခတ်ပါသည်။ တတိယနေ့တွင် ညပိုင်းအချိန်အတွင်း အရှေ့မြောက် (NE) နှင့် အနောက်မြောက် (NW) တို့မှ သိသာထင်ရှားစွာ တိုက်ခတ်ပါသည်။ ပဉ္စမနေ့တွင် နေ့ပိုင်းအချိန်အတွင်း မြောက် (N) နှင့် မြောက်-အရှေ့မြောက် (NNE) တို့မှ သိသာထင်ရှားစွာ တိုက်ခတ်ပါသည်။ (နောက်ဆက်တွဲ-၁ တွင်ဖော်ပြထားပါသည်)

နေရာ-၁ (AQ-1) ၏လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်အရ အနောက်မြောက် (NW) နှင့် အရှေ့မြောက် (NE) ရပ်ဝန်းတို့မှ သိသာထင်ရှားစွာ အများဆုံးတိုက်ခတ်ပြီး၊ လေတိုက်ခတ်ရာအရပ်စုစုပေါင်း၏ ၇၀ ရာခိုင်နှုန်း ကျော်သည် ၎င်းရပ်ဝန်းများမှတိုက်ခတ်နေခြင်းဖြစ်ပါသည်။ (ဇယား ၂.၅-၃ တွင် ဖော်ပြထားပါသည်)

အမှုန်အမွှား (PM₁₀) နှင့် အမှုန်အမွှား (PM_{2.5}) တို့၏ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ ဇွန်အပိုင်း(ခ)၏ အပြင်ဘက်တွင်ရှိသော မြေသားလမ်းများမှ သဘာဝအတိုင်း ဖြစ်ပေါ်လာသော ဖုန်မှုန့်များကြောင့်လည်းကောင်း၊ စောင့်ကြည့်လေ့လာသော ဧရိယာ၏ သယ်ယူပို့ဆောင်ရေး လုပ်ငန်းများ လုပ်ဆောင်ခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ဓာတ်ငွေ့ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ စောင့်ကြည့်လေ့လာသော နေရာ၏ အနီးတစ်ဝိုက်ရှိ ကားလမ်းမပေါ်တွင် သွားလာနေသော ယာဉ်များမှ လောင်စာများ လောင်ကျွမ်းခြင်း၊ လူနေရပ်ကွက်ရှိ နေ့စဉ်လှုပ်ရှားဆောင်ရွက်မှုများ (ထင်း သို့မဟုတ် မီးသွေးဖြင့် ချက်ပြုတ်ခြင်း၊ အကာအကွယ်မရှိ မီးရှို့ခြင်း အစရှိသည်)၊ သီလဝါဆိပ်ကမ်း၏ လုပ်ငန်း ဆောင်ရွက်မှုများကြောင့် ဖြစ်ပေါ်လာသောဓာတ်ငွေ့များ ပြည်တွင်းစက်မှုဇုန်၏ လုပ်ငန်းဆောင်ရွက်မှုများနှင့် ဇွန်အပိုင်း(ခ)၏ လုပ်ငန်းဆောင်ရွက်မှုများကြောင့် ဖြစ်နိုင်ပါသည်။



ဆောင်းရာသီအတွင်း ညနေပိုင်းနှင့် ညအချိန်များတွင် တိုက်ခတ်သောလေသည် အေးမြသိပ်သည်းလာပြီး နေအချိန်ထက် ရွေ့လျားမှု ပိုနွေးလာပါသည်။ ထို့ကြောင့် အေးမြသောလေသည် အမှုန်အမွှားများ သို့မဟုတ် ညစ်ညမ်းစေသော အရာများကိုထိန်းချုပ်ထားနိုင်ပြီး၊ နေရာတာနေရာတွင် အချိန်ကြာမြင့်စွာ တည်ရှိနေစေခြင်းကြောင့် ညအချိန်တွင် လေထုညစ်ညမ်းမှု မြင့်မားမှုကို ဖြစ်ပေါ်စေပါသည်။ ထို့အပြင် ပင်လယ်ရေမျက်နှာပြင်အထက် ၀ မှ ၁.၅ ကီလိုမီတာခန့်အကွာရှိ လေထု၏အပိုင်းတစ်ပိုင်းဖြစ်သော ကမ္ဘာလေထု၏ အောက်ဆုံးပိုင်းအလွှာ (Planetary Boundary Layer) သည် ညအချိန်တွင် နိမ့်ပါးလာသဖြင့် လေထုညစ်ညမ်းမှုအမှုန်အမွှားများ လှည့်ပတ်သွားလာရန် နေရာနည်းပါးသွားပြီး လေထုညစ်ညမ်းမှုကို ပိုမိုဖြစ်ပေါ်စေပါသည်။

ဇယား ၂.၅-၂ ကျော်လွန်သောအချိန်စုစုပေါင်း

	တိုင်းတာသော အမျိုးအစားများ	ကျော်လွန်သော အချိန်စုစုပေါင်း
ပထမနေ့မှ သတ္တမနေ့အထိ	အမှုန်အမွှား (PM _{2.5})	၅၆
	အမှုန်အမွှား (PM ₁₀)	၇၀
	ဆာလဖတ်ဒိုင်အောက်ဆိုက် (SO ₂)	၅၂

မှတ်:- ဖြန့်ဖြူးခံရသောနေရာနှင့်နယ်လီမီတာ

ဇယား ၂.၅-၃ နေရာ-၁ (AQ-1)၏ လေတိုက်ခတ်ရာအရပ်အကျဉ်းချုပ်

လေတိုက်ရပ်	(ရာစုက်)	နေအချိန်	ညနေအချိန်	ညအချိန်
မြောက် (N)	၁၉.၇%	၁၀.၇%	၃.၀%	၅.၄%
မြောက်-အရှေ့မြောက် (NNE)	၁၈.၅%	၆.၅%	၃.၀%	၈.၉%
အရှေ့မြောက် (NE)	၆.၅%	၄.၈%	၁.၂%	၀.၆%
အရှေ့-အရှေ့မြောက် (ENE)	၅.၄%	၄.၂%	၁.၂%	၀.၀%
အရှေ့(E)	၁.၈%	၁.၀%	၀.၀%	၀.၀%
အရှေ့-အရှေ့တောင် (ESE)	၂.၄%	၂.၄%	၀.၀%	၀.၀%
အရှေ့တောင် (SE)	၃.၆%	၁.၈%	၁.၈%	၀.၀%
တောင်-အရှေ့တောင် (SSE)	၄.၂%	၃.၆%	၀.၆%	၀.၀%
တောင် (S)	၆.၅%	၃.၀%	၀.၀%	၃.၆%
တောင်-အနောက်တောင် (SSW)	၄.၈%	၀.၀%	၀.၀%	၄.၈%
အနောက်တောင် (SW)	၁.၂%	၁.၂%	၀.၀%	၀.၀%
အနောက်-အနောက်တောင် (WSW)	၁.၈%	၀.၀%	၀.၆%	၁.၂%
အနောက် (W)	၂.၄%	၁.၂%	၀.၆%	၀.၆%
အနောက်-အနောက်မြောက် (WNW)	၃.၀%	၁.၂%	၀.၆%	၁.၂%
အနောက်မြောက် (NW)	၉.၅%	၄.၂%	၀.၀%	၅.၄%
မြောက်အနောက်မြောက် (NNW)	၉.၅%	၃.၆%	၀.၀%	၆.၀%
စုစုပေါင်း	၁၀၀.၀%	၅၀.၀%	၁၂.၅%	၃၇.၅%

မှတ်:- ဖြန့်ဖြူးခံရသောနေရာနှင့်နယ်လီမီတာ



အခန်း ၃ နိဂုံးချုပ် နှင့် အကြံပြုချက်များ

စောင့်ကြည့်လေ့လာသော (၇)ရက်ကာလအတွင်း ကာဗွန်မိုနောက်ဆိုဒ် (CO)၊ နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုဒ် (NO₂)၊ အမှုန်အမွှား (PM_{2.5})၊ အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) တို့၏ (၇)ရက်ပျမ်းမျှ လေထု အရည်အသွေးရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေခြင်း မရှိသောကြောင့် ဘေးအန္တရာယ်ပတ်ဝန်းကျင်သို့ ထိခိုက်မှုမရှိပါ။ သို့သော်လည်း ရက်(၃)ရက်၏ နေ့စဉ် အမှုန်အမွှား (PM_{2.5}) ပါဝင်နှုန်းပျမ်းမျှတန်ဖိုးနှင့် ရက် (၂)ရက်၏ နေ့စဉ် အမှုန်အမွှား (PM₁₀) နှင့် ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ပါဝင်နှုန်း ပျမ်းမျှတန်ဖိုးတို့သည် ရည်မှန်းတန်ဖိုးထက်ကျော်လွန်နေသည်ကို တွေ့ရှိရသည်။ အမှုန်အမွှား (PM_{2.5}) ၏ နေ့စဉ် ပျမ်းမျှတန်ဖိုးအား ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင်ထိန်းသိမ်းရေးဝန်ကြီးဌာန (MOEJ) ၏ ပတ်ဝန်းကျင်စံတန်ဖိုး ၃၅ $\mu\text{g}/\text{m}^3$ (၀.၀၃၅ mg/m^3) နှင့် နှိုင်းယှဉ်ရာ၌ ကျော်လွန်နေသော တန်ဖိုးများသည် ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင်ထိန်းသိမ်းရေး ဝန်ကြီးဌာန (MOEJ) ၏ ပတ်ဝန်းကျင်စံတန်ဖိုး နှင့် ကိုက်ညီကြောင်း တွေ့ရှိရသည်။

ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်သောအခါတွင် အမှုန်အမွှား (PM_{2.5}) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၉၆) နာရီ ဖြစ်ပြီး ဒုတိယနေ့၊ တတိယနေ့ နှင့် ပဉ္စမနေ့ တို့တွင် ညနေအချိန်မှ မနက်စောစောအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။ အမှုန်အမွှား (PM₁₀) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၇၀) နာရီ ဖြစ်ပြီး ဒုတိယနေ့ နှင့် တတိယနေ့ တို့တွင် ညနေအချိန်မှ မနက်စောစောအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။

အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) တို့၏ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ ဇုန်အပိုင်း(ခ)၏ အပြင်ဘက်တွင်ရှိသော မြေသားလမ်းများမှ သဘာဝအတိုင်း ဖြစ်ပေါ်လာသော ဖုန်မှုန့်များကြောင့်လည်းကောင်း၊ စောင့်ကြည့်လေ့လာသော ဧရိယာ၏ သယ်ယူပို့ဆောင်ရေး လုပ်ငန်းများ လုပ်ဆောင်ခြင်းကြောင့် လည်းကောင်း ဖြစ်နိုင်ပါသည်။

အမေရိကန် ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး အေဂျင်စီ (EPA) နှင့် WHO တို့၏ ကျန်းမာရေး အကျိုးသက်ရောက်မှု အရ အန္တရာယ်ကင်းသော ထိတွေ့မှုအဆင့် သို့မဟုတ် ဆိုးရွားသော ကျန်းမာရေးဆိုင်ရာ ဆိုးကျိုးများ မဖြစ်ပေါ်နိုင်သည့် အနိမ့်ဆုံး သတ်မှတ်ထားသည့် အဆောက်အထားမရှိပါ။ အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) ထိတွေ့မှုကြောင့် ဒေသလူဦးရေ၏ သက်တမ်းမှာ ပျမ်းမျှအားဖြင့် ၈.၆ လ အထိ လျော့နည်းစေသည်။ အမှုန်အမွှား (PM_{2.5}) နှင့် အမှုန်အမွှား (PM₁₀) တို့၏ ခဏတာထိတွေ့မှု (နာရီ ရက်) သည် အဆုတ်ရောဂါကို ဝိမိုဆိုးရွားစေပြီး ပန်းနာရင်ကျပ်ရောဂါနှင့် နှုတ်သွယ် ရောင်ရမ်းမှု ရောင်ရမ်းခြင်းများ ဖြစ်စေနိုင်သည်။ နှလုံးရောဂါ ရှိသူများအနေဖြင့် ထိုခဏတာ ထိတွေ့မှုသည် နှလုံးရောဂါနှင့် မူမှန်မကန်ဖြစ်ခြင်း တို့နှင့် ဆက်စပ်လျက်ရှိသည်။ သို့သော် ကျန်းမာသော ကလေးများနှင့် အရွယ်ရောက်ပြီးသော လူများသည် ထိုခဏတာ ထိတွေ့မှုကြောင့် ပြင်းထန်သော သက်ရောက်မှုများမစားခဲ့ရခြင်းမရှိပါ။ ရေရှည်ထိတွေ့မှု (လများ၊ နှစ်များ)သည် အဆုတ်၏ လုပ်ဆောင်မှု လျော့ချခြင်း၊ နာတာရှည် လည်ချောင်းနာခြင်းနှင့် အချိန်မတိုင်မှီ သေဆုံးခြင်း ကဲ့သို့သော ပြဿနာများနှင့် ဆက်စပ်နေသည်။ နေ့စဉ် ပျမ်းမျှတန်ဖိုးသည် ရည်မှန်း တန်ဖိုးထက် ကျော်လွန်နေသော်လည်း ဂျပန်နိုင်ငံရှိ ပတ်ဝန်းကျင်ထိန်းသိမ်းရေးဝန်ကြီးဌာန (MOEJ) မှ သတိပေးချက်လမ်းညွှန်ချက်အဆင့် ၁ (Level 1 Guideline for alert) မှ ထုတ်ပြန်ထားသောတန်ဖိုးဖြစ်သော ၇၀ $\mu\text{g}/\text{m}^3$ (၀.၀၇ mg/m^3) နှင့် တူညီသော (သို့မဟုတ်)လျော့နည်းသောတန်ဖိုး ထက်မကျော်လွန်ကြောင်း တွေ့ရှိရသည်။ ထို့ကြောင့် ကျန်းမာရေးကို ဆိုးရွားစွာ ထိခိုက်မှုမရှိဟု ယူဆကာ ပြင်ပလူဝင်ရှာမှုများကိုလည်း ရှောင်ရှားရန် မလိုအပ်ပါ။ သို့သော်လည်း



ထိခိုက်လွယ်သော သက်ရောက်မှုများ (sensitive receptors) အတွက် ၎င်းတို့၏ကျန်းမာရေးအခြေအနေအပေါ်ကို ဖြစ်နိုင်သော သက်ရောက်မှု ဂရုပြုရန်လိုအပ်သည်။

ဆာလဖာဒိုင်အောက်ဆိုဒ်(SO₂) ၏ (၇)ရက်ဆက်တိုက် တိုင်းတာမှုအတွင်း ကျော်လွန်သောအချိန်စုစုပေါင်းမှာ (၅၂) နာရီ ဖြစ်ပြီး ၇တိယနေ့ နှင့် တတိယနေ့ တို့တွင် နေ့လည်အချိန်မှ ညနေအချိန်ထိတိုင်အောင် ကျော်လွန်နေသည်ကို တွေ့ရှိရပါသည်။

ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ခေတ်ငွေ့ ထုတ်လွှတ်နိုင်ခြေ ရှိသော အရင်းမြစ်များမှာ စောင့်ကြည့်လေ့လာသော နေရာ၏ အနီးတစ်ဝိုက်ရှိ ကားလမ်းမပေါ်တွင် သွားလာနေသော ယာဉ်များမှ လောင်စာများ လောင်ကျွမ်းခြင်း၊ လူနေရပ်ကွက်ရှိ နေ့စဉ်လုပ်ရားဆောင်ရွက်မှုများ (ထင်း သို့မဟုတ် မီးသွေးဖြင့် ချက်ပြုတ်ခြင်း၊ အကာအကွယ်မရှိ စီးပွားခြင်း အစရှိသည်)၊ သီလဝါဆိပ်ကမ်း၏ လုပ်ငန်း ဆောင်ရွက်မှုများကြောင့် ဖြစ်ပေါ်လာသောခါတ်ငွေ့များ ပြည်တွင်းစက်မှုစနစ်၏ လုပ်ငန်းဆောင်ရွက်မှုများနှင့် စုန်အပိုင်း(ခ)၏ လုပ်ငန်းဆောင်ရွက်မှုများကြောင့် ဖြစ်နိုင်ပါသည်။

အမေရိကန်ပြည်ထောင်စုတွင် အဆိပ်အတောက် ဖြစ်စေသော ပစ္စည်းများနှင့် ရောဂါများဆိုင်ရာ မှတ်ပုံတင်ဌာနမှ အများပြည်သူ ကျန်းမာရေးကြေငြာချက်တွင် အစီရင်ခံတင်ပြထားသော ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂) ပမာဏ ၁၀၀ ppm (၂၆၁.၈ mg/m³)သည် အသက်အန္တရာယ်နှင့် ကျန်းမာရေးအတွက် ချက်ချင်းအန္တရာယ်ပေးနိုင်ပါသည်။ ၀.၄ ppm မှ ၃ ppm (၁.၀၅ mg/m³ မှ ၇.၈၅ mg/m³) အထိပမာဏကို နှစ်(၂၀)နှင့်အထက် ရေရှည်ထိတွေ့သောအခါတွင် အဆုတ်၏လုပ်ဆောင်နိုင်မှုများသည် ပြောင်းလဲလာနိုင်ပါသည်။ ထို့ကြောင့် စောင့်ကြည့်လေ့လာသော ကာလအတွင်း ဆာလဖာဒိုင်အောက်ဆိုဒ် (SO₂)၏တန်ဖိုးမှာ ရည်မှန်းတန်ဖိုးထက် ကျော်လွန်နေကြောင်း တွေ့ရှိရသော်လည်း လူကျန်းမာရေးအပေါ် ထိခိုက်နိုင်သည့် ထင်ရှားသော သက်ရောက်မှုများ မရှိကြောင်း တွေ့ရှိရပါသည်။

စုန်အပိုင်း(ခ)တွင် လေထုအရည်အသွေးကို အနာဂတ်တွင်ဆက်လက် စောင့်ကြည့်လေ့လာရာတွင် ရည်မှန်းအဆင့်ကို ရရှိနိုင်ရန် အောက်ပါဆောင်ရွက်ချက်များကို လုပ်ဆောင်နိုင်ပါသည်။

- (၁) စုန်မှန်အလွန်များခြင်းကို ရွှောင်ရှားရန်နှင့် စွန့်ထုတ်စာတ်ငွေ့များကြောင့် လေထုညစ်ညမ်းမှုကို လျှော့ချနိုင်ရန် စက်ယန္တရားများနှင့် ယာဉ်များ၏ အမြန်နှုန်းကို တစ်နာရီလျှင် ၂၅ ကီလိုမီတာအထိ ထိန်းချုပ်သတ်မှတ်ရန်။
- (၂) စက်ယန္တရားများကို ကောင်းမွန်စွာလည်ပတ်အောင်ဆောင်ရွက်ရန် (စက်ယန္တရားများကို မလိုအပ်ပဲ လည်ပတ်နေခြင်း မပြုလုပ်ရန်)။
- (၃) လုပ်ငန်းများလည်ပတ်နေစဉ် ကာလအတွင်းတွင် အသုံးပြုသောစက်ပစ္စည်းများကို ပြုပြင်ထိန်းသိမ်းမှုများ ပုံမှန်ဆောင်ရွက်ရန်။

သီလဝါအထူးစီးပွားရေးစနစ် အပိုင်း(ခ)၏ လုပ်ငန်းလည်ပတ်နေစဉ်ကာလအတွင်း စက်မှုစုန်အတွင်းနှင့်အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား သိရှိနိုင်ရန်အတွက် ပုံမှန်စောင့်ကြည့်လေ့လာခြင်းကို လုပ်ဆောင်ရန် လိုအပ်ပါသည်။ ပုံမှန်စုန်ဆောင်းရရှိထားသော ပတ်ဝန်းကျင်ဆိုင်ရာအချက်အလက်များကို အခြေခံ၍ နောင်တွင် ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှုအတွက် ဆိုးကျိုးလျော့ပါးသက်သာစေမည့် နည်းလမ်းများကို ပြန်လည် သုံးသပ်သွားမည်ဖြစ်ပါသည်။



နောက်ဆက်တွဲ-၁၁ နာရီပျမ်းမျှလေထုအရည်အသွေးတန်ဖိုး



သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း၊ ခရိုင်ကုမ္ပဏီနှင့် ပြည်တိုက်ကပ်ရေးအတွက် လေထုအရည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေသည့်ကာလ အပိုင်း ၁ အပိုင်း ၂ နှင့် အပိုင်း ၃၊ စီစဉ်ကာလ ၂၀၂၃ခုနှစ်)

နေ့ရက်	အချိန်		ကာဗွန်ဒိုင်အောက်ဆိုက် (CO)		နိုက်ထရိုဂျင်ဒိုင်အောက်ဆိုက် (NO ₂)		အမှုန်အမွှား (PM ₁₀)		ဆာလဖာဒိုင်အောက်ဆိုက် (SO ₂)		သေတိုက်စွန်း		လေတိုက်ခတ်ရာအရပ်	
			ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက	ကျွန်းက
			ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ	ဇနာနီပျမ်းမျှ
၁၀ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၁:၀၀	-	အတွင်း	၀.၂၄၁	၀.၀၁၉	၀.၀၀၉	၀.၀၁၃	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၄၁	၉၈	အတွင်း	အတွင်း
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၂:၀၀	-	၁၂:၀၀	၀.၁၆၇	၀.၀၁၀	၀.၀၂၈	၀.၀၁၂	၀.၀၁၆	၀.၀၁၆	၀.၀၁၆	၀.၄၄	၁၁	ပြင်ပ	ပြင်ပ
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၃:၀၀	-	၁၃:၀၀	၀.၆၂၄	၀.၀၂၂	၀.၀၀၈	၀.၀၁၄	၀.၀၁၉	၀.၀၁၉	၀.၀၁၉	၀.၄၅	၁၅၄	ပြင်ပ	ပြင်ပ
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၄:၀၀	-	၁၄:၀၀	၀.၂၈၂	၀.၀၂၈	၀.၀၂၂	၀.၀၁၂	၀.၀၂၁	၀.၀၁၂	၀.၀၁၂	၀.၄၅	၈၁	အတွင်း	အတွင်း
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၅:၀၀	-	၁၅:၀၀	၀.၁၃၃	၀.၀၁၀	၀.၀၀၈	၀.၀၁၃	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၀	၁၄၀	အရပ်အဝင်	အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၆:၀၀	-	၁၆:၀၀	၀.၀၉၉	၀.၀၁၄	၀.၀၁၄	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၁၅	၁၈၈	အတွင်း-အရပ်အဝင်	အတွင်း-အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၇:၀၀	-	၁၇:၀၀	၀.၁၃၆	၀.၀၁၂	၀.၀၁၂	၀.၀၁၄	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၂၀	၁၆၅	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၈:၀၀	-	၁၈:၀၀	၀.၂၅၇	၀.၀၁၃	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၁၅	၁၇၃	လောင်	လောင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၉:၀၀	-	၁၉:၀၀	၀.၂၆၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၁၅	၁၅၄	အရပ်အဝင်	အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၂၀:၀၀	-	၂၀:၀၀	၀.၁၃၅	၀.၀၁၃	၀.၀၁၃	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၀	၂၆၅	အရပ်အဝင်	အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၂၁:၀၀	-	၂၁:၀၀	၀.၁၃၅	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၀	၂၅၄	အရပ်အဝင်-အရပ်အဝင်	အရပ်အဝင်-အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၂၂:၀၀	-	၂၂:၀၀	၀.၁၃၄	၀.၀၁၂	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၀	၂၅၄	အရပ်အဝင်-အရပ်အဝင်	အရပ်အဝင်-အရပ်အဝင်
၁၁ မျက် စီစဉ်ကာလ ၂၀၂၃	၂၃:၀၀	-	၂၃:၀၀	၀.၁၆၅	၀.၀၁၆	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၀၀	၂၁၀	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၀၀:၀၀	-	၀၀:၀၀	၀.၂၀၅	၀.၀၁၈	၀.၀၂၃	၀.၀၁၃	၀.၀၁၆	၀.၀၁၆	၀.၀၁၆	၀.၀၀	၂၀၄	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၀၁:၀၀	-	၀၁:၀၀	၀.၁၈၃	၀.၀၁၄	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၀	၂၀၄	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၂:၀၀	-	၂:၀၀	၀.၁၂၇	၀.၀၀၈	၀.၀၁၈	၀.၀၁၈	၀.၀၁၅	၀.၀၁၅	၀.၀၁၅	၀.၀၀	၂၀၄	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၃:၀၀	-	၃:၀၀	၀.၀၆၅	၀.၀၀၃	၀.၀၁၈	၀.၀၁၈	၀.၀၁၄	၀.၀၁၄	၀.၀၁၄	၀.၀၀	၂၀၃	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၄:၀၀	-	၄:၀၀	၀.၀၁၅	၀.၀၁၂	၀.၀၁၈	၀.၀၁၅	၀.၀၁၆	၀.၀၁၆	၀.၀၁၆	၀.၀၀	၂၀၃	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၅:၀၀	-	၅:၀၀	၀.၀၁၅	၀.၀၁၂	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၀	၂၀၃	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၆:၀၀	-	၆:၀၀	၀.၀၁၈	၀.၀၁၈	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၀	၂၀၃	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၇:၀၀	-	၇:၀၀	၀.၂၃၃	၀.၀၁၈	၀.၀၁၄	၀.၀၁၄	၀.၀၁၄	၀.၀၁၄	၀.၀၁၄	၀.၀၅	၂၀၄	လောင်-အရပ်အဝင်	လောင်-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၈:၀၀	-	၈:၀၀	၀.၀၃၆	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၁၀	၃၂၄	အရပ်အဝင်	အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၉:၀၀	-	၉:၀၀	၀.၀၁၅	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၀၁၃	၀.၂၅	၁၈	ပြင်ပ-အရပ်အဝင်	ပြင်ပ-အရပ်အဝင်
၁၂ မျက် စီစဉ်ကာလ ၂၀၂၃	၁၀:၀၀	-	၁၀:၀၀	၀.၀၁၈	၀.၀၁၉	၀.၀၁၈	၀.၀၁၈	၀.၀၁၂	၀.၀၁၂	၀.၀၁၂	၀.၄၁	၁၁	ပြင်ပ	ပြင်ပ

အရပ်အဝင်	၀.၆၂၄	၀.၁၇၈	၀.၀၃၂	၀.၀၁၃	၀.၀၁၆
လောင်	၀.၁၆၆	၀.၀၁၃	၀.၀၁၄	၀.၀၁၆	၀.၀၁၆
အရပ်အဝင်	၀.၀၁၅	၀.၀၁၂	၀.၀၁၈	၀.၀၁၈	၀.၀၁၈



[illegible]

အချက်အလက်	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃
ပုံစံ	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃
အချက်အလက်	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃	၁၄၀၃



သီပေါမြို့နယ်၊ ပွားရေစုနယ်အပိုင်၊ ခါးရိုက်ရွာနယ်မြေတို့ဆက်ရေအတွက်ဝေဝေရေစည်အသွေးစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းစဉ်ဆက်နေ့စဉ်ကာလ အပိုင် ၁၊ အပိုင် ၂ နှင့် အပိုင် ၃၊ ဒီဇင်ဘာလ ၂၀၂၃ခုနှစ်)

နေ့ရက်	အပိုင်		ကလွန်မီနောက်	နိုက်ထရိုဂျင်	အမှုန်အမွှား	အမှုန်အမွှား	ဆာလဖာဒိုင်	လေတိုက်နှုန်း	လေတိုက်မတ်ရေအမြင့်		
			ဆိုဒ် (CO)	(NO ₂)	(PM ₁₀)	(PM ₁₀)	(SO ₂)		တပ်	တပ်	
			မီတာ	မီတာ	မီတာ	မီတာ	မီတာ				
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၁၀၀	-	၁၁၅၅	၀.၁၂၂	၀.၁၂၅	၀.၀၁၂	၀.၀၂၃	၀.၀၁၂	၀.၅၅	၁၅	မြောက်-အလွန်မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၂၀၈	-	၁၂၅၈	၀.၂၄၉	၀.၀၃၃	၀.၀၀၈	၀.၀၁၇	၀.၀၁၇	၀.၆၅	၁၉	အလွန်မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၃၀၈	-	၁၃၅၅	၀.၂၆၄	၀.၀၃၂	၀.၀၀၇	၀.၀၁၃	၀.၀၃၅	၀.၆၈	၂၆	အလွန်မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၄၀၈	-	၁၄၅၅	၀.၅၈၄	၀.၀၃၀	၀.၀၀၇	၀.၀၂၈	၀.၀၃၇	၀.၆၇	၁၇	အလွန်မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၅၀၀	-	၁၅၅၅	၀.၆၆၀	၀.၀၀၈	၀.၀၁၈	၀.၁၁၅	၀.၀၄၈	၀.၄၂	၃၅၅	မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၆၀၀	-	၁၆၅၅	၀.၄၄၅	၀.၀၃၂	၀.၀၁၃	၀.၀၃၆	၀.၂၈	၁၃၃		မြောက်-အနောက်မြောက်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၇၀၀	-	၁၇၁၅	၀.၃၃၆	၀.၀၆၃	၀.၀၄၇	၀.၀၆၂	၀.၀၅၂	၀.၁၈	၁၅၇	အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၈၀၀	-	၁၈၅၅	၀.၃၅၅	၀.၁၇၃	၀.၀၅၅	၀.၀၈၆	၀.၀၃၁	၀.၂၃	၁၆၂	အောင်-အလွန်အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၉၀၀	-	၁၉၅၅	၀.၄၈၉	၀.၁၉၃	၀.၀၄၇	၀.၀၈၇	၀.၀၂၃	၀.၀၅	၁၄၂	အလွန်အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၂၀၀၀	-	၂၀၅၅	၀.၀၂၈	၀.၂၅၀	၀.၀၄၁	၀.၀၆၈	၀.၀၀၅	၀.၀၁	၁၄၁	အလွန်အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၂၀၀၀	-	၂၀၅၅	၀.၃၆၈	၀.၂၂၇	၀.၀၄၂	၀.၀၅၁	၀.၀၀၁	၀.၀၀	၁၅၈	အောင်-အလွန်အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၂၁၀၈	-	၂၁၅၅	၀.၃၆၈	၀.၂၅၅	၀.၀၅၆	၀.၀၅၅	၀.၀၀၁	၀.၀၂	၂၇၇	အနောက်-အနောက်အောင်
၁၅ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၂၃၀၈	-	၂၃၅၅	၀.၂၆၇	၀.၂၇၃	၀.၀၃၆	၀.၀၄၃	၀.၀၂၀	၀.၁၅	၂၅၂	အနောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၀၀၀၈	-	၀၀၅၅	၀.၂၄၈	၀.၁၈၇	၀.၀၁၁	၀.၀၂၁	၀.၀၀၄	၀.၀၈	၂၈၈	အနောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၁၀၈	-	၁၁၅၅	၀.၁၂၉	၀.၀၄၂	၀.၀၀၈	၀.၀၄၂	၀.၀၀၇	၀.၀၇	၂၈၇	အနောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၂၀၀၈	-	၂၀၅၅	၀.၀၄၁	၀.၀၅၃	၀.၀၁၃	၀.၀၁၄	၀.၀၀၁	၀.၂၈	၁	မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၃၀၀၈	-	၃၀၅၅	၀.၀၈၆	၀.၀၈၄	၀.၀၁၁	၀.၀၁၈	၀.၀၀၈	၀.၃၇	၃၄၅	မြောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၄၀၀၈	-	၄၀၅၅	၀.၀၅၈	၀.၀၅၅	၀.၀၀၈	၀.၀၁၁	၀.၀၀၅	၀.၂၃	၃၄၅	မြောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၅၀၀၈	-	၅၀၅၅	၀.၀၅၅	၀.၀၆၆	၀.၀၀၅	၀.၀၁၂	၀.၀၁၁	၀.၁၇	၃၄၀	မြောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၆၀၀၈	-	၆၀၅၅	၀.၁၁၄	၀.၀၈၁	၀.၀၀၈	၀.၀၁၅	၀.၀၀၇	၀.၁၃	၃၄၇	မြောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၇၀၀၈	-	၇၀၅၅	၀.၁၂၂	၀.၀၉၄	၀.၀၀၅	၀.၀၁၃	၀.၀၁၄	၀.၂၅	၃၃၈	မြောက်-အနောက်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၈၀၀၈	-	၈၀၅၅	၀.၁၁၅	၀.၀၈၇	၀.၀၁၂	၀.၀၁၅	၀.၂၈	၃၅၇		မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၉၀၀၈	-	၉၀၅၅	၀.၀၅၁	၀.၀၀၄	၀.၀၀၇	၀.၀၁၄	၀.၄၈	၃၇		မြောက်-အလွန်မြောက်
၁၈ ရက် ဒီဇင်ဘာလ ၂၀၂၃	၁၀၀၀၈	-	၁၀၀၅၅	၀.၀၅၇	၀.၀၀၅	၀.၀၀၇	၀.၀၁၈	၀.၅၂	၇၁		အလွန်-အလွန်မြောက်

အမှတ်အမှတ်	၀.၀၆၈	၀.၂၄၃	၀.၀၅၇	၀.၀၈၇	၀.၀၆၂
မြေရေ	၀.၂၅၁	၀.၀၃၃	၀.၀၂၁	၀.၀၃၁	၀.၀၂၈
အနည်အနှစ်	၀.၀၂၃	၀.၀၁၄	၀.၀၀၇	၀.၀၀၈	၀.၀၀၅



နောက်ဆက်တွဲ-၂ လေထုအရည်အသွေးတိုင်းတာသည့်စက်ကို
စံကိုက်ညီထားသောလက်မှတ်





SYSTEM HEALTH CHECK REPORT

Information

Instrument	Thermoair
Model	PM25
Serial number	90009
Unit Name	TH2500 (S/N) 90009
	PM2.5 T & RH/CO2 WCH/RR
Company	Mahachulalongkornrajavidyalaya International LTD
Date	Sep-23

Check List

General Check	OK
Supply Voltage Check	OK
PM10/PM2.5 Air Flow Check	OK
SLBUT & RH/CO2 WCH/RR sensor Check	OK
NO2 Sensor Health Check	Moderate
CO2/CO/CO2O2 Sensor Health Check	Full Check
Lowest Battery Voltage Check	OK
Data Logging Check	OK
Data Downloading Check	OK

Recommend

- Need to replace new acid gas sensor (calibration is 6 months)
- Need to replace internal filter (calibration is 6 months)
- Need to perform factory calibration or in field calibration (calibration is 42 months)

Performed by
Phat Saw Htoo
Technical Service Engineer
NANOVA CO., LTD

Approved by
Myo Oo
Technical Service Manager
NANOVA CO., LTD

Address: 22-A, Street, Sathorn-Bangkok, Sathorn-Bangkok, Tel: +66 (0) 222-4407, 230-8952
Fax: +66 (0) 222-4407, 230-8952
E-mail: info@nanova.co.th, sales@nanova.co.th
Website: www.nanova.co.th, www.nanova.co.th



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ဆူညံသံ နှင့် တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း အစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့အံ့ အင်တာနေရှင်နယ် လီမိတက်



မာတိကာ

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသော အစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ	၂
၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း	၃
၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ	၄
အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ	၁၂

ဇယားများစာရင်း

ဇယား ၁.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၁-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ	၂
ဇယား ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L _{eq})	၄
ဇယား ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L _{eq})	၄
ဇယား ၂.၄-၃ နေရာ-၁ (NV-1) ၏နာရီအလိုက်ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L _{eq})	၅
ဇယား ၂.၄-၄ နေရာ-၂ (NV-2) ၏နာရီအလိုက်ဆူညံသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L _{eq})	၆
ဇယား ၂.၄-၅ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L ₁₀)	၆
ဇယား ၂.၄-၆ နေရာ-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L ₁₀)	၈
ဇယား ၂.၄-၇ နေရာ-၁ (NV-1) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L ₁₀)	၉
ဇယား ၂.၄-၈ နေရာ-၂ (NV-2) ၏နာရီအလိုက်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L ₁₀)	၁၀

ပုံများစာရင်း

ပုံ ၂.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသည့်တည်နေရာများ	၂
ပုံ ၂.၃-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုအခြေအနေ	၃
ပုံ ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်	၇
ပုံ ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆူညံသံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်	၇
ပုံ ၂.၄-၃ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်	၁၁
ပုံ ၂.၄-၄ နေရာ-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်	၁၁



အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုဓာတ်ငွေ့များအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက် စောင့်ကြည့် လေ့လာမှုများကို ရေးဆွဲပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသော အစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန်လုပ်ငန်းလည်ပတ်နေခြင်းကြောင့် စက်မှုဇုန်အတွင်းနှင့်အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ ၁၁ ရက်နေ့မှ ဒီဇင်ဘာလ ၁၂ ရက်နေ့အထိ ဆူညံသံနှင့်တုန်ခါမှုအဆင့်အား စောင့်ကြည့် လေ့လာခဲ့သည်။

ဇယား ၁.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာ သည့် ရက်စွဲ	စောင့်ကြည့်လေ့လာမှု အမျိုးအစား	တိုင်းတာသော အမျိုးအစား များ	တိုင်းတာသော နေရာ အရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
ဒီဇင်ဘာလ ၁၂ ရက်နေ့ ၂၀၂၃ ခုနှစ်	ဆူညံမှုအဆင့်	L_{Aeq} (dB)	၁ (NV-1)	၈ နာရီ	Rion NL-42 အသံအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် ဖြေဖြင့်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၁၁ ရက်နေ့ ၂၀၂၃ ခုနှစ်	ဆူညံမှုအဆင့်	L_{Aeq} (dB)	၁ (NV-2)	၈ နာရီ	Rion NL-42 အသံအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် ဖြေဖြင့်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၁၂ ရက်နေ့ ၂၀၂၃ ခုနှစ်	တုန်ခါမှုအဆင့်	L_{wv} (dB)	၁ (NV-1)	၈ နာရီ	VM-53A တုန်ခါမှုအဆင့်တိုင်းတာသည့်ကိရိယာ ဖြင့် ဖြေဖြင့်တွင်ကွင်းဆင်းတိုင်းတာခြင်း
ဒီဇင်ဘာလ ၁၁ ရက်နေ့ ၂၀၂၃ ခုနှစ်	တုန်ခါမှုအဆင့်	L_{wv} (dB)	၁ (NV-2)	၈ နာရီ	VM-53A တုန်ခါမှုအဆင့်တိုင်းတာသည့်ကိရိယာ ဖြင့် ဖြေဖြင့်တွင်ကွင်းဆင်းတိုင်းတာခြင်း

မှတ်။ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်



အခန်း ၂ ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား

ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့်လေ့လာသော အမျိုးအစားများအား ဇယား ၂.၁-၁ တွင် ဖော်ပြထားပါသည်။

ဇယား ၂.၁-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ

စဉ်	စောင့်ကြည့်လေ့လာမှု	အမျိုးအစား
၁	ဆူညံသံ	အသံကြိမ်နှုန်း "ခေ" နှင့် ညီမျှသော ကျယ်လောင်မှု (LAeq)
၂	တုန်ခါမှု	တုန်ခါမှုအဆင့် (L _w)

မှရင်း၊ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ

ယာဉ်သွားလာမှုကြောင့်ဖြစ်ပေါ်လာသော ဆူညံသံနှင့်တုန်ခါမှုများကို အဓိကထားတိုင်းတာနိုင်ရန် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ အရှေ့မြောက်ဘက်ထောင့် မြောက်လတ္တီတွဒ် ၁၆°၄၀'၁၈.၂၂"၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၈.၁၈" တွင် စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (NV-1) နှင့် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ တောင်ဘက် ဖလမ်းကျေရွာ၊ ဖလမ်းရွာဦးကျောင်းဝန်းအတွင်း မြောက်လတ္တီတွဒ် ၁၆°၃၉'၂၄.၉၀" ၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၆.၇၀" တွင် စောင့်ကြည့်လေ့လာသည့် နေရာ-၂ (NV-2)ဟူ၍ ဆူညံသံနှင့်တုန်ခါမှုအဆင့်များကို နှစ်နေရာ တိုင်းတာခဲ့ပါသည်။ ဆူညံသံနှင့်တုန်ခါမှုစောင့်ကြည့် လေ့လာခဲ့သည့် တည်နေရာများကို ပုံ ၂.၂-၁ တွင် ပြသထားပါသည်။



မှရင်း၊ ဂျဂီယံအင်ဂျင်နီယာ

ပုံ ၂.၂-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာသည့်တည်နေရာများ

ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်နေရာ-၁ (NV-1)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (NV-1)သည် သီလဝါဖွံ့ဖြိုးရေးလမ်း၏ ဘေးဘက်တွင်ရှိသော သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ လည်ပတ်နေသောလုပ်ငန်းခွင်၏ ယာယီဂိတ်ပေါက်အရှေ့ဘက်၌ ရှိပါသည်။ စောင့်ကြည့်လေ့လာသည့် နေရာကို အနောက်မြောက်ဘက်တွင် ဇုန်အပိုင်း(က)နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ဖြင့် ဝန်းရံထားပါသည်။ ဤစောင့်ကြည့်လေ့လာသည့်နေရာ၏ အဓိကဆူညံသံနှင့်တုန်ခါမှု ဖြစ်နိုင်သော အရင်းအမြစ်များမှာ ဆောက်လုပ်ရေးလုပ်ငန်းကြောင့်ဖြစ်သော ဆူညံမှုနှင့်တုန်ခါမှုများနှင့် ယာဉ်သွားလာမှုများကြောင့် ဖြစ်နိုင်ပါသည်။


ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာသည့်နေရာ-၂ (NV-2)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၂ (NV-2) သည် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ တောင်ဘက် ဗလမ်းကျေးရွာ၊ ဗလမ်းရွာဦးဘုန်းကြီးကျောင်းဝန်းအတွင်းတွင် တည်ရှိပြီး တောင်ဘက်တွင် ဗလမ်းကျေးရွာ၏ လူနေအိမ်များ၊ အနောက်ဘက်တွင် လယ်ကွင်းများ တည်ရှိပြီး မြောက်ဘက်တွင် သီလဝါ အထူးစီးပွားရေးဇုန် အပိုင်း(က)နှင့် အရှေ့မြောက်ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ဖြင့် ဝန်းရံထားပါသည်။ ဤစောင့်ကြည့် လေ့လာသည့်နေရာ၏ အဓိကဆူညံသံနှင့် တုန်ခါမှု ဖြစ်နိုင်သော အရင်းအမြစ်များမှာ ဇုန်အပိုင်း(ခ)ရှိ ဆောက်လုပ်ရေး လုပ်ငန်းများနှင့် ဗလမ်းကျေးရွာရှိ နေထိုင်သူများ၏ နေ့စဉ်လုပ်ငန်းဆောင်တာများကြောင့် ဖြစ်နိုင်ပါသည်။

၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း

ဆူညံသံအဆင့်အား “Rion NL-42” အသံအဆင့်တိုင်းတာသည့်ကိရိယာဖြင့် ၁၀မီနစ်တိုင်း အလိုအလျောက်တိုင်းတာပြီး စက်အတွင်းရှိ မန်မိုနီတာဒ်အတွင်း မှတ်သားထားပါသည်။ တုန်ခါမှုအဆင့် တိုင်းတာသည့် “Rion VM-53A” ကိရိယာတွင်တွဲတက်ပါရှိသော ဝင်ရိုး(၃)ဘက်၏အရှိန်ကိုအာရုံခံနိုင်သည့် “PV-83C” ကိရိယာအား မြေကြီးပေါ်တွင် ထားရှိပါသည်။ ဒေါင်လိုက်ဝင်ရိုးအတိုင်းရှိသောတုန်ခါမှု (L_{eq})အား နေရာ-၁ (NV-1)နှင့် နေရာ-၂ (NV-2)တို့၌ လိုက်လျောညီထွေရှိသော တုန်ခါမှုအပိုင်းအခြား (၁၀-၇၀) dB အတွင်းထားရှိပြီး ၁၀ မီနစ်တိုင်း အလိုအလျောက် တိုင်းတာပြီး စက်အတွင်းရှိ မန်မိုနီတာဒ်အတွင်း မှတ်သားထားပါသည်။

စောင့်ကြည့်လေ့လာသော နေရာတစ်ခုစီတွင် ဆူညံသံနှင့်တုန်ခါမှု စောင့်ကြည့်လေ့လာမှုအား ၈ နာရီ တိုင်းတာပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ရှိ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့် လေ့လာသောအခြေအနေကို ပုံ ၂.၃-၁ တွင် ပြသထားပါသည်။



ဗုရင်အ မြန်မာနိုင်ငံအဆင်တာနေ့စဉ် နယ်လီပီတက်

ပုံ ၂.၃-၁ ဆူညံသံနှင့်တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုအခြေအနေ



၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ

ဆုညံ့သံစောင့်ကြည့်လေ့လာမှုရလဒ်များ

ဆုညံ့သံစောင့်ကြည့်လေ့လာမှုရလဒ်များအတွက် နေရာ-၁ (NV-1) တွင် နေ့အချိန် (မနက် ၆ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၆ နာရီ)ဟု အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပြီး နေရာ-၂ (NV-2) တွင် နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)၊ ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ) ဟူ၍ အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပါသည်။ ဆုညံ့သံ တိုင်းတာမှုအား သတ်မှတ်ထားသောနေရာတွင် ၂၄နာရီကြာ တိုင်းတာမည့်အစား ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ စောင့်ကြည့်လေ့လာသောရလဒ်များအား ဇယား ၂.၄-၁ နှင့် ဇယား ၂.၄-၂ တွင် အကျဉ်းချုပ် ဖော်ပြထားပါသည်။ နေရာ-၁ (NV-1)နှင့် နေရာ-၂ (NV-2)ရှိ တစ်နာရီဆုညံ့မှုအဆင့် (LAeq)၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၄-၃ နှင့် ဇယား ၂.၄-၄ တွင် ဖော်ပြထားပါသည်။ ပုံ ၂.၄-၁ နှင့် ပုံ ၂.၄-၂ တွင် နေရာ-၁ (NV-1)နှင့် နေရာ-၂ (NV-2)၏ ဆုညံ့မှုအဆင့် (LAeq) ရလဒ်များအား ပြသထားပါသည်။ သီလဝါ အထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးမှု စီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသော လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်၌ ရည်မှန်းထားသော ဆုညံ့သံအဆင့်နှင့် နှိုင်းယှဉ်ရာတွင် ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းကြောင်း တွေ့ရှိရသည်။

ဇယား ၂.၄-၁ နေရာ-၁ (NV-1) ၏ဆုညံ့သံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	ယာဉ်အသွားအလာကြောင့်ဖြစ်ပေါ်သောဆုညံ့သံအဆင့် (LAeq dB)	
	နေ့အချိန် (မနက် ၆ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၆ နာရီ)
၁၂ ဒီဇင်ဘာလ ၂၀၂၃	၆၀	-
ရည်မှန်းတန်ဖိုး	၇၅	၇၀

မှတ်ချက်။ ရည်မှန်းတန်ဖိုးများကို ဆုညံ့သံစည်းဝှေ့ဝေ (၇၅dB) တွင်ဖော်ပြထားသော အဓိကလမ်းကြီးတစ်လျှောက်ရှိ ဆုညံ့သံခွန်ဖြင့် ကျင့်သုံးထားပါသည်။ ၁၀၅၀၀ ခုနှစ် ဥပဒေအမှတ် ၅၈၊ နောက်ဆုံးပြင်ဆင်ချက် ၂၀၀၀ ခုနှစ် ဥပဒေအမှတ် ၉၁၊

မူရင်း ပြန်မာဒီဇံအင်တာနေရှင်နယ်လီမိတက်

ဇယား ၂.၄-၂ နေရာ-၂ (NV-2) ၏ဆုညံ့သံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	ဘုန်းကြီးကျောင်း ဆေးရုံ နှင့် စာသင်ကျောင်း အစရှိသော ထိခိုက်မှုလွယ်သော ဧရိယာနှင့် ကပ်လျက်နေရာ (LAeq dB)		
	နေ့အချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၁၁ ဒီဇင်ဘာလ ၂၀၂၃	၅၀	-	-
ရည်မှန်းတန်ဖိုး	၆၀	၅၅	၅၀

မှတ်ချက်။ ရည်မှန်းတန်ဖိုးများကို သီလဝါအထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ) အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရာဆုညံ့သံအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မူရင်း ပြန်မာဒီဇံအင်တာနေရှင်နယ်လီမိတက်



ဇယား ၂.၄-၃ နေရာ-၁ (NV-1) စီနာရီအလိုက်ဆွဲသံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LA_{eq})

စက်စွဲ	အမျိုး	ရလဒ် (L_{Aeq} , dB)	အမျိုးအစားအခြား တန်ဖိုးအတွက် (L_{Aeq} , dB)	ရည်မှန်းတန်ဖိုး (L_{Aeq} , dB)	မှတ်ချက်
၁၂ ဒီဇင်ဘာလ ၂၀၂၃	မီးဝင်-ဂျာဝ	-	၆၀	၇၅	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	ဂျာဝ-စာဝ	-			
	စာဝ-ဥမာဝ	၆၂			
	ဥမာဝ-ဝမာဝ	၆၀			
	ဝမာဝ-ဝမာဝ	၆၁			
	ဝမာဝ-၁၂မာဝ	၆၂			
	၁၂မာဝ-၁၃မာဝ	၇၉			
	၁၃မာဝ-၁၄မာဝ	၆၀			
	၁၄မာဝ-၁၅မာဝ	၆၀			
	၁၅မာဝ-၁၆မာဝ	၆၀			
	၁၆မာဝ-၁၇မာဝ	-			
	၁၇မာဝ-၁၈မာဝ	-			
	၁၈မာဝ-၁၉မာဝ	-			
	၁၉မာဝ-၂၀မာဝ	-			
	၂၀မာဝ-၂၁မာဝ	-			
	၂၁မာဝ-၂၂မာဝ	-			
	၂၂မာဝ-၂၃မာဝ	-	-	၇၀	
	၂၃မာဝ-၂၄မာဝ	-			
	၂၄မာဝ-၂၅မာဝ	-			
	၂၅မာဝ-၂၆မာဝ	-			
	၂၆မာဝ-၂၇မာဝ	-			
	၂၇မာဝ-၂၈မာဝ	-			
	၂၈မာဝ-၂၉မာဝ	-			
	၂၉မာဝ-၃၀မာဝ	-			
၃၀မာဝ-၃၁မာဝ	-				
၃၁မာဝ-၃၂မာဝ	-				
၃၂မာဝ-၃၃မာဝ	-				
၃၃မာဝ-၃၄မာဝ	-				
၃၄မာဝ-၃၅မာဝ	-				

မှတ်ချက်- ဖြန့်ဝေပို့သံအဆင့်အနေဖြင့်မရှိပါ။




သီလဝါအတွေးဦးပွားရေးစနစ်အပိုင်း၊ အချို့စက်မှုစနစ်ဖြိုဖျက်တိုက်မှုအတွက်ဆွည့်သံနှင့်တွန်းခါမှုစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းခွင်သံစက်နေ့စဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃ ၊ ဒီဇင်ဘာလ ၂၀၂၃ ခုနှစ်)

ဇယား ၂.၄-၄ နေရာ-၂ (NV-2)၏နာရီအလိုက်ဆွည့်သံအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (LAeq)

ရက်စွဲ	အချိန်	ရလဒ် (LAeq, dB)	အချိန်အပိုင်းအခြား တစ်ခုစီအတွက် (LAeq, dB)	ရည်မှန်းတန်ဖိုး (LAeq, dB)	မှတ်ချက်
၁၁ ဒီဇင်ဘာလ ၂၀၂၃	၇:၀၀-၈:၀၀	-	၅၈	၆၀	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၈:၀၀-၉:၀၀	၄၆			
	၉:၀၀-၁၀:၀၀	၄၆			
	၁၀:၀၀-၁၁:၀၀	၄၃			
	၁၁:၀၀-၁၂:၀၀	၃၉			
	၁၂:၀၀-၁:၃၀	၄၅			
	၁:၃၀-၁:၄၀	၄၀			
	၁:၄၀-၁:၅၀	၄၅			
	၁:၅၀-၂:၀၀	၄၅			
	၂:၀၀-၂:၁၀	-			
	၂:၁၀-၂:၂၀	-			
	၂:၂၀-၂:၃၀	-			
	၂:၃၀-၂:၄၀	-	-	၄၀	
	၂:၄၀-၂:၅၀	-			
	၂:၅၀-၃:၀၀	-			
	၃:၀၀-၃:၁၀	-			
	၃:၁၀-၃:၂၀	-	-	၅၀	
	၃:၂၀-၃:၃၀	-			
	၃:၃၀-၃:၄၀	-			
	၃:၄၀-၃:၅၀	-			
	၃:၅၀-၄:၀၀	-			
	၄:၀၀-၄:၁၀	-			
	၄:၁၀-၄:၂၀	-			
	၄:၂၀-၄:၃၀	-			


မှတ်ချက် ပြန်လည်အင်တာနေရှင်နယ်လီတိုက်





မှတိုင်း မြန်မာ့စွန်အင်္ဂါတစ်ခုခုရှိနေပါသည်။

ပုံ ၂.၄-၁ ဇယား-၁ (NV-1) ၏ဆည်သံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်



မှတိုင်း မြန်မာ့စွန်အင်္ဂါတစ်ခုခုရှိနေပါသည်။

ပုံ ၂.၄-၂ ဇယား-၂ (NV-2) ၏ဆည်သံအဆင့်စောင့်ကြည့်လေ့လာမှုရလဒ်

တုန်ခါမှုစောင့်ကြည့်လေ့လာမှု ရလဒ်များ

တုန်ခါမှုစောင့်ကြည့်လေ့လာမှုရလဒ်များအား နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) နှစ်ခုလုံးအတွက် နေအချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)၊ ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ) နှင့် ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)ဟူ၍ အချိန်အပိုင်းအခြား ခွဲခြားသတ်မှတ်ထားပါသည်။ တုန်ခါမှုတိုင်းတာခြင်းအား သတ်မှတ်ထားသောနေရာတွင် ၂၄ နာရီကြာ တိုင်းတာမည့်အစား ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ တုန်ခါမှုအဆင့် (L_{eq}) စောင့်ကြည့်လေ့လာမှုရလဒ်များအား ဇယား ၂.၄-၅ နှင့် ဇယား ၂.၄-၆ တွင် ဖော်ပြထားပါသည်။ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ရှိ တစ်နာရီတုန်ခါမှုအဆင့် (L_{eq})၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များကို ဇယား ၂.၄-၇ နှင့် ဇယား ၂.၄-၈ တွင် ဖော်ပြထားပါသည်။ ပုံ ၂.၄-၃ နှင့် ပုံ ၂.၄-၄ တွင် နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ တုန်ခါမှုအဆင့်စောင့်ကြည့်လေ့လာမှု ရလဒ်များအတွက် ပြသထားပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်မြို့ပွဲ စီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်းအစီအရင်ခံစာတွင်ပါရှိသော လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင် ရည်မှန်းထားသော တုန်ခါမှုအဆင့်နှင့် နှိုင်းယှဉ်ရာ၌ ရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းသည်ကို တွေ့ရှိရသည်။

ဇယား ၂.၄-၅ နေရာ-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{eq})

ရက်စွဲ	ရိုးရှင်းစီးပွားရေးဆိုင်ရာနေရာများနှင့် စက်မှုဇုန်များ (L_{eq} , dB)		
	နေအချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၁၂ ဒီဇင်ဘာလ ၂၀၂၃	၃၈	-	-
ရည်မှန်းတန်ဖိုး	၇၀	၆၅	၆၅

မှတ်ချက်- ရည်မှန်းတန်ဖိုးများကို သီလဝါအထူးစီးပွားရေးဇုန် မြို့ပြတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ)အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရမည့် တုန်ခါမှုအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မှရင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတက်

ဇယား ၂.၄-၆ နေရာ- ၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{eq})

ရက်စွဲ	လူနေအိမ်များနှင့် ဘုန်းကြီးကျောင်း (L_{eq} , dB)		
	နေအချိန် (မနက် ၇ နာရီ မှ ည ၇ နာရီ)	ညနေခင်းအချိန် (ည ၇ နာရီ မှ ည ၁၀ နာရီ)	ညအချိန် (ည ၁၀ နာရီ မှ မနက် ၇ နာရီ)
၁၁ ဒီဇင်ဘာလ ၂၀၂၃	၂၂	-	-
ရည်မှန်းတန်ဖိုး	၆၅	၆၀	၆၀

မှတ်ချက်- ရည်မှန်းတန်ဖိုးများကို သီလဝါအထူးစီးပွားရေးဇုန် မြို့ပြတိုးတက်မှုစီမံကိန်း အပိုင်း(ခ)အတွက် လုပ်ငန်းလည်ပတ်နေစဉ် အဆင့်တွင်ရှိရမည့် တုန်ခါမှုအဆင့် ရည်မှန်းတန်ဖိုးကို အသုံးပြုထားပါသည်။

မှရင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတက်



ဇယား ၂-၄-၇ နေရာ-၁ (NV-1) စီနာရီအလိုက်တိုက်ရိုက်အသံစောင့်ကြည့်လေ့လာမှုရလဒ်များ (L₁₀)

ရက်စွဲ	အချိန်	ရလဒ် (L ₁₀ , dB)	အချိန်အပိုင်းအခြား တစ်ခုစီအတွက် (L ₁₀ , dB)	ရည်မှန်းတန်ဖိုး (L ₁₀ , dB)	မှတ်ချက်	
၁၂ ဒီဇင်ဘာလ ၂၀၂၃	၇:၀၀-၈:၀၀	-	၃၈	၇၀	ဆောက်လုပ်နေသည့်နေရာ လုပ်ဆောင်နေခြင်းအမျိုးမျိုး	
	၈:၀၀-၉:၀၀	၃၉				
	၉:၀၀-၁၀:၀၀	၃၈				
	၁၀:၀၀-၁၁:၀၀	၃၉				
	၁၁:၀၀-၁၂:၀၀	၃၇				
	၁၂:၀၀-၁:၃၀	၃၆				
	၁:၃၀-၁:၄၀	၃၇				
	၁:၄၀-၁:၅၀	၃၉				
	၁:၅၀-၂:၀၀	၃၉				
	၂:၀၀-၃:၀၀	-				
	၃:၀၀-၃:၁၀	-				
	၃:၁၀-၃:၂၀	-				
	၃:၂၀-၃:၃၀	-	-	၆၅		
	၃:၃၀-၃:၄၀	-				
	၃:၄၀-၃:၅၀	-				
	၃:၅၀-၄:၀၀	-	-	၆၅		
	၄:၀၀-၄:၁၀	-				
	၄:၁၀-၄:၂၀	-				
	၄:၂၀-၄:၃၀	-				
	၄:၃၀-၄:၄၀	-				
	၄:၄၀-၄:၅၀	-				
	၄:၅၀-၅:၀၀	-				
	၅:၀၀-၅:၁၀	-				
	၅:၁၀-၅:၂၀	-				
	၅:၂၀-၅:၃၀	-				
	၅:၃၀-၅:၄၀	-				

မှတ်ချက်: မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမီတာ




ဇယား ၂.၄-စ နေရာ-၂ (NV-2) စက်မှုအလိုက်တူနီမြို့စောင့်ကြည့်လေ့လာမှုရလဒ်များ (L_{max})

ရက်စွဲ	အချိန်	ရလဒ် (L _{max} , dB)	အချိန်အပိုင်းအခြား တစ်ခုစီအတွက် (L _{max} , dB)	ရည်မှန်းတန်ဖိုး (L _{max} , dB)	မှတ်ချက်
၀၁ ဒီဇင်ဘာလ ၂၀၂၃	၇၀၀-၈၀၀	-	၂၂	၆၅	ဆောက်လုပ်ရေးလုပ်ငန်း လုပ်ဆောင်နေခြင်းမရှိပါ။
	၈၀၀-၉၀၀	၂၂			
	၉၀၀-၁၀၀၀	၂၄			
	၁၀၀၀-၁၁၀၀	၂၄			
	၁၁၀၀-၁၂၀၀	၂၂			
	၁၂၀၀-၁၃၀၀	၁၉			
	၁၃၀၀-၁၄၀၀	၂၁			
	၁၄၀၀-၁၅၀၀	၂၃			
	၁၅၀၀-၁၆၀၀	၂၃			
	၁၆၀၀-၁၇၀၀	-			
	၁၇၀၀-၁၈၀၀	-			
	၁၈၀၀-၁၉၀၀	-			
	၁၉၀၀-၂၀၀၀	-	-	၆၀	
	၂၀၀၀-၂၁၀၀	-			
	၂၁၀၀-၂၂၀၀	-			
	၂၂၀၀-၂၃၀၀	-			
	၂၃၀၀-၂၄၀၀	-	-	၆၀	
	၂၄၀၀-၂၅၀၀	-			
	၂၅၀၀-၂၆၀၀	-			
	၂၆၀၀-၂၇၀၀	-			
	၂၇၀၀-၂၈၀၀	-			
	၂၈၀၀-၂၉၀၀	-			
	၂၉၀၀-၃၀၀၀	-			
	၃၀၀၀-၃၁၀၀	-			


မှရင်း မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီတီတော်





မှတ်ချက်- ပြန်မောင်းအဆင်တာနေရှင်နယ်လီမီတာကို

ပုံ ၂.၄-၃ ဇယား-၁ (NV-1) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်



မှတ်ချက်- ပြန်မောင်းအဆင်တာနေရှင်နယ်လီမီတာကို

ပုံ ၂.၄-၄ ဇယား-၂ (NV-2) ၏တုန်ခါမှုအဆင့် စောင့်ကြည့်လေ့လာမှုရလဒ်



အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ

သီလဝါ အထူးစီးပွားရေးဇုန် ဖွံ့ဖြိုးမှုစီမံကိန်း အပိုင်း(ခ)၏ ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်း အစီအရင်ခံစာတွင် ပါရှိသည့် လုပ်ငန်း လည်ပတ်နေစဉ် ကာလအတွက် သတ်မှတ်ထားသော ဆွဲသံ နှင့် တုန်ခါမှုအဆင့် ရည်မှန်းတန်ဖိုးများနှင့် နှိုင်းယှဉ်ရာ၌ နေရာ-၁ (NV-1) နှင့် နေရာ-၂ (NV-2) ၏ ဆွဲသံ နှင့် တုန်ခါမှုရလဒ်များသည် ရည်မှန်းတန်ဖိုးထက် လျော့နည်းနေသည်ကို တွေ့ရှိရသည်။ ထို့ကြောင့် ဇုန်အပိုင်း(ခ)မှ လည်ပတ်နေသော လုပ်ငန်းများကြောင့် ဖြစ်ပေါ်လာသော ဆွဲသံနှင့် တုန်ခါမှုသည် ဘေးပတ်ဝန်းကျင်အား သက်ရောက်မှုမရှိပါ။

ဤပတ်ဝန်းကျင် စောင့်ကြည့်လေ့လာမှုအား ကောက်ချက်ချရာတွင် စောင့်ကြည့်လေ့လာသော ကာလအတွင်း သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)အတွင်းရှိ စက်မှုမြေနေရာများမှ ဘေးပတ်ဝန်းကျင်အား သိသာထင်ရှားသော ဆွဲသံ နှင့် တုန်ခါမှုဆိုင်ရာ သက်ရောက်မှုများ မရှိကြောင်းတွေ့ရှိရပါသည်။



သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ
စက်မှုဇုန်ဖွံ့ဖြိုးတိုးတက်ရေးအတွက်
ယာဉ်သွားလာမှုနှုန်းစောင့်ကြည့်လေ့လာခြင်းအစီရင်ခံစာ
(လုပ်ငန်းလည်ပတ်နေစဉ်ကာလ အပိုင်း ၁၊ အပိုင်း ၂ နှင့် အပိုင်း ၃)

(တစ်နှစ်နှစ်ကြိမ် စောင့်ကြည့်လေ့လာခြင်း)

၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ
မြန်မာ့သို့အဲ အင်တာနေရှင်နယ် လီမိတက်



မာတိကာ

အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်	၁
၁.၁ ယေဘုယျ ဖော်ပြချက်	၁
၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ	၁
အခန်း ၂ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း	၂
၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား	၂
၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ	၃
၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း	၄
၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ	၄
အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ	၇

ဇယားများစာရင်း

ဇယား ၁.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသောအစီအစဉ်	၁
ဇယား ၂.၁-၁ ယာဉ်သွားလာမှုနှုန်းအတွက် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ	၂
ဇယား ၂.၁-၂ ယာဉ်အမျိုးအစားခွဲခြားခြင်း	၂
ဇယား ၂.၄-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း မှတ်တမ်းအကျဉ်းချုပ်	၅
ဇယား ၂.၄-၂ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (မလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့)	၆
ဇယား ၂.၄-၃ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဒဂုံ-သီလဝါလမ်းမှ မလမ်းကျေးရွာသို့)	၆

ပုံများစာရင်း

ပုံ ၂.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်တည်နေရာ	၃
ပုံ ၂.၃-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်းအခြေအနေ	၄



အခန်း ၁ စောင့်ကြည့်လေ့လာသော အစီအစဉ်နှင့်အကျဉ်းချုပ်

၁.၁ ယေဘုယျ ဖော်ပြချက်

သီလဝါအထူးစီးပွားရေးဇုန်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ တောင်ပိုင်းခရိုင်တွင်တည်ရှိပြီး ရန်ကုန်မြို့၏ အရှေ့တောင်ဘက် ၂၃ ကီလိုမီတာတွင် တည်ရှိပါသည်။ သီလဝါအထူးစီးပွားရေးဇုန်၏ အကောင်အထည် ဖော်ဆောင်သူအနေဖြင့် ဇုန်အပိုင်း(ခ)အတွင်းရှိ စက်မှုဓါတ်များအတွက် ခွင့်ပြုချက်ရရှိထားသော ပတ်ဝန်းကျင်ထိခိုက်မှုဆန်းစစ်ခြင်း အစီရင်ခံစာနှင့် ပတ်ဝန်းကျင်ဆိုင်ရာစီမံခန့်ခွဲမှုအစီအစဉ်အတိုင်း ပုံမှန်စောင့်ကြည့်စစ်ဆေးခြင်းကို ဆောင်ရွက်ရန် မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်တွင် တာဝန်ရှိပါသည်။ မြန်မာ-ဂျပန် သီလဝါဖွံ့ဖြိုးရေးလီမိတက်သည် ဇုန်အတွင်းနှင့် အနီးပတ်ဝန်းကျင်ရှိ သဘာဝပတ်ဝန်းကျင် အခြေအနေများကို သိရှိစေရန် သဘာဝပတ်ဝန်းကျင်နှင့်သက်ဆိုင်သော အချက်အလက်စောင့်ကြည့် လေ့လာမှုများကို ရေးဆွဲထားပြီး ထိုအစီအစဉ်များအရ အကောင်အထည်ဖော် ဆောင်ရွက်ခဲ့ပါသည်။

၁.၂ စောင့်ကြည့်လေ့လာသောအစီအစဉ်ဖော်ပြချက်များ

သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ) စက်မှုဇုန်လည်ပတ်နေခြင်းကြောင့် စက်မှုဇုန်အတွင်းနှင့်အပြင်ရှိ ပတ်ဝန်းကျင်အခြေအနေအား အကဲဖြတ်နိုင်ရန်အတွက် ယာဉ်သွားလာမှုနှုန်း တိုင်းတာမှုအား သတ်မှတ်ထားသောနေရာတွင် ၂၄ နာရီကြာ တိုင်းတာမည့်အစား၊ ဘေးအန္တရာယ်ကင်းရှင်းစေရန် နှင့် ဘေးကင်းလုံခြုံမှုရရှိစေရန် အလုပ်ချိန်အနေဖြင့် ၈ နာရီ (မနက် ၈ နာရီ မှ ညနေ ၄ နာရီ) ကြာ တိုင်းတာခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း တိုင်းတာမှုအား အကဲဖြတ်နိုင်ရန်အတွက် အောက်ပါဇယားတွင် ဖော်ပြထားသည့်အတိုင်း ၂၀၂၃ ခုနှစ်၊ ဒီဇင်ဘာလ ၁၂ ရက်နေ့တွင် ယာဉ်သွားလာမှုနှုန်းအား စောင့်ကြည့်လေ့လာခဲ့ပါသည်။

ဇယား ၁.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသောအစီအစဉ်

စောင့်ကြည့်လေ့လာသည့် ဗဟိုခွဲ	စောင့်ကြည့်လေ့လာမှု အမျိုးအစား	တိုင်းတာသော အမျိုးအစားများ	တိုင်းတာသောနေရာ အရေအတွက်	ကြာချိန်	စောင့်ကြည့်လေ့လာသော နည်းလမ်း
၁၂ ဒီဇင်ဘာလ ၂၀၂၃	ယာဉ်သွားလာမှုနှုန်း	-	နေရာ-၁ (TV-1)	၈ နာရီ	လူကိုယ်တိုင် တိုက်ရိုက်စောင့်ကြည့်၍ တာလီချိုမှတ်သားခြင်း

မှတ်- မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်



အခန်း ၂ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း

၂.၁ စောင့်ကြည့်လေ့လာသည့် အမျိုးအစား


ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသော အမျိုးအစားကို ဇယား ၂.၁-၁ တွင် ဖော်ပြထားပါသည်။ ယာဉ်များကို ဇယား ၂.၁-၂ တွင် အသေးစိတ်ဖော်ပြထားသည့်အတိုင်း၊ အမျိုးအစား ၄ မျိုး ခွဲခြားထားပါသည်။

ဇယား ၂.၁-၁ ယာဉ်သွားလာမှုနှုန်းအတွက် စောင့်ကြည့်လေ့လာသောအမျိုးအစားများ

စဉ်	စောင့်ကြည့်လေ့လာမှု	အမျိုးအစား
၁	ယာဉ်သွားလာမှုနှုန်း	ယာဉ်အမျိုးအစား (၄ မျိုး)

မှတ်။ ပြန်လည်အဆင်တာနေမှုနှင့်နယ်လီမီတာ

ဇယား ၂.၁-၂ ယာဉ်အမျိုးအစားခွဲခြားခြင်း

စဉ်	အမျိုးအစားခွဲခြားခြင်း		ဖော်ပြချက်
၁	နှစ်ဘီးတပ်ယာဉ် နှင့် ဘေးတွဲဆိုင်ကယ်		ဆိုင်ကယ်၊ ဘေးတွဲဆိုင်ကယ်(အငွားယာဉ်)
၂	လေးဘီးတပ်ယာဉ်ငယ်		ပစ်ကပ်ကား၊ ကွန်ကရစ် အငွားယာဉ်၊ ဆလွန်းကား၊ လိုက်ထရက် (၂ တန်အထက်)
၃	လေးဘီးတပ်ယာဉ်ကြီး		တစ်စက်ကားအလတ်၊ မှန်လုံကား၊ တစ်စက်ကားအကြီး၊ ထရပ်ကားအလတ်၊ ဝင်ရိုး ၂ခု၊ ၃ခု နှင့် ၄ခုထက်ပိုသော ထရပ်ကားအကြီး နှင့် နောက်တွဲယာဉ် (၄၅ တန်အထက်)
၄	အခြား		လယ်ထွန်စက်

မှတ်ချက်။ ယာဉ်အမျိုးအစားခွဲခြားခြင်းတွင် နှစ်ဘီးတပ်ယာဉ် နှင့် ဘေးတွဲဆိုင်ကယ်များအား နံပါတ် ၁ တွင် ထည့်သွင်းထားပါသည်။ ဘေးတွဲဆိုင်ကယ် ဆိုသည်မှာ ဘေးတွဲဆိုင်ကယ်ဖြစ်ပြီး ရည်ရွယ်ချက် ဆိုင်ကယ်အား ဘေးတွဲတပ်ဆင်ထားသော ယာဉ်အမျိုးအစားဖြစ်ပါသည်။

မှတ်။ ပြန်လည်အဆင်တာနေမှုနှင့်နယ်လီမီတာ



၂.၂ စောင့်ကြည့်လေ့လာသည့် တည်နေရာ

ယာဉ်သွားလာမှုနှုန်းအား သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)၏ အရှေ့မြောက်ဘက်ထောင့်၊ မြောက်လတ္တီတွဒ် ၁၆°၄၀'၁၇.၉၀" ၊ အရှေ့လောင်ဂျီတွဒ် ၉၆°၁၇'၁၈.၂၀"နေရာ၌ စောင့်ကြည့်လေ့လာခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသော တည်နေရာကို ပုံ ၂.၂-၁ တွင် ပြသထားပါသည်။



မူရင်း ပုံရိပ်အက်

ပုံ ၂.၂-၁ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်တည်နေရာ

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာသည့်နေရာ-၁ (TV-1)

စောင့်ကြည့်လေ့လာသည့် နေရာ-၁ (TV-1)သည် သီလဝါအထူးစီးပွားရေးဇုန် အပိုင်း(ခ)ရှိ လည်ပတ်နေသော လုပ်ငန်းခွင်၏ ပင်မကိတ်ပေါက်အရှေ့ဘက်ခြမ်းတွင်ရှိသော၊ သီလဝါဖွံ့ဖြိုးရေးလမ်း၏ ဘေးဘက်တွင်ရှိပါသည်။ စောင့်ကြည့်လေ့လာသည့်နေရာ၏ အနောက်မြောက်ဘက်တွင် ဇုန်အပိုင်း(က)နှင့် အရှေ့ဘက်တွင် ပြည်တွင်းစက်မှုဇုန်တို့ တည်ရှိပါသည်။



၂.၃ စောင့်ကြည့်လေ့လာသည့် နည်းလမ်း

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း ဆောင်ရွက်နေစဉ်တွင် ယာဉ်သွားလာမှုကြောင့် ဖြစ်ပေါ်နိုင်သော ဆူညံသံနှင့်တူနဲ့ခါမှတိုင်းတာခြင်းကိုပါ တစ်ပြိုင်နက်တည်း စနစ်ကျကျ ဆောင်ရွက်ခဲ့ပါသည်။ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာမှုကို ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့ လာသော ယာဉ်အရေအတွက်နှင့် ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့လာသော ယာဉ်အရေအတွက် အသီးသီးကို အမျိုးအစားအလိုက် ရေတွက်ခဲ့ပါသည်။ ယာဉ်အရေအတွက်ကို လူကိုယ်တိုင် တိုက်ရိုက်စောင့်ကြည့်၍ တာလီမျိုးမှတ်သားခြင်းဖြင့် မှတ်သားခဲ့ပါသည်။ နေရာ-၁ (TV-1)၌ ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်း အခြေအနေကို ပုံ ၂.၃-၁ တွင် ပြသထားသည်။



မှတ်စု ပြန်မာရုံအိမ်အင်တာနေရှင်နယ်လီမီတက်

ပုံ ၂.၃-၁ နေရာ-၁ (TV-1) ၌ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာခြင်းအခြေအနေ

၂.၄ စောင့်ကြည့်လေ့လာမှု ရလဒ်များ

ယာဉ်သွားလာမှုနှုန်း စောင့်ကြည့်လေ့လာမှုရလဒ်များအား ဇယား ၂.၄-၁ တွင် အကျဉ်းချုပ် ဖော်ပြထားသည်။ ယာဉ်တစ်မျိုးချင်းစီအတွက် တစ်နာရီအလိုက် အရေအတွက်ကို မှတ်သားထားပါသည်။ ရုံးဖွင့်ရက်များ (တနင်္လာနေ့ မှ သောကြာနေ့)၌ လေးဘီးတပ်ယာဉ်ငယ်များကို ပိုမိုအသုံးပြုမှုများကြောင်း ဇယား ၂.၄-၁ တွင် တွေ့နိုင်ပါသည်။ ဖလမ်းကျေးရွာဘက်မှ ဒဂုံ-သီလဝါ လမ်းဘက်သို့ သွားသော လေးဘီးတပ် ယာဉ်ကြီးများ အရေအတွက်သည် လေးဘီးတပ် ယာဉ်ငယ်များ အရေအတွက်ထက် သုံးဆခွဲ ပိုမိုနည်းပါးပြီး၊ ဒဂုံ-သီလဝါဘက်လမ်းမှ ဖလမ်းကျေးရွာဘက်သို့ လာသော လေးဘီးတပ် ယာဉ်ကြီးများ အရေအတွက်သည်လည်း လေးဘီးတပ် ယာဉ်ငယ်များ အရေအတွက်ထက် လေးဆ ပိုမိုနည်းပါးကြောင်း တွေ့ရသည်။

ဇယား ၂.၄-၁ နေရာ-၁ (TV-1) ၌ ယာဉ်သွားလာမှုစနစ် မှတ်တမ်းအကျဉ်းချုပ်

စစ်တမ်း ကောက်ယူ သောနေရာ	ဦးတည်ရာ	ရက်စွဲ	မှီဖွင့်ရက်များ (တနင်္လာနေ့ မှ သောကြာနေ့)	နှစ်သီးတပ် ယာဉ်	လေဆီး တပ် ယာဉ်မယ်	လေဆီး တပ် ယာဉ်ကြီး	အခြား	စုစုပေါင်း
နေရာ-၁ (TV-1)	ဖလမ်းကျေးရွာ မှ ဒဂုံ-သီလဝါလမ်း	၁၂ ဒီဇင်ဘာလ	အင်္ဂါနေ့	၂၆၉	၅၄၅	၁၅၈	၁၈	၉၉၀
	ဒဂုံ-သီလဝါလမ်း မှ ဖလမ်းကျေးရွာ	၂၀၂၃		၂၅၁	၆၅၂	၁၇၁	၁၅	၁၀၈၉

မူရင်း ပြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီတက်

နေရာ-၁ (TV-1) ၌ တစ်နာရီအလိုက် ယာဉ်သွားလာမှုစနစ်၏ စောင့်ကြည့်လေ့လာမှုရလဒ်များ အကျဉ်းချုပ်ကို ဇယား ၂.၄-၂ နှင့် ဇယား ၂.၄-၃ တွင် ဖော်ပြထားသည်။ ယာဉ်သွားလာမှုကို နှိုင်းယှဉ်ရာတွင် မနက်ပိုင်း ယာဉ်သွားလာမှု အများဆုံးအချိန်ဖြစ်သည့် စနေ ၈ မှ ၉ နာရီတွင် ဒဂုံ-သီလဝါလမ်းဘက်မှ ဖလမ်းကျေးရွာဘက်သို့ သွားသည့် ယာဉ်သွားလာမှုစနစ်သည် ဆန့်ကျင်ဘက်လမ်းကြောင်းအတိုင်း သွားသည့် ယာဉ်အရေအတွက်ထက် ပိုမိုများပါသည်။ ထိုနည်းတူစွာ နေ့လည်ခင်း ယာဉ်သွားလာမှုအများဆုံးအချိန်ဖြစ်သည့် ၁၅ နာရီ ၀၀ မှ ၁၆ နာရီ ၀၀ တွင် ဒဂုံ-သီလဝါလမ်းဘက်မှ ဖလမ်းကျေးရွာဘက်သို့ သွားသည့် ယာဉ်သွားလာမှုစနစ်သည်လည်း ၎င်း၏ ဆန့်ကျင်ဘက်အတိုင်း သွားသည့် ယာဉ်အရေအတွက်ထက် ပိုမိုများပါသည်။ ထိုသို့ ယာဉ်အရေအတွက်များ ရှိခြင်းမှာ အဆိုပါ စောင့်ကြည့်လေ့လာသော ကာလအတွင်း ဒဂုံ-သီလဝါလမ်းဘက်မှ ဖလမ်းကျေးရွာဘက်သို့ သွားသည့် လမ်းကြောင်း၌ မနက်ပိုင်း နှင့် နေ့လည်ခင်း ယာဉ်သွားလာမှု အများဆုံးအချိန်တို့တွင် အလုပ်သွားအလုပ်ပြန် ယာဉ်များ ဖြတ်သန်းသွားလာမှုကြောင့် ဖြစ်နိုင်ပါသည်။



ဇယား ၂.၄-၂ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဖလမ်းကျေးရွာမှ ဒဂုံ-သီလဝါလမ်းသို့)

မှ	အထိ	အမျိုးအစားခွဲခြားခြင်း				စုစုပေါင်း
		ယာဉ်အမျိုးအစား				
		နှစ်လီးတပ်ယာဉ်	လေးလီးတပ်ယာဉ် ငယ်	လေးလီးတပ်ယာဉ် ကြီး	အခြား	
၈၀၀	၉၀၀	၅၆	၆၅	၂၃	၃	၁၄၇
၉၀၀	၁၀၀၀	၃၂	၅၀	၁၁	၀	၉၃
၁၀၀၀	၁၁၀၀	၃၂	၆၅	၂၈	၄	၁၃၀
၁၁၀၀	၁၂၀၀	၃၂	၇၅	၁၉	၀	၁၂၆
၁၂၀၀	၁၃၀၀	၂၈	၈၂	၁၄	၃	၁၂၈
၁၃၀၀	၁၄၀၀	၂၆	၈၂	၂၀	၃	၁၃၁
၁၄၀၀	၁၅၀၀	၃၂	၆၄	၁၈	၃	၁၁၇
၁၅၀၀	၁၆၀၀	၃၀	၆၂	၂၄	၂	၁၁၈
စုစုပေါင်း		၂၆၉	၅၄၅	၁၅၈	၁၈	၉၉၀

မှရင်း၊ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

ဇယား ၂.၄-၃ နေရာ-၁ (TV-1)၌ နာရီအလိုက် ယာဉ်သွားလာမှုနှုန်းရလဒ် (ဒဂုံ-သီလဝါလမ်းမှ ဖလမ်းကျေးရွာသို့)

မှ	ထိ	အမျိုးအစားခွဲခြားခြင်း				စုစုပေါင်း
		ယာဉ်အမျိုးအစား				
		နှစ်လီးတပ်ယာဉ်	လေးလီးတပ်ယာဉ် ငယ်	လေးလီးတပ်ယာဉ် ကြီး	အခြား	
၈၀၀	၉၀၀	၅၃	၁၁၉	၂၄	၄	၂၀၀
၉၀၀	၁၀၀၀	၂၈	၅၅	၁၇	၂	၁၀၂
၁၀၀၀	၁၁၀၀	၂၆	၈၅	၂၂	၁	၁၃၄
၁၁၀၀	၁၂၀၀	၃၉	၇၈	၁၆	၂	၁၃၅
၁၂၀၀	၁၃၀၀	၂၅	၉၃	၁၆	၁	၁၃၅
၁၃၀၀	၁၄၀၀	၁၉	၈၃	၁၇	၄	၁၂၃
၁၄၀၀	၁၅၀၀	၃၀	၇၁	၃၅	၁	၁၃၇
၁၅၀၀	၁၆၀၀	၃၁	၆၈	၂၄	၀	၁၂၃
စုစုပေါင်း		၂၅၁	၆၅၂	၁၇၁	၁၅	၁၀၈၉

မှရင်း၊ မြန်မာနိုင်ငံအင်တာနေရှင်နယ်လီမိတက်

အခန်း ၃ နိဂုံးချုပ်နှင့်အကြံပြုချက်များ

စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ယာဉ်သွားလာမှုနှုန်းရလက်များအရ လေးဘီးတပ်ယာဉ်ငယ်များ ပိုမိုအသုံးပြုမှုများကြောင်း တွေ့ရှိရပါသည်။ လမ်းကြောင်းအသီးသီးတွင် သွားလာနေကြသော လေးဘီးတပ်ယာဉ်ကြီး အရေအတွက်မှာ လေးဘီးတပ်ယာဉ်ငယ် အရေအတွက်ထက် သုံးဆခွဲ နှင့် လေးဆ သီသီသာသာနည်းပါးကြောင်း တွေ့ရှိရသည်။ စောင့်ကြည့်လေ့လာသည့်ကာလအတွင်း ဆောက်လုပ်ရေး လုပ်ငန်းသုံးယာဉ် (လေးဘီးတပ်ယာဉ်ကြီးများ) အရေအတွက်ထက် အလုပ်သွားအလုပ်ပြန် အသုံးပြုသော ယာဉ်အရေအတွက်သည် ပိုများကြောင်း တွေ့ရှိနိုင်ပါသည်။

သီလဝါအထူးစီးပွားရေးဇုန်အပိုင်း(ခ)၏ လုပ်ငန်း လည်ပတ်နေစဉ်ကာလအတွင်း ယာဉ်သွားလာမှုနှုန်း အချက်အလက်များရရှိနိုင်ရန် ပုံမှန်စောင့်ကြည့်လေ့လာမှုများ လိုအပ်ပါသည်။ ယာဉ်သွားလာမှုနှုန်း အချက်အလက်များ လုံလောက်စွာ ရရှိပြီးနောက် အနာဂတ်တွင် ယာဉ်သွားလာမှုနှုန်း စီမံခန့်ခွဲမှုအတွက် သင့်တော်သောနည်းလမ်းများကို ထည့်သွင်းစဉ်းစားနိုင်ပါသည်။



End of Document

